

(CLASSIFICATION)

GENERAL ELECTRIC

HANFORD ATOMIC PRODUCTS OPERATION - RICHLAND, WASHINGTON

DOCUMENT NO.

HW-70807

SERIES AND COPY NO.

DATE

August 21, 1961

TITLE

RADIOCHEMISTRY FOR THE RUPTURE OF ZIRCALOY-2
CLAD HEAVY-WALLED TUBULAR FUEL ELEMENT IN
KER LOOP-3

OTHER OFFICIAL CLASSIFIED INFORMATION

THIS MATERIAL CONTAINS INFORMATION AFFECTING
THE NATIONAL DEFENSE OF THE UNITED STATES
WITHIN THE MEANING OF THE ESPIONAGE LAWS,
TITLE 18, U. S. C., SECS. 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER
TO AN UNAUTHORIZED PERSON IS PROHIBITED BY
LAW.

AUTHOR

L. D. Perrigo

ISSUING FILE

THIS DOCUMENT IS NOT TO BE LEFT UNATTENDED OR WHERE AN UNAUTHORIZED PERSON MAY HAVE ACCESS
TO IT. WHEN IN USE, IT MUST BE STORED IN AN UNLOCKED REPOSITORY WITH APPROVED
GUARDIAN. WHILE IT IS YOUR POSSESSION, YOU MUST OBTAIN A RECEIPT FROM THE
ISSUING FILE, IT IS YOUR RESPONSIBILITY TO KEEP IT AND ITS CONTENTS WITHIN THE LIMITS OF
THIS PROJECT AND FROM ANY UNAUTHORIZED PERSON. ITS TRANSMITTAL AND STORAGE AT YOUR PLACE
OF RESIDENCE IS PROHIBITED. IT IS NOT TO BE DUPLICATED. IF ADDITIONAL COPIES ARE REQUIRED,
OBTAIN THEM FROM THE RELATED ISSUING FILE. ALL PERSONS USING THIS DOCUMENT ARE REQUESTED
TO SIGN IN THE SPACE PROVIDED BELOW.

ROUTE TO:

PAYROLL NO.

LOCATION

FILES ROUTE
DATE

SIGNATURE AND DATE

SEP 6 - 1961

NOV 3 - 1961

NOV 10 - 1961

DECLASSIFIED

DECLASSIFIED

HW-70807

This document classified

by JA Ayres

This document consists of

8 pages, No. 17 of
23 copies. [REDACTED]DISTRIBUTION:

- | | |
|-----------------|----------------------------|
| 1. FW Albaugh | 13. WK Kratzer |
| 2. JA Ayres | 14. GA Last |
| 3. LV Barker | 15. CG Lewis |
| 4. JH Brown | 16. NR Miller |
| 5. RL Call | 17. SL Nelson - G Fiorelli |
| 6. AC Callen | 18. LD Perrigo |
| 7. TF Demmitt | 19. JL Stringer |
| 8. DR Dickinson | 20. RE Trumble |
| 9. TW Evans | 21. FW Woodfield |
| 10. GT Geering | 22. 300 File |
| 11. RB Hall | 23. Record Center |
| 12. NT Hildreth | |

August 21, 1961

RADIOCHEMISTRY FOR THE RUPTURE OF ZIRCALOY-2 CLAD
HEAVY-WALLED TUBULAR FUEL ELEMENT IN KER LOOP-3.

MASTER

L. D. Perrigo

Classification Cancelled and Changed To

DECLASSIFIEDBy Authority of R M DenCG-PR-2 3-2-94By J E Savely 3-15-95Verified By DK Harrison 3-25-94**DISCLAIMER****DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED.**

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DECLASSIFIED

-2-

HW-70807

RADIOCHEMISTRY FOR THE RUPTURE OF ZIRCALOY-2 CLAD
HEAVY-WALLED TUBULAR FUEL ELEMENT IN KER LOOP-3

INTRODUCTION

On the 0000 - 0800 shift, December 9, 1960, the delayed neutron monitor on KER Loop 3 gave a high coolant activity signal indicating a possible fuel element failure in this loop. KE Reactor was shut down immediately thereafter.

This report is being written to summarize the events pertinent to this KE Reactor scram and to discuss the results and significance of data from analyses on coolant and coupon samples taken from the KER Loop 3 system.

SUMMARY AND CONCLUSIONS

A high delayed neutron signal on the coolant in KER Loop 3 on December 9, 1960 indicated the possibility of a fuel element rupture. The KE Reactor was shut down. The fuel elements in this loop were discharged during the outage. A crack was found near the end cap weld on one fuel element in the 105 KE viewing pit. Further investigations in the 300 Area showed that several of the fuel elements had cracks at the base of the end caps.

Coolant samples were drawn from the KER Loop 3 system and subjected to radio-chemical analyses. Higher than normal concentrations of fission products were discovered.

DISCUSSION

There were two test objectives in the irradiation of the Zircaloy-2 jacketed heavy-walled tubular fuel elements in KER Loop 3.^(1,2) The first was to determine the behavior of these fuel elements during high-temperature operation. The second was to obtain irradiated, predefected, capped, heavy-walled Zircaloy-2 clad tubular fuel elements for in-reactors failure testing in this ETR after irradiation to a desired exposure in the KER Loops. The operating conditions in KER Loop 3 for this test were as follows:

1. Equilibrium effluent temperature - 270-280 C.
2. Temperature at time of rupture - 40 C.
3. Coolant pH - 9.9 maintained by flow through a lithium based ion exchange resin and LiOH additions.
4. Loop flow - 60 gpm.
5. Cleanup flow - 2-3 gpm.
6. System pressure - ~ 1600 psi.
7. Degasification rate - ~ 0.25 gpm.

KER Loop 3 is a stainless steel system with a Zircaloy-2 in-reactor tube. The operational chronology pertinent to this fuel failure is as follows:

1. July 3, 1960 - Charged Zircaloy-2 clad heavy walled tubular fuel elements in KER Loop 3.
2. October 27, 1960 - Charged 1 Zircaloy-2 clad predefected capped element in KER Loop-3.

DECLASSIFIED

HW-70807

3. ~ 0350 Dec. 9, 1960 - KER Loop 3 delayed neutron monitor began to rise.
4. ~ 0450 Dec. 9, 1960 - KER Loop 3 delayed neutron monitor went full scale.
KE Reactor shut down. KER Loop 3 began depressurization cycle.
5. ~ 0457 Dec. 9, 1960 - KER Loop 3 began single pass operation.
6. 0000 - 0800 shift, Dec. 9, 1960 - discharged KER Loop 3 fuel elements.

No noticeably discolored liquid passed from the process tube at the time of the discharge. Visual inspection of the heavy-walled tubular fuel elements in the KE viewing facility revealed that all were covered with dark adherent, comparatively thin oxide coatings along all heat generating surfaces. A 1/16" crack was found during this inspection on Element Number 17, a heavy-walled fuel element (not a capped defect specimen).* The uranium core was not visible. Inspection in the Radiometallurgical Facility 300 Area showed that five elements from the charge experienced a "necking-down" effect of the Zircaloy-2 at the base of the end cap. Cracks were found on all of these five.** The uranium cores were however not visible. All this information indicates that only a small amount of uranium was corroded from the fuel element responsible for the high activity signal. Shut down, discharge, handling and transfer doubtlessly aggravated the already deteriorated condition of these fuel pieces at the base of the end cap. Likewise for all of the cracks and "necking-down", there was only one piece from the charge that caused the high delayed neutron indications that caused the shut down of the KE Reactor. For cracks to appear simultaneously on two different fuel elements does not seem highly likely.

A. Coolant Radiochemical Analyses

A water sample was drawn from K-3 during the loop depressurization and dump cycle. Another was later drawn from the K-3 emergency storage tank. These samples were subjected to certain radiochemical procedures to determine fission product loadings in the water.

The data in Table I should be the best radiochemical data to date from a KER Loop rupture. Even though the loop was in its depressurization cycle there should not be very many diluting factors to modify the loadings that are actually present from this rupture.

* W. K. Kratzer - Personal Communication.

** G. T. Geering - Personal Communication.

DECLASSIFIED

TABLE I

Radioanalysis of KER Loop-3 Coolant During The
Rupturing Of A 16" Heavy-Walled Tubular Fuel Element

| <u>Isotope</u> | <u>Activity (in MAC /ml)</u> | <u>Isotope</u> | <u>Activity (in MAC /ml)</u> |
|------------------------------------|---|------------------|---|
| I ¹³¹ | 5.7 | Sc ⁴⁶ | 8 |
| La ¹⁴⁰ | 310 | Co ⁶⁰ | 12 |
| Ce ¹⁴³ | 410 | P ³² | 150 |
| Np ²³⁹ | .2 | Cu ⁶⁴ | 140 |
| Sm ¹⁵³ | 130 | Na ²⁴ | ND* |
| Ce ¹⁴⁴ | 970 | Mn ⁵⁶ | ND |
| Cs ¹³⁷ | 310 | As ⁷⁶ | ND |
| Zn ⁶⁵ | 27 | Sr ⁸⁹ | 80 |
| Zr ⁹⁵ -Nb ⁹⁵ | 270 | Sr ⁹⁰ | 26 |

* ND means nondetectable.

Following other ruptures, a sample was taken from the emergency storage for a radiochemical analysis.^(3,4,5,6) Certain modifying factors always influenced this data, however. The loadings in the emergency storage tank are lower by a factor of ~2.5 than those in the loop because the depressurization and dumping operation dilutes the coolant. Some settling of relatively large particulate matter probably, also, occurs in the tank before sampling. The thermal shock of the loop system seems to have caused some activity fluctuations such as the large increase of Cu⁶⁴ activity over normal conditions. These data are presented in Table II.

DECLASSIFIED

TABLE II

Radioanalysis Results of K-3 Emergency Storage Tank Water

| <u>Isotope</u> | <u>Activity</u> <u>(in mc c/ml)</u> | <u>Isotope</u> | <u>Activity</u> <u>(in mc c/ml)</u> |
|-------------------|---|------------------------------------|---|
| As ⁷⁶ | 200 | P ³² | 16 |
| Cr ⁵¹ | 57 | Zn ⁶⁵ | 3.7 |
| Np ²³⁹ | .2 | Sc | .9 |
| Sm ¹⁵³ | 210 | Co ⁶⁰ | 3.2 |
| Eu ¹⁵² | 35 | Zr ⁹⁵ -Nb ⁹⁵ | 56.0 |
| La ¹⁴⁰ | 41 | Sr ⁸⁹ | 73 |
| Ce ¹⁴³ | 50 | Sr ⁹⁰ | 1.8 |
| I ¹³¹ | 8.3 | | |
| Cu ⁶⁴ | 2100 | | |
| Ce ¹⁴⁴ | 220 | | |
| Cs ¹³⁷ | 19 | | |

A comparison of the data in Tables I and II with data from the coolant under normal conditions shows that most of the fission product activities were higher than normal. A few such as I¹³¹ were of comparable levels. From a radiochemical standpoint there is, however, little doubt that there was a rupture in KER Loop 3. The difference in the fission product spectrum for the rupture in this case can be attributed to the type of fuel element failure. Examination of the fuel pieces revealed that there was little corrosion of the uranium core. Most of the species that were in the coolant were the daughters of gaseous or very soluble species and could therefore be easily transferred to the coolant with only small portions of the uranium seeing the coolant.

A small amount of fission products is observed in the coolant during normal operation.^(3,4,5,6) This is presumed to be primarily due to fissioning of the uranium impurity in the Zircaloy-2 process tube and the resulting recoil of the products into the coolant stream. Some diffusion from the fuel elements probably also occurs.

B. Instrumentation Response


The first indication of a fuel element failure in KER Loop 3 was given by a

DECLASSIFIED

HW-70807

rise in the activity indicated on the delayed neutron monitor at approximately 0350 December 9, 1960. By changing the scale from 0 - 250 neutrons/sec to 0 - 500 neutrons/sec the increase in instrument readings was only momentarily checked. At 0450 the readings were such that the KE Reactor shut down. These fluctuations are seen in Figure 1.

The three precursors known with certainty that give delayed neutrons are Br^{87} , $t_{1/2}$, 54 sec; Br^{89} , $t_{1/2}$, 5.8 sec; and I^{137} , $t_{1/2}$, 22 sec. The I^{137} isotope decays according to the following scheme:




The Cs^{137} isotope, a I^{137} daughter, was determined in the two samples by radiochemical analyses. These concentrations were higher than normal. No attempt was made to correlate delayed neutron monitor signal height with concentration and fuel element irradiation: but the presence of Cs^{137} at these higher concentrations suggests that there were significant quantities of delayed neutron emitters in the coolant to cause a higher than normal instrument response.

Only very weak sympathetic delayed neutron responses were noted on KER Loops 2 and 4.

Another interesting factor can be noted by comparing the delayed neutron response on KER Loop 3 with a rupture (Figure 1) and the response on KER Loop 1 with a rupture (Figure 2). Figure 1 shows a rise in activity occurring over a period of nearly an hour while Figure 2 shows an abrupt rise that could not be checked even by an instrument scale change.⁽⁴⁾ This behavior sheds light on the difference in rupture mechanisms. The response in KER Loop 3 resulted from the exposure of a small amount of the uranium core to the coolant at low temperatures while the KER Loop 1 failure resulted from the rupture of a blister that discharged at high temperature, relatively large quantities of rupture products very rapidly into the coolant.

ACKNOWLEDGEMENT

The efforts of W. C. Johnson and his coworkers in the Purex Analytical Operation are gratefully acknowledged. C. L. Buckner, IPD, assisted in obtaining KER charts and rupture data. KER Loop 3 is operated by the Coolant Testing Unit, IPD.


 L. D. Perrigo
 Coolant Systems Development Operation
 HANFORD LABORATORIES OPERATION

LDP:mf

DECLASSIFIED




FIGURE 1. KER Loop 3 Delayed Neutron Indications.




FIGURE 2. KER Loop 1 Delayed Neutron Indications

DECLASSIFIED

BIBLIOGRAPHY

1. Kratzer, W.K., Production Test IP-309-A, Irradiation of Heavy Walled Tubular Elements in the KER Loops, HW-64183, Secret.
2. Kratzer, W.K., Supplement A Production Test IP-309-A Irradiation of Heavy Walled Tubular Elements in the KER Loops. HW-65476, Secret.
3. Perrigo, L.D., Radiochemistry for the Rupture of a Zircaloy-2 Clad 36" Tube in Tube Fuel Element in KER Loop 4. HW-66777, Secret.
4. Perrigo, L.D., Radiochemistry for the Rupture of a Zircaloy-2 Clad Seven Rod Cluster Element in KER Loop 1. HW-64355, Secret.
5. Perrigo, L.D., Radiochemistry for the Rupture of a Zircaloy-2 Clad Seven Rod Cluster Fuel Element in KER Loop 2.
6. Perrigo, L.D., Radiochemistry for the Rupture of a Tube in Tube Fuel Element in KER Loop 3, HW-62677, Secret.

DATE

FILMED

8/2/94

END

