

LA-UR- 11-04934

Approved for public release;
distribution is unlimited.

Title: High Performance Sustainable Buildings *HPSB*
Re-commissioning at LANL
(RC x)

Author(s): Cindy Dilworth

Intended for: Public Release



Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the Los Alamos National Security, LLC for the National Nuclear Security Administration of the U.S. Department of Energy under contract DE-AC52-06NA25396. By acceptance of this article, the publisher recognizes that the U.S. Government retains a nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

Abstract:

Retro-commissioning (RCx) provides the opportunity to go beyond the standardized maintenance and energy management procedures that appear as facility documentation; RCx provides a systematic approach for discovering and resolving chronic building concerns. Typical issues that are uncovered during the RCx process pivot around ineffective building control systems, poor monitoring of energy consumption, repetitive repairs, and inadequate maintenance.

Lessons learned in RCx demonstrate that there are many low-cost/no-cost repairs and adjustments that can be implemented to restore building performance, occupant comfort and energy optimization.

UNCLASSIFIED

HPSB
Re-Commissioning (RCx)
at LANL



UNCLASSIFIED



TA 03-1411 Occupational Medical Building

The HPSB (High Performance Sustainable Buildings) program at LANL has targeted 5 buildings for re-commissioning in FY2011.

The goal of the program is to reduce energy consumption and qualify for LEED rating.

With existing buildings, the key to achieve LEED certification is with optimizing facility operation and maintenance through re-commissioning.

TA 03-1411 Occupational Medical Building

The five buildings selected for the HPSB program in FY2011 are:

03-1411 Occupational Medical Building

03-1409 Security Systems Support Facility

03-1400 NSSB

60-0175 Communication Ops Building

63-0111 Office Building

TA 03-1411 *Occupational Medical Building*



TA 03-1411 *Occupational Medical Building*

Original construction: 2003

Type: Single story medical facility

Size: 14,250 ft²

HVAC: (1) 55 ton air handling unit
DX cooling, hot water heating

Rated: 22,000 cfm supply
18,800 cfm exhaust

TA 03-1411 *Occupational Medical Building*

With existing buildings, the most effective energy reduction measures are achieved with lighting and HVAC operational improvements.

Re-lamping, de-lamping, occupancy controls and *daylight* analysis activities were performed under a separate part of the HPSB program.

The bulk of the remaining energy saving opportunities are based on the re-commissioning role in operation and control of the HVAC and air distribution system.

TA 03-1411 *Occupational Medical Building*

Major components of the 03-1411 HVAC system include:

TRANE Air Handling Unit
Supply and Exhaust fan VFDs
Economizer w/Fresh Air Damper

Steam/water heat exchanger

34 VAV Terminals each with:
Individual thermostatic control
Damper regulated air volume
Hot water reheat with 3-way valve

TA 03-1411 *Occupational Medical Building*

AHU evaluation was conducted by performing system shutdown and entering each compartment to review components.

Random VAV terminals were located by removing ceiling panels and using system drawings as a guideline.

Thermostats were verified using a calibrated temperature sensor.

Airflow volumes were measured using a flow hood at supply and return air diffusers.

TA 03-1411 *Occupational Medical Building*

AHU Concerns

Exhaust Fan Mounting

Not secured at base – ineffective discharge through “relief air” louvers

Damper Actuator and Linkage

Poor stroke adjustment and alignment

Filters

Automatic alarm reset doesn't get response
Installation method

TA 03-1411 *Occupational Medical Building*



TA 03-1411 *Occupational Medical Building*



TA 03-1411 *Occupational Medical Building*



UNCLASSIFIED

TA 03-1411 *Occupational Medical Building*



UNCLASSIFIED

Slide 12

TA 03-1411 Occupational Medical Building

Control System Concerns

Limited interface between TRANE control package and Building Automation System

System remains in “Occupied” mode 24/7
No night / weekend setback

Redundant sensors do not have equal values

TA 03-1411 Occupational Medical Building

System Air Balance Concerns

Inappropriate supply diffusers used for high-bay ceiling

Common return air plenum results in uncontrolled airflow and poor distribution

Total supply air volume averages 20% lower than design

TA 03-1411 *Occupational Medical Building*

In addition to concerns with the facility HVAC, the following building issues were revealed:

No access to exhaust fans on roof

Double doors at entry vestibules not working

Excessively chilled supply air (45°F) results in drips and condensate stains on ceiling tiles

TA 03-1411 *Occupational Medical Building*



TA 03-1411 *Occupational Medical Building*

Follow-up Activities Include

- Mechanical repairs for air handler
- System communication and controls re-work
- Change supply and return air diffusers, as required
- Access fans on roof and repair as required
- Re-balance airflow distribution, validate upgraded sequence of operations
- Repair/replace entry vestibule automatic doors
- Develop O&M hand-over manual