




DOCUMENT RELEASE FORM

(1) Document Number: RPP-RPT-56464		(2) Revision Number: 0	(3) Effective Date: 1/20/2014	
(4) Document Type: <input type="checkbox"/> Digital Image <input type="checkbox"/> Hard copy <input checked="" type="checkbox"/> PDF <input type="checkbox"/> Video		(a) Number of pages (including the DRF) or number of digital images 66 1/20/14		
(5) Release Type <input checked="" type="checkbox"/> New <input type="checkbox"/> Cancel		<input type="checkbox"/> Page Change	<input type="checkbox"/> Complete Revision	
(6) Document Title: 241-AY-102 Leak Detection Pit Drain Line Inspection Report		(7) USQ No.: R- <input checked="" type="checkbox"/> N/A	USQ Evaluator Sign/Date	
(8) Change/Release Description: Initial Release				
(9) Change Justification: Initial Release				
(10) Associated Structure, System, and Component (SSC) and Building Number:	(a) Structure Location: 200E		(c) Building Number: 241-AY-102 <input type="checkbox"/> Project Number: N/A	
	(b) System Designator: N/A		(d) Equipment ID Number (EIN): N/A	
(11) Impacted Documents:	(a) Document Type N/A		(b) Document Number N/A <input type="checkbox"/> Document Revision N/A	
(12) Approvals:				
(a) Author (Print/Sign): B.J. Vazquez 		Date: 12/17/2013		
(b) Reviewer (Optional, Print/Sign): K.D. Boomer 		Date: 12/18/2013	Date: _____	
		Date: _____	Date: _____	
		Date: _____	Date: _____	
(c) Responsible Manager (Print/Sign): D.G. Baide 		Date: 12/26/13		
(13) Distribution:				
(a) Name see attached	(b) MSIN	(a) Name _____	(b) MSIN _____	Release Stamp
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
(14) Clearance <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		(b) Restricted Information? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		(c) Restriction Type:
(15) Clearance Review (Print/Sign):		APPROVED By Janis D. Aardal at 12:49 pm, Jan 20, 2014		Date:

DISTRIBUTION SHEET

To Distribution	From B.J. Vazquez	Page	<u>1 Of 2</u>		
		Date	17-Dec-2013		
Project Title/Work Order		EDT No.	DRF		
241-AY-102 Leak Detection Pit Drain Line Inspection Report		ECN No.	N/A		
Name	MSIN	Text With All Attach.	Text Only	Attach./Appendix Only	EDT/ECN Only
K.D. Boomer	R2-53	x			
W.C. Clark	H6-63	x			
J.K. Engeman	R3-26	x			
J.S. Garfield	R2-53	x			
D.J. Houghton	R2-58	x			
W.L. Isom	R2-58	x			
J.M. Johnson	H6-60	x			
S.E. Killoy	R1-51	x			
K.M. Leonard	S7-08	x			
D.B. Little	R2-58	x			
E.M. Mattlin	R2-52	x			
T.L. Sams	R2-52	x			
S.P. Guillot	S7-08	x			
D.G. Baide	R3-26	x			
D.M. Jorgensen	S7-92	x			
G.J. McCallum	S7-08	x			
D. Scott	R3-26	x			
B.J. Vazquez	R2-53	x			
T.J. Venetz	R2-53	x			
J.A. Voogd	R1-51	x			
D.J. Washenfelder	R2-53	x			
R.E. Wilkinson	R3-27	x			
K.G. Duncan	R2-53	x			
F.A. Jensen	S7-68	x			
R.E. Gregory	S7-68	x			
J.E. Geary	R3-26	x			

DISTRIBUTION SHEET

INFORMATION CLEARANCE REVIEW AND RELEASE APPROVAL

Part I: Background Information

Title: 241-AY-102 Leak Detection Pit Drain Line Inspection Report		Information Category: <input type="checkbox"/> Abstract <input type="checkbox"/> Journal Article <input type="checkbox"/> Summary <input type="checkbox"/> Internet <input type="checkbox"/> Visual Aid <input type="checkbox"/> Software <input type="checkbox"/> Full Paper <input checked="" type="checkbox"/> Report <input type="checkbox"/> Other
Publish to OSTI? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		

Document Number: RPP-RPT-56464, Rev 0

Date: 17-Dec-13

Author: KD Boomer et al.

Purpose of Document: Report on visual inspection of 241-AY-102 Leak Detection Pit Drain Line.

Part II: External/Public Presentation Information

Conference Name: N/A

Sponsoring Organization(s): N/A

Date of Conference: N/A Conference Location: N/A

Will Material be Handed Out? Yes No Will Information be Published? Yes No (If Yes, attach copy of Conference format instructions/guidance.)

Part III: WRPS Document Originator Checklist

Description	Yes	N/A	Signature
Information Product meets requirements in TFC-BSM-AD-C-01?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Document Release Criteria in TFC-ENG-DESIGN-C-25 completed? (Attach checklist)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
If product contains pictures, safety review completed?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	H. K. Lawrence, E-mail Pg. 3

Part IV: WRPS Internal Review

Function	Organization	Date	Print Name/Signature/Date
Subject Matter Expert	Tk & Pipeln Integrity	17-Dec-13	S. J. Venetz / T. J. Venetz 12/17/2013
Responsible Manager	Tk & Pipeln Integrity	17-Dec-13	D. B. Reid / D. B. Reid 12/26/13
Other:			

Part V: IRM Clearance Services Review

Description	Yes	No	Print Name/Signature
Document Contains Classified Information?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	If Answer is "Yes," ADC Approval Required Print Name/Signature/Date
Document Contains Information Restricted by DOE Operational Security Guidelines?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Reviewer Signature: Print Name/Signature/Date
Document is Subject to Release Restrictions? <i>If the answer is "Yes," please mark category at right and describe limitation or responsible organization below:</i>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Document contains: <input type="checkbox"/> Applied Technology <input type="checkbox"/> Protected CRADA <input type="checkbox"/> Personal/Private <input type="checkbox"/> Export Controlled <input type="checkbox"/> Proprietary <input type="checkbox"/> Procurement - Sensitive <input type="checkbox"/> Patentable Info. <input type="checkbox"/> Business - Sensitive <input type="checkbox"/> Predecisional Info. <input type="checkbox"/> UNCNI <input type="checkbox"/> Restricted by Operational Security Guidelines <input type="checkbox"/> Other (Specify)
Additional Comments from Information Clearance Specialist Review?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Information Clearance Specialist Approval <div style="background-color: #90EE90; border: 1px solid black; padding: 2px; text-align: center;"> APPROVED </div> By Janis D. Aardal at 12:50 pm, Jan 20, 2014 Print Name/Signature/Date

When IRM Clearance Review is Complete – Return to WRPS Originator for Final Signature Routing (Part VI)

Part VI: Final Review and Approvals

1544

INFORMATION CLEARANCE REVIEW AND RELEASE APPROVAL

Description	Approved for Release		Print Name/Signature
	Yes	N/A	
WRPS External Affairs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	John Britton John Britton
WRPS Office of Chief Counsel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	John Britton
DOE - ORP Public Affairs/Communications	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Steve Belliveau Steve Belliveau
Other:	<input type="checkbox"/>	<input type="checkbox"/>	
Other:	<input type="checkbox"/>	<input type="checkbox"/>	

Comments:

APPROVED

By Janis D. Aardal at 12:51 pm, Jan 20, 2014

**Approved for Public Release;
Further Dissemination Unlimited**

Information Release Station

Was/Is Information Product Approved for Release? Yes No

If Yes, what is the Level of Releaser? Public/Unrestricted Other (Specify) _____

Date Information Product Stamped/Marked for Release: 01/20/2014

Was/Is Information Product Transferred to OSTI? Yes No

Forward Copies of Completed Form to WRPS Originator and WRPS CIO Office

Description	Yes	N/A	Print Name/Signature
WRPS Information Product	<input type="checkbox"/>	<input type="checkbox"/>	
Conference Paper Guidelines	<input type="checkbox"/>	<input type="checkbox"/>	
Trademark/Copyright "Right to Use" Information or Permission Documentation	<input type="checkbox"/>	<input type="checkbox"/>	
WRPS Administrative Checklist	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	

Venetz, Theodore J

From: Lawrence, Hugh K
Sent: Monday, December 30, 2013 8:53 AM
To: Venetz, Theodore J; Wolfley, Clinton T
Cc: Vazquez, Brandon J; Boomer, Kayle D; Kunz, Ashley C
Subject: RE: Safety review for external clearance RPP-RPT-56464

Ted,

I have reviewed the photos contained in the document "*241-AY-102 Leak Detection Pit Drain Line Inspection Report*", as requested, from an industrial safety point of view. Based on that review the photos are **approved** for use.

Any question or comment, please ask.

Hugh Lawrence
WRPS Safety Programs
cell (208) 547-7334

From: Venetz, Theodore J
Sent: Thursday, December 26, 2013 9:19 AM
To: Lawrence, Hugh K; Wolfley, Clinton T
Cc: Vazquez, Brandon J; Boomer, Kayle D
Subject: Safety review for external clearance RPP-RPT-56464

Hugh, Clint

I need safety review for this document. It is the AY-102 Leak Detection Pit Drain Line Inspection Report and will be approved for Public Release. An email back ifs fine.

<http://idmsweb.rl.gov/idms/livelink.exe?func=ll&objId=180526069&objAction=Open&nexturl=%2Fidms%2Flivelink%2Ee xe%3Ffunc%3D%26objId%3D180528041%26objAction%3Dbrowse%26viewType%3D1>

Thanks
Ted Venetz
376-9669

241-AY-102 Leak Detection Pit Drain Line Inspection Report

K.D. Boomer, J.K. Engeman

J.R. Gunter, C.C. Joslyn,

B.J. Vazquez, T.J. Venetz

Washington River Protection Solutions, LLC.

Richland, WA 99352

U.S. Department of Energy Contract DE-AC27-08RV14800

EDT/ECN: DRF

UC: N/A

Cost Center: 2KE00

Charge Code: 201334

B&R Code: N/A

Total Pages: 66 JDA 1/20/14

Key Words: Robot, Inspection, Tank 241-AY-102, IHI Southwest Technologies Inc., Leak Detection Pit

Abstract: This document provides a description of the design components, operational approach, and results from the Tank AY 102 leak detection pit drain piping visual inspection. To perform this inspection, a custom robotic crawler with a deployment device was designed, built, and operated by IHI for WRPS to inspect the 6 in. leak detection pit drain line.

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

APPROVED

By Janis D. Aardal at 12:51 pm, Jan 20, 2014

Release Approval

Date

DATE:

Jan 20, 2014

HANFORD
RELEASE

Release Stamp

Approved For Public Release

241-AY-102 Leak Detection Pit Drain Line Inspection Report

B. J. Vazquez
J. K. Engeman
K.D. Boomer
T. J. Venetz
J. R. Gunter
C. C. Joslyn
Washington River Protection Solutions, LLC

J. S. Garfield
A E M Consulting, LLC

Date Published
December 17, 2013

Prepared for the U.S. Department of Energy
Office of River Protection



Contractor for the U.S. Department of Energy
Office of River Protection under Contract DE-AC27-08RV14800

P.O. Box 850
Richland, Washington

EXECUTIVE SUMMARY

On November 20, 2013, Washington River Protection Solutions LLC (WRPS) inspected the 6-in. diameter drain line that collects liquid outside of Tank 241-AY-102 (referred to herein as Tank AY-102) secondary containment and routes the liquid to the leak detection pit sump. To accomplish this inspection on an accelerated timescale, WRPS used an integrated team employing both IHI Southwest Technologies, Inc. (IHI) and Hanford personnel. To ensure success when deployed in the field, the inspection equipment was demonstrated at both the IHI facility in Denver, Colorado, and the Hanford Site.

This document provides a description of the design components, operational approach, and results from the Tank AY-102 leak detection pit drain piping visual inspection. To perform this inspection, a custom robotic crawler with a deployment device was designed, built, and operated by IHI for WRPS to inspect the 6-in. leak detection pit drain line. These tasks were accomplished, from initial award of the work to completion of the inspection, in about two months.

The deployment device successfully attached to the drain line, and the crawler entered the drain line and traversed to within approximately 7 feet of the central sump located under the center of the tank before losing traction. The crawler performed well, and the quality of the camera image and lighting provided sufficient detail to document the current condition of the visible regions of the pipe.

The inspection showed that the majority of the drain line was dry. Two wet areas were observed, a portion of the line nearest the leak detection pit and a portion near the center of the tank. The portion nearest the leak detection pit was under water prior to pumping on November 14, 2013. The portion of pipe near the center of the tank showed an accumulation of moisture.

The visual results from the inspection are listed below, starting from the leak detection pit riser and moving toward the center of the tank (Figure ES-1 provides leak detection pit drain pipe features):

1. Starting at the entry point, the drain line was wet with considerable debris (i.e., dirt, scale, and miscellaneous items from construction) and corrosion in the bottom of the pipe into an expansion loop containing four elbows. Between the third and fourth elbows, the pipe transitioned to a dry environment. This change from wet to dry conditions is believed to be consistent with the level of the water in the leak detection pit prior to pumping, which occurred six days prior to the inspection.
2. Beyond the expansion loop elbows to the first and second tee, the drain line was very dry and showed no evidence of dripping or drainage from the 4-in. drain lines from the base pad slots. These sections showed less debris and corrosion product in the bottom of the pipe.
3. Past the second tee, the piping was wetted with moisture circumferentially, and a similar volume of debris and corrosion product was evident compared to the portion of the line nearest to the leak detection pit.
4. The central sump was not observed since the crawler could not traverse the last 7 feet to reach the center of the tank due to a combination of the debris and moisture present.




Figure ES-1 Tank AY-102 Leak Detection Pit

Although sediment and debris were seen during the inspection, it is believed to be construction debris and corrosion products. No material was found in the inspection that looked like tank waste or the material seen in the Tank AY-102 annulus (i.e., no greenish or yellowish deposits or dark fluids, dried salt deposits, or crystalline material). The contamination levels seen on the crawler were consistent with past values seen on leak detection pit pumping equipment. Sampling and analysis of the recovered residues from the crawlers did not find material consistent with tank waste.

CONTENTS

1.0	INTRODUCTION/BACKGROUND	1-1
1.1	Leak Detection Pit System Description	1-1
1.2	Temperature Gradients in the Tank Bottom.....	1-5
1.3	Water Intrusion Pathway	1-7
1.3.1	Previous Visual Inspection of 241-AY-102 Leak Detection Pit.....	1-8
1.3.2	Airflow through the Leak Detection Pit Drain.....	1-9
1.4	Past Intrusion Investigations and Activity Levels.....	1-11
2.0	EQUIPMENT DESCRIPTION.....	2-1
2.1	IHI-Supplied Robotic Pipe Inspection Equipment.....	2-1
2.2	Onsite Demonstration.....	2-2
3.0	VISUAL OBSERVATIONS FROM DRAIN INSPECTION	3-1
3.1	Historic Waterline Review	3-12
3.2	Analysis of Solids on the Crawler and Tether.....	3-14
4.0	DISCUSSION	4-1
4.1	Summary Observations	4-1
4.2	Possible Intrusion Pathways.....	4-2
5.0	RECOMMENDED PATH FORWARD	5-1
6.0	REFERENCES.....	6-1

APPENDIX

Appendix A – Leak Detection Pit Intrusion Rates and Vacuum	A-i
Appendix B– Tank AY 102 Temperature Gradients in the Refractory and Foundation	B-i

FIGURES

Figure 1-1.	Foundation Drain Locations	1-2
Figure 1-2.	Leak Detection Pits Riser for the AY Farm Tanks (8160-1) (Tank AY-102 in background)	1-2
Figure 1-3.	Original Leak Detection Pit Construction (Photo 64090-21) (SY Farm, June 21, 1974).....	1-3
Figure 1-4.	Ventilation Air Supply (primary tank not shown for clarity. Refractory air slots shown transparent.).....	1-4
Figure 1-5.	AY Farm Foundation Fabrication with Leak Detection Drains in Place (Photo 8000-1) (9/25/1968)	1-5
Figure 1-6.	Workers Cleaning Debris from Foundation Drain Slots Prior to Lowering Secondary Tank Bottom (Photo 8096-1)	1-5
Figure 1-7.	Central Plenum and Sump Arrangement for Tank AY-102	1-6
Figure 1-8.	Air Distribution Piping and Slots (cooling effect).....	1-7
Figure 1-9.	Tank AY-102 Leak Detection Pit Intrusion Pathway	1-8
Figure 1-10.	Tank AY-102 Leak Detection Pit Drain Line	1-9
Figure 1-11.	Tank AY-102 Leak Detection Pit Drain Line Interior During 2012 Inspection.....	1-9
Figure 1-12.	Tank AY-102 Leak Detection Pit Drain Line Airflow Test (October 2012)....	1-10
Figure 1-13.	Photos from Video Showing Bubbling from Drain Line on 12/19/2012 (A). Photos from Video Showing Drain Line Just Underwater and No Bubbling on 9/18/2012 (B)	1-10
Figure 2-1.	Robotic Pipe Crawler	2-1
Figure 2-2.	Delivery Mechanism and Crawler Relationship	2-2
Figure 2-3.	Onsite Leak Detection Pit Mockup Demonstration	2-3
Figure 3-1.	Inspection Overview	3-1
Figure 3-2.	Inspection Photograph Location Identification and Thermocouple Layout	3-2
Figure 3-3.	View of 6-in. Drain Line Prior to Crawler Leaving Deployment System	3-3
Figure 3-4.	View of 6-in. Drain Line with Crawler Traversing Towards First Elbow.....	3-3
Figure 3-5.	View of First Elbow Prior to Entering	3-4
Figure 3-6.	View of 6-in. Drain Line Directly After First Elbow	3-4
Figure 3-7.	View of 6-in. Drain Line Part Way Between First and Second Elbow	3-4
Figure 3-8.	View of Second Elbow Prior to Entering	3-5
Figure 3-9.	View of 6-in. Drain Line Directly After Second Elbow.....	3-5
Figure 3-10.	View of Standing Liquid on the Bottom of the Drain Line (Reflection).....	3-5

Figure 3-11. View of Third Elbow Prior to Entering	3-6
Figure 3-12. View of 6-in. Drain Line Directly After Third Elbow.....	3-6
Figure 3-13. View of Region Downstream of Third Elbow (a distinct color change, perhaps a transition to a completely dry region).....	3-6
Figure 3-14. View of Debris on the Bottom of the Drain Line Just Prior to Entering Fourth Elbow (very dry)	3-7
Figure 3-15. View of Fourth Elbow Prior to Entering.....	3-7
Figure 3-16. View of 6-in. Drain Line Directly After Fourth Elbow.....	3-7
Figure 3-17. View of 4-in. Tee Entering the Side of the 6-in. Drain Line	3-8
Figure 3-18. View of 6-in. Drain Line Approximately 10 ft After the First Tee	3-8
Figure 3-19. View of Debris on the Bottom of the Drain Line (about 2 ft from second tee).....	3-8
Figure 3-20. View of Moisture Seen after Second 4-in. Tee	3-9
Figure 3-21. View of 4-in. Tee Connecting to 6-in. Drain Line.....	3-9
Figure 3-22. View of Corrosion Along 6-in. Drain Line (in region where moisture was seen after second tee).....	3-9
Figure 3-23. View of 6-in. Drain Line a Couple Feet after Second Tee.....	3-10
Figure 3-24. Partial View of the Saturated Debris on the Bottom of the Drain Line, Which Stopped Crawler Progress (approximately 7 ft from center of the tank)	3-10
Figure 3-25. Last View Looking Down 6-in. Drain Line (approximately 7 ft from center of the tank)	3-10
Figure 3-26. Water Movement from Wall Debris in the Drain Line.....	3-11
Figure 3-27. Leak Detection Pit Drain Hydraulics.....	3-12
Figure 3-28. Stagnant Water High Water Mark Overview.....	3-13
Figure 3-29. Crawler Solids Recovery in the 222-S Laboratory	3-14
Figure 3-30. Cs-137/Sr-90 ratio from Crawler Solids Compared to other AY-102 Samples....	3-16
Figure 3-31. Cs-137 and Sr-90 Concentrations of the Crawler Solids Compared to other AY-102 Samples.....	3-17
Figure 3-32. SEM Image (Left) and EDS Spectrum (Right) Showing Quartz in Crawler Sample.....	3-19
Figure 3-33. SEM Image (Left) and EDS Spectrum (Right) showing Graphite in Crawler Sample.....	3-19

TABLES

Table 1-1. Tank AY-102 Temperatures in Refractory and Foundation.....	1-6
Table 3-1 Crawler Solids Laboratory Results.....	3-15
Table 3-2. Major and Minor XRD Phase Identification in the Crawler Solids	3-18

TERMS

Acronyms and Abbreviations

DST	double-shell tank
HEPA	high-efficiency particulate air
IHI	IHI Southwest Technologies, Inc.
LDP	leak detection pit
PVC	polyvinyl chloride
SST	single-shell tank
WRPS	Washington River Protection Solutions, LLC
XRD	x-ray diffraction (analysis)

Units

°F	degrees Fahrenheit
µCi	microcurie
µg	microgram
dpm	disintegrations per minute
ft	feet
ft ³	cubic feet
gal	gallon
hr	hour
in.	inch
in. WC	inch water column
min	minutes
mL	milliliter
mRad	millirad
mrem	millirem

1.0 INTRODUCTION/BACKGROUND

In October 2012, Washington River Protection Solutions LLC (WRPS) determined that waste had leaked into the annulus of Tank 241-AY-102 (referred to herein as Tank AY-102). The WRPS Executive Safety Review Board made this determination based on information presented at the board's October 19, 2012 meeting. The condition and history of this tank is documented in RPP-ASMT-53793, *Tank 241-AY-102 Leak Assessment Report*. WRPS conducted an extensive review of Tank AY-102 and increased both inspection and monitoring of the tank; however, the precise cause and location of the leak could not be determined.

In parallel with the leak in the primary tank, the Tank AY-102 leak detection pit (LDP) was accumulating water through the drain system outside the secondary liner. The liquid collecting in the LDP is suspected to be from water intrusion. The rate of water accumulating in the LDP is such that the LDP must be pumped routinely to comply with OSD-T-151-00007, *Operating Specifications for the Double-Shell Storage Tanks*. Appendix A discusses the 2 to 3-gal per day rate of accumulation of water in this system.

On June 20, 2013, during routine pumping of the Tank AY-102 LDP, a radiation dose rate was noted on the transfer hose and elevated surface contamination readings were found on the transfer pump when it was removed from the LDP. These two field readings suggested that tank waste from a secondary liner breach might be leaking into the LDP. As a result, WRPS initiated a plan to ascertain the integrity of the liner.

WRPS concluded that a leak from the liner into the LDP has not occurred (RPP-RPT-55939, *Tank 241-AY-102 Secondary Liner Integrity Investigation Resolution*). The investigation results recommended the inspection of the LDP as a confirmatory action. This document provides an overview of the inspection of the LDP drain line with a robot provided by IHI Southwest Technologies, Inc. (IHI).

1.1 LEAK DETECTION PIT SYSTEM DESCRIPTION

The double-shell tank (DST) LDPs are tertiary containment systems designed to collect any liquid draining from beneath the secondary liner. The concrete foundation beneath the secondary liner is slotted and fitted with drain connections at the center of the tank, at the edge of the concrete foundation, and at a mid-point between these two drains (see Figure 1-1). The system was designed so that any tank waste released from the secondary liner would accumulate in the foundation slots and drain into the LDP.




Figure 1-1. Foundation Drain Locations


For the AY Farm, the 6-in. diameter drain line manifold runs to a 4-ft diameter by 18-in. high carbon steel sump tank that is located approximately 62 ft below-grade and below the level of the tank foundation (see Figure 1-2). The drain line connects to the sump tank in a single 24-in. riser, which extends to a leak detection pump pit. The pump pit is located flush with the ground surface.



**Figure 1-2. Leak Detection Pits Riser for the AY Farm Tanks (8160-1)
(Tank AY-102 in background)**

The LDP is also equipped with a separate, closed 6-in. diameter radiation detection well that extends from the surface and terminates adjacent to, but outside, the 48-in. diameter tank, as shown in

Figure 1-3. The radiation detection wells on all DST LDPs were removed from service in 1997.



**Figure 1-3. Original Leak Detection Pit Construction (Photo 64090-21)
(SY Farm, June 21, 1974)**

For a breach from the secondary liner to be detected, the foundation drains and LDP drain system need to direct the flow of waste into the LDP tank, where the leak can be detected via sampling. A leak would be indicated by an increase in the LDP liquid level and an increase in radioactivity in the samples taken from the LDP.

The LDP is ventilated with a 2-in. vent line connected to the DST annulus exhaust manifold and, therefore, under annulus negative pressure. Four 4-in. diameter pipes supply ambient air to the central air distributor. The air flows radially outwards from the central air distributor, through air channels in the refractory, to the annulus, as shown in Figure 1-4.




Figure 1-4. Ventilation Air Supply (primary tank not shown for clarity. Refractory air slots shown transparent.)

From the annulus, the air is exhausted through two stages of high-efficiency particulate air (HEPA) filters and monitoring devices to a stack where it is discharged to the environment.

Figure 1-5 shows construction of the foundation for Tank AY-102 with the LDP drain system already in place. Construction conditions within the excavated area were typically dusty, making it difficult to keep the drain piping and the foundation slots clear of debris. In Figure 1-6, workers can be seen cleaning the drain slots before the secondary bottom is lowered. Some blow sand and debris likely remained after cleaning.




Figure 1-5. AY Farm Foundation Fabrication with Leak Detection Drains in Place
(Photo 8000-1) (9/25/1968)



Figure 1-6. Workers Cleaning Debris from Foundation Drain Slots Prior to Lowering Secondary Tank Bottom (Photo 8096-1)

1.2 TEMPERATURE GRADIENTS IN THE TANK BOTTOM

The central LDP drain is located directly below the central plenum for the annulus air supply, separated by the $\frac{1}{4}$ -in. thick secondary steel liner. The central sump was filled with mineral fiber insulation during construction to protect the tank foundation from exposure to high heat during primary tank stress relief operations. Figure 1-7 shows the arrangement of the central plenum and sump.




Figure 1-7. Central Plenum and Sump Arrangement for Tank AY-102

In Tank AY-102, the ambient ventilation air is cooler than the tank, which causes temperature gradients when the annulus ventilation is operating. Thermocouples installed during construction provide temperature data from the concrete foundation and refractory concrete. As the annulus air is distributed through a central plenum, it warms about 20 °F as it moves to the outer edges of the tank, as summarized in **Error! Reference source not found.**. The cooling effect is illustrated in Figure 1-8. A more detailed presentation of the historic temperature profiles taken from thermocouples in the concrete foundation and refractory concrete are provided in Appendix B.

Table 1-1. Tank AY-102 Temperatures in Refractory and Foundation

Tank zone	Refractory (°F)	Average foundation (°F)
Inner	75-105	82.5
Mid-Point	90-130	102.5
Outer	105-120	105




Figure 1-8. Air Distribution Piping and Slots (cooling effect)

The 4-in. drain lines, which tee into the 6-in. drain line of the LDP, are located below the warmer areas of the concrete foundation. The section of the drain line between these tees did not show moisture accumulation. The drain line near the LDP sump, which is located beyond the outside of the tank, and the center drain line section are located in cooler areas created by thermal gradient along the length of the 6-in. drain line. These sections of the drain line showed moisture accumulation.

1.3 WATER INTRUSION PATHWAY

The DST farms contain several variations in the design of the joint between the concrete wall and foundation. The foundations of the AY, AZ, and SY Farms were built in such a way that accumulation of liquid/moisture at the interface of the concrete sidewall and the foundation is highly likely. The concrete sidewall rests on the foundation between two steel bearing plates that allow for minor movement of the concrete wall from expansion and contraction. The foundation was constructed with a 1.5-in. tall curb (as seen in Figure 1-9) at the 41.5-ft radius just outside the outer wall. This curb sits above the slotted portion of the foundation where the secondary liner rests, and creates a foundation groove where water can accumulate and seep between the steel bearing plates.

Water accumulation in the foundation groove, coupled with high vacuum in the annulus and LDP, may be enough to draw soil moisture as free liquid or humid air under the concrete wall and into the LDP drain system. This groove was filled at the time of construction with a polysulfide organic sealant often used in expansion joints. Additional discussion on inleakage pathways for all DST LDPs is provided in RPP-RPT-55666, *Double-Shell Tank Tertiary Leak Detection System Evaluation*.




Figure 1-9. Tank AY-102 Leak Detection Pit Intrusion Pathway

1.3.1 Previous Visual Inspection of 241-AY-102 Leak Detection Pit

The near-constant accumulation of water in the Tank AY-102 LDP has led to numerous investigations. These inspections have included visual inspection of the 24-in. LDP riser, the 48-in. diameter sump tank, and the 6-in. drain line viewed from the LDP, which allows a view up to the first elbow of the pipe expansion loop.

Figure 1-10 shows comparative photos of the 6-in. drain line entry into the riser from inspections done in 2008 and 2012.




Figure 1-10. Tank AY-102 Leak Detection Pit Drain Line Condition in 2008 (A) and 2012 (B)

Figure 1-11 shows photos of the LDP drain line as far as access would allow during the 2012 inspection. Sediment and tubercles (formed by microbial organisms present in the LDP) are present in this section. Extensive photographs of all sections of the LDP riser and sump tank from the previous inspections are provided in RPP-RPT-55666.




Figure 1-11. Tank AY-102 Leak Detection Pit Drain Line Interior During 2012 Inspection

1.3.2 Airflow through the Leak Detection Pit Drain

During the 2012 inspections, a test confirmed the presence of airflow out of the 6-in. drain line and into the LDP riser (RPP-RPT-53793, Section 4.3.7). The annulus ventilation system was operating and indicated a negative 12-in. water column (WC) vacuum. The riser at the leak detection pump pit cover was sealed to maximize vacuum in the LDP. Using a red ribbon flag to allow visual indication of airflow, a camera was lowered into the LDP. Airflow was confirmed when the flag would deflect outward and upward when positioned in front of the LDP drain line (Figure 1-12).




Figure 1-12. Tank AY-102 Leak Detection Pit Drain Line Airflow Test (October 2012)

Another indication of airflow out of the drain line into the LDP was discovered in December 2012. After the LDP liquid level rose unexpectedly to 24 in., preparations were made to pump the LDP as the level was back up to the maximum allowed by the operating specification. A video camera was placed into the pit on December 19, 2012, in preparation for pumping. Bubbles were observed coming from the 6-in. drain line prior to the pumping of the LDP sump.

The high rate of bubbling exiting the drain line into the LDP riser is shown in Figure 1-13(A). The 6-in. drain line was barely submerged in the video. If the level rises slightly above this level (as it was in September 2012), there is no bubbling to be seen from the drain line.




Figure 1-13. Photos from Video Showing Bubbling from Drain Line on 12/19/2012 (A), Photos from Video Showing Drain Line Just Underwater and No Bubbling on 9/18/2012 (B)

The video taken on September 18, 2012, doesn't have any bubbles, as shown in Figure 1-13(B). It is believed that when the water level in the LDP is high enough to overcome the influence of the LDP vacuum, inleakage to the LDP system via the wall-to-foundation joint stops.

1.4 PAST INTRUSION INVESTIGATIONS AND ACTIVITY LEVELS


The intrusions into Tank AY-102 have been investigated in the past, and extensive sampling of the LDP liquid accumulations has been performed. Appendix A provides a summary of these past investigations and sampling efforts. The key factors from these investigations include:

- Intrusion in the Tank AY-102 LDP is only seen when the annulus ventilation system is operating (the same correlation has been seen in Tank AZ-102);
- High rates of intrusion in the Tank AY-102 LDP starting in 1998 when the annulus ventilation system was modified to operate at very high negative pressures; and
- All Tank AY-102 LDP liquid accumulation samples show low, but detectable, levels of legacy contamination.

2.0 EQUIPMENT DESCRIPTION

WRPS conducted a down-selection among four vendors for three inspections in Tank AY-102 (RPP-ASMT-55798, *Alternative Evaluation for Tank 241-AY-102 Robotic Inspection*). The first of these inspections was awarded to IHI to examine the LDP in Tank AY-102. The proof-of-concept demonstration performed at the IHI facility is described in RPP-RPT-56431, *Trip Report: Demonstration for Robotic Inspection of 241-AY-102 Leak Detection Pit Drain Line Piping*.

2.1 IHI-SUPPLIED ROBOTIC PIPE INSPECTION EQUIPMENT



The IHI robotic pipe crawler, shown in

Figure 2-1, was deployed down the LDP riser to 61 ft below-grade by using a deployment mechanism, shown in Figure 2-2. The deployment mechanism serves to hold the robotic crawler as it is lowered with a crane down to where the 6-in. drain line pipe intersects the 24-in. LDP riser.




Figure 2-1. Robotic Pipe Crawler




Figure 2-2. Delivery Mechanism and Crawler Relationship

After the deployment mechanism has been lowered by the crane and locks itself in place on the inner wall of the 24-in. LDP riser, the robotic pipe crawler is remotely driven into the 6-in. drain line and performs a visual inspection.

Upon completion of the visual inspection, the crawler is driven in reverse through the 6-in. drain line back into the 24-in. riser and retrieved to the surface.

2.2 ONSITE DEMONSTRATION

The IHI robotic inspection system was demonstrated using a full-scale mockup at the vendor shop (described in RPP-RPT-56431). Following the demonstration at the vendor's shop, the equipment was demonstrated a second time in the Hanford 200 East Area before deployment at

Tank AY-102. The primary function of the onsite demonstration was to fine-tune the deployment/retrieval strategies. This work was conducted with the WRPS personnel who would be participating in the inspection of the Tank AY-102 LDP drain line piping. The mockup was constructed of polyvinyl chloride (PVC) pipe and cast iron elbows.

Figure 2-3 shows the final construction of the onsite mockup. The onsite demonstration followed the same steps used during the demonstration at the IHI facility.



Figure 2-3. Onsite Leak Detection Pit Mockup Demonstration

The onsite demonstration included the use of a crane, rigging crew, and operators who were involved in the actual inspection. The onsite demonstration showed that the crew was ready to perform the inspection in the field, and that the robotic inspection system provided and run by IHI personnel was ready for in-field operation.

3.0 VISUAL OBSERVATIONS FROM DRAIN INSPECTION

On November 20, 2013, the crawler deployment device was lowered into the LDP riser and successfully aligned with the drain line. The inspection crawler entered the drain and traversed to within approximately 7 ft of the central plenum before losing traction. This section provides descriptions and inspection photographs of each section of the pipe, indexed to Figure 3-1 and Figure 3-2. The figures are screen captures of the video inspection. In some cases, the captures do not reflect the actual orientation of the drain pipe (i.e., top of illustration is not always the top of the pipe).

The condition of the drain pipe system is summarized as follows:

1. The entrance was partially wetted and had sediment and corrosion consistent with past inspections.
2. The pipe was wet with considerable sediment and rust in the bottom of the pipe into Section 4, which is between the third and fourth elbows in the expansion loop. This wetness is consistent with the level of water in the LDP prior to pump down six days before the inspection (see Section 3.1).
3. Sections 5 and 6 were very dry and showed no evidence of dripping or drainage from the slots in the 4-in. drain lines. These sections showed less debris and corrosion product in the bottom of the pipe.
4. Sections 7 and 8, past the second tee, were wet and had a similar volume of debris and corrosion products as found in the first four sections.
5. The central plenum was not observed, since the crawler could not traverse through the last few feet of the drain line. The amount of debris prevented further progress.




Figure 3-1. Inspection Overview




Figure 3-2. Inspection Photograph Location Identification and Thermocouple Layout

Section 1: Leak Detection Pit Riser to First Elbow

Section 1 consists of the first 6 ft of pipe, starting from the opening in the LDP riser and up to the first elbow. This section showed residual moisture from the backup of water that had accumulated in the LDP prior to inspection. The level prior to pumping before the inspection is depicted in Figure 3-27 (Section 3.1).

The corrosion-related tubercles and small amounts of debris were unchanged from prior photos of this area (see

Figure 1-10 for photos from prior inspections in 2008 and 2012). The presence of moisture in this section of the drain line is due to the liquid level of the LDP. Prior inspections showed more wetting due to the higher liquid level in the LDP.

In addition, the 2008 inspection occurred two days after pumping, and the 2012 inspection occurred the same day as pumping. This robotic crawler inspection occurred six days after pumping the LDP, so the drain line had more time to dry out.

The top of the pipe was in good condition, as shown in Figure 3-3 and Figure 3-4. The amount of debris in the bottom of the pipe is similar to the 2012 inspection.




Figure 3-3. View of 6-in. Drain Line Prior to Crawler Leaving Deployment System

Figure 3-4. View of 6-in. Drain Line with Crawler Traversing Towards First Elbow

Section 2: From First Elbow to Second Elbow

Section 2 is the first elbow of the piping expansion loop and the 4 ft of pipe between the first and second elbows. This section showed substantial wetness and corrosion debris on the bottom of the pipe. The crawler movement through this material was similar to driving through mud. A horizontal waterline consistent with the historical level in this system can be seen on the wall in Figure 3-5.



Figure 3-5. View of First Elbow Prior to Entering

Figure 3-6 shows the straight section just after exiting the first elbow and indicates an increasing amount of sediment. (This figure is an example of a screenshot that does not show the true vertical configuration.) Most corrosion tubercles are present below the historical liquid level line.

Figure 3-7 shows the straight section about halfway between the first and second elbow and also shows an increasing amount of sediment.




Figure 3-6. View of 6-in. Drain Line Directly After First Elbow



Figure 3-7. View of 6-in. Drain Line Part Way Between First and Second Elbow

Section 3: From Second Elbow to Third Elbow

Section 3 is the second elbow of the piping expansion loop and the 4-ft long section between the second and third elbows. The section contained debris and corrosion products, as shown in Figure 3-8 through Figure 3-10. The waterline from previous filling of the LDP is clearly visible on the wall (Figure 3-8). This section was very wet, and standing liquid can be seen in shallow pools dammed up between the debris in the pipe, as shown in Figure 3-10. It was noted during

the inspection that the height of tubercle growth continued to drop in elevation and has a correlation to the historical liquid level represented by the waterline along the pipe wall.



Figure 3-8. View of Second Elbow Prior to Entering



Figure 3-9. View of 6-in. Drain Line Directly After Second Elbow



Figure 3-10. View of Standing Liquid on the Bottom of the Drain Line (Reflection)

Section 4: From Third Elbow to Fourth Elbow

Section 4 is the third elbow of the piping expansion loop and the 4-ft long section between the third and fourth elbows. This section appears much drier than previous sections. Figure 3-11 shows considerable debris in the third elbow. There is a distinct color change from wet to dry in this section between the two elbows, as shown in Figure 3-12 and Figure 3-13. The corrosion debris on the bottom of the pipe, along with the waterline, is still evident. Traversing through this material was less challenging because crawler traction was better in the drier environment. The transition point (dark-to-light color at the bottom of the pipe) is the anticipated location of the liquid level prior to the pumping of the LDP on November 14, 2013.



Figure 3-11. View of Third Elbow Prior to Entering



Figure 3-12. View of 6-in. Drain Line Directly After Third Elbow



Figure 3-13. View of Region Downstream of Third Elbow (a distinct color change, perhaps a transition to a completely dry region)

Section 5: From Fourth Elbow to First Tee

Section 5 is the 6.5-ft long section of the drain from the fourth elbow to the first 4-in. branch tee that drains the space under the tank annulus. The inspection did not detect any moisture in this region, including the bottom of the 6-in. pipe. There was no evidence of flow marking/remnants from the upstream 4-in. tees. As captured in Figure 3-14, the debris on the bottom of the pipe is flaky and dry compared to the wet debris that the crawler had to traverse through in the lower sections of the pipe expansion loop. Figure 3-14 through Figure 3-16 provide views of this region. Corrosion debris can still be seen on the bottom of the pipe. The volume of debris diminishes as the crawler progresses up the drain line and tubercles visible in earlier sections have disappeared. Overall, the drain pipe in this region is in good condition considering its age and the historic presence of liquid defined by the visible waterline.



Figure 3-14. View of Debris on the Bottom of the Drain Line Just Prior to Entering Fourth Elbow (very dry)




Figure 3-15. View of Fourth Elbow Prior to Entering



Figure 3-16. View of 6-in. Drain Line Directly After Fourth Elbow

Section 6: From First Tee to Second Tee

Section 6 is an 18-ft long section that starts at the first tee and goes up to the second tee. This section was observed to be completely dry, with suspended dust particulate observed when the crawler would come to a stop. The ability to disturb the material and mobilize dust particulate for the camera to detect strongly suggests that this region has not been wet for some time.

The legacy stain from the waterline can be seen on the bottom third of the tee (Figure 3-17). Camera operability at this section of the drain line was limited, so additional views looking up into the tee 4-in. drain line were not performed. However, since the views gathered of the 4-in. branch connection were dry, this observation supports the conclusion that no liquid has recently traversed through the 4-in. line and into the 6-in. drain line. These features are shown in Figure 3-17 through Figure 3-19. Some of the debris in Figure 3-18 appears to be from construction (e.g., wood fragments).



Figure 3-17. View of 4-in. Tee Entering the Side of the 6-in. Drain Line



Figure 3-18. View of 6-in. Drain Line
Approximately 10 ft After the First Tee



Figure 3-19. View of Debris on the
Bottom of the Drain Line
(about 2 ft from second tee)

Section 7: From the Second Tee to Six Feet Toward the Center Drain

Section 7 begins at the second tee and extends about 6 feet toward the center drain. Moisture accumulation begins immediately after the second 4-in. tee, as seen in Figure 3-20. The moisture is seen to cover the entire inner surface of the drain line pipe as the crawler traverses further from the second tee. This region of the drain line was not in contact with liquid from the LDP sump during the previous pumping evolution.



Figure 3-20. View of Moisture Seen after Second 4-in. Tee

The anomaly apparent in this region of the drain line is that the wetness is seen around the circumference of the pipe. The wetness seen in Figure 3-20 suggests condensation formation since liquid was not in this region that would have completely wetted the pipe wall.

The 4-in. drain line from the second tee is dry and shows dry sediment in the bottom, similar to the first tee. This sediment may be blow sand or construction debris left in the system from construction. Debris and corrosion product were visible on the bottom of the 6-in. line (see Figure 3-21). As the crawler entered the moist region after the second tee, corrosion and tubercles were present again, indicating that this region has seen increased moisture over a long period of time. This corrosion formation and the condition of a section of the pipe sidewall can be seen in Figure 3-22.




Figure 3-21. View of 4-in. Tee Connecting to 6-in. Drain Line



Figure 3-22. View of Corrosion Along 6-in. Drain Line (in region where moisture was seen after second tee)

Section 8: From Six Feet to Thirteen Feet Beyond the Second Tee

Section 8 is the last section of the drain pipe beyond the second 4-in. tee. In this section, wet sediment and corrosion debris are present along with significant amounts of moisture, as seen in

Figure 3-23 through Figure 3-25. Traversing this section was similar to driving through mud. The crawler did not have enough traction to overcome both the debris and the resistance from the crawler tether to reach the central plenum.

The crawler was reversed back and forth multiple times trying to make further progress. It is about 20 feet from the second tee to the center of the tank, and the crawler progressed about 13 feet beyond the second tee, stopping about 7 feet from the center of the tank. Figure 3-24 shows the wheel tracks left by the crawler's attempts to push through the mud in the drain line. These tracks delineate the extent of progress of the crawler into the drain line.



Figure 3-23. View of 6-in. Drain Line a Couple Feet after Second Tee



Figure 3-24. Partial View of the Saturated Debris on the Bottom of the Drain Line, Which Stopped Crawler Progress (approximately 7 ft from center of the tank)



Figure 3-25. Last View Looking Down 6-in. Drain Line (approximately 7 ft from center of the tank)

Debris

As seen in several preceding figures, the drain line contained sufficient debris so that the crawler's progress to the center of the tank was prevented. This quantity of material was unexpected. From a review of the construction photographs in Section 1.2, one potential debris source could be from construction activities. The debris may consist of dirt and concrete that could have blown or fallen into the drain line during construction. Also, in some sections of the drain line, the debris appears to be corrosion products, but the drain line does not show signs of excessive degradation. None of the material seen had the appearance of tank waste (i.e., no greenish or yellowish deposits or dark fluids, dried salt deposits, or crystalline material).

Removing Crawler from the 6-Inch Drain Line

During the removal of the crawler, it was observed that the moisture pattern along the pipe wall was changing. This was noticed a few feet from the exit of the 6-in. drain line. During the process of preparing the crawler to be removed from the drain line, the crawler remained still. By viewing the footage via a time-lapse sequence, small changes were observed along a section of the pipe where the corrosion tubercles are present.

As seen in Figure 3-26, over a span of two minutes, the moisture had begun to rewet the pipe wall in a direction traveling towards the top of the pipe. Although this location is near a weld, the most probable explanation of this observation is that the tubercles themselves contain moisture and when disturbed and/or slowly over time, they release this moisture into the surrounding regions. This conclusion is supported by the view of the drain line prior to the crawler entering (see Figure 3-3), where the existing tubercles have isolated areas of moisture around them.




Figure 3-26. Water Movement from Wall Debris in the Drain Line

3.1 HISTORIC WATERLINE REVIEW

Prior to the robotic inspection of the 6-in. drain line on November 20, 2013, the LDP was pumped to reduce the amount of liquid present in the pit. On November 11, 2013, the liquid level in the LDP was measured to be 20.7 in. LDP pumping operations occurred on November 14, 2013, and the liquid level, following pumping, was measured to be 0.1 in. Figure 3-27 shows the liquid level in the 6-in. drain pipe, with 20.7 in. in the sump tank, as measured on November 11, 2013. Because the pit was not pumped until November 14, 2013, there were three additional days for the level to increase further than that shown in Figure 3-27.




Figure 3-27. Leak Detection Pit Drain Hydraulics

Historically, the level in the Tank AY-102 LDP has been stagnant at approximately 25 in., as measured on the dip tube system. This level corresponds to the top of the 6-in. drain line entrance to the pit. The level remained there from 2010 until the primary tank was discovered to be leaking in August 2012. Drain line fill behavior is discussed in Appendix A, describing the reasoning for this specific stagnant level. Figure 3-28 represents the historical water level of the LDP and the extent to which the water would have filled the drain line. This level was compared to the waterlines in the inspection photographs. These waterline levels in the drain line are similar to those shown in Figure 3-28.

At the entrance of the drain pipe (Figure 3-28, Item A), the 6-in. pipe is expected to be full of water when the pit has stopped filling. As such, no waterlines are present in this section of the drain line.

Farther up the drain line, at the first tee (Figure 3-28, Item B), the historical water level represents just under half of the pipe being filled with stagnant liquid for extended durations. The waterlines discovered during the visual inspection support this and show evidence of water filling part of the first branch of the drain line.




Figure 3-28. Stagnant Water High Water Mark Overview

Continuing to the second tee (Figure 3-28, Item C), the water level during historical extended water retention would begin to taper at or near this location. Photographic evidence supports this conclusion, showing a waterline similar to the model.

3.2 ANALYSIS OF SOLIDS ON THE CRAWLER AND TETHER

As the tether, deployment device, and robot were withdrawn from the LDP drain, field measurements of direct dose readings on the cable and crawler were 13 and 27 mRad/hr window open, <0.5 mRad/hr window closed, respectively. (Window open measurements include beta and gamma radiation, and window closed measurement are only gamma radiation.)

On completion of the field inspection the crawler was packaged in the field, and shipped to and examined at the 222-S Laboratory. About 3 grams of solids were collected from the wheels and crawler externals for analysis (Figure 3-29). Residues recovered from the crawler and tether were examined using chemical and radiological analyses found in RPP-PLAN-56497, *Sampling and Analysis Plan for Solids on the 241-AY-102A Leak-Detection Pit Robotic Pipe Crawler, Attached Cabling, and Sleeve*.



Figure 3-29. Crawler Solids Recovery in the 222-S Laboratory

Radiation Survey

The dose readings taken in the laboratory were somewhat lower than field readings; 12 mRad/hr (versus 27 mRad/hr) window open and both readings were <0.5 mRad/hr window closed. The primarily beta particle dose is consistent with past surveys of the equipment removed from the sump. Both field and laboratory surveys were higher than past readings from equipment removed from the sump. The source of the contamination in the LDP has not conclusively identified, but is suspected to be legacy contamination from historical air reversals of the primary and annulus ventilation systems, or unknown historical contamination events. Since the crawler was not in contact with the water in the LDP sump tank, these levels suggest that there is contamination in the drain itself, which may have come from the water in the LDP when it filled the drain line.

Laboratory Analysis

Preliminary laboratory analysis of solid particulates recovered from the crawler yielded no evidence for phases that are characteristic of Hanford tank waste^{1,2}. Final results will be issued at a later date. The solids consisted, in a large part, of a very fine particulate and appeared dark orange to brown in color. A large majority of the total solids on the crawler were recovered. The particulates can be attributed to rust and/or mill scale, soil minerals, and cement and/or soil calcite.

Of these solids, the majority were composed of rust and scale. Minor amounts of silicate soil minerals and a calcium-rich phase were also found. The calcium-rich phase is probably derived from cement or groundwater precipitation. Traces of a phase consistent with graphite were also observed. This compound may have come from the dry lubricant that was scattered about the sliding joint of the tank concrete wall during construction. Additional details on the results of specific analysis that were performed are provided below.

The chemical characterization of the solids was primarily iron from rust in the debris with trace quantities of cesium (Cs) and Strontium (Sr) (Table 3-1). The Cs-137 to Sr-90 ratio is similar to past LDP liquid samples from the pit and not similar to waste samples from the tank or the annulus (Figure 3-30). The overall concentration of radionuclides in the crawler sample compared to other Tank AY-102 samples is shown in Figure 3-31. The overall concentration of Sr-90 is similar to annulus materials, but the more mobile component, Cs-137, is much lower than any of the tank or annulus materials.

Table 3-1 Crawler Solids Laboratory Results

Radionuclides	
Cs-137	0.126 uCi/gm
Sr-90	1.67 uCi/gm
Cs-137/Sr-90	
Element	ug/g
Iron	487000
Calcium	10800
Manganese	3490
Aluminum	1680
Lead	1380
Anions	Trace NO3, NO2, Sulfate (20-40 ppm) (Analysis not performed for Oxide, Hydroxide, Carbonate)

¹ Email, Gary Cooke to T.J. Venetz dated 12/12/2013, *Preliminary results from Solid Phase Characterization of AY-102 LDP RPC*

² Email, Duc Nguyen to T.J. Venetz dated 12/13/2013, *FW: 20131349 AY102 Crawler Prelim Results w/o ICP*




Figure 3-30. Cs-137/Sr-90 ratio from Crawler Solids Compared to other AY-102 Samples




Figure 3-31. Cs-137 and Sr-90 Concentrations of the Crawler Solids Compared to other AY-102 Samples

Polarized Light Microscopy of Recovered Solids

Visually, the sample consisted of dry, rust-brown, flighty solids. Sample preparation indicated that few (if any) of the solids were water-soluble. The sample contained several different types of solids, but none appeared to be sodium salts of the type commonly found in tank waste.

X-ray Diffraction Analysis of Recovered Solids

X-ray Diffraction Analysis (XRD) showed no diffraction peaks, consistent with crystalline phases identified in Hanford tank waste, were observed in the sample. Quartz, graphite, calcite, and three iron-bearing phases were observed in the sample. In general, these findings are consistent with particulate derived from soil, concrete, carbon steel corrosion products, and graphite from the slip plates. The minor and major phases reported by XRD analysis are shown in Table 3-2.

Table 3-2. Major and Minor XRD Phase Identification in the Crawler Solids

Chemical Name	Mineral Name	Formula	Relative Amount
Silicon Dioxide	Quartz	SiO ₂	Major
Carbon	Graphite	C	Major
Iron Oxide	Maghemite	Fe ₂ O ₃	Major
Iron Oxide Hydrate	Lepidocrocite	FeO(OH)	Major
Iron Oxide	Hematite	Fe ₂ O ₃	Minor
Calcium Carbonate	Calcite	CaCO ₃	Minor

Scanning Electron Microscopy Analysis of Recovered Solids

In decreasing order of abundance, iron, oxygen, silicon, calcium manganese, potassium, and aluminum were detected. The particle types, which dominate the sample surface, have chemistries and morphologies that are consistent with rust or mill scale. Quartz (see Figure 3-32), plagioclase and potassium feldspars, and vermiculite were all observed. The source of the calcite identified in the XRD spectrum could be from the soil, precipitated from vadose zone waters, or could be an alteration product of cement. Minor iron, present in all of these spectra, is derived from the ubiquitous rust/scale particles. There was no evidence of particles with chemical signatures consistent with tank waste. Specifically, no sodium-rich, potassium-rich, nitrate, sulfate, or phosphorus bearing salts were found. Graphite was identified as a discrete phase present in the sample (see Figure 3-33) and is likely from the dry lubricant installed to reduce friction on the bearing plates between the concrete wall and foundation.




Figure 3-32. SEM Image (Left) and EDS Spectrum (Right) Showing Quartz in Crawler Sample




Figure 3-33. SEM Image (Left) and EDS Spectrum (Right) showing Graphite in Crawler Sample

4.0 DISCUSSION

A summary of the key observations is provided from the recent crawler inspection and other considerations from past experience. These points suggest a plausible explanation for what was observed in the LDP drain piping and how that relates to LDP intrusion. These observations are discussed further in Section 4.2.

4.1 SUMMARY OBSERVATIONS

From Crawler Inspection

Specific source of intrusion not observed – Prior to inspection, it was assumed that the intrusion was liquid migrating through the expansion joint between the vertical concrete sidewall and the foundation pad. The expectation was that the first tee might show the presence of liquid because it drains from a point nearest this joint. Both tees were dry and did not show the presence of any liquid.

Wet areas of the drain – The drain was wet from the center of the tank to the second tee connection (mid-point) away from the LDP and from between the second and third elbows down to the LDP sump. This second area matched the liquid level prior to pumping down the LDP (six days before the inspection).

Debris in drain piping – Although the debris proved to be an impediment to the crawler and may cause a delay in the flow of waste to the LDP, it is insufficient to restrict the flow of a substantial amount of liquid to the LDP. If small leaks occur in the secondary liner, it is unlikely that the waste would reach the LDP sump in a timely fashion with or without the presence of the debris. This conclusion is based on the rate of flow of waste from the Tank AY-102 primary tank, in which waste has moved slowly over a year or more to cover a relatively small fraction of the liner floor.

Radiation and chemical analysis on the crawler residue

The dose readings taken in the field and the laboratory were 12-27 mRad/hr window open, <0.5 mRad/hr window closed, respectively. A lower dose rate was reported in the laboratory. The primarily beta particle dose is consistent with past surveys of the equipment removed from the sump.

Radionuclides, Cs-137 and Sr-90, were present in low concentrations and in a ratio similar the LDP samples. There was no evidence of particles with chemical signatures consistent with tank waste. Specifically, no sodium-rich, potassium-rich, nitrate, sulfate, or phosphorus bearing salts were found. These results indicate the material analyzed from the crawler was not tank waste.

Other Considerations

Temperature gradients in the foundation – The annulus air is distributed radially through a central plenum in the refractory layer, which leaves the refractory and concrete foundation cooler in the middle and warmer toward the outer radius of the tank by approximately 20 °F, as discussed in Section 1.2.

Vacuum and water intrusion – The liquid level rise stops during the periods when the annulus exhaust is shut down and the vacuum is off. This correlation suggests that the vacuum drawing air into the drain system plays a role in the intrusion. The rate of intrusion does not appear to vary with seasonal temperature fluctuations.

Airflow through the drain line – There is airflow through the drain line, seen as bubbles, when the liquid level rises to the top of the drain; there is also positive indication when using a physical item to detect airflow. The motive force for the airflow is a connection with the annulus exhaust ventilation system via a 2-in. pipe that routes from the LDP riser to the 6-in. annulus vent header. The airflow stops when the liquid level rises to a point such that the 6-in. drain line is submerged.

Condensation in LDP – Prior visual inspections of AY and AZ Farm LDPs show condensation in the form of droplets in the sump tank, along the wall of the riser, and in the pump pit near-grade. The visual inspections show fogging conditions in the riser on some occasions. These condensation droplets are formed due to the air rising in the 24-in. riser towards grade. As the warm, moist air rises and cools to the temperature of the surrounding structure, an ideal environment for surface condensation is created once the dew point is reached.

Moisture sources – There are two potential sources of moisture at the tank; humid air in the soil and liquid. Most of the single-shell tank (SST) farms exhibit higher soil moisture profiles compared to native soil. The original excavation has a layer of low-moisture permeability soil at the base of the excavation. Although water-saturated soil is not expected, the air present in the pore-space of the soil that may be drawn in at the foundation level is likely be at 100 percent relative humidity (Hillel 1998).

Additionally, the tank domes creates an umbrella effect that directs moisture into the soil next to the tank. Past construction reviews have shown the rainfall and snowmelt flow through a construction joint in the dome concrete and enter the annulus. This finding shows that adequate quantities of moisture exist from the umbrella effect of dome runoff to be present at the foundation groove.

4.2 POSSIBLE INTRUSION PATHWAYS

As previously discussed, WRPS addressed the potential of waste being the source of intrusion in the LDP sump in RPP-RPT-55939 and showed the intrusion was not from the secondary liner. The following other potential pathways for intrusion are discussed in this section:

- A crack or pit in the sump tank;
- A crack or pit in the drain line; or
- Air inleakage through the concrete wall/foundation joint and condensation in the LDP.

Sump tank – Cracks or pits in the sump tank above the normal liquid level could be possible based on the age and service of the system. The previous inspections showed the LDP sump is in relatively good condition, taking into account the presence of stagnant water and the humid atmosphere for long periods of time. There is no supporting visual evidence of cracking or pitting from the visual inspection or the previous inspections. Intrusion at or above the liquid level ceiling would be visible by stains around the crack or pit and by streaks from flow of the liquid down to the sump. There are some streaks on the wall, but these streaks occur near the

condensation transition point. This transition point was observed in previous inspections when the camera was lowered and condensation occurred on the camera lens.

The sump itself is well below this transition and offers no temperature differential to support a condensation mechanism in the sump. Below the liquid ceiling level there is no evidence of leakage or loss of liquid level, which should occur when the ventilation system is shut down. The leakage should happen under this condition, because equilibrium established with the ventilation would have shifted and the water would seek a new equilibrium level.

Drain line – As with the sump tank, cracks or pits could potentially be present in the drain line, but no evidence of either defect was found in the visual inspection.

- In the dry portions of the line, any defects would show the presence of liquid such as pooling or flow patterns. The inspection did not find any such patterns.
- In the wet section, as with the dry section, there was no evidence of cracks or pits in the portion observed. If defects were present in the portion not observed or potentially under the mud present in this section, this liquid would have to move through the dry portion of the drain line. There is no evidence of moisture from the center of the tank flowing into the LDP sump.

Air inleakage/condensation – Vacuum applied to the LDP system may be pulling moisture from the surrounding soil through the 6-in. drain line into the sump and the 24-in. riser. The pathway is likely at the polysulfide-sealed slide plate joint between the footing and the bottom of the concrete side wall. The soil in this location is warmed by contact with the tank wall. This relatively warm, moist air is drawn in 57 ft below-grade and can condense in cooler parts of the LDP drain system if the temperature differential is sufficient.

The 4-in. drains coming into the 6-in. drain line draw from warmer areas of the secondary liner bottom and concrete foundation and showed no condensation. These warmer areas would heat the moist air, reducing the relative humidity below the saturation point and account for the dry condition in the 4-in. drains and the central portion of the drain line.

When the ventilation system is operating, the coolest part of the tank bottom and foundation is the tank center, which is directly below the supply point for the inlet air stream. The cooler areas underneath the tank center and outside the tank perimeter can condense moisture, which then collects in the LDP. When the vacuum is off, or when the LDP level is high enough to block airflow out of the drain system into the LDP riser, there is no water accumulation because no more humid air can be pulled into the foundation slots and drain system.

Humidity levels 60 to 70 ft below-grade are at, or near, saturation. As a rough approximation, a 10 to 15 °F temperature drop in saturated air and 10 to 20 ft³/min of airflow does produce a condensation rate near the observed LDP fill rate of 2 to 3 gal/day. Based on the observations from the inspection and the analysis above, the “air inleakage/condensation” pathway offers the best explanation.

5.0 RECOMMENDED PATH FORWARD

The inspection of the drain line for the Tank AY-102 LDP has not definitively identified the source of moisture in the LDP. Conditions in the LDP drain line indicate a high probability that a significant leak through secondary containment would be collected in the LDP. Although the continuing intrusion could indicate a leak, sampling the contents of LDP prior to transfer will confirm whether or not waste material has entered the pit. Further exploration of the leak detection system is unlikely to alter the intrusion or increase understanding of its source.

6.0 REFERENCES

Hillel, D., 1998. *Environmental Soil Physics*, Academic Press, San Diego, California.

OSD-T-151-00007, 2013, *Operating Specifications for the Double-Shell Storage Tanks*, Rev. 12, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-ASMT-53793, 2012, *Tank 241-AY-102 Leak Assessment Report*, Rev. 0, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-ASMT-55798, 2013, *Alternative Evaluation for Tank 241-AY-102 Robotic Inspection*, Rev. 0, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-PLAN-56497, 2013, *Sampling and Analysis Plan for Solids on the 241-AY-102 Leak-Detection Pit Robotic Pipe Crawler, Attached Cabling, and Sleeve*, Rev. 0, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-RPT-55666, 2013, *Double-Shell Tank Tertiary Leak Detection System Evaluation*, Rev. 1, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-RPT-55939, 2013, *Tank 241-AY-102 Secondary Liner Integrity Investigation Resolution*, Rev. 0, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-RPT-56431, 2013, *Trip Report: Demonstration for Robotic Inspection of 241-AY-102 Leak Detection Pit Drain Line Piping*, Washington River Protection Solutions, LLC, Richland, Washington.

Appendix A

LEAK DETECTION PIT INTRUSION RATES AND VACUUM

The level history of the Tank AY-102 LDP is provided in RPP-ASMT-53793, *Tank 241-AY-102 Leak Assessment Report*, and RPP-RPT-55666, *Double-Shell Tank Tertiary Leak Detection System Evaluation*, both of which identify a correlation of leak detection pit (LDP) level increase with annulus ventilation system operation. Liquid levels are measured manually via a dip tube system, and the liquid volumes can be calculated from these liquid level readings.

The level in the Tank 241-AY-102 (referred to herein as Tank AY-102) LDP was stagnant at about 25 in. from 2010 until the primary tank was discovered to be leaking. As part of the leak assessment, the LDP was pumped to ensure the integrity of the secondary liner. Since then, the LDP has been pumped regularly as it refills. When the annulus ventilation system is operating, the filling is nearly constant at a rate of 2 to 3 gal per day (

Figure A-1 shows the accumulation periods).




Figure A-1. Tank AY-102 Leak Detection Pit Level Showing Nearly Constant Level Increase

This increase occurs up to a specific liquid level where the liquid completely covers the 6-in. drain line at the entrance to the 24-in. riser for the LDP. After reaching this liquid level, the increase stops regardless of the operating status of the annulus ventilation system. Additional evidence of this level is shown by water lines in the drain line seen during the visual inspection.

Additional discussion on inleakage pathways is documented in RPP-RPT-55666. This document makes two pertinent observations that demonstrate the correlation between water intrusion and vacuum maintained in the LDP:

1. Level increases for the Tank AY-102 LDP began in 1998, which corresponds to retrieval of single-shell tank (SST) 241-C-106 (Tank C-106). Tank AY-102 annulus ventilation was modified, increasing negative pressure to very high levels (14 to 16 in. WC) and to direct all incoming flow into the central air distributor through four 4-in. supply pipes routed through the refractory insulating concrete between the primary and secondary steel liners. This change was made to increase cooling along the tank bottom, which was anticipated to become very hot from the high-heat waste being transferred from Tank C-106.
2. When the liquid level slightly exceeds the top of the tertiary LDP drain line, the water level creates a vapor seal, which effectively seals off the drain system from annulus vacuum pressures and the increase of liquid levels in the LDP stops (discussed in Section 1.3).

Tank AY-102 Leak Detection Pit Activity Levels

As part of the pumping procedure, samples have been routinely taken from the liquid in the LDP sump tank and occasional smears have been taken from the pump used to remove liquid from the sump tank. The sample results have shown a low concentration of radionuclides, and smear results show low levels of contamination (near background), which do not suggest waste leakage through the secondary liner into the tertiary leak collection system.

On June 20, 2013, the LDP was pumped without first having a sample taken. The field readings showed a higher than expected dose rate, and the smear taken showed elevated levels of contamination. These findings led to an investigation of the pump and additional sampling. This investigation, documented in RPP-RPT-55939, *Tank 241-AY-102 Secondary Liner Integrity Investigation Results*, concluded that no waste had breached the secondary liner.

Liquid Samples from the Leak Detection Pit Sump Tank

The water that steadily accumulates in the Tank AY-102 LDP consistently has low levels of detectable contamination. The Tank AY-102 LDP was sampled once in 2007, twice in 2012 prior to pumping, after pumping the LDP in June 2013 when high background was noted, and again in July, twice in August, and in November about four days prior to the LDP drain line inspection.

The results for these sampling events are summarized in Table A-1. The results show low but detectable levels of contamination, near-neutral pH, and low concentrations of a common groundwater ion (nitrate). The concentration of ^{137}Cs is much less than ^{90}Sr , more indicative of legacy contamination that has been water-leached many times and not consistent with current leakage of tank waste, as discussed in RPP-RPT-55939.

Table A-1. Sampling Results

Analyte	Dec 2007 ^a	Sept 2012 ^a	Dec 2012 ^a	June 2013 ^a	July 2013 ^a	Aug 6 2013 ^a	Aug 28 2013 ^b	Nov 2013 ^b
¹³⁷ Cs	3.3 – 6.3 (10 ⁻⁴) µCi/mL	2.2 – 2.4 (10 ⁻⁵) µCi/mL	1.4 – 1.7 (10 ⁻⁵) µCi/mL	2.6 – 2.8 (10 ⁻⁵) µCi/mL	2.1 – 2.5 (10 ⁻⁵) µCi/mL	1.4 – 1.5 (10 ⁻⁵) µCi/mL	1.4 – 1.7 (10 ⁻⁵) µCi/mL	1.3 – 1.6 (10 ⁻⁵) µCi/mL
⁹⁰ Sr	5.5 – 5.6 (10 ⁻³) µCi/mL	2.2 – 2.3 (10 ⁻³) µCi/mL	5.1 – 5.2 (10 ⁻³) µCi/mL	4.2 – 4.3 (10 ⁻³) µCi/mL	2.5 – 3.7 (10 ⁻³) µCi/mL	4.0 – 4.1 (10 ⁻³) µCi/mL	3.4 – 3.6 (10 ⁻³) µCi/mL	2.4 – 3.2 (10 ⁻³) µCi/mL
pH	7.9 – 8.1	6.6 – 6.9	7.7 – 7.8	8.2 – 8.3	7.4 – 7.7	7.4 – 7.6	7.2 – 7.4	7.1 – 7.2
NO ₃ ⁻	13.3 – 13.4 µg/mL	1.83 – 1.91 µg/mL	4.9 – 5.1 µg/mL	2.21 – 2.41 µg/mL	2.34 – 2.95 µg/mL	2.16 – 2.68 µg/mL	2.66 – 2.72 µg/mL	1.89 – 2.32 µg/mL
Appearance	Clear, colorless	Clear colorless, trace amount of brown suspended solids	Clear colorless liquid, trace amount of black solids	Clear colorless liquid, no solids	Clear colorless liquid, no solids	Clear colorless liquid, no solids	Clear colorless liquid	Clear colorless liquid

^a RPP-RPT-55939, 2013, *Tank 241-AY-102 Secondary Liner Integrity Investigation Results*, Rev. 0, Washington River Protection Solutions, Richland, Washington.

^b Nguyen, D. M., 2013, "Results of AY-102 LDP Samples Taken on 11-5-13," (email to T. J. Venetz, November 18), Washington River Protection Solutions, LLC, Richland, Washington.

In Figure A-2, the ratio of ¹³⁷Cs to ⁹⁰Sr is shown for all LDP sampling events. The ratio is also shown for all Tank AY-102 annulus samples, the Tank AY-102 waste itself (supernatant and interstitial liquid), and Tank SY-103 LDP samples. This pit was contaminated when tank waste was misrouted during the 1970s and has been flushed extensively. The data shows that the material in the LDP is distinctly different than any of the material that has leaked into the annulus or waste in the tank.




Figure A-2. Ratio of $^{137}\text{Cs}/^{90}\text{Sr}$ in Tank AY-102 Leak Detection Pit Samples Compared to Other Sources Known to be Waste

Past Contamination on Leak Detection Pit Pumping Equipment

On June 20, 2013, during routine pumping of the Tank AY-102 LDP, higher than normal dose rates were seen during pumping and high contamination levels were noted on the transfer pump. High, predominately beta contamination was measured (resulting in a direct dose rate of 3.5 mRad/hr window open, <0.5 mRad/hr window closed) and contamination measurements of 800.000 dpm were found on the submersible pump. These two field readings raised concerns that tank waste from the secondary liner may have leaked into the LDP.

Prior to and after this June 2013 event, contamination levels on the LDP pump were noted (again primarily beta contamination) but with dose rates more on the order of less than 1 mRad/hr window open and contamination levels typically on the order of 10 to 30,000 dpm or less. As shown in Figure B-2, the concentrations of the radionuclides in the LDP liquid samples have remained relatively unchanged since 2007.

The WRPS follow-up investigation, documented in RPP-RPT-55939, concluded that a leak from the secondary liner into the LDP has not occurred. This evaluation included detailed forensics of the pump and sample analyses performed by the 222-S Laboratory. The investigation recommended the inspection of the LDP drain line as a confirmatory action to demonstrate that no waste has leaked into the LDP.

References

Nguyen, D. M.. 2013. "Results of AY-102 LDP Samples Taken on 11-5-13," (email to T. J. Venetz, November 18). Washington River Protection Solutions, LLC, Richland, Washington.

RPP-ASMT-53793. 2012. *Tank 241-AY-102 Leak Assessment Report*. Rev. 0, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-RPT-55666, 2013, *Double-Shell Tank Tertiary Leak Detection System Evaluation*, Rev. 1, Washington River Protection Solutions, LLC, Richland, Washington.

RPP-RPT-55939. 2013. *Tank 241-AY-102 Secondary Liner Integrity Investigation Results*, Rev. 0, Washington River Protection Solutions, Richland, Washington.

Appendix B

TANK AY 102 TEMPERATURE GRADIENTS IN THE REFRactory AND FOUNDATION

Temperature data for the concrete foundation and refractory of Tank AY-102 was gathered for RPP-ASMT-53793, *Tank 24I-AY-102 Leak Assessment Report*. This data provides an indication of temperature during normal operations (annulus ventilation on) at three radial locations: 7 ft (inner), 21 ft (middle), and 36 ft (outer) radially from the center of the tank, which roughly corresponds to the locations of the drain legs to the leak detection pit. These temperatures in the refractory and concrete foundation are the best indicators currently available of temperatures in the leak detection pit drain piping due to their location. Nominal normal operating temperatures presented in Table B-1 are extracted from Figure B-1 through Figure B-5, which examine the period from July 2007 to July 2010.

Table B-1. Normal Operating Temperatures

	Refractory (°F)	Concrete foundation (°F)	Observed difference (°F)	Estimated temperature (°F)	Average foundation (°F)
Inner	75-105	N/A		75-90	82.5
Middle	90-130	95-110	Minimum: 0±5 Maximum: -15±5	N/A	102.5
Outer	105-120	100-110		N/A	105

The inner thermocouples of the concrete foundation have not produced usable data since prior to 1980. The temperature of the concrete foundation at this location can be estimated by observing the temperature drop from the refractory to the foundation at the other two radial locations and applying it to the observed refractory temperatures.

Assuming the leak detection drain piping is pulling air/liquid that is in thermal equilibrium with the concrete, the air pulled in from the center of the tank is approximately 20 °F cooler than through the other drain legs. The cooler air could explain moisture dropping out in the tank-center portion of the drain piping and the warmer air preventing condensation in the middle section of the drain piping. Moisture in the section nearest the leak detection pit is explained by the observed filling of the pit via condensation on the pit sidewalls and potentially on the last section of the drain piping as the distance from the tank (the heat source) increases.




Figure B-1. Tank AY-102 Embedded Refractory Thermocouples (7-ft ring)




Figure B-2. Tank AY-102 Embedded Refractory Thermocouples (21-ft ring)




Figure B-3. Tank AY-102 Embedded Refractory Thermocouples (36-ft ring)




Figure B-4. Tank AY-102 Concrete Base Thermocouples (21-ft ring)




Figure B-5. Tank AY-102 Concrete Base Thermocouples (36-ft ring)