

THREE MILE ISLAND UNIT 2

(TMI-2)

THE REACTOR

THE ACCIDENT

THE CONSEQUENCES

II

2/9/2010

OBJECTIVES

2. Describe the role in the reactor accident at Three Mile Island, Unit 2 [TMI-2] of each of the following:

- Pilot-operated relief valve, high-pressure injection system, and reactor coolant pumps
- Post-shutdown decay-heat load, zirconium-water reactions, and hydrogen evolution

OBJECTIVES

4. Compare the TMI-2 and Chernobyl-4 reactor accidents in terms of:

- Nature and extent of core damage
- Release of noble gases, iodine, cesium, and particulates
- Final station configuration after recovery

Three Mile Island Nuclear Station




ACCIDENT AT THREE MILE ISLAND UNIT 2

- THREE MILE ISLAND [TMI] NUCLEAR STATION
 - Owned & Operated by Metropolitan Edison & General Public Utilities (GPU)
 - Located Near Middletown, PA; 10 mi SE of Harrisburg, the State Capital
 - Babcock & Wilcox (B&W) PWR Units
 - Unit 1 - 792 MWe
 - Unit 2 - 880 MWe


TMI-2

- REACTOR
 - Babcock & Wilcox (B&W) PWR Primary System
 - Reactor Vessel
 - Two Once-Through Steam Generators
 - Four Coolant Pumps
 - Pressurizer
 - Hot-Leg Piping to Steam Generator
 - Cold-Leg Piping (Dual) from Steam Generator


TM-2 Reactor Coolant System



TMI-2 Reactor Coolant System




Babcock & Wilcox (B&W) PWR



TMI-2


- REACTOR SCHEMATIC LAYOUT
 - One of Two Coolant Loops
 - Engineered-Safety-System Features
 - Control Rods
 - High-Pressure Injection [HPI]
 - Borated Water Storage Tank
 - ECCS-Recirculation Sump
 - Other Components

TMI-2 Station Schematic



Engineered-Safety-System Features

- Control Rods
- High-Pressure Injection [HPI]
- Borated Water Storage Tank
- ECCS-Recirculation Sump



THREE MILE ISLAND UNIT 2 (TMI-2)

THE REACTOR

THE ACCIDENT



THE CONSEQUENCES

TMI-2 Control Room



TMI-2 ACCIDENT

- SEQUENCE OF EVENTS
 - Before 4:00 a.m. on March 28, 1979
 - 97 % Power
 - Problems Assumed Minor
 - Small Loss of Coolant Through Pressurizer Valve to Drain Tank
 - » One *Electromatic* (Pressure) Relief Valve [ERV]; Also Referred to as a Pilot-Operated Relief Valve [PORV]
 - » Two Passive “Code” Safety Valves



TMI-2
Pressurizer

TMI-2 ACCIDENT

- SEQUENCE OF EVENTS
 - Before 4:00 a.m. on March 28, 1979
 - 97 % Power
 - Problems Assumed Minor
 - Small Loss of Coolant Through Pressurizer Valve to Drain Tank
 - Emergency Feedwater Valves Closed (Unintentional and Unknown to Operators)
 - Feedwater Demineralizer Blockage

TMI-2 ACCIDENT

- SEQUENCE OF EVENTS

4:00:36 a.m. March 28, 1979

- INITIATOR: Unable to Clear Demineralizer Blockage → Loss of Condensate (Feedwater) Flow to Steam Generators
→ Degradation of Reactor Heat Removal Capability

TMI-2 ACCIDENT

- SEQUENCE OF EVENTS

4:00:36 a.m. March 28, 1979

- INITIATOR: Unable to Clear Demineralizer Blockage
- Main Feedwater Pump Tripped Off-Line
- Turbine Tripped Off-Line
- Emergency Feedwater Pump Auto-Started
- Pressurizer Pilot-Operated Relief Valve (PORV)
Opened to Reduce Pressure
- Reactor Tripped on Overpressure Signal
 - - - Normal System Response (First 8 sec) - - -
 - Chain-Reaction Shutdown
 - Decay-Heat Source Remains

TMI-2 ACCIDENT

- SEQUENCE OF EVENTS
 - Emergency Feedwater Blockage
 - Prevented Steam-Generator Function
 - Distraction Until Valves Re-Opened
 - Overall Effect on Accident Progression
Uncertain
 - PORV Indicated “Closed” (Solenoid Was De-Energized)
 - PORV Actually Was Stuck Open
 - Small-Break Loss of Coolant Accident (SBLOCA) in Progress

TMI-2 ACCIDENT


- SEQUENCE OF EVENTS
 - Pressurizer Drain Tank Filled
 - Pressure Shown by Meter on Back-Facing Panel
 - Reading Nominal Before Tank Filled
 - No Chart Recorder for Trending
 - Drain-Tank Rupture Disk “Popped”
 - Reading Nominal Again
 - No Lasting Positive Indication of Pressurizer Coolant Loss

TMI-2 ACCIDENT


- SEQUENCE OF EVENTS
 - High-Pressure Injection (HPI)
 - Auto-Started
 - Operator Throttled HPI Manually
 - Responded to Pressurizer Filling w/ Water (“Going Solid”)
 - However, Simultaneously, Coolant Was Being Lost from Reactor Coolant System As-a-Whole
 - System Configuration Led to Ambiguous Indications & Inappropriate Action



TM-2 Reactor Coolant System




Piping Configuration
Allows RCS to Empty
While Pressurizer
Appears to be Filling




TMI-2 ACCIDENT

- SEQUENCE OF EVENTS
 - Coolant Pump Vibration
 - Two-Phase Coolant Flow
 - Pump Seal Destruction Would Cause LOCA
 - Pumps Shutdown
 - Water & Steam Separated

Voiding Effects



Separation




TMI-2 ACCIDENT

- SEQUENCE OF EVENTS
 - Coolant Pump Vibration
 - Core Uncovered w/ Subsequent Heat-Up
 - Zr-Steam Reactions
 - Hydrogen Evolution
 - Cooling Restoration
 - Pressurizer Relief Block Valve Closed
 - Hydrogen & Steam Blockage Remained

TMI-2 PORV

Block Valve



TMI-2 ACCIDENT


- SEQUENCE OF EVENTS
 - Cooling Restoration
 - Pressurizer Relief Block Valve Closed
 - Hydrogen & Steam Blockage Remained
 - Minimal Natural & Forced Circulation to Steam Generators
 - “Feed-and-Bleed” Through PORV
 - Cycle Low-Pressure Coolant Injection Pumps
 - Cycle PORV Open-and-Closed
 - Restart of Coolant Pump Restored Cooling
 - ~9:00 a.m. [+5 hrs] – Coolable Geometry

ACCIDENT TECHNICALLY OVER !!

TMI-2 ACCIDENT

- **RADIOACTIVITY**
 - Drain Tank Rupture Disk “Popped”
 - Radioactive Water Collected in Sump
 - Automatic Transfer from Sump to Auxiliary Building
 - Very High Radioactivity Transfer w.r.t. Typical
 - No Isolation (Set-Point @ 4 psi for Large LOCA)
 - Fission Gas Release from Auxiliary Building
 - Noble Gases 5%
 - Iodine 10⁻⁵%
 - Emergency Declarations

Radioactivity Release Pathways



TMI-2 ACCIDENT

- HYDROGEN
 - Normal Operation: Excess Hydrogen to Limit Oxidation of Cladding & Structures
 - Accident: Generated in Zr-Steam Reactions
 - Entered Containment Building via PORV and Drain Tank
 - Burned w/ Resulting 28-psi Pressure Spike
 - “Hydrogen Bubble” in Vessel Head
 - Concern for Hydrogen Explosion Rupture of Vessel
 - Public May Have Thought “Hydrogen Bomb”
 - Concluded to be Chemically Not Credible

TMI-2 ACCIDENT

- REACTOR CORE STATUS - INITIAL EVALUATION
 - Clad Damage Assessment Based on:
 - Neutron-Detector Response
 - Hydrogen Generation History
 - Fission-Product Releases
 - Coolant Restoration Presumed to Have Caused Damage by Quenching Hot Fuel
 - Some Melting of Ag-In-Cd & Other Materials Expected
 - No Indication of Global Fuel Melting


TMI-2 ACCIDENT

- REACTOR CORE STATUS
 - Evolutionary Knowledge Over Recovery & Cleanup
 - “Quick Look” Camera
 - Reactor Vessel Head Removal
 - Core Boring
 - Defueling
 - Lower Plenum Removal
 - Completion of Defueling


TMI-2 ACCIDENT

- REACTOR CORE STATUS - FINAL HYPOTHESIZED SCENARIO
 - Damage Sequence
 - Coolant Pumps Turned Off → Heat-Up
 - Blocked PORV → No Steam Flow
 - Coolant Restoration → Quenching & Collapse
 - Insulation → Melting
 - Molten Mass Formation / Extrusion
 - Molten Fuel in Bottom of Vessel



After
Pumps
Off



After
Pumps
On



Melt &
Melt-
Through



1987
End State
Configuration

TMI-2 ACCIDENT

- RADIOLOGICAL CONSEQUENCES
 - Ad Hoc Interagency Dose Assessment Group
 - Findings
 - 2,000,000 Persons → 3300 Person-Rem
 - Average Population Dose 1.5 mrem
 - Maximum “Fence-Post” Dose 83 mrem
(Estimated Actual Maximum Dose 37 mrem)
 - One Excess Cancer (Over 325,000 Bkgd)
 - Food Sampling - All Below FDA Limits


TMI-2 ACCIDENT

- POST-ACCIDENT RESPONSE
 - Emergency Response
 - Initial Emergency Declarations
 - Helicopter Sampling
 - During Planned Release of Radioactive Gases
 - » One-Time
 - » Purged Tanks for Other Near-Term Uses
 - Assumed by Samplers to be Typical of On-Going Releases
 - Severity Significantly Overestimated
 - Led to Consideration of Evacuation

TMI-2 ACCIDENT

- POST-ACCIDENT RESPONSE
 - Emergency Response
 - Initial Emergency Declarations
 - Helicopter Sampling
 - Evacuation Recommendation on Day 2
 - Shelter w/in 10 Miles
 - Close Schools
 - Evacuate Pre-School Children & Pregnant Women
 - Overall: 144,000 Persons/50,000 Households
 - Talk of "Hydrogen Bubble"
 - Evacuation Called Off on Day 10

Dignitaries, Briefings & Media



TMI-2 ACCIDENT

- POST-ACCIDENT RESPONSE
 - Plant Recovery
 - Stabilization - Core Cooling
 - Begin Auxiliary Building Decontamination
 - Technical Support - 1400 Personnel Worldwide

Technical Support




POST-ACCIDENT RESPONSE

- DECONTAMINATION
 - Auxiliary Building & Containment Entrance
 - Hands-On Methods
 - Heavy-Duty Ion-Exchange System for Removal of Radioactive Species from Accident Water

Radiation Safety


Closed-Circuit
Monitor



Change
Room



Respirator





POST-ACCIDENT RESPONSE

- DECONTAMINATION
 - Auxiliary Building & Containment Entrance
 - Radioactive Noble Gases (Primarily ^{85}Kr)
Vented from Containment Building
 - First Personnel Entries


First Manned Entry



Damage from Hydrogen Burn



Stairwell to Flooded Basement



POST-ACCIDENT RESPONSE

- DECONTAMINATION
 - Auxiliary Building & Containment Entrance
 - Radioactive Noble Gases (Primarily ^{85}Kr)
Vented from Containment Building
 - First Personnel Entries
 - Brute-Force → State-of-the-Art Methods

Containment Decontamination



Strippable Coatings



Scabbling






HydroLasing Manual Robotic




POST-ACCIDENT RESPONSE

- DEFUELING
 - “Quick Look”
 - Sampling & Mapping

Quick Look



Sampling & Mapping






Fuel in Lower Head




POST-ACCIDENT RESPONSE

- DEFUELING
 - “Quick Look”
 - Approach
 - Shielded Platform / TV Monitors
 - Long-Handled Tools
 - Vacuum System
 - Fuel Canisters
 - Vacuum
 - Filter
 - Manual (for Fuel Assembly)

Rotating Defueling Platform



Fuel-Assembly & Vacuum Canisters



TMI-2 Fuel Canister Shipping Cask



THREE MILE ISLAND UNIT 2 (TMI-2)

THE REACTOR
THE ACCIDENT

THE CONSEQUENCES

TMI-2 ACCIDENT

- ECONOMIC & OTHER CONSEQUENCES
 - Direct Costs
 - Recovery - \$1 Billion
 - Price-Anderson Payments - \$14.3 M
 - 2000+ Unresolved Claims
 - Minimal Local Residual Impact
 - TMI-1 Restart Hearings & 6-1/2-Year Shutdown
 - Nuclear Industry
 - Backfit & License-Related Costs
 - No Reactor Orders Post-Accident Through 2008

TMI-2 ACCIDENT

- SUMMARY
 - Most Serious Accident in U.S. Commercial Nuclear Power History
 - Reactor Core Melted (Not Known at Time)
 - Large Releases to Containment Building
 - Only Minor Environmental Releases & Consequences
 - Profound Effects
 - Utility
 - Nuclear Industry
 - Regulatory Authorities

TMI-2 LESSONS LEARNED

1. The NRC
 1. Resident Inspectors
2. The Utility and Its Suppliers
 1. Human-Factored Control Rooms
3. Training of Operating Personnel
 1. Ops - Engineering – Training – Management
 2. Replica Simulators
4. Technical Assessment
 1. First-Principles Simulation/Modeling
5. Worker and Public Health and Safety
 1. Radiation Effects Studies
6. Emergency Planning and Response
 1. Off-Site EOC
 2. Full Scope Drills/Exercises
7. The Public Right to Information
 1. Professional Organization

INDUSTRY RESPONSE

- Institute for Nuclear Power Operations (INPO)
 - Membership: All U.S. Nuclear Utilities [Now + Operating Companies]
 - HQ: Atlanta, GA
 - Role: Industry “Self-Assessment” and “Self-Policing”
 - INPO Staff and Utility Peer Assessments
 - Operations & Maintenance
 - Training & Qualification
 - Radiological Protection
 - . . .
 - Reporting

INPO

Communitarian Regulation – A system that has a well-defined industrial morality that is backed by enough communal pressure to institutionalize responsibility among its members