

Double-Shell Tank AY-102 Radioactive Waste Leak Investigation

14178 - Session 116, Storage and Retrieval of HLW

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Contractor for the U.S. Department of Energy
Office of River Protection under Contract DE-AC27-08RV14800

 **washingtonriver**
protectionsolutions
P.O. Box 850
Richland, Washington 99352

Double-Shell Tank AY-102 Radioactive Waste Leak Investigation

14178 - Session 116, Storage and Retrieval of HLW

D. J. Washenfelder
Washington River Protection Solutions

Date Published
March 2014

To be Presented at
Waste Management 2014

Waste Management Symposia
Phoenix, Arizona

03/02/2014 - 03/06/2014

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Contractor for the U.S. Department of Energy
Office of River Protection under Contract DE-AC27-08RV14800

 washington**river**
protectionsolutions
P.O. Box 850
Richland, Washington 99352

Copyright License
By acceptance of this article, the publisher and/or recipient acknowledges the U.S. Government's right to retain a non exclusive, royalty-free license in and to any copyright covering this paper.

APPROVED

By Janis D. Aardal at 3:30 pm, Apr 10, 2014

Release Approval

Date

LEGAL DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced from the best available copy.


Printed in the United States of America

#14178 Double-Shell Tank AY-102 Radioactive Waste Leak Investigation

D. J. Washenfelder
Washington River Protection
Solutions LLC / AEM
Consulting LLC



March 6, 2014




Agenda



- Describe Effort to Determine Whether Tank AY-102 Leaked
- Review Probable Causes of the Tank AY-102 Leak
- Discuss Influence of Leak on Hanford's Double-Shell Tank Integrity Program

Hanford Double-Shell Tanks

At Hanford 28 double-wall tanks built in six generations between 1968 – 1986 contain ~ 27 million gallons radioactive waste



- **Tank AY-102 was the first double-shell tank constructed at Hanford**



Double-Shell Tank Annulus Detail

- DOE developed integrity requirements for high level waste storage tanks with Brookhaven National Laboratory expert panels
 - BNL-52361, Structural Analysis Guideline Panel proceedings (1995)
 - BNL-52527, Tank Structural Integrity Panel proceedings(1997)
 - DOE G 435.1-1 incorporated the Panels' recommendations
 - Series of Hanford Tank expert panels refined these requirements
- Double-Shell Tank Integrity Program Elements
 - Primary Tank Wall Ultrasonic Inspection / 8-10 year cycle
 - Primary and Annulus Tank Visual Inspection / 5-7 year cycle
 - In-Tank Corrosion Monitoring / Real Time
 - Waste Chemistry Corrosion Control program
 - Structural Analysis and evaluations of thermal, operating, and seismic loads


- Prior to August, 2012 no suggestion of incipient tank leakage
 - No primary tank wall loss from corrosion
 - No tank annulus video inspection anomalies
 - In-tank corrosion probe results within limits
 - Waste chemistry within corrosion control limits
 - Tank operated within allowable thermal and operating load limits



Tank AY-102 Leak Discovery

Date	Event
Jan-2007	Last annulus video inspection
Jan-2007	Last primary tank ultrasonic wall inspection
Aug 1, 2012	Annulus video inspection commences; Floor anomaly found below Riser 87
Aug 5, 2012	“Brown Mound” found beyond Riser 77
Aug 10, 2012	“Frozen Cascade” found below Riser 90; Swabs indicate high levels of contamination
Aug 20, 2012	Leak Assessment initiated
Aug 29, 2012	Liquid accumulation discovered below Riser 83
Sep 26, 2012	Riser 83 material sampled
Oct 10 & 15, 2012	Riser 90 Brown Mound and Cascade sampled
Oct 19, 2012	Tank declared “Assumed Leaker”
Oct-2012 / Present	Video surveillance of Riser 83 and 87 leak sites


Tank AY-102 Annulus Video Inspection: Sites with Floor Material



- Annulus Floor Material near Riser 83, September 26, 2012:
 - 45 mR/hr dose rate
 - Principal Chemical Constituents: NaNO_3 , Na_2CO_3 , NaNO_2 , KNO_3 ¹
 - Principal Radionuclide Constituents: Sr-90; Cs-137
 - Conclusion: Tank Waste
- Annulus Floor Material near Riser 90, October 10 & 15, 2012:
 - “Brown Mound”: Feldspar and quartz – “Hanford Soil”
 - “Cascade”: Tank Waste

¹ In 1994, 4,000 gallons of KOH containing about 2,600 pounds of potassium were added to tank AY-102 to increase the pH. The tank AP-101 supernatant transferred into tank AY-102 in 2007 contained a significant potassium inventory. Tank AY-102 has second highest potassium inventory of any Hanford waste tank.

Hanford Tank Leak Assessment Process



- Structured process using experienced Operating, Technical, Environmental staff
- “If tank were leaking, what is probability the observed phenomena would be present?”

Tank AY-102 Leak Assessment – Lines of Inquiry


Lines of Inquiry	Yes	No
Chemistry	X	
Tank Construction	X	
Liquid Level Changes		X
In-Tank Corrosion Probe		X
Primary Tank Ultrasonic Wall Inspections		X
Waste Temperature		X
Tank Dome Deflection and Tank Settlement		X
Fill Cycle Fatigue		X

Tank AY-102 Waste Chemistry History





- Parameters influencing corrosion of carbon steel liner:
 - Aggressive ions (Nitrate, Carbonate, Chloride)
 - Inhibitory ions (hydroxide and nitrite)
 - Temperature
- Two main corrosion concerns for Hanford waste:
 - Stress Corrosion Cracking in presence of high nitrate ion or carbonate ion concentrations
 - Pitting Corrosion in presence of nitrate or chloride ion concentrations
- Five chronological chemistry phases in Tank AY-102 based on susceptibility to corrosion:
 - The first solids layer deposited in tank AY-102 in 1977 – 1984 (“Interval 2”) have the characteristics which cause pitting corrosion when subjected to higher temperatures experienced after 1999 (“Interval 4”)



Tank AY-102 Waste Chemistry History (cont.)



Tank AY-102 Construction Sequence



- First-of-a-Kind Construction at Hanford
 - Secondary Liner Warpage
 - Insulating Refractory Cracking
 - Primary Tank Bottom Plate Weld Rejection
 - Insulating Refractory Damage from Stress Relief and Hydrostatic Testing of Primary Tank



**Welding Tank AY-102 Secondary Tank Bottom
(8051-1-Photo)**

- Secondary Liner Warpage

- Use of thin $\frac{1}{4}$ -inch plates complicated by work in extreme cold (-20°F to -10°F) caused liner warpage. As plates were preheated and welded, convex bulges and wrinkles appeared.
- Flame heating and water fast quench partially eliminated wrinkles. But when plates were heated by the sun new wrinkles appeared.
- February, 1969 survey found 22 liner locations exceeding allowable 2-inch convexity. Root-to-crown slopes up to 1-inch per foot were present, exceeding allowable 3/8-inch per foot.
- These were eventually accepted for placement of the insulating refractory.




Example of Warped Secondary Tank Bottom Knuckle (8074-Photo)

Tank AY-102 Construction (cont.)

Insulating Refractory Placement

- Insulating Refractory Placement on Secondary Liner

- The insulating refractory pad is sandwiched between the bottom of the primary tank and the secondary liner. It supports the primary tank, and protects the structural concrete foundation under the secondary liner from high-temperature damage during post-weld stress relief and from tank contents.
- Cracks 1 to 2-inches deep and up to 7-feet long appeared in cured refractory as pours continued. These were blamed on flexing of the secondary liner from movement of the bulges.
- The cured surface was not flat or level in some locations. In March, 1969, 25 locations were identified with variations up to 1-1/4-inches between the high points and low points. These were corrected.




Double-Shell Tank Annulus Detail

Tank AY-102 Construction (cont.)

Primary Tank Bottom Weld Rejection Rate

- Primary Tank Bottom Weld Rejection Rate
 - Weld quality was a continuing concern. The floor plate weld rejection rate was ~ 36%. Many welds were repaired several times before passing radiographic examination.



Primary Tank Bottom Plate Weld Map for northern section of tank showing rejected welds in red, and accepted welds in blue. The weld map shows instances of welds being repaired several times before passing inspection.

Tank AY-102 Construction (*cont.*)

Insulating Refractory Damage


- Rainwater saturated the insulating refractory pad in the weeks before the primary tank was scheduled for post-weld stress-relief.
- During stress relief, the tank bottom temperature could not be raised above 210°F for two days, while steam escaped from the water-soaked refractory.
- The tank temperature eventually reached the required annealing temperature and was held at temperature for the required time.



Tank AY-102 Construction (cont.)

Insulating Refractory Damage

- Insulating refractory damage from stress-relief and hydrostatic test of primary tank
 - Full depth cracks $\frac{1}{4}$ -inch wide extending several feet under primary tank
 - Spongy top surface; affected depth increased as outer lip approached
 - Air passages blocked with spalled refractory
 - Thought to result from skin friction as primary tank expanded and contracted across surface of refractory concrete pad during stress-relief, and “oil-canning” of the tank on the outside perimeter of the pad



Tank AY-102 Construction (cont.)

Insulating Refractory Damage Repair




Preparing Insulating Refractory for modification with use of reinforced concrete



Tank AY-101 Primary Tank Gap over Insulating Refractory (52788-8-Photo). Gaps in Tank AY-102 were reported to be larger.


Summary Effect of Construction Difficulties



Tank Configuration with 3-Inch Secondary Tank Convex Bottom Curvature during Hydrostatic Test.

- Corrosion at high waste temperatures in a tank whose waste containment margins had been reduced by construction difficulties.
 - During 1977 – 1979 and 1983 – 1984 waste with insufficient NaNO_2 corrosion inhibitor probably came into contact with tank bottom. The corrosion situation was exacerbated by introduction of high-temperature tank C-106 sludge during 1998-1999.
 - Secondary floor liner bulges and primary tank post-stress relief condition created untenable performance demands for insulating refractory and primary tank bottom.

Tank AY-102 Leak Influence on Double-Shell Tank Integrity Program



QUESTIONS?

