


# Low Voltage E-Beam Diagnostics

**March 6, 2007**

**J. Puskar, G. Gibbs and R. Campiotti**


# Background

- Upgrade existing HV (120kV) machine
  - KCP procuring several LV (60kV) machines
- Ordered ~ 2004
- Received ~ early 2006
- Labview based system
- Typical new installation issues
  - Door frame, alignment coil, drift tube, etc
- Beam quality issues
- Limited experience with low voltage
- Rely on HV comparisons, faraday cup profiles, LLNL and R.F. experience
- Trade secrets, black magic and science?




# Faraday Cup Profiles Low and High Voltage


Low Voltage  
Ribbon Gun  
Ribbon Fil.  
60kV, 5mA?  
*"Old Coil" CR*



Focus -10 mA




Focus 563 mA




Focus +10 mA


High Voltage  
Ribbon Gun  
120kV, 5mA?



Focus -10 mA




Focus 710 mA



Focus +10 mA

- Image scales are consistent
- Faraday cup profiles using LLNL MFC
- Initial concern for LV was 90° rotation





# Focus Current Effects



**X**  
Low Voltage  
Ribbon Gun  
Ribbon Fil.  
60kV, 5mA?  
30 ipm

*"Old Coil" CR*

**Y**




**Focus +5mA**

**Focus 562 mA**

**Focus -5mA**

- Small changes in focus current, but big changes in beam power distribution
  - Deep penetration shift
  - Width of weld pool different in x and y




**This is a real issue!**



# E-beam Guns


## Standard Configurations



**Ribbon – LV**  
Up to 150mA

**Ribbon – HV**  
Up to 60 mA

**Hairpin - LV**  
Hole  $\phi$  .100"



**Low Voltage**  
**Hairpin Gun w/**  
**Ribbon Filament**  
**Hole  $\phi$  .100"**  
**Diagonal 0.093"**





# Diagnosing the Problem

---

- Rotated the gun in the LV machine – no effect
- Turned off coil currents
- Melted with 0 mA focus current
  - Found peaking problems
- Compared our HV to our LV

LV Machine  
Ribbon filament  
“Ribbon gun”  
60kV, 10’s mA







HV Machine  
Ribbon filament  
120kV, 30 mA



Concluded that any issues that may exist with our LV guns were not root cause issues




# Focus Coils



- Initial thought was focus coil issue
- Original coil may have hysteresis
- Received second coil with “improved” ferromagnetic alloy – but had sizeable gaps
- Coil fabrication not trivial
- Top and bottom

Original Coil (Left)    Replacement (Right)


# Vapor Tube



## Lower Column Details


- Tube is nominally an austenitic stainless
- Around circumference slight Magne-gage readings 0 to 0.5 FN
- Tube position had significant beam quality implications
  - Removing, Rotating & Shimming
- 2<sup>nd</sup> tube was different and nonmagnetic, but base wasn't – FN 3

Low Voltage  
Hairpin Gun  
Ribbon Fil.  
60kV, 5mA?  
New Coil  
553 mA focus



# “Optimized” Configuration

- Low Voltage
- Hairpin Gun
- Ribbon Fil.
- 60kV, 10mA, 60ipm
- Tube Optimized




Focus -8/10 mA

Focus 556 mA

Focus +8/10 mA


- There must be more to the story???
- Rotate the Gun – little difference
- Rotate the Tube – large difference



## Future Experiments

---


- Change the filament
- Flip coil over
- Fabricate new vapor tube from other material
- Characterize the ribbon gun and filament
- Optimal hole diameter



# Summary / Lessons Learned

---

- Three continued areas of interest
  - Guns, Coils and Vapor Tube
- The symptoms are much improved, but is the problem really any better?
- Long-term viability of ribbon filament in hairpin gun?
- Future of the vapor tube
- Faraday cup provided fast, cheap and reliable means for assessing the value of changes
- Relearning need to be deliberate, take good notes and stay organized



# Acknowledgements

---

- **John Elmer, Todd Palmer and Alan Teryua**
- **Joe Michael**
- **Paul Burgardt**
- **Andy Gardea**