

Center of Wafer Gate Leakage Resulting in Product Yield Loss: A Failure Analysis Perspective

Darlene Meloche Udoni & Mary A. Miller


SAND2017-4202D

Research Problem

- Look for historic trending in data or in previous work
- Look for similar electrical signals in chronologically relevant lots
- Understand scope of problem: wafer and/or package-level
 - Problem was limited to center of wafer evidenced by product lot spatial yield loss


Electrical Analysis

- Confirm failure type on both on wafer level and on packaged device



Wafer-level: Discrete Transistor

Data indicates high current at center site ($\sim 10^{-4}$ A at 3V) and at good die sites ($\sim 10^{-10}$ A at 3V).




Packaged Eiger Device

Determined characteristic shape of current-voltage sweep: Bad site ($> 10^{-6}$ A @ 3V). Good site ($\sim 10^{-7}$ A @ 3V).

Optical inspection




- Optical inspection of area of interest
- May require jet-etch to expose die on packaged parts



Laser-based Technique



- Laser technique used to localize failure sites (thermally-induced voltage alteration, TIVA)
 - In packaged parts, we determined a characteristic pattern for this failure mode
 - Directional with respect to the center of the wafer
 - Diffuse dark signals

Die layout, kill zone in orange



Cross-sectional Focused Ion Beam (FIB) / Scanning Electron Microscopy


- Ability to cross-section, image and provide chemical analysis at defect location
- Typically utilized after other localization FA techniques
- At wafer level, the leaky transistors had leakage paths to the substrate (Box defects)
 - Transistors without gate leakage also exhibited Box defects
- At package level, we never found macroscopic physical defects



Conclusions/Further Work

- Helped identify CMP as the source of charge-induced damage
 - Determined scope of affected area (wafer real estate)
 - Characterized Box defects
 - Provided iterative and timely FA to support empirical fab experiments
- Generated a failure mode library both of TIVA imaging and I-V sweeps on packaged parts characteristic to charge-induced damage
- This work enabled quick identification of a similar charge-induced damage issue in backend processing outside of the fab causing product yield loss**
- Similar charge-induced damage caused by atomized DI water rinse on topside of finished wafers

Optical image of 'tetris-like' defects observed on test structure dummies at the center of wafer




Backside Thinning and Analysis


- Determine large area density of box defects and extent of affected area

Method:


- Cleave and isolate area of interest
- Backside lap
- Chemical etch (XeF_2) to reveal defect
- Defect provides pathway through Box to etch island
- Process can be applied to both wafers and packaged parts after the die is removed from the package.



Optical image of a cleaved section from a wafer post thinning



Backside optical image of a single transistor where part of the Si island has been etched away indicating the presence of a Box defect.






Optical image of Box defects found in dummy structures

Box Defects were found in:

- Areas outside of the four center die
- Passing discrete transistors (confirm FIB results)
- Die I/O circuitry that does not influence device leakage
- Dummy structures

Box Defects were not found at the TIVA signal sites (confirmed FIB results) but were found in close by I/O structures and dummy structures.



Acknowledgements: Thanks to Kira Fishgrab for backside processing, Pai Tangyunyong for his technical advice and to Alex Pimentel for FIB cross-sectional work.