

Accident Investigation Board (AIB) for the Test Site 9920 Event

SAND2014-16600PE

Carol Adkins, 06100



Sandia
National
Laboratories





Department of Energy
National Nuclear Security Administration
Washington DC 20585

DEC 13 2013

OFFICE OF THE ADMINISTRATOR

MEMORANDUM FOR DON F. NICHOLS
ASSOCIATE ADMINISTRATOR FOR SAFETY AND
HEALTH

MICHAEL HAZEN
VICE PRESIDENT, INFRASTRUCTURE OPERATIONS
DIVISION
SANDIA NATIONAL LABORATORIES

FROM: EDWARD BRUCE HELD *EBH*
ADMINISTRATOR

SUBJECT: Accident Investigation into Explosion Injury at Sandia National
Laboratory, December 11, 2013

- *Identify relevant facts*
- *Determine causes*
- *Develop conclusions*
- *Determine needs to prevent reoccurrence*



Printed with soy ink on recycled paper

TEAM PRINCIPLES

- Maximize the investigation as a **learning experience**, not just for Sandia, but for the entire DOE Complex
- Find **solutions**, rather than blame while respecting individuals
- Review the event using the **principles** of Integrated Safety Management, **Safety Culture**, Human Performance Improvement and **Engineered Safety**
- Demonstrate a **Just Culture** by looking at the event as a result of a system of interoperable parts, not an individual failure, and find the underlying causes, not just 'surface' causes

AIB CORE TEAM

Don Nichols NNSA

Co-Chair

Michael Hazen 4000

Co-Chair

Carol Adkins 1800

AIB Team Lead

Philip Heermann 6512

TAT Lead

AIB TEAM

Caren Wenner 0431

Mike Lopez 1679

Marce Armendariz 1751

Ralph Fevig 4122

Noel Duran 4021

Tim Wallace 4122

Mike Zamorski NNSA

Jef Franchere NNSA

TAT TEAM

Kim Merewether 0434

Pat Smith 1732

Marce Armendariz 1751

Robert Brocato 1751

Matt Celina 1819

David Damm 2554

Tim Wallace 4122

SUPPORT TEAM


Bess Campbell-Domme 4021

Pam Maestas 4024

Stephanie Holinka 3651

Robin Johnson TCR

EVENT SUMMARY




During an explosives test at Site 9920, an individual received an injury to their left hand when the detonator in the test unit fired during troubleshooting.

TECHNICAL ADVISORY TEAM (TAT)

Conducted scientific and engineering analysis and provided technical expertise

- Review and understand the design
 - Conduct design reviews (both hardware and software)
- Determine potential failure paths



WHY THE CONCERN... ?

RP-2 Detonator


(50 mg NEW)

Placed On Palm Of

Simulated Hand

DIRECT CAUSE

The direct cause of this accident was a failure in the test device, from mechanical disturbance or electrostatic discharge, which caused an unexpected detonation.



CORE CAUSES

- ① Failure to effectively implement “safe by design” intent
- ② Insufficient WP&C of Test Operations
- ③ Lack of integration and understanding of the project
- ④ Differing safety culture maturity levels

1: FAILURE TO EFFECTIVELY IMPLEMENT “SAFE BY DESIGN” INTENT

Design group did not analyze the development and testing cycle of the device, make the device as safe as they could, and require it to be treated as unsafe while engineered safety protocols were being confirmed.



ENGINEERED SAFETY IN DESIGN

Fireset Design

- Recognized that safety of the system is inherent in the system design, not the design of individual components.
- Made safety recommendations to other component designers, such as the use of the shorting plug.
- Designed in safety features, such as the LED light.

Explosive Assembly


- Applied engineered safety principles when installing the detonator into the test unit.
- Understood the technical basis by learning enough about the test unit to apply three controls to ensure energy would not reach the capacitor.
- Exhibited defense in depth by assuming the detonator would initiate anyway; used a blast shield to protect the worker.

2: INSUFFICIENT WP&C OF TEST OPERATIONS

The operations group accepted and then executed a job that their **existing hazards analysis** and operating procedures did not address, without analyzing the hazard, identifying controls & implementing controls.



3: LACK OF INTEGRATION AND UNDERSTANDING OF THE PROJECT



4: DIFFERING SAFETY CULTURE MATURITY LEVELS

Sandia's diverse workforce has varying levels of safety practice maturity. Typical approaches to advancing the maturity of safety culture have not been sufficiently tailored to reach all individuals in the workforce, according to their individual needs.



*People who think
they "get it," but don't*

*People who don't
realize they need it*

IS THIS INCIDENT RELEVANT TO DIVISION 8000?

Do you...

- Have matrixed work?
- Do troubleshooting?
- Do active verification?
- Follow all your processes?
- Communicate well with your partners?
- Modify equipment?
- Have security-driven communication challenges?
- Understand the requirements?
- Understand what is in/out of scope for the safety case?
- Do the critical thinking about how things could go wrong?
- Challenge each other?
- Think about test and use during design?
- Clearly understand and communicate the level of maturity of a design to others?

Accident Investigation Board (AIB) for the Test Site 9920 Event

Marcelino Armendariz
01751




Sandia
National
Laboratories



Technical Advisory Team

- TAT was formed to provide technical expertise to the AIB.
 - *Understand the technical aspects of detonator initiation (failure modes that contributed to the incident)*
- Composed of experts in firing sets, energetic materials, polymer materials, communications electronics, microprocessors, EM/ESD
- TAT was primarily focused on answering the following question:
 - *Why did the detonator go off when it did?*


Punctured cable and electronics compartment fragmentation




Items that helped expedite analysis

- Evaluation Units available for TAT analysis
- Design reviews with TAT & Design Team
- Device without a detonator immediately available for analysis
- Rapid prototyping of mechanical samples
- Sandia Arming & Firing Integrated Telemetry (SAFIT) available for measurements


SAFIT: Sandia Arming and Firing Integrated Telemetry




Labview-based display of up to 8 simultaneous signals



Portable data collection using laptop and digitizer



Fiber-optic telemetry of low and high voltage signals. Basic setup is shown: ARM, FIRE, low voltage, and high voltage.



Additional sensors include RF field power, magnetic field, high current discharge (CVT), and small current or voltage sitting at a very high voltage.

Plausible Scenarios

FO attempted to remove the detonator assembly from its housing and found that the threads were seized. On his second attempt, FO applied additional torque to the detonator (based on testimony).

This level of torque caused significant distortion of the interior plastic housing which contained the electronics (verified by lab testing)

- **Scenario 1:** The distortion led to an intermittent power connection which reset the microprocessor and generated an unintended firing signal
- **Scenario 2:** Human ESD in the vicinity of the detonator caused the CDU to trigger (demonstrated in the lab)

Scenario 1

- The distortion led to an intermittent power connection which reset the microprocessor and generated an unintended firing signal
 - TAT demonstrated in the lab that a momentary power glitch will reliably cause the microprocessor to reset
 - When the microprocessor resets, it briefly sends a FIRE signal which is sufficient to reliably trigger the CDU
 - The power glitch can be caused by a mechanical shock equivalent to dropping the detonator onto a hard surface from 1/16".
 - Distortion of the housing is plausible, but was not demonstrated in the lab

Safety Features to Consider When Designing Electronic Systems


- What happens to the electronics when power is interrupted?
- Characterize the system interconnects (cables, vias, etc.) to make sure they are reliable for the design intended.
- Power glitches need to be considered in the design of electronics.



Scenario 2


- Human ESD in the vicinity of the detonator caused the CDU to trigger (demonstrated in the lab)
 - TAT demonstrated in the lab that indirect human body ESD/EMI couples into the electronics and reliably causes the CDU to trigger
 - The microprocessor was not observed to become “upset” by the EMI

Typical setup for ESD/EMI characterization



Div. 8000 Briefing on the Accident Investigation Board (AIB) for Site 9920

Mike Lopez, 00421



**Sandia
National
Laboratories**

Discussion

1. Let's go to the site
2. Engineered safety lessons learned
 - Overarching criteria clarifications
 - Safety case insights

c1

Slide 25

c1 Does this meeting still pertain?

cladkin, 4/1/2014



Albuquerque
International
Sunport

onship
ourse

USS Bullhead
Memorial Park

Sandia F
Open Sp



Tijeras Arroyo
Golf Course

Kirtland Air
Force Base





Location of the accident

Location of 1 lb C-4



Location of 1 lb C-4 with armed detonator installed



20-25 ft

Location of software engineer



“It doesn’t apply to us” mindset

- Seen in the responses to past audits.


We will be tempted

- Fundamental Attribution Error
 - If someone else makes a mistake, they are negligent or incompetent.
 - If you make a mistake, there were all kinds of external factors.

Good safety cultures can only be recognized from the outside.
Inside the culture, everyone thinks there is a long way to go.

Things should get slower towards the end

Longest Minute in Sports
(Length of final minute in close NCAA basketball games in March 2013)



What is engineered safety?

Revised approach to WP&C with
engineered safety principles

Engineered safety is not uniformly understood by the workforce

While “engineered safety” is in the vernacular, it is not defined by the corporation.

The new WP&C manual does not define the one term everyone talks about.

The overarching criteria must be interpreted through these principles

- Safety is an attribute of an operational system achieved by intent.
- Use technical expertise to systematically and critically analyze ways in which the system can fail to perform as intended.
- Engineering design of the system prevents identified potential failures or mitigates their consequences.

Safe by design intent

- Designers apply technical expertise to design safety into the system from the beginning of the project.

Understand the technical basis

- It should be demonstrated, through engineering analysis and scientific understanding, how a system is intended to perform and how it can fail to perform.

Identify and control energy sources

- Many of the most serious accidents occur due to the release of hidden or unexpected forms of energy. This criteria specifically asks for extra diligence in controlling energy sources.

Define unacceptable consequences

- Defining the unacceptable consequences is the formal and written addition of specific system safety requirements to the operational system.

Assess risk

- Use of probability of occurrence in determining whether or not to mitigate a failure should be avoided unless the probability of occurrence can be demonstrated through quantifiable evidence.

Require positive verification

- Part of this assurance is that the person in charge assumes “the worst” until the correct configuration is specifically assured by responsible individuals.

The purpose of a safety case is to demonstrate critical thinking

Demonstrated

- Specific to the process
- Technical details
- Involves the workers
- Answers
 - How can it fail?
 - How do you prevent failure?
 - What if it fails anyway?

Not Demonstrated

- Stops at a general overview
- Index of other documents
- Unknown to worker
- Summary of the PHS hazards
- Tied more to space than activity level work

Some good indicators

- Describes work scope
- Specifies unacceptable consequences
- Team members' names are recorded
- Team meetings times and discussions summarized
- Describes hazards of activity level work
- Describes mitigations of hazards for the work
- What if scenario analysis
- Describes independent review/assessment (if done)

“Red flag” language

- “Summary” documents
- “Cut & paste” or “Copy this over”
- “We did an umbrella analysis for all work in the lab.”
 - Red flag for overconfidence.
- “Safety case is useless or meaningless.”

If you find no value in the safety case, don't sign it.


ENGINEERED SAFETY IN DESIGN

Fireset Design

- Recognized that safety of the system is inherent in the system design, not the design of individual components.
- Made safety recommendations to other component designers, such as the use of the shorting plug.
- Designed in safety features, such as the LED light.

Explosive Assembly

- Applied engineered safety principles when installing the detonator into the test unit.
- Understood the technical basis by learning enough about the test unit to apply three controls to ensure energy would not reach the capacitor.
- Exhibited defense in depth by assuming the detonator would initiate anyway; used a blast shield to protect the worker.



AST SHIELD
GRAMS TNT EQUIVALENT
15 cm from explosive
Kemper Explosives Safety Manual
2 Safety Shields
Marin Cooper 846-0892

AST SHIELD
GRAMS TNT EQUIVALENT
15 cm from explosive
Kemper Explosives Safety Manual
2 Safety Shields
Marin Cooper 846-0892

AST SHIELD
GRAMS TNT EQUIVALENT
15 cm from explosive
Kemper Explosives Safety Manual
2 Safety Shields
Marin Cooper 846-0892