


# Directional Dependence of Mechanical Properties and Defects of LENS 304L

Cole Britt, David Keicher, and  
Shaun Whetten

Sandia National Laboratories




# Outline

- Introduction
- High Throughput Tensile Testing
- Results
- Additional Testing
- Discussion


# LENS

- Laser parallel to z axis creates melt pool
- Powdered metal feed into melt pool creates deposition
- X-Y motion table moves substrate to create continuous weld bead
- Z motion controls layer height




# Print Parameters


- Platten Temp - 30 C
- Powder Feeder Voltage - 3.5V
- Laser Power 450W
- Table Feedrate - 600 mm/min
- Layer height - .25 mm




Sample Sets 1 & 2



Pull direction,  
transverse to  
build plane




Sample Sets 3 & 4





Pull direction,  
parallel to  
build plane

# Stress and Strain of Samples







- On average, builds 2, 3, and 4 surpassed the typical UTS for wrought 304L.
- Roughly half of the samples from builds 3 and 4 surpassed the typical strain for 304L.
- Only one sample from build 1 surpassed the typical UTS for 304L.

# Weibull Distributions UTS and Strain at Failure






- Samples pulled orthogonal to build planes have much lower ductility than samples pulled parallel to build plane.

# Build 1 (Transverse to Build Plane)




- Large lack of fusion defects around one edge.
- Oxide particles are present throughout microstructure.

# Build 2 (Transverse to Build Plane)







- Large lack of fusion defects.
- Defect based failure mode accounts for wider distribution of the set and lower strength than sets 3 and 4.

# Build 2 Metallography




# Build 3






- More ductile fracture, with few defects in fracture surfaces
- Difference in topology, ridge behavior in some samples

# Build 3 Metallography




- Low porosity (possibly)
- This orientation does not show any correlation between defects and layer interfaces
- Possible defects at build layer interface

# Build 4



- More ductile fracture, with few defects in fracture surfaces
- Difference in topology, ridge behavior in some samples




# Build 4 Metallography



- Low porosity
- This orientation does not show any correlation between defects and layer interfaces
- Possible defects at build layer interface


# Possible Causes of Directional Dependence

- Directionality of Defects
- Possibility of heat buildup in substrate






# Additional Exploration

- Analyze samples 3 and 4 for interface defects
  - Tomography to identify internal defects
  - Additional sectioning as needed
- Analyze samples 1 and 2 for interface defects
  - Analysis of grain structure at build interface
- Repeat tensile testing
  - More samples fabricated
    - Heated Platent
  - Tomography performed to ensure high density
  - Samples in testing



# Tomography Images



# Discussion

- Additional work ongoing
- Possibility of part alignment to build direction

# Thank You