

Transducers for Structural Dynamics and Solid Mechanics

01520

October 30, 2007

Corporate Learning & Professional Development & Training P.O. Box 5800, (MS 0653) Albuquerque, NM 87185-0653 Phone: 845-CLAS (845-2527)




Corporate Learning & Professional Development
Chart your course!



Sandia National Laboratories

Topics

- ◆ Introduction
- ◆ Strain Gages
- ◆ Accelerometers
- ◆ Force Transducers
- ◆ Displacement Transducers




Strain Gages

- ◆ Used to measure strain
- ◆ Available in
 - Uniaxial: one axis of strain
 - Biaxial: two orthogonal axis of strain
(principal strains when orientation is known)
 - Three element Rosettes: complete 2-D state of strain
 - Shear: direct measure of shear strain

How does a Strain Gage work



$$\Delta\text{resistivity} = \Delta\text{resistivity due to } \Delta\text{geometry} + \Delta\text{resistivity due to piezoresistive effect}$$



- ◆ Gage consists of loops of wire
- ◆ Stretching of gage produces a change in resistance in the wire
- ◆ Resistance drop is measured by a voltage change in a Bridge
- ◆ Measured strain is an average over the length of gage

Applications


- ◆ Monitoring for yield in materials
- ◆ Model validation
- ◆ Failure Analysis
- ◆ Load Characterization



Implementation Details

- ◆ Typically mounted using high strength glue
 - Abnormal environments require advanced bonding
- ◆ Requires amplifiers to complete bridge circuit
- ◆ Temperature Compensation
- ◆ Noise Attenuation
 - Strain gages look and act like antennas

Basic Setup
(3 wire)



Calibration and Sensitivity

- ◆ Sensitivity specified in Gage Factor
 - Define Gage Factor
- ◆ Gage Factor provided by manufacturer based upon “lot” that gage is a member of
- ◆ Sensitivity (strain/voltage) is based upon gage factor
- ◆ Sensitivity varies based upon expected range to be measured
 - Resistivity change in wire is slightly non-linear

What to look for in a Strain Gage

- ◆ Range of strains expected
- ◆ Mounting Surface
- ◆ Material being strained
 - Softer material requires softer strain gage
 - Most strain gages designed for steel/aluminum like stiffness
 - Orthotropic
- ◆ Operating environment
 - Temperature
 - Electric Fields
 - Flying Debris



Piezoelectric Strain Gages




- ◆ Self contained like an accelerometer
- ◆ Conditioned like an accelerometer
- ◆ Mounts like an accelerometer
- ◆ Only measures dynamic strain
 - PZT is not sensitive to static loads

Accelerometers

- ◆ Used to measure acceleration
- ◆ Most common measurement in structural dynamics/solid mechanics
- ◆ Two major types of accelerometers
 - Piezoelectric
 - Piezoresistive
- ◆ Available in
 - Uniaxial: Measures single direction
 - Biaxial: Measures two orthogonal axes
 - Triaxial: Measures three orthogonal axes



Piezoelectric Accelerometers



Shear Mode Accelerometer

- ◆ Used to measure low accelerations
 - Modal levels
 - Shaker Environments
 - Non-shock Environments
- ◆ Measure the current from a deformed quartz crystal to estimate acceleration
- ◆ Not sensitive to DC

Signal Conditioning

- ◆ Three types of Piezoelectric Accelerometers
 - Integrated Circuit (IEPE, ICP, etc)
 - Most common
 - Requires a small current (4-10 millamps) power
 - Outputs a voltage proportional to acceleration
 - Circuits internal to accelerometer convert charge to voltage
 - Charge Mode
 - Requires external conditioning to convert charge to voltage
 - TEDS (Transducer Electronic Data Sheet)
 - Has internal permanent (ROM) and programmable (EEPROM) memory
 - Has serial number, manufacturer, sensitivity, cal date, etc stored internally
 - Can access serial number, etc through conditioning system
 - Has small amount of internal memory to store other information such as location

Environment Sensitivity

◆ Base Strain

- Strain at the base of the accelerometer appears as a measured acceleration
- Gage needs to be isolated through the use of a mounting block

◆ Thermal loads

- Temperature variations cause the sensitivity of the gage to vary
- May need to insulate gages to protect from thermal variations

◆ Acoustics

- Sound waves around test article can induce measured response on accelerometer (non-structural)
- Test when lab is quiet or isolate gage

Mounting Techniques


◆ Wax

- Low frequency/Amplitude applications
- Quick
- Not permanent or reliable
 - Not for internal gages

◆ Hot Glue


- Quick
- Very common mounting technique
- Can debond adhesive on mounting surface (copper tape)

Copper Tape



Hot Glue

Mounting Techniques (con't)



Super Glue

Dental Cement

- ◆ Super Glue
 - Cyanoacrylate
 - Quick, very common
 - Good for small accelerometers
 - Strong bond
 - No filling capabilities
 - Weak in shear
- ◆ Dental Cement
 - Strong, Stiff
 - Can act as filler
 - Good for large accelerometers
- ◆ Torr Seal
 - Vacuum bonding agent
 - Very strong bond
 - Not used much with PE

Mounting Techniques (con't)

◆ Stud Mounting

- Extremely Strong
- Used for permanent mounting
- Sometimes used in combination with a bond
- Failure requires mounting screw to break



Piezoelectric Accelerometer Summary

- ◆ Good for low amplitude, non-shock responses
 - Modal measurements
 - Shaker Environments
- ◆ Measures response of crystal to estimate acceleration
- ◆ Requires a small current to drive
- ◆ Can measure environment as well as acceleration
 - Need to minimize environment sensitivity
 - Acts as an unknown bias (epistemic uncertainty) on the gage
- ◆ Mounting dependent on application




Piezoresistive Accelerometers

- ◆ Used to measure shock events

- Hopkinson Bar
- Drop table
- Drop/pull-down tests
- LIHE/Mag-flyer Impulse tests
- Sled Track
- Explosive tests


How does a PR Gage work?



- ◆ Piezoresistive gages measure the strain developed in a beam during loading
- ◆ The strain is linearly related to acceleration (to a point)
- ◆ Calibration is used to relate strain to acceleration
- ◆ Gage contains three legs of the Bridge
- ◆ Conditioning amplifier completes the bridge

Mounting Techniques

- ◆ Base Stain Sensitive
 - Mount on a Block
 - Endevco 7270 has mounting requirements called out
- ◆ Short duration/High Frequency responses can “ring” the gage
 - Ringing is defined as exciting the natural resonance of the accelerometer
 - Typically for these environments, the gage is mechanically isolated (filtered) to minimize ringing
 - Isolation affects frequency response
 - Can attenuate frequencies of interest
 - Characterize the isolation
- ◆ Sensitive to high electric fields
 - Need to isolate/ground properly



Which PR gage do I use?

◆ Expected range of Accelerations

- 2 kG, 6 kG, 20 kG, 60 kG, 200 kG
- Size high for application to insure gage doesn't over-range
- Gage is linear (good) to about 2 (3) times the rated range of gage – except for 200 kG gage

◆ Mounting Technique

- If low frequency, hard mount accelerometer to structure
- If high frequency
 - Choose appropriate isolation
 - Choose gage resonance to be out of bandwidth of interest, if possible

Summary of Accelerometers

◆ Piezoelectric


- Low acceleration, low frequency environments
- Very common in modal applications

◆ Piezoresistive

- Shock environments
- High accelerations, high frequency events
- May need mechanical isolation (mechanical filtering)

Force Transducers

- ◆ Used to measure force
- ◆ Available for static and dynamic applications
 - Static works like a strain gage
 - Dynamic operates similar to a piezoelectric accelerometer
 - Down to 0.0003 Hertz for some
 - Based upon charge leakage from crystal
- ◆ Available with a built in accelerometer (Impedance head)
- ◆ Instrumented bolts are also available to measure preload/fixture loads
- ◆ Pressure transducers are similar



Signal Conditioning



- ◆ Static Force Gages require bridge completion like strain gages
- ◆ Dynamic Force Gages are conditioned with amplifiers used for piezoelectric accelerometers
 - Require a small (4-20 milliamp) current source
 - Output a voltage

Mounting Techniques

- ◆ Typically stud mounted or bolted to structure
- ◆ Can be part of testing machine (MTS)
- ◆ Calibration performed using reference load cell
- ◆ Alignment critical to insure accurate measurement (no moments)

Which Force Gage do I use?

- ◆ Static vs Dynamic
- ◆ Load range expected
 - Appropriately sized gage will be more accurate in range of interest
- ◆ Operating environment
 - Explosive
 - Corrosive
 - High Temperature
- ◆ Gage size for application
- ◆ Impact of inserting gage into system
 - Typically gage will soften the original system



Displacement Transducers

- ◆ Used to measure displacement
- ◆ Many different types
 - Linear variable differential transformer (LVDT)
 - String potentiometers
 - LASER based
 - Extensometers (Strain based)
- ◆ Frequency response of displacement gages vary greatly



LVDT

- ◆ Linear variable differential transformer
- ◆ The gage generates a voltage dependent on the location of the center rod
- ◆ Has an internal transformer
- ◆ Very little applied force
- ◆ Very common gage



String Potentiometer

String Potentiometer




- ◆ Very simple in principle
- ◆ A string is wrapped around a potentiometer.
- ◆ As string is pulled out, the resistance across the pot changes
- ◆ Very low frequency response
- ◆ Low displacement resolution
- ◆ Exhibits drag on string
- ◆ Good for measuring very large displacements (inches to feet)

LASER Displacement Gages

- ◆ Good for measuring very small displacements (< 0.001 inches)
- ◆ Requires accurate alignment
- ◆ Non-contacting (no applied force)
- ◆ Large mass

Extensometers



- ◆ Operates like a strain gage
- ◆ Measures very small displacements
- ◆ Produces a force in parallel with test region
- ◆ Very robust

Which Displacement Gage to Use?

- ◆ Estimate displacement range expected
- ◆ Is the force over the test region important?
 - If so than non-contacting or low force gages are important
 - If not than more common options are available
- ◆ Operating environment (any special concerns)
- ◆ Is the mass of the gage important
 - A displacement gage in a drop test with many accelerometers would need to be smaller than a test to yield of a material



Summary

- ◆ Many different quantities to be measured
 - Strain
 - Acceleration
 - Force
 - Displacement
 - Velocity (to be covered in a later lecture)
- ◆ Different gages for different response levels/environments
 - Important to choose proper gage for application
- ◆ Mounting of gage important
 - Ease of mounting vs integrity of mount
 - Mounts can affect response



Thanks for the Help!

Brendan Rogillio

David Kelton

Larry Dorrell

Gary Rivera

Patrick Hunter

John Laing

Brian Resor





Measurement Techniques for Structural Dynamics and Solid Mechanics

01520

November 6, 2007

Corporate Learning & Professional Development & Training P.O. Box 5800, (MS 0653) Albuquerque, NM 87185-0653 Phone: 845-CLAS (845-2527)



Corporate Learning & Professional Development
Chart your course!




Sandia National Laboratories

Topics

- ◆ Test Preparation
- ◆ Test Setup
- ◆ Data Quality Evaluation
- ◆ Signal Processing



Test Article Example



- ◆ Two large masses connected with a sample of foam
- ◆ Model validation experiment for the foam
- ◆ Example will be used throughout lecture/lab

PreTest Planning

◆ Identify Purpose of Test

- Model Validation
- Production Qualification
- Control Design
- Identification (Experimental)
- Damage Assessment
- Trouble Shooting (instead of Problem Analysis)

◆ Level of Rigor

- Low (Quick, few accelerometers, only relative amplitudes)
- Medium (many accelerometers, model assessment helpful)
- High (many accelerometers, care in input/response placement, absolute amplitude matters, reviews and assessments to insure quality of test)



Safety Issues



- ◆ Generate Test Plan of work
 - Hazards mitigated by ISMS
 - Classification
 - Desired data, analysis and format
 - Input/Response locations
 - Reporting requirements
- ◆ Perform Safety Assessment
 - Preliminary Hazard Assessment
 - Experiment Development Plan
 - Management Operational Review

Boundary Conditions


- ◆ Boundary Condition characterization crucial to understanding results
 - Perfect boundary conditions do not exist
 - Fixed boundaries are not fixed and have some flexibility
 - Suspension rigging will have stiffness and damping
 - Any fixturing will influence the measurements in some way
 - The key is to minimize/*understand* the effects of the fixture

Free Boundary Condition

- ◆ Can only really be achieved on-orbit
- ◆ Can be simulated on the ground with soft suspensions
 - Suspension by bungee cords
 - Placing test article on soft, resilient foam
 - Structure will be preloaded by suspension
- ◆ First frequency (flexible response) of the structure will not be affected by the suspension if it is approximately 10 times higher than highest rigid body frequency
- ◆ Suspension system will change the damping
- ◆ Suspension system should have safety controls to minimize damage in the event of failure



“Fixed” Boundary Condition




- ◆ True, zero displacement/rotation boundary cannot be realized
 - “Everything is Jello above 500 Hz” – Smallwood
 - Bolts have flexibility
 - Seismic masses are flexible
 - Shaker heads are flexible
 - Fixturing is flexible
- ◆ Understand fixture flexibility through instrumentation
 - Triaxial Accelerometers in the corners of your fixture
 - Base accelerometers

Identification of Input/Output Locations


◆ Intuitive

- Instrument to identify key modes
 - Bending
 - Axial
 - Torsion
- Instrument all appendages of interest
 - Antennas
 - IMUs (Inertial Mass Units)
 - Fins
 - Cantilevered Components
- Models can provide valuable insight for test planning



Identification of Input/Output Locations

- ◆ Model based identification of Input/Output locations
 - Important for model validation
 - Typically based upon Observability/Controllability of Modes
 - OTD is the in-house code used
 - Utilizes the Modal Assurance Criteria
 - Requires a FE model modal solution
 - Only as good as the model
 - Other techniques/packages available



Data Acquisition Parameters

- ◆ Are multiple data acquisition systems required?
 - High cost, one-off tests should have a backup system
 - Backup *may* not have to be as “complete” as primary system
 - Lower sample rate
 - Less resolution
- ◆ Sample Rate
 - Need to know maximum frequency of interest and maximum frequency excited
 - Piezoresistive (and other) gages
 - Set Sample rate high enough to capture resonance of gage
 - Necessary to fully assess over ranging
 - Understand anti-aliasing filters (to be discussed later)
 - Data can always be decimated (resampled at lower rate), if necessary

Sampling Parameters

◆ Bandedge Predictions

- Necessary to optimize dynamic range of A/D process
- For modals, range is set based upon input (Autoranging)
- For one-off testing, range is more critical
 - Use model to predict expected ranges
 - Add large safety factor to prevent overloads
 - Be conservative with gage choices
 - Overloads, clipping, and under-sized gages exceeding capabilities suck



Duration Specification

◆ Duration

- Fully capture event of interest
- Based upon duration/type of input
 - Long duration input requires longer recording times
 - Random inputs require very long durations
 - Shock events are typically short
- Frequency range of interest
 - Would like several cycles of lowest modes
- Dependent on Damping
 - Low damped structures require longer durations
 - High damped structures can use shorter duration
- Can always truncate time history if too much data is recorded



End-to-End Calibration

- ◆ Uncertainty Quantification of Data Acquisition
 - Some labs quantify each component of the Data Acquisition system is individually
 - Some labs perform end-to-end
 - Combination
- ◆ Interactions between the cabling and components could produce variations
- ◆ Need to send a known signal through as much of the system as possible to insure data quality
 - Pure sine tone at single frequency
 - Random Inputs
 - Chirps

Data Setup Check-outs

- ◆ Many accelerometers, many cables provide greater chance for errors
- ◆ Careful bookkeeping will help
- ◆ More rigorous to verify location of gages
 - Squeeze test
 - Some accelerometers are base strain sensitive
 - “squeezing” these mounted accels should induce a response at the data acquisition system
 - If the accel produces a response on the expected channel then all is well
 - Thermal test
 - Similar to squeeze test, many accels are sensitive to heat (Kistler – B50)
 - Place a heat source (soldering gun) near (don’t touch) accelerometer
 - An expected response at the data acquisition system will verify the location


Data Setup Check-outs

◆ Quick Modal Test to verify channel setup

- Quick Modal consists of impact test
- Frequency Response Function/Time history
 - Verify that the accelerometers are functional
- Low Frequency Mode Shape
 - Orientation of accelerometers
 - Location of the accelerometers
 - Approximately the correct sensitivity
 - Confirm accelerometers are functional


What input do I use?

- ◆ Hammer Impact (Modal)
 - Quickest first time setup
 - Can exercise nonlinearity
 - Minimal boundary condition effects
- ◆ Shaker (Modal, higher levels)
 - Better signal/noise ratio than a hammer impact for modal
 - Input can be tailored to frequency band
 - Minimizes nonlinearity for modal
 - Requires fixturing to interface with structure
 - Longer first time setup
 - Faster for multiple inputs or retaking data
- ◆ Explosive (High level)
 - Plenty of energy
 - Typically expensive (few number of tests)
 - Requires large effort to characterize input




Shock Inputs

- ◆ Hopkinson Bar
 - Smaller test articles
 - Repeatable, easily characterized
- ◆ Drop table
 - Large velocity changes
 - Single sided inputs
- ◆ Resonant plate/beam
 - Double sided inputs
- ◆ Others – pneumatic actuators, air guns, etc.




Data Quality Evaluation

Electrical Noise



Noise/60 cycle




- ◆ Electrical noise comes from many sources
 - Line (60 cycle)
 - Broken cables, loose connections
 - EMF
 - Ground loops
- ◆ Sometimes can be removed (minimized) with signal processing





Data Quality Evaluation

- ◆ Clipping occurs due to bandedge set too tight
- ◆ Sometimes data is salvageable
- ◆ Need good predictions and lots of safety factors on expensive tests
- ◆ Modal is usually set through trial and error (low cost of repeating test)
- ◆ Gage range can also be exceeded producing bad data which looks “good”

Overload/Clipping



Data Quality Evaluation



- ◆ Zero shift can occur in shock events
- ◆ Not visible in measured acceleration
- ◆ Very clear in integrated acceleration (velocity)
- ◆ Causes problems in calculated quantities
 - SRS (flat at low frequencies)
 - FFT (can corrupt all of frequency range)
- ◆ If it is mild, it can sometimes be reduced with signal processing
 - Produces “plausible” trace
- ◆ Double hits
- ◆ Coherence (output~input)






Signal Processing

- ◆ Some form of processing/analysis necessary for most/all measurements
- ◆ Anti-aliasing filters critical to good measurements
 - Analog only, low pass filters
 - Removes frequency content above Nyquist frequency
 - Without some form of anti-aliasing filters, data is questionable
- ◆ Digital filtering most basic form of post processing
 - Minimizes out of band response
 - Isolates response of interest
 - Minimizes high frequency noise




Filtering




- ◆ Low pass (Left) removes high frequency content
- ◆ Band pass (center) removes high and low frequency content
- ◆ High pass (Right) removes low frequency content

Frequency Response Function



- ◆ Frequency Domain, used in structural dynamics
- ◆ Transfer function between single point input and single point response
- ◆ Requires measurement of input and response



Frequency Response Function




- ◆ Peaks indicate natural frequency (pole, mode, resonance)
- ◆ Width of peak indicates damping levels
- ◆ Low frequency shows static (rigid) response, boundary response
- ◆ Dips indicate frequencies where location does not respond (zeros, anti-resonances)

Shock Response Spectra

Time History




Shock Response Spectra



- Used to assess short duration, transient events
- Calculated using response of a single degree of freedom oscillator to a base input of the signal



Shock Response Spectra




- ◆ Abscissa is “natural frequency” not “frequency”
- ◆ Low frequency asymptote indicates velocity change
- ◆ High frequency asymptote indicates peak acceleration
- ◆ Typically plotted in “g’s”

Structural Dynamics Curve Fitting


- ◆ Curve fits typically performed on Frequency Response Functions
- ◆ Fitting parameters
 - Frequency
 - Damping
 - Mode shapes
- ◆ Many different methods available, we use SMAC
- ◆ Fit quality assessed using Mode Indicator Functions
 - CMIF (Complex mode indicator function)
 - NMIF (Normal mode indicator function)

Fit Quality Comparisons



Complex Mode Indicator Function

- ◆ Fits performed using SMAC



Frequency Response Function

Data Management and Archival

- ◆ Large quantities of data can be produced
- ◆ Keeping track of data for documentation and archival important
- ◆ Ability to track processing and pedigree of data difficult
- ◆ Many test parameters need to be recorded/documentated
- ◆ Need some form of database
 - IMAT – Matlab based, written by ATA Engineering
 - sdChannels – Matlab based, currently under development at SNL

Summary

- ◆ Test Planning important

- Safety/hazard concerns
- Location of sensors
- Type of excitation
- Boundary Conditions

- ◆ Data Quality is critical

- End-to-End Calibration
- Preliminary data checks
- Signal Processing

- ◆ Documentation and Data Archival Important