




Development of a high-temperature and high-pressure electrical feedthrough



E. Arata, C. Koripella – 10/24/2022






Sandia National Laboratories is a multimission laboratory managed and operated by National Technology & Engineering Solutions of Sandia, LLC, a wholly owned subsidiary of Honeywell International Inc., for the U.S. Department of Energy's National Nuclear Security Administration under contract DE-NA0003525.


Problem statement – 1000°C and 1000 psi



Design and build a small sized electrical feedthrough capable of maintaining hermeticity during and after high temperature and high pressure exposure.



- Avoid excess braze fillet near edges to prevent stress cracks.
- Leave ~0.010" clearance at OD during metallization.




Two paths – Braze Pins and Cermet Vias



Brazed pins



- Kovar or Ni pins
- Kovar or Ni leads
- Kovar flange
- Ni plate and Non



Cermet Vias

- Kovar leads
- Kovar flange
- Ni plated

Optical cross section



Common braze filler metals:

- Palni (1238°C)
- Palco (1219°C)
- Paloro (1200°C)
- Palniro-4 (1169°C)
- **Palniro-1 (1121°C)**
- **Copper, 1084°C**
- Gold (1064°C)
- Palsil-10 (1025°C)
- Silver, 985°C
- *Silver-based, 650°C - 850°C*

furnace limit:
~1200C

$T_{solidus}$ adequate

$T_{solidus}$ too low


Pins

Flang
e Lead
s



Alumina
Ceramic
Cermet Via

Lead
s


EDX maps of Pin type feedthrough – as manufactured




Back scattered
SEM




Alumina Ceramic
Ni-plate
Kovar
Metallization/Cu braze




High temperature and pressure testing




Furnace and pressure experimental setup



Thermocouple setup



Pressure test housing design & first round failures




Pin type – after high temperature and pressure



High pressure - Inert gas


side




Oxidation side

Cu braze
material still
present and
NDL (no
detectable
leak).


Kovar although
Ni plated is still
heavily
oxidized.



Oxidation is less on thinner side of braze
joint.



Most of braze material is
present




Oxidation side

Metallization removed with braze
alloy

Via type – after high temperature and pressure




High pressure - Inert gas




Oxidation side

Sample exposed to air on both sides.
Minimal oxidation of vias.




All sample still NDL after exposure.

Heavy oxidation seen on Ni plated Kovar flange.



Incomplete braze fill



Oxidation side

Failure at metallization/alumina interface

Conclusions – Suggestions for future improvements



Brazed Pins

- Brazes fail due to oxidation: Focus on better braze fit up on pin brazes - thinner brazes.
 - Oxidation appears slower when brazes are thin. Flange braze is thin enough.
- Ni pins better for oxidation than Ni-plated Kovar.
 - 2x Ni plating. Kovar flange before and after brazing.
- Metallization has good adhesion.
- Investigation of Au-based braze alloys to increase oxidation resistance.

Cermet Vias

- Brazes fail due to cracking of metallization/ceramic interface: Focus on metallization strength.
- Vias are hermetic after high-temperature exposure.
- Improvement needed on lead braze strength.
 - Geometry change to larger lead head in a metallized ceramic blind hole.
- 2x Ni plating. Kovar flange before and after brazing.



Pressure test housing redesign and test

9 | Palniro – air fired both sides exposed




Cu pin braze
◦ Heavily oxidized

Palniro flange braze
◦ Au25Ni25Pd
◦ Minimal oxidation



Metallization/Alumina interface
failure



Bulk Alumina
failure