

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof. Reference herein to any social initiative (including but not limited to Diversity, Equity, and Inclusion (DEI); Community Benefits Plans (CBP); Justice 40; etc.) is made by the Author independent of any current requirement by the United States Government and does not constitute or imply endorsement, recommendation, or support by the United States Government or any agency thereof.

(HAN-
BARTON

HW-62052

DE92 000583

UNCLASSIFIED

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES. WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U. S. C., SECS 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

RESTRICTED DATA

THIS DOCUMENT CONTAINS RESTRICTED DATA AS DEFINED IN THE ATOMIC ENERGY ACT OF 1954. ITS TRANSMISSION, DISCLOSURE, OR REVELATION OF ITS CONTENTS IN ANY MANNER TO ANY UNAUTHORIZED PERSON IS PROHIBITED.

THIS DOCUMENT MUST NOT BE LEFT UNATTENDED OR WHERE AN UNAUTHORIZED PERSON MAY HAVE ACCESS TO IT. WHEN NOT IN USE, IT MUST BE STORED IN AN APPROVED LOCKED REPOSITORY WITHIN AN APPROVED GUARDED AREA. WHILE IT IS IN YOUR POSSESSION AND UNTIL YOU HAVE RETURNED IT TO YOUR CLASSIFIED DOCUMENT RESPONSIBILITY STATION, IT IS YOUR RESPONSIBILITY TO KEEP IT AND ITS CONTENTS WITHIN THE LIMITS OF THIS PROJECT AND FROM ANY UNAUTHORIZED PERSON. ITS TRANSMISSION TO, AND STORAGE AT YOUR PLACE OF RESIDENCE IS PROHIBITED. IT WILL BE DUPLICATED ONLY IN ACCORDANCE WITH EXISTING SECURITY REGULATIONS.

Revised by OSTI
ALL PERSONS READING THIS DOCUMENT ARE REQUESTED TO SIGN IN THE SPACE BELOW

ROUTE TO:	READ BY:	DATE	ROUTE TO:	READ BY:	DATE
<i>Manager</i>					
<i>YEM</i>					
<i>ATG</i>					
<i>RHP</i>					

APPROVED FOR
PUBLIC RELEASE

M. Boston 7/30/91

BEST AVAILABLE COPY

A
E
C
UNCLASSIFIED

DISTRIBUTION RESTRICTED TO AEC ONLY

U.S. GOVERNMENT PRINTING OFFICE 1954 1-2500

MASTER

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

PCT 16 ER10

DA T

10/14/59

FROM *✓* ORGANIZATION
MANAGER

CHIEF COUNSEL
CLASSIFICATION OFFICER
INDUSTRIAL LIAISON ENGINEER
INFORMATION DIVISION
INSPECTION DIVISION

ASST'MGR. FOR TECHNICAL OPERATION
PROCESS ENGINEERING & MFG. DIVISION
~~CONSTRUCTION ENGINEERING & SUPPORT~~
GENERAL CONSTR. & ENG. BRANCH
NPR CONSTRUCTION BRANCH
PROCUREMENT BRANCH
PROPERTY MGMT. BRANCH
TRANS. & TRAFFIC BRANCH
CONTRACT BRANCH
SAFETY DIVISION

ASST.MGR. FOR ADMINISTRATION
BUDGET DIVISION
COMMUNITY DIVISION
FINANCE DIVISION
ORGANIZATION & PERSONNEL DIVISION
CENTRAL MAIL ROOM
OFFICE SERVICES
RECORDS SERVICES
TELETYPE
SECURITY DIVISION

1 2 3 4 5

REMARKS

~~get~~ and file —
Get and prepare make
a report on them.
Then — can all be read
now on screen seating?
W/NAW 73609 *(This)*
C-3A
HW-62052
OCT 16 1959 /16

BEST AVAILABLE COPY

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

GENERAL  ELECTRIC
COMPANY

1-3. AEC-HOO, Att: JE Travis

RICHLAND, WASHINGTON HANFORD ATOMIC PRODUCTS OPERATION

October 8, 1959

U. S. Atomic Energy Commission
Hanford Operations Office
Richland, Washington

Attention: J. E. Travis, Manager

Gentlemen:

OPERATIONAL INTERRUPTION - B-REACTOR
Reference: HW-62052, dated September 22, 1959

Copies of the reference B-C Reactors Operation report covering this incident are being forwarded to you through Classified Files. Although this operational interruption might be attributed to normal wear and tear, and then would not require reporting under AEC Manual Chapter 0502, it was unusual in nature and time consuming in correction.

Very truly yours,

W. E. Johnson

GENERAL MANAGER

WE Johnson:RLD:bs

M. Boston 7/30/91
APPROVED FOR
PUBLIC RELEASE

RETURN TO: RECORDS SERVICE CENTER
BUILDING 712
BOX NUMBER 024721 *0188*
700 AREA

BEST AVAILABLE COPY

OCT 16 1959



1-3. AEC-HOO, Att: JE Travis

RICHLAND, WASHINGTON HANFORD ATOMIC PRODUCTS OPERATION

October 8, 1959

U. S. Atomic Energy Commission
Hanford Operations Office
Richland, Washington

Attention: J. E. Travis, Manager


Gentlemen:

OPERATIONAL INTERRUPTION - B-REACTOR

Reference: HW-62052, dated September 22, 1959

Copies of the reference B-C Reactors Operation report covering this incident are being forwarded to you through Classified Files. Although this operational interruption might be attributed to normal wear and tear, and then would not require reporting under AEC Manual Chapter 0502, it was unusual in nature and time consuming in correction.

Very truly yours,



GENERAL MANAGER

WE Johnson:RLD:bs

OCT 16 1959

GENERAL  ELECTRIC
COMPANY

1-3. AEC-HOO, Att: JE Travis

RICHLAND, WASHINGTON HANFORD ATOMIC PRODUCTS OPERATION

October 8, 1959

U. S. Atomic Energy Commission
Hanford Operations Office
Richland, Washington

Attention: J. E. Travis, Manager


Gentlemen:

OPERATIONAL INTERRUPTION - B-REACTOR

Reference: HW-32052, dated September 22, 1959

Copies of the reference B-C Reactors Operation report covering this incident are being forwarded to you through Classified Files. Although this operational interruption might be attributed to normal wear and tear, and then would not require reporting under AEC Manual Chapter 0502, it was unusual in nature and time consuming in correction.

Very truly yours,


W. E. Johnson

GENERAL MANAGER

WE Johnson:RLD:bs

OCT 10 1959

UNCLASSIFIED

HW-62052

September 22, 1959

This document consists of
4 pages, No. 5 of
25 copies. Series

DISTRIBUTION

73609

1 thru 6. R. L. Dickeman
7. J. T. Baker
8. J. W. Baker
9. R. S. Bell
10. R. J. Bursey
11. R. G. Clough
12. W. J. Ferguson
13. E. J. Filip
14. W. J. Gartin
15. O. H. Greager
16. C. N. Gross
17. E. T. Hubbard
18. D. S. Lewis
19. A. R. Maguire
20. J. F. Music - R. W. Reid
21. S. L. Nelson
22. C. A. Priode - T. W. Hauff
23. W. D. Richmond
24. Record Center
25. 300 Files

Classification cancelled (Change to

UNCLASSIFIED

By Authority of RLC-CG-4

TE Edwards, Princ. Eng. 2/22/91

By JL Strope 6/24/91

Verified By CF Ransdell

7-1-91

September 22, 1959

R. L. Dickeman
Manager
Manufacturing Section
IRRADIATION PROCESSING DEPARTMENT

OPERATIONAL INTERRUPTION
B REACTOR - SEPTEMBER 12, 1959

SUMMARY

B Reactor was scrammed on September 10 and again on September 12 by panellit trips. Subsequent investigations revealed the scrams were caused by small pieces of neoprene in an orifice screen. Extensive checks following the September 12 scram revealed pieces of neoprene in all seven near-side process water header basket screens, in all crossheader screens, and in three process tube orifice screens. The source of the neoprene was found to be a deteriorated curtain seal in the No. 4 process water storage tank, 190 Building. A portion of this seal had fallen into the storage tank and become dispersed throughout the downstream process water supply system. Total outage time required to clean and flush the process water supply system and resume reactor operation was 88.6 hours. Of the total outage time, approximately 40 hours were utilized in the performance of necessary project and maintenance work in the discharge area, which otherwise would have required outage time at later dates.

FINDINGS

1. Following a panellit trip on row 13 at 12:52 P.M. on September 10, 1959, small pieces of neoprene were found in the orifice screen of Tube No. 1353. At this time, the gauge pressure showed only a five- to seven-pound decrease, and there was no change in the gauge base range setting. All other gauge pressures on the row appeared normal. After a recurrence of this situation at 7:27 A.M. on September 12, approximately three hours after the initial startup, a full-scale investigation of the process water system was initiated. A rupture indication which showed on the gamma monitor at the time of the initial scram proved false. Investigation of a previous panellit scram, following startup, on row No. 46 showed nothing abnormal at that time.
2. Pieces of neoprene and fabric were found in all crossheader screens, the greater amounts being in the near-side header screens. Considerably more of the material was in the screens on the lower headers than the upper headers. The pieces ranged in size from very small bits to occasional pieces as large as one inch by three inches. All of the basket screens in the seven process water headers supplying the near riser were found to contain rather large

R. L. Dickeman

- 3 -

September 22, 1959

FINDINGS (Continued)

2. amounts of the neoprene pieces consisting of pieces as large as four inches by four inches. No neoprene was found in any of the far-side header basket screens. Approximately 200 process tube orifice screens and venturis were inspected. In addition to 1353-B, neoprene pieces were found only on the orifice screens of 1354-B and 4665-B. Also, one piece was found in the rod water supply screen.
3. Inspection of the curtain seal in Process Tank No. 4 showed the seal had deteriorated, and a piece approximately 36 square feet in size had dropped into the tank. These seals consist of laminations of neoprene sheets and canvas and were installed during the original tank construction. Power supervision had recognized the possible condition of the curtain seals and the damage they could cause, and the curtain seals had been removed from the No. 1, No. 2, and No. 3 Process Tanks during the fall of 1958 and the spring of 1959. No deterioration was evident upon inspection of these seals. It was intended to continue with the removal of the No. 4 seal, but during the spring of 1959, a windstorm removed part of the 190-B Tank Room roof, creating a safety hazard to operating personnel at this location. At this time it was decided to repair the Tank Room roof and to postpone removal of the No. 4 tank seal until roof repair was completed. It was necessary to cover the No. 2, No. 3, and No. 4 tanks with tarpaulins to prevent pieces of concrete, tar, and gravel from falling into the tanks during the roof repair work.
4. All crossheader screens were cleaned, the crossheaders were flushed, and the screens were replaced. A defective flexitalllic gasket was found on the No. 12 $\frac{1}{2}$ near-side crossheader screen, which could have permitted passage of the pieces causing the scrums, since these pieces appeared too large to pass through the crossheader screen. The defective gasket was probably caused by misalignment of the gasket and cover during tightening of the cover on the original CG-558 installation.
5. Some of the material in the crossheader screens was too large to pass through the valve pit basket screens. Since there were no ruptured basket screens, it must be assumed that a wrench found below the false bottom in one of the screen chests was not permitting the screen to seat properly. It was also found that neither the screen flanges or their mating surfaces were machined to fit closely, thereby creating a potential for material to bypass all screens. The process water system was thoroughly flushed, and during final installation, each screen was matched to its chest and the seating improved as much as possible by grinding the mating surfaces.

R. L. Dickeman

- 4 -

September 22, 1959

6. Prior to startup, the panellit pressure monitoring system was thoroughly checked to assure that no sensing lines were plugged and that all gauge base ranges were normal. Duplicate sets of data were taken by Process Technology personnel, calculations were double-checked and the results were analyzed by Process Technology personnel.
7. The reactor was started up at 2:57 P.M. on September 15. Additional temperature maps and flow and pressure readings, as recommended by the Process Technology Operation, were taken during the startup and subsequent operation. No unusual conditions have been observed since startup.

CONCLUSIONS

1. The primary cause of the incident was failure of the No. 4 tank curtain seal.
2. Improper screen fit on the pump discharge headers and improper installation of No. 12 $\frac{1}{2}$ crossheader screen were contributing factors in the magnitude of the incident.

RECOMMENDATIONS AND ACTION

The following preventive measures have been taken or will be initiated. They are recommended for other facilities where applicable:

1. The No. 4 Process Tank was isolated and the curtain seal removed. The tank and adjacent lines were thoroughly flushed before returning the tank to service.
2. Each of the other tanks are to be drained and inspected for foreign materials.
3. Future inspections of process water screens are to include checking for proper fit.

A. R. Maguire

A. R. Maguire, Manager
B-C Reactor Operation
IRRADIATION PROCESSING DEPARTMENT

AR Maguire:JWB:asn