

M-5242

DOE/OR/01-1501&D1

ORNL/M--5242

**Removal Site Evaluation Report
for the Isotope Facilities
at Oak Ridge National Laboratory,
Oak Ridge, Tennessee**

RECEIVED

JAN 29 1997

OSTI



MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This document has been approved by the
ORNL Technical Information Office
for release to the public. Date: 7/29/94

Advanced Sciences, Inc.

contributed to the preparation of this document and should not be considered an eligible contractor for its review.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from 423-576-8401 (fax 423-576-2865).


Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

DISCLAIMER

**Portions of this document may be illegible
in electronic image products. Images are
produced from the best available original
document.**

PREFACE

This document, *Removal Site Evaluation Report for the Isotope Facilities at Oak Ridge National Laboratory, Oak Ridge, Tennessee* (DOE/OR/01-1501&D1) was prepared in accordance with requirements under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980. This work was performed under Work Breakdown Structure 1.6.6.2.10.2, "Oak Ridge National Laboratory Isotopes Facilities," and Activity Data Sheet Number 6504IS, "Oak Ridge National Laboratory Isotopes Facilities Shutdown Program." Publication of this document provides the Environmental Restoration Program with information necessary to evaluate whether hazardous and/or radiological contaminants in and around the Isotopes Facilities pose a substantial risk to human health or the environment and if remedial site evaluations or removal actions are required.




CONTENTS

PREFACE	iii
FIGURES	vii
ABBREVIATIONS	ix
EXECUTIVE SUMMARY	xi
1. INTRODUCTION	1-1
2. SUMMARY OF REMOVAL SITE EVALUATIONS	2-1
2.1 BUILDING 3026-C—KRYPTON-85 ENRICHMENT FACILITY	2-1
2.2 BUILDING 3026-D—SEGMENTING HOT CELL FACILITY	2-1
2.3 BUILDING 3028—ALPHA POWDER FACILITY	2-2
2.4 BUILDING 3029— SOURCE DEVELOPMENT LABORATORY	2-2
2.5 BUILDINGS 3030, 3031, AND 3118—ISOTOPES PRODUCTION LABS C, D, AND H	2-3
2.6 BUILDING 3032/(3099)—RADIOISOTOPES PRODUCTION LABORATORY E	2-3
2.7 BUILDING 3033/(3093)— KRYPTON AND TRITIUM FACILITY	2-3
2.8 BUILDING 3033-A—ACTINIDE FABRICATION FACILITY	2-4
2.9 BUILDING 3034—RADIOISOTOPE AREA SERVICES BUILDING	2-4
2.10 BUILDING 3038 (AHF, E, M)—ISOTOPE DEVELOPMENT LABORATORY ..	2-5
2.11 BUILDING 3047—RADIOISOTOPE DEVELOPMENT LABORATORY ..	2-5
2.12 BUILDING 3517—FISSION PRODUCTS DEVELOPMENT LABORATORY ..	2-5
2.13 BUILDING 7025—TRITIUM TARGET FACILITY	2-6
3. BUILDING 3026-C—KRYPTON-85 ENRICHMENT FACILITY	3-1
4. BUILDING 3026-D—SEGMENTING HOT CELL FACILITY	4-1
5. BUILDING 3028—ALPHA POWDER FACILITY	5-1
6. BUILDING 3029— SOURCE DEVELOPMENT LABORATORY	6-1
7. BUILDINGS 3030, 3031, AND 3118—ISOTOPES PRODUCTION LABS C, D, AND H	7-1
8. BUILDING 3032/(3099)—RADIOISOTOPES PRODUCTION LABORATORY E ..	8-1
9. BUILDING 3033/(3093)— KRYPTON AND TRITIUM FACILITY	9-1
10. BUILDING 3033-A—ACTINIDE FABRICATION FACILITY	10-1
11. BUILDING 3034—RADIOISOTOPE AREA SERVICES BUILDING	11-1

12. BUILDING 3038 (AHF, E, M)—ISOTOPE DEVELOPMENT LABORATORY	12-1
13. BUILDING 3047—RADIOISOTOPE DEVELOPMENT LABORATORY	13-1
14. BUILDING 3517—FISSION PRODUCTS DEVELOPMENT LABORATORY	14-1
15. BUILDING 7025—TRITIUM TARGET FACILITY	15-1

FIGURES

1. Diagram of the first floor of Building 3026-C	3-12
2. Diagram of the first floor of Building 3026-D (perimeter is in bold)	4-12
3. Diagram of the second floor of Building 3026-D (perimeter is in bold)	4-13
4. Diagram of the third floor of Building 3026-D (perimeter is in bold)	4-14
5. Diagram of Building 3028	5-11
6. Diagram of Building 3029	6-10
7. Diagram of Building 3030	7-10
8. Diagram of Building 3031	7-11
9. Diagram of Building 3032/(3099)	8-10
10. Diagram of Building 3033/3093	9-10
11. Diagram of Building 3033-A	10-10
12. Diagram of Building 3034	11-10
13. Diagram of Building 3038-AHF	12-11
14. Diagram of Building 3038-W	12-12
15. Diagram of Building 3038-M	12-13
16. Diagram of Building 3038-E	12-14
17. Diagram of Building 3047	13-11
18. Diagram of Building 3517	14-11
19. Diagram of Building 7025	15-9



ABBREVIATIONS

ACM	asbestos containing material
<i>CFR</i>	<i>Code of Federal Regulations</i>
D&D	Decontamination and Decommissioning
FPDL	Fission Products Development Laboratory
HAZMAT	hazardous material
HEPA	high-efficiency particulate air (filter)
HSRD	Health Sciences Research Division
IFDP	Isotopes Facilities Deactivation Project
KEF	Krypton-85 Enrichment Facility
LBP	lead-based paint
LLLW	liquid low-level (radioactive) waste
LMES	Lockheed Martin Energy Systems, Inc.
ORNL	Oak Ridge National Laboratory
PCB	polychlorinated biphenyl
RAD	radiologic
RCRA	Resource Conservation and Recovery Act
RDL	Radioisotope Development Laboratory
RmSE	removal site evaluation
RSE	remedial site evaluation
S&M	surveillance and maintenance
TCLP	Toxicity Characteristic Leaching Procedure
WAG	waste area grouping
WOC	White Oak Creek



EXECUTIVE SUMMARY

This removal site evaluation report for the Isotope Facilities at Oak Ridge National Laboratory was prepared to provide the Environmental Restoration Program with information necessary to evaluate whether hazardous and/or radiological contaminants in and around the Isotopes Facilities pose a substantial risk to human health or the environment (i.e., a high probability of adverse effects) and if remedial site evaluations or removal actions are, therefore, required. The scope of the project included (1) a review of historical evidence regarding operations and use of the facility; (2) interviews with facility personnel concerning current and past operating practices; (3) a site inspection; and (4) identification of hazard areas requiring maintenance, removal, or remedial actions.

The results of the removal site evaluation indicate that no substantial risks exist from contaminants present in the Isotope Facilities because adequate controls and practices exist to protect human health and the environment. There are, however, several maintenance actions being undertaken or proposed:

- Building 3026-C—The crawl space at the southwest corner of the facility is posted as a radiological hazard area. Openings in the foundations could allow wind or small animals to carry contamination away from the area. Repairs are scheduled for completion by the end of July 1996.
- Buildings 3026-C and D—Paint from exterior walls and cell ventilation duct work is peeling off and has fallen to the ground. The paint is assumed to be lead based, and this poses a potential direct impact to the soil below and an indirect impact to surface water. A maintenance action will be necessary to prevent further deterioration and dislodging of the paint. Also, a remedial site evaluation should be conducted to determine whether lead from fallen paint chips has impacted the soil.
- Building 3026-D—Zinc-bromide leaking from viewing windows is being recycled back into the windows. The windows should be repaired and the leaks stopped.
- Building 3034—Paint from exterior piping is peeling off and has fallen to the ground. The paint is assumed to be lead based, and this poses a potential direct impact to the soil below and an indirect impact to surface water. A maintenance action will be necessary to prevent further deterioration and dislodging of the paint. Also, a remedial site evaluation should be conducted to determine whether lead from fallen paint chips has impacted the soil.
- Building 3047—An emergency diesel generator outside the facility may generate small quantities of fuel during repairs. Maintenance personnel have been reminded of the precautions that need to be taken to prevent spills during repairs.
- Building 7025—An underground collection tank outside the facility was reportedly the discharge point for the hot sink located in the tritium hood within the building. Reportedly, the hood did not generate liquid waste, and the contents of the tank have been removed. While no evidence of a leak exists, an internal tank inspection will be conducted by September 30, 1996.

The recommended corrective actions from the removal site evaluation are being conducted as maintenance actions; accordingly, this removal site evaluation is considered complete and terminated.

1. INTRODUCTION

This removal site evaluation (RmSE) report for the Isotope Facilities at Oak Ridge National Laboratory (ORNL) was prepared to provide the Environmental Restoration Program with information necessary to evaluate whether hazardous and/or radiological contaminants in and around the Isotopes Facilities pose a substantial risk to human health or the environment (i.e., a high probability of adverse effects) and if remedial site evaluations (RSEs) or removal actions are, therefore, required. The scope of the project included (1) a review of historical evidence regarding operations and use of the facility; (2) interviews with facility personnel concerning current and past operating practices; (3) a site inspection; and (4) identification of hazard areas requiring maintenance, removal, or remedial actions.

The results of the RmSE indicate that no substantial risks exist from contaminants present in the Isotope Facilities because adequate controls and practices exist to protect human health and the environment. The recommended corrections from the RmSE (see Buildings 3026-C and D, 3034, 3047, and 7025) are being conducted as maintenance actions; accordingly, this RmSE is considered complete and terminated.

2. SUMMARY OF REMOVAL SITE EVALUATIONS

2.1 BUILDING 3026-C—KRYPTON-85 ENRICHMENT FACILITY

Building 3026-C is currently in an inactive, standby mode awaiting entry into the Decontamination and Decommissioning (D&D) Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct various surveillance and maintenance (S&M) and deactivation activities; otherwise, the building remains secured from public access.

There were no imminent hazard areas requiring removal actions identified inside Building 3026-C during this RmSE. Radiologic (RAD) hazard areas, asbestos containing materials (ACMs), and items containing polychlorinated biphenyl (PCBs) are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3026-C are considered adequate until D&D activities begin.

There were, however, two external imminent hazard areas identified to be associated with Building 3026-C. One involved the crawl space area located at the southwest corner of the facility. The area is posted as a RAD hazard area due to contaminated soil. Openings in the foundation surrounding the crawl space were observed during the site inspection. Soil in the crawl space appeared dry, with a loose surface layer. As a result, strong air movement through this area due to winds could potentially disturb the loose soil and carry contaminated particles away from the crawl space. This poses an exposure potential to personnel who might be in the immediate area during a wind episode. Additionally, these foundation openings allow access to small animals, which could become contaminated and leave the crawl space carrying contamination away from the area. Regarding the recommended maintenance action to control air movement and access in this area, a request for repair of the opening to the crawl space under Building 3026-C was prepared and is scheduled for completion by the end of July 1996.

The other imminent hazard area involves deteriorating painted, wooden exterior walls and cell ventilation duct work surfaces adjacent to the north side of the building. The paint in this building has been assumed to contain lead by the ORNL Lead Management Program based on the age of the facility. Paint in the areas mentioned is peeling off, posing a potential direct impact to the soil below and an indirect impact to surface water as a result of runoff with storm water. The paint on the building has been sampled, and the analysis is expected by the end of June 1996. If the paint contains lead, a maintenance action will be necessary to prevent further deterioration and dislodging of this paint. In addition, an RSE should be conducted to determine whether lead from fallen paint chips has impacted the soil in the immediate area. (See the Building 3026-C RmSE information form for additional information concerning these areas.)

2.2 BUILDING 3026-D—SEGMENTING HOT CELL FACILITY

Building 3026-D is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to

conduct various S&M and deactivation activities; otherwise, the building remains secured from public access.

There were no imminent hazard areas requiring removal actions identified inside Building 3026-D during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3026-D are considered adequate until D&D activities begin.

There was, however, one external imminent hazard area identified to be associated with Building 3026-D. This is an area involving deteriorating painted, wooden exterior walls and cell ventilation duct work surfaces adjacent to the north side of the building. The paint in this building has been assumed to contain lead by the ORNL Lead Management Program based on the age of the facility. Paint in the areas mentioned is peeling off, posing a potential direct impact to the soil below and an indirect impact to surface water as a result of runoff with storm water. The paint on the building has been sampled, and the analysis is expected by the end of June 1996. If the paint contains lead, a maintenance action will be necessary to prevent further deterioration and dislodging of this paint. In addition, an RSE should be conducted to determine whether lead from fallen paint chips has impacted the soil in the immediate area.

It should also be noted that zinc-bromide is leaking from some of the viewing windows in the east cell bank. These leaks are currently controlled by collecting leaking fluid in a drum and pumping it back into the window. While this provides a temporary means of control and does not present an immediate threat, it is recommended that either the leaking windows be repaired and the leaks stopped or that the fluid be drained and disposed of if it is no longer needed. This will reduce or eliminate the potential for an inadvertent hazardous material (HAZMAT) release within the facility. (See Building 3026-D RmSE information form for additional information concerning these areas.)

2.3 BUILDING 3028—ALPHA POWDER FACILITY

Building 3028 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct various S&M and deactivation activities; otherwise, the building remains secured from public access.

There were no imminent hazard areas requiring removal actions identified to be associated with Building 3028 during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3028 are considered adequate until D&D activities begin.

2.4 BUILDING 3029—SOURCE DEVELOPMENT LABORATORY

Building 3029 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is occupied by personnel who are responsible for conducting

various S&M and deactivation activities. There were no imminent hazard areas requiring removal actions identified to be associated with Building 3029 during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3029 are considered adequate until D&D activities begin.

2.5 BUILDINGS 3030, 3031, AND 3118—ISOTOPES PRODUCTION LABS C, D, AND H

Buildings 3030, 3031, and 3118 are currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in these buildings other than surveillance, maintenance, and deactivation activities. The buildings are accessed periodically by personnel to conduct S&M and deactivation activities; otherwise, the buildings remain secured from public access.

There were no imminent hazard areas requiring removal actions identified to be associated with Buildings 3030, 3031, or 3118 during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within these facilities. In addition, a combination of engineering and administrative controls are in place and are enforced within these facilities for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Buildings 3030, 3031, and 3118 are considered adequate until D&D activities begin.

2.6 BUILDING 3032/(3099)—RADIOISOTOPES PRODUCTION LABORATORY E

Building 3032 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct S&M and deactivation activities; otherwise, the building remains secured from public access. Building 3099 is actually a concrete pad adjacent to the west side of Building 3032 which is used for temporary storage of many different items, from equipment to containerized radioactive materials and wastes.

There were no imminent hazard areas requiring removal actions identified to be associated with Building 3032 or the adjacent concrete storage pad (3099) during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3032 are considered adequate until D&D activities begin.

2.7 BUILDING 3033/(3093)—KRYPTON AND TRITIUM FACILITY

Building 3033 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct S&M and deactivation activities; otherwise, the building remains secured from public access. Building 3093

is a small permanent krypton storage enclosure adjacent to the northwest corner of Building 3033 which houses three empty krypton storage tanks.

There were no imminent hazard areas requiring removal actions identified to be associated Building 3033 or the adjacent concrete storage enclosure (3093) during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3033 are considered adequate until D&D activities begin.

2.8 BUILDING 3033-A—ACTINIDE FABRICATION FACILITY

Building 3033-A is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct S&M and deactivation activities; otherwise, the building remains secured from public access.

There were no imminent hazard areas requiring removal actions identified to be associated Building 3033-A during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3033-A are considered adequate until D&D activities begin.

2.9 BUILDING 3034—RADIOISOTOPE AREA SERVICES BUILDING

Building 3034 is currently in an inactive, standby mode awaiting entry into the D&D Program. Building 3034 was reportedly never used for operations involving radioisotopes, although some isolated low-level areas of residual surface contamination exist. The building is being prepared for use as office space in addition to continuing to house the electrical distribution station for the Isotopes Circle area until its entry into the D&D Program. There were no imminent hazard areas requiring removal actions identified within Building 3034 during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3034 are considered adequate until D&D activities begin.

There was, however, one notable, exterior, imminent hazard area identified to be associated with Building 3034. This is an area involving deteriorating, painted exterior piping adjacent to the east side of the building. The paint in this and surrounding buildings has been assumed to contain lead by the ORNL Lead Management Program based on the age of the facilities. Paint on the piping is peeling off and has fallen to the ground below. This poses a potential direct impact to the soil below and an indirect impact to surface water as a result of runoff with storm water. The paint on this piping should be sampled and analyzed for lead content to determine if, in fact, a hazard exists. If so, a maintenance action will be necessary to prevent further deterioration and dislodging of this paint. In addition, an RSE should be conducted to determine whether lead from fallen paint chips has impacted

the soil in the immediate area. (See the Building 3034 RmSE information form for additional information concerning this area.)

2.10 BUILDING 3038 (AHF, E, M)—ISOTOPE DEVELOPMENT LABORATORY

Building 3038 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is occupied by personnel who are responsible for conducting various S&M and deactivation activities.

There were no imminent hazard areas requiring removal actions identified to be associated with Building 3038 during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering/administrative controls are in place/enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3038 are considered adequate until D&D activities begin.

2.11 BUILDING 3047—RADIOISOTOPE DEVELOPMENT LABORATORY

Building 3047 is currently in an inactive, standby mode. All isotopes activities within Building 3047 are shut down with the exception of waste removal and transloading of radioactive material in the beta/gamma hot cells. However, a large number of different work items are currently performed within this facility. Although portions of the building are being deactivated, Building 3047 has been removed from the Isotopes Facilities Deactivation Program (IFDP), and its future use was uncertain at the time of the RmSE. The building is occupied by personnel who are responsible for conducting S&M, deactivation, and various other activities.

There were no imminent hazard areas requiring removal actions identified within Building 3047 during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3047 are considered adequate.

There was, however, one notable, exterior, imminent hazard area identified to be associated with Building 3047. This is an area involving the emergency diesel generator adjacent to the north side of the facility. A follow-up inspection of the diesel generator was conducted, and no leak was found. During routine maintenance, small quantities of fuel may be generated. Maintenance personnel have been reminded of precautions that need to be taken to prevent spills of fuel while performing repairs to the generator. No other actions are planned. (See the Building 3047 RmSE information form for additional information concerning this area.)

2.12 BUILDING 3517—FISSION PRODUCTS DEVELOPMENT LABORATORY

Building 3517 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and

deactivation activities. The building is occupied by personnel who are responsible for conducting various S&M and deactivation activities.

There were no imminent hazard areas requiring removal actions identified to be associated with Building 3517 during this RmSE. RAD hazard areas, ACMs, and items containing PCBs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 3517 are considered adequate until D&D activities begin.


2.13 BUILDING 7025—TRITIUM TARGET FACILITY

Building 7025 is currently in an inactive, standby mode awaiting entry into the D&D Program. There are no current, on-going operations in this building other than surveillance, maintenance, and deactivation activities. The building is accessed periodically by personnel to conduct S&M and deactivation activities; otherwise, the building remains secured from public access.

There were no imminent hazard areas requiring removal actions identified to be associated with Building 7025 during this RmSE. RAD hazard areas and ACMs are marked and isolated as necessary to ensure worker safety and inadvertent release within the facility. In addition, a combination of engineering and administrative controls are in place and are enforced within the facility for worker and environmental protection. Current actions being taken to prevent further release of contamination and ensure worker safety within Building 7025 are considered adequate until D&D activities begin.

It should be noted, however, that an underground collection tank exists adjacent to the east side of the facility. This tank was reportedly the discharge point for the hot sink located in the tritium hood within the facility. It was also reported that the processes in this hood did not generate liquid waste; therefore, the sink was only used by personnel for washing and decontamination. The contents have reportedly been removed, and the tank currently sits empty. No evidence was identified during this RmSE to indicate whether or not the tank has leaked. An internal tank inspection will be conducted by September 30, 1996. Based upon this inspection, additional actions may be merited. (See the Building 7025 RmSE information form for additional information concerning this area.)

3. BUILDING 3026-C—KRYPTON-85 ENRICHMENT FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3026-C Krypton-85 Enrichment Facility (KEF)
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i> R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES	
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 45	
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Historical operations included development of methods for isolating fission products and radioisotope processing for research and medical purposes. Waste from processing irradiated reactor fuel elements for uranium and plutonium recovery in Building 3019 was piped directly to Building 3026-C where it was processed to isolate short-lived isotopes. Radiologic elements processed in Building 3026-C included ^{129}I, ^{131}I, ^{79}Se, ^{107}Pd, ^{147}Pm, ^{137}Cs, ^{90}Sr, ^{60}Co, ^3H, ^{85}Kr, ^{188}W, and ^{191}Os. Radioisotope processing and handling was performed primarily in contained hot cells and lab hoods. Resulting primary waste streams from these processes included exhausted air and liquid process waste.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3026-C was originally constructed in 1943. This facility is a two-story, wooden frame building. Portions of the exterior of the building are sided with metal. Paint on metal exterior surfaces is in good condition. Paint on exposed wooden exterior surfaces is deteriorating and in poor condition (particularly on the north wall). Paint on exhaust duct work located adjacent to the north wall of the building is deteriorating in localized areas. Building 3026-C is physically connected to Building 3026-D, which is to the east. The two buildings share utilities (electric, steam, plant air). Building 3026-C is located in an industrial area of ORNL, adjacent to Isotope Circle. The immediate area surrounding the facility is paved for the most part with some grassy areas, particularly on the north side of the building. The building contains office space, laboratories, hot cells, and process areas. There are two hot cell banks consisting of 4 cells each, located in the central portion of the building. The viewing windows of the hot cells were filled with zinc-bromide. The fluid from all but one window has been drained and removed from the facility. Floor drains in the cells discharge to the low-level liquid waste (LLLW) system (tanks W-17 and W-18). The cells are currently shutdown. Work with radioactive materials was performed in the hot cells, laboratories, counting room, and tritium facility. Some interior portions of the building are restricted access areas due to radiologic contamination. Generally, the interior of the building is in fair to good condition. Asbestos Containing Material (ACM), radiation (RAD) hazard areas, and polychlorinated bi-phenol (PCB) containing equipment are posted and/or labeled as appropriate. The hot cells are kept under negative pressure relative to the interior of the building. The building itself is not sealed. A building space diagram is attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<i>Description of release, or threatened release, and source:</i>
<p>Low levels of residual fixed and transferable radiologic surface contamination exist in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state.</p>
<p>Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.</p>
<i>Hazardous substances present:</i>
<p>Hazardous substances remaining in Building 3026-C consist mainly of residual RAD surface contamination (α, β, γ), zinc-bromide, PCBs, and a small quantity of miscellaneous HAZMATs. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells and process equipment. Zinc-bromide remains present in one hot cell viewing window. PCBs are present in electrical capacitors within the building. Hazardous materials present in the building are listed on the attached HAZMAT inventory sheet.</p>
<i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i>
<p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p>
<ul style="list-style-type: none">< 1 μCi α contamination in facility - not identified by individual isotope.< 10 μCi fission products - including ^{137}Cs, ^{85}Kr and ^{60}Co.< 100 μCi ^3H (tritium).\approx 50 gallons zinc-bromide (estimated based on size of viewing window).\approx 1.25 gallons PCBs.\approx 320 pounds total miscellaneous HAZMATs (see attached HAZMAT inventory sheet).
<p>(Quantity estimates obtained from Building 3026-C Hazard Screening Report, ORNL PCB Large High- and Low-Voltage and Small Capacitor Inventory database, ORNL Hazardous Material Information System database.)</p>

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Paint on exterior wood surfaces (particularly the north side of the building) and exterior cell ventilation duct work is chipped and flaking off to the ground below in some areas. According to the ORNL Lead Management Office, no verification samples of this paint have been taken and analyzed; therefore, the area remains assumed to contain lead.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3026-C is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3026-C. It is likely that liquid waste from activities involving radioisotopes in Building 3026-C have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Although it is not impossible, it is unlikely that groundwater has been, or will be, impacted by the flaking and chipping exterior paint located on the north side of the building if, in fact, it is lead-containing. Because of the depth to the water table in the area of Building 3026-C (\approx 20 feet) and physical characteristics of soil in the area, it is doubtful that any significant amount of lead has, or will, reach the groundwater through percolation with storm water and vertical migration.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Stormwater (from surface runoff and stormwater drainage system) and treated water from the process waste system discharges into WOC. The only potential for direct impact to surface water from Building 3026-C in its current state would be from lead-containing paint chips which fall off the first and second story exterior painted surfaces and find their way into the stormwater drainage system and eventually to WOC. The apron around the north side of the building is gravel and grass below the areas of deteriorating paint. Peeling paint from the second story of the building in this area could fall off onto the first story roof and could get washed off the roof through the roof drains with stormwater. The roof drain in this area spills to the surface of the north-central portion of the building apron. This area of the apron is a restricted area and was not accessible during the building inspection. No storm drains were observed in this area from a distance; however, if a storm drain exists, there is a potential that paint chips could migrate to WOC through the stormwater drainage system.

Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with stormwater drainage piping. Contamination from leaking waste lines could potentially enter deteriorated stormwater piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Other than the potential for historical impact, the only existing immediate threat to surface water identified during this RmSE is that from the assumed lead-containing paint at the north of the building.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3026-C indicates a slight potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air flow in the building is controlled by the design of the ventilation system which moves air from areas with a low potential for contamination through areas with a higher potential for contamination and exhausts the air through the Isotopes Circle cell ventilation system to stack 3039. Apart from catastrophic failure of the hot cells or cell ventilation system, it is unlikely that radioactive air emissions from Building 3026-C would impact personnel or the environment in its current state. An additional potential for air quality impact outside the building exists as a result of air movement through the crawlspace below the building (see discussion in Soil section of this report).

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

The only existing immediate threat to soils identified in the area of Building 3026-C is located adjacent to the north side of the facility. Paint on the exterior of the north wall is badly deteriorated and is peeling off the building. Paint on the cell ventilation system duct work in this area also shows evidence of localized deterioration. This paint is assumed to contain lead by the ORNL Lead Management Office. The soil in this area is at risk of being impacted by lead contamination from paint that has peeled or chipped off the wall or duct work if, in fact, the paint does contain lead.

There is also evidence that soil beneath the building has been historically impacted by radiologic contamination. Postings at the entry points to the building's crawlspace indicate radioactive soil contamination in the crawlspace. Access to the crawlspace is restricted; however, it is not controlled. Access doors to the crawlspace were found to be open leaving the area easily accessible should the RAD warning sign be removed somehow (by strong wind, for example). In addition, soil in the crawlspace was observed to be very dry with a loose surface. Openings in the building's foundation can allow wind to enter the crawlspace stirring up potentially contaminated dust which can subsequently exit the crawlspace through these openings. This would pose a pathway for migration of radiologic contamination as well as a potential airborne contamination hazard to those in the immediate area during a wind episode. These openings could also allow small animals to enter the crawlspace and become contaminated internally and externally from dust. Contamination could then migrate from the crawlspace in the animals coat, fecal matter, urine, and decaying body upon death.

As stated for groundwater, there is also a potential for historical impact to soils in the area of Building 3026-C due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in Building 3026-C. Whether waste from Building 3026-C has actually contributed to this contamination is unknown, given the information reviewed during this RmSE. It is unlikely that the small quantities of chemicals used in Building 3026-C have significantly impacted soil in the surrounding area.

Release Beyond Facility or Reservation Boundaries

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).

The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:

- Contaminated dust in the building crawlspace becomes airborne and carried away due to wind blowing through openings in the foundation.
- An animal enters the crawlspace, becomes contaminated, and leaves carrying the contamination away.
- A person becomes inadvertently contaminated and leaves the facility/reservation undetected.
- Catastrophic failure of hot cells and/or contaminated equipment.

There is also a potential for assumed lead-containing paint which peels off the north side of the building to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.

Worker Safety
<p><i>Could the release pose a threat to workers? If yes, please describe.</i></p> <p>Radio logically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.</p>
Environmental Receptors
<p><i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i></p> <p>The following are the potential environmental receptors of contamination resulting from any potential releases discussed in this form:</p> <ul style="list-style-type: none">• Animals — Vermin which find their way into the contaminated crawlspace. <p>The potential for impact to this receptor is considered slight.</p> <p>No other existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently associated with Building 3026-C.</p>
Mitigation
<p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none">• Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building.• Openings in the foundation surrounding the crawlspace should be boarded up and sealed to prevent vermin access and minimize air movement through the space.• Exterior paint on the north wall of the facility and on cell ventilation system duct work in the area should be tested for lead content. If the paint is found to be lead-containing, a maintenance action will be required to eliminate areas of deteriorating paint. In addition, a remedial site evaluation will be necessary to determine whether the soil in this area has been impacted by lead from the peeling paint.• Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the D&D Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3026-C.

With the exception of the crawlspace and deteriorating areas of exterior paint, current actions being taken to prevent further release and ensure worker safety in Building 3026-C are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

Access to the contaminated crawlspace should be controlled. The area is presently marked with RAD warning signs at each access. While this should prevent human access, wind and vermin can still enter the area, potentially stirring up contaminated dust. All openings in the foundation surrounding the crawlspace should be sealed to prevent air movement and vermin access.

Samples should be taken of the exterior paint located on the north wall of the facility and adjacent cell ventilation duct work. The samples should then be analyzed to determine whether the paint does, in fact, contain lead. Such analysis should include TCLP (40 CFR 261, Appendix II) to determine whether Building 3026-C qualifies as a RCRA generator point. If the paint is found to contain lead, abatement actions will be required to prevent deteriorated areas of paint from dislodging and falling to the ground below, potentially having a direct impact on soil in this area.

No further potential hazards requiring maintenance actions were identified to be associated with Building 3026-C.

Removal Actions
<p><i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i></p> <p>No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3026-C.</p>
Remedial Site Evaluation
<p><i>Is a Remedial Site Evaluation needed?</i></p> <p>Pending confirmatory sampling and analysis results of the exterior paint in the north area of the facility, a Remedial Site Evaluation (RSE) should be conducted to determine whether the soil in this area has been impacted by lead from chipping paint and whether remediation of the soil is necessary.</p> <p>Areas of radiologic contamination associated with Building 3026-C have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.</p> <p>ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.</p> <p>Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.</p>
No Further Investigation
<p><i>Is a finding of No Further Investigation appropriate? Please explain.</i></p> <p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3026-C contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Building 3026-C:

- Phase I Safety Documentation, The Krypton-85 Enrichment Facility, Building 3026-C, Hazard Screening, Document No. HS/3026-C/F/RT-4 (Rev. 0).
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3026-C Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Building 3026-C.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3026-C:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant

Evaluator's Signature

6/18/96

Date

ORNL DWG 90-600






Fig. 1. Diagram of the first floor of Building 3026-C.



4. BUILDING 3026-D—SEGMENTING HOT CELL FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3026-D Segmenting Hot Cell Facility
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	<i>Years of Operation:</i> ≈ 40
<p><i>Description of Operation:</i></p> <p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Building 3026-D houses a high-level radioactivity storage facility and a Chemical Separation Laboratory in addition to the Segmenting Hot Cells Facility. Historically, the Chemical Separations Laboratory has served as a facility for the production of ^{32}P and ^{131}I; separation of numerous fission products; isolation of ^{99}T, ^{147}Pm, and ^{237}Np; and the isolation of ^{135}Xn for neutron cross-section determination. The Segmenting Hot Cells Facility was originally used to isolate large quantities of fission-produced ^{140}Ba for criticality testing purposes. The cells in the Segmenting Hot Cells Facility have been greatly modified since the ^{140}Ba process was discontinued. They now provide facilities for the segmenting, examination, and assembly of irradiated metallurgical specimens which remain in storage within the facility. Radioisotope processing and handling was performed primarily in contained hot cells. Resulting primary waste streams from these processes included exhausted air and liquid process waste.</p>	
<p><i>Physical description of area/facility:</i></p> <ul style="list-style-type: none"> • Building 3026-D was originally constructed in the late 1940s. • The facility is a three-story, wooden frame building. Portions of the exterior of the building are sided with metal. Paint on metal exterior surfaces is in good condition. Paint on exposed wooden exterior surfaces is deteriorating and in poor condition (particularly on the north wall). • Paint on exhaust duct work located adjacent to the north wall of the building is deteriorating in localized areas. • Building 3026-D is physically connected to Building 3026-C, which is to the west. The two buildings share utilities (electric, steam, plant air). • Building 3026-D is located in an industrial area of ORNL adjacent to Isotope Circle. The immediate area surrounding the facility is paved for the most part with some grassy areas, particularly on the north side of the building. • The building contains office space, changing rooms, process areas, hot cells, and associated equipment. The principle structure within the building is a two-story, 5-ft thick concrete cell block which is divided into two connecting radioactive material handling cells (hot cells) located in a north-south direction (Cell A and Cell B-1/2). The west face of the cell block is equipped with manipulators and zinc-bromide filled viewing windows. To the west of the cell block, located at floor level is the high-level radioactivity storage facility. This facility is connected to the south hot cell (Cell A) via a tunnel below the floor for material transfer purposes. Floor drains in the cells and hood hot sinks discharge to the low-level liquid waste (LLLW) system (Tank W-16). The cells are currently shut down. Work with radioactive materials was performed primarily in the hot cells. 	

Physical description of area/facility (Continued):

- Some interior portions of the building are restricted access areas due to radiologic contamination. Generally, the interior of the building is in poor to fair condition. Asbestos Containing Material (ACM), radiation (RAD) hazard areas, and polychlorinated bi-phenol (PCB) containing equipment are posted and/or labeled as appropriate.
- The hot cells are kept under negative pressure relative to the interior of the building. The building itself is not sealed.
- A building space diagram is attached to this form showing the locations of the various process areas and equipment.

Release Information*Description of release, or threatened release, and source:*

Information concerning the extent of radiological contamination in Building 3026-D was found to be limited in availability during this RmSE. Information provided in the Hazard Screening Report prepared for the facility is not as detailed as that of other buildings evaluated, but does indicate the presence of radiologic contamination. Based on past practices and process in this facility and comparison with the condition of other Isotopes facilities, it can be assumed with some certainty that residual radiologic surface contamination exists in hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination would have accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. Approximately 150 Ci (4,000 lbs) of ⁶⁰Co remains in the Storage Cell within the building. Storage of this material is considered a potential radiologic release source. The total existing levels of RAD contamination in the facility are unknown based on available information. However, the presence of this contamination is not considered a significant hazard in its current state.

Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. Additionally, zinc-bromide remains present in the cell viewing windows. This fluid is leaking from some windows of Cell A. The leaks are contained by collecting the leaking fluid in a drum or bucket and pumping it back into the window. While this does not stop the leak, it does provide interim control preventing the fluid from migration until either the windows are repaired or the fluid is removed. However, this presents a potential release source in that any fluid spilled or not captured in the collections drums could find its way to an active floor drain in the Operating Area adjacent to the east cell bank and migrate away from the building. The Operating Area was inaccessible during the facility inspection, and no drain location information was available for Building 3026-D at the time of this report; therefore, it is not known whether a floor drain is located in close proximity to the leaking windows. The potential for significant release of zinc-bromide is considered slight in this case. No other conditions were identified which present a potential for a significant HAZMAT release.

Hazardous substances present:

Hazardous substances remaining in Building 3026-D consist mainly of residual RAD surface contamination (α , β , γ), irradiated metal specimens, zinc-bromide, PCBs, and a small quantity of miscellaneous HAZMATs. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells, storage cell, and process equipment. Zinc-bromide remains present in the hot cell viewing windows. PCBs are present in cell lighting ballasts within the building. Hazardous materials present in the building are listed on the attached HAZMAT inventory sheet.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

- ≈ 150 Ci ^{60}Co .
- ≈ 2,000 gallons zinc-bromide.
- < 5 gallons PCBs. Quantity estimated based on visual inspection (information on exact quantity was not available at the time of this report.)
- ≈ 139 pounds total miscellaneous HAZMATs (see attached HAZMAT inventory sheet).

(Quantity estimates obtained from Building 3026-D Hazard Screening Report, Visual Inspection of PCB Containing Equipment, ORNL Hazardous Material Information System Database.)

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Paint on exterior wood surfaces (particularly the north side of the building) and exterior cell ventilation duct work is chipped and flaking off to the ground below in some areas. According to the ORNL Lead Management Office, no verification samples on this paint have been taken and analyzed; therefore, the area remains assumed to contain lead.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3026-D is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3026-D. It is likely that liquid waste from activities involving radioisotopes in Building 3026-D have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources (Continued).

Because of the reported small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Additionally, no information was available to determine drain locations within the facility. Cell and hot sink drains reportedly discharge to Tank W-16 of the LLLW system.

Although it is not impossible, it is unlikely that groundwater has been, or will be, impacted by the flaking and chipping exterior paint located on the north side of the building if, in fact, it is lead-containing. Because of the depth to the water table in the area of Building 3026-D (\approx 20 feet) and physical characteristics of soil in the area, it is doubtful that any significant amount of lead has, or will, reach the groundwater through percolation with storm water and vertical migration.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. The only potential for direct impact to surface water from Building 3026-D in its current state would be from lead-containing paint chips which fall off the first and second story exterior painted surfaces and find their way into the storm water drainage system and eventually to WOC. The apron around the north side of the building is gravel and grass below the areas of deteriorating paint. Peeling paint from the second story of the building in this area could fall off onto the first story roof and could get washed off the roof through the roof drains with storm water. The roof drain in this area spills to the surface of the north-central portion of the building apron. This area of the apron is a restricted area and was not accessible during the building inspection. No storm drains were observed in this area from a distance; however, if a storm drain exists, there is a potential that paint chips could migrate to WOC through the storm water drainage system.

Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Other than the potential for historical impact, the only existing immediate threat to surface water identified during this RmSE is that from the assumed lead-containing paint at the north of the building.

Air
<i>Are there any suspected impacts due to air emissions? If yes, please describe.</i>
<p>It can be reasonably assumed, based on information provided in the Hazard Screening Report prepared for Building 3026-D that a slight potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air flow in the building is controlled by the design of the ventilation system which moves air from areas with a low potential for contamination through areas with a higher potential for contamination and exhausts the air through the Isotopes Circle cell ventilation system to stack 3039. Apart from catastrophic failure of the hot cells or cell ventilation system, it is unlikely that radioactive air emissions from Building 3026-D would impact personnel or the environment in its current state.</p> <p>There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.</p>
Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
<p>The only existing immediate threat to soils identified in the area of Building 3026-D is located adjacent to the north side of the facility. Paint on the exterior of the north wall is badly deteriorated and is peeling off the building. Paint on the cell ventilation system duct work in this area also shows evidence of localized deterioration. This paint is assumed to contain lead by the ORNL Lead Management Office. The soil in this area is at risk of being impacted by lead contamination from paint that has peeled or chipped off the wall or duct work if, in fact, the paint does contain lead.</p> <p>As stated for groundwater, there is also a potential for historical impact to soils in the area of Building 3026-D due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in Building 3026-D. Whether waste from Building 3026-D has actually contributed to this contamination is unknown, given the information reviewed during this RmSE. It is unlikely that the small quantities of chemicals used in Building 3026-D have significantly impacted soil in the surrounding area.</p>
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
<p>The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:</p> <ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment.

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors). (Continued)

A potential also exists for assumed lead-containing paint which peels off the north side of the building to be carried away with surface runoff during a rain event. Additionally, a potential exists for zinc-bromide to migrate away from the facility if a floor drain is located in close proximity to leaking hot cell windows. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.

Worker Safety

Could the release pose a threat to workers? If yes, please describe.

Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.

Environmental Receptors

Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.

No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently associated with Building 3026-D.

Mitigation

What action(s) might be taken to abate/prevent release or impacts from release?

- Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building.
- Exterior paint on the north wall of the facility and on cell ventilation system duct work in the area should be tested for lead content. If the paint is found to be lead-containing, a maintenance action will be required to eliminate areas of deteriorating paint. In addition, a remedial site evaluation will be necessary to determine whether the soil in this area has been impacted by lead from the peeling paint.
- Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Zinc-bromide from leaking cell windows is collected and pumped back into the window. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3026-D.

With the exception of the deteriorating areas of exterior paint, current actions being taken to prevent further release and ensure worker safety in Building 3026-D are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

Samples should be taken of the exterior paint located on the north wall of the facility and adjacent cell ventilation duct work. The samples should then be analyzed to determine whether the paint does, in fact, contain lead. Such analysis should include TCLP (40 CFR 261, Appendix II) to determine whether Building 3026-D qualifies as a RCRA generator point. If the paint is found to contain lead, abatement actions will be required to prevent deteriorated areas of paint from dislodging and falling to the ground below, potentially having a direct impact on soil in this area.

Although the leaking zinc-bromide windows do not present an immediate threat, it is recommended that either the leaking windows be repaired and the leaks stopped or that the fluid be drained and disposed of, if it is no longer needed. This will reduce/eliminate the potential for an inadvertent HAZMAT release within the facility.

No further potential hazards requiring maintenance actions were identified to be associated with Building 3026-D.

Removal Actions
<p><i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i></p> <p>No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3026-D.</p>
Remedial Site Evaluation
<p><i>Is a Remedial Site Evaluation needed?</i></p> <p>Pending confirmatory sampling and analysis results of the exterior paint in the north area of the facility, a remedial site evaluation (RSE) should be conducted to determine whether the soil in this area has been impacted by lead from chipping paint and whether remediation of the soil is necessary.</p> <p>Areas of radiologic contamination associated with Building 3026-D have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.</p> <p>ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.</p> <p>Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.</p>
No Further Investigation
<p><i>Is a finding of No Further Investigation appropriate? Please explain.</i></p> <p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3026-D contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Building 3026-D:

- Hazard Screening, Segmenting Hot Cell Facility, Building 3026-D, Document No. HS/3026D/F/92/R0.
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3026-D Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3026-D:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant

Evaluator's Signature

6/18/96

Date




Fig. 2. Diagram of first floor of Building 3026-D (perimeter is in **bold**).




Fig. 3. Diagram of second floor of Building 3026-D (perimeter is in **bold**).




Fig. 4. Diagram of third floor of Building 3026-D (perimeter is in bold).

23b
Hazardous Materials Inventory System
MSR003C
13:54:05

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM

Management Inventory Summary Report (by Building)


Plant: 3 Division: Department: Control Area: Room: Area:
Item ID: LIST: Building: 3026D Mix Comp: HAZ Class: HAZ Rating:
Date Expiration: Inv Status: MSDS Avail: Haz Mat Grp Cd: Phy State: Pressure Cd: Temp Cd:
Building: 3026D

RECID	**	CASNO	Material Name
04624	--	007727-37-9	NITROGEN
89735	--	NISS	P-10 NUCLEAR COUNTER MIXTURE


Building 3026D Totals:

NMES			Total	Total	No of
	C	R	LBS	KILOGRAMS	Items
	-	-	-	-	-
	N	N	74.3244	33.7132	4
	N	N	64.4252	29.2228	4
			138.7496	62.9360	8

UNCLASSIFIED
Page: 1
Installation: ORNL



5. BUILDING 3028—ALPHA POWDER FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3028 Radioisotope Laboratory A (Alpha Powder Facility)
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
	<i>Years of Operation:</i> ≈ 38
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Building 3028 was originally constructed to separate ^{131}I, ^{133}Xe, and other short-lived fission products from uranium-aluminum targets. The building was later expanded to include curium processing cells. It has been used for storage, processing, conversion, and dispensing of radioactive isotopes. Building 3028 originally housed the ^{131}I processing facility (now the Short-Live Fission Product Operating Area) and the separation facility (a four-story ion-exchange column) for ^{147}Pm. The ^{131}I facility was converted to manipulator cells in the early 1960s and expanded to the Short-Lived Fission Product Facility. The ^{133}Xe facility was added at about the same time. Products and processes developed for sale included ^{133}Xe, ^{131}I, and ^{99}Mo. ^{133}Xe operations continued through 1980, and the Short-Lived Fission Product Program was discontinued in 1985. Radioisotope processing and handling was performed primarily in contained hot cells and lab hoods. Resulting primary waste streams for these processes included exhausted air and liquid process waste.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3028 was originally constructed in 1950. The facility is a steel frame structure with metal siding, consisting of a four-story central section with single-story operating areas on east and west end of building. Exterior surfaces of building have been covered with polyurethane foam sealant for containment purposes. During operations, the building was kept under negative pressure. Currently, building is inactive and only contaminated hot cells remain under negative pressure relative to the building interior. Exterior of building is generally clean and in good condition with no visible areas of significant damage or deterioration. Equipment has been removed from story 2, 3, and 4 and these areas are currently empty. The interior portions of the first three stories are in fair to good condition. The fourth story is in poor condition. Painted surfaces throughout the facility are cracking, flaking, and chipping in some locations (particularly the 4th floor). Asbestos Containing Material (ACM), and radiation (RAD) hazard areas are posted and/or labeled as appropriate. Access to the Alpha Powder Cell on the 1st floor is restricted due to contamination. Building 3028 is located in Isotopes Circle, an industrial area of ORNL. The immediate area surrounding the facility is paved. Building utilities include steam, plant air and electrical service. 	

Physical description of area/facility: (Continued)

- The building contains primarily laboratories, hot cells, and process areas. There are seven hot cells located on the first floor of the building. The viewing windows of the hot cells are filled with water or mineral oil. Floor drains in Cells 1-4 discharge to an intermediate holding tank (W11) before discharging to the low-level liquid waste (LLLW) system (Tank WC-10). Cells 5-6 drain directly to the LLLW system (Tank WC-10). Cell 7 contains one drain which discharges to Tank WC-2 and two drains which discharge to Tank WC-10 of the LLLW system.
- Cell 7 has been decontaminated and cleaned.
- Work with radioactive material was performed primarily in the hot cells, hoods, and laboratory areas within this facility.
- A building space diagram is attached to this form showing the locations of the various process areas and equipment.

Release Information***Description of release, or threatened release, and source:***

Low levels of residual fixed radiologic surface contamination exists in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state.

Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.

Hazardous substances present:

Bulk HAZMATs have been removed from Building 3028. Hazardous substances remaining consist mainly of residual radiologic surface contaminants (α , β , γ). Fixed radiologic contamination exists in localized areas throughout the facility. Some of these areas have been painted over to contain α contamination. Highest levels of radiologic contamination exist in hot cells 1-6 which are isolated and kept under negative pressure. Hot cell 7 has been decontaminated to allow personnel access.

No items containing PCBs were identified to present within this building.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

$\approx 10 \mu\text{Ci}$ α contamination in facility, $\approx 150 \text{ mCi}$ α in hot cells
 $\approx 25 \mu\text{Ci}$ β/γ contamination in facility, $\approx .45 \text{ Ci}$ β/γ in hot cells

(Quantity estimates obtained from Building 3028 Hazard Screening Report)

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition on the first three floors and poor condition on the fourth floor. These areas pose no immediate health threat given the status of this facility.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3028 is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening the groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3028. It is likely that liquid waste from activities involving radioisotopes in Building 3028 have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. The only potential for direct impact to surface water from Building 3028 in its current state would be from lead-containing paint chips which fall off the exterior painted surfaces and find their way into the storm water drainage system and eventually to WOC.

Based on the age of this facility, it is assumed that painted surfaces contain lead. The exterior paint of Building 3028 is in good condition and there was no visible evidence of significant deterioration observed during the site inspection. Therefore, the potential for impact to surface water due to assumed exterior lead-based paint is considered slight.

Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3028 indicates a slight potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Hot cells in the building are kept under negative pressure; however, the building is no longer operated under negative pressure. The Alpha Cells (Cell 1-4) exhaust through high efficiency particulate air (HEPA) filters to the process off-gas system and stack 3039. Cells 5-7 exhaust through HEPA filters to the cell ventilation system and stack 3039. Apart from catastrophic failure of the hot cells or cell ventilation system, it is unlikely that radioactive air emissions from Building 3028 would impact personnel or the environment in its current state.

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
<p>As stated for groundwater, there is also a potential for historical impact to soils in the area of Building 3028 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in Building 3028.</p> <p>The WAG 1 Site Characterization Report and interviews with facility personnel indicated that a LLLW drain line was found to be leaking adjacent to Building 3028 in the early 1980's. The leak contaminated the soil in the immediate area. The soil was reportedly remediated and the leak was repaired. As a result of this spill, it is likely that past activities in Building 3028 have contributed to the isotopes area soil contamination plume.</p> <p>It is unlikely, however, that the small quantities of chemicals used in Building 3028 have significantly impacted soil in the surrounding area.</p>
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
<p>The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:</p> <ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment. <p>There is also a potential for assumed lead-containing paint which peels off of the building to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.</p>
Worker Safety
<i>Could the release pose a threat to workers? If yes, please describe.</i>
<p>Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. Asbestos containing material is appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.</p>
Environmental Receptors
<i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i>
<p>No significant immediate threat to environmental receptors within the area surrounding Building 3028, including natural resources, was identified to exist as a result of contamination and conditions currently present in the facility.</p>

Mitigation
<p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none"> Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building. Continue S&M activities per Procedure IP-900.
<p><i>What actions are currently being taken to abate/prevent release or impacts from release?</i></p> <p>Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, and ACM hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3028.</p>
<p>Current actions being taken to prevent further release and ensure worker safety in Building 3028 are considered adequate until D&D activities begin.</p>
Other Environmental Authorities
<p><i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i></p> <p>If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).</p>
Maintenance Actions
<p><i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i></p> <p>No potential hazards requiring maintenance actions were identified to be associated with Building 3028.</p>
Removal Actions
<p><i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i></p> <p>No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3028.</p>

Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
<p>Areas of radiologic contamination associated with Building 3028 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.</p> <p>Asbestos containing material has also been identified, marked and documented. No further remedial investigation involving this hazard is considered necessary given the current status and future plans of this facility.</p> <p>Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.</p>
<i>No Further Investigation</i>
<p><i>Is a finding of No Further Investigation appropriate? Please explain.</i></p> <p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3028 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>
<i>Additional Comments</i>
<p>The following documents and databases were referenced for historical and hazard information related to Building 3028:</p> <ul style="list-style-type: none"> • Phase 1 Safety Documentation, Radioisotope Laboratory A, Building 3028 - Hazard Screening, Document No. HS/3028/F/RI-5 (Rev. 1) • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Building 3028 Occurrence Reports, 1989 to present. • Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1. • ORNL Hazardous Material Information System Database. • ORNL Drain System Survey Report for Building 3028. <p>The following personnel and offices were contacted and provided historical and current use/condition information for Building 3028:</p> <ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Mr. R.E. Eversole, Project Manager, Isotopes Facilities Deactivation Project, LMES. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.



The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Grant
Evaluator's Signature

6/18/96
Date

ORNL DWG 80-698



First Floor Building 3028

Fig. 5. Diagrams of Building 3028.



6. BUILDING 3029— SOURCE DEVELOPMENT LABORATORY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3029 The Source Development Laboratory
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 40	
<i>Description of Operation:</i>	
<p>There are no current operations on-going in this building, other than surveillance, maintenance, and decontamination activities required for facility stabilization. The Source Development Laboratory originally contained a system of remotely operated barricades and a small manipulator cell. Isotopes originally handled and processed in the facility were ^{192}Ir (source fabrication) and small ^{60}Co sources. Cell 1 was built to handle large quantities of ^{60}Co during the mid-1950s. Very little ^{60}Co source fabrication has been done since the late-1950s. Cell 3 was built and used for ^{137}Cs source fabrication in the early-1960s. Cell 2 was built and used for waste handling and pass-through between Cells 1 and 3. The main operations performed in this facility involved ^{60}Co, ^{137}Cs, ^{90}Sr, and ^{192}Ir source fabrication and ^{131}I processing. A ^{60}Co storage and irradiation facility, known as the ^{60}Co Garden, is located below the floor of the east wing. All inventory in the ^{60}Co Garden has reportedly been removed. Radioactive material was processed and handled primarily in the hot cells and glove boxes. Resulting primary waste streams included exhausted air and liquid process waste.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3029 was originally constructed in 1952. The facility is a single-story, metal frame building with metal siding consisting of approximately 3,000 sq. ft. of floor space. The exterior of the building is cocooned with polyurethane foam for containment. Building 3029 is located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facility is paved. Building utilities include electric, steam, and plant air. The building currently consists primarily of four hot cells and associated operating areas and process equipment. Work involving radioactive materials was performed primarily in the hot cells and glove boxes. The building and hot cells are kept under negative pressure for containment purposes. Building ventilation is local and exhausts through high efficiency particulate air (HEPA) filters on the roof. Cell ventilation exhausts through HEPA filters to the cell ventilation system and stack 3039. Building sinks and floor drains discharge to process waste system. Cell drains discharge to the low-level liquid waste (LLLW) system (Tank WC-10). Exterior of the building is in good condition with no visual evidence of significant damage or deterioration. Access to some of the interior portions (i.e., the East Wing) of the building was restricted during the facility inspection. The interior areas of the building that were accessible were observed to be in fair to good condition without any significant areas of damage or deterioration. A building space diagram is attached to this form showing the location of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>Low levels of residual fixed and transferable radiologic surface contamination exist in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells, ⁶⁰Co Garden, and related process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. Specific areas of contamination include the drain to Glove Box B which has leaked and contaminated the area beneath the box with α contamination. Attempts have been made to clean this area to acceptable levels without success. The area currently is sealed and isolated. Also, the access area behind Cells 2 and 3 in the East Wing of the building has been zoned as a radiation contamination area as the result of ¹³⁷Cs contamination which leaked from Cell 3. Clean up efforts to decontaminate this area were on-going at the time of this writing. The existing levels of RAD contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state according to the Building 3029 Hazard Screening Report.</p> <p>Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Building 3029 consist mainly of residual RAD surface contamination (α, β, γ), PCBs, and a small quantity of miscellaneous HAZMATs. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells, ⁶⁰Co Garden, and process equipment. PCBs are reportedly present in the form of fork lift hydraulic fluid within the building. The Hazard Screening Report for this facility indicates that small quantities of HAZMATs are currently used for S&M activities; however, an inventory list was not identified during this RmSE.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <p>0 μCi α contamination in facility (Hazard Screening Report indicates "no alpha contamination present"; however, IFDP Work Plan and facility personnel interviews indicate that the area under Glove Box B is alpha contaminated and sealed.)</p> <p>< 700 μCi β/γ as ⁹⁰Sr.</p> <p>\approx 2 Ci β/γ as ⁶⁰Co.</p> <p>PCB quantity not known (assumed to be less than 1 gallon).</p> <p>Quantity of miscellaneous HAZMATs unknown (assumed to be less than 5 gallons or 100 pounds).</p> <p>(Radioactive material quantity estimates obtained from Building 3026-C Hazard Screening Report, PCB and HAZMAT quantities assumed based on visual inspection and available information.)</p>

Other pollutants or contaminants:

Asbestos containing material (ACM), primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Exterior paint is also in good condition with no visible evidence of significant damage or deterioration.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3029 is located in Waste Area Grouping (WAG) 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility, as evidenced by Glove Box B. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3029. It is likely that liquid waste from activities involving radioisotopes in Building 3029 have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically and currently used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. The only potential for direct impact to surface water from Building 3029 in its current state would be from lead-containing paint chips which fall off the exterior painted surfaces and find their way into the storm water drainage system and eventually to WOC.

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources. (Continued)

Based on the age of this facility, it is assumed that painted surfaces contain lead. The exterior paint of Building 3029 is in good condition and there was no visible evidence of deterioration observed during the site inspection. Therefore, the potential for impact to surface water due to assumed exterior lead-based paint is considered slight.

Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

No existing immediate threats to surface water were identified to be associated with Building 3029 during this RmSE.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3029 indicates a slight potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air in the building is controlled by a local ventilation system which exhausts building air through high efficiency particulate air (HEPA) filters, keeping the building under slight negative pressure relative to atmosphere. Air in the hot cells is exhausted through the cell ventilation system to stack 3039, keeping the cells at a slight negative pressure relative to the interior of the building. Apart from catastrophic failure of the hot cells or ventilation systems, it is unlikely that radioactive air emissions from Building 3029 would impact personnel or the environment in its current state.

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

As stated for groundwater, there is also a potential for historical impact to soils in the area of Building 3029 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in Building 3029. Whether waste from Building 3029 has actually contributed to this contamination is unknown, given the information reviewed during this RmSE.

Since the area surrounding Building 3029 is paved, there is no potential for areas of soil adjacent to the facility to be impacted from lead if, in fact, exterior paint is found to be lead-containing. The exterior paint was observed to be good condition and does not pose an immediate threat in its current state.

It is unlikely that the small quantities of chemicals reportedly used in Building 3029 have significantly impacted soil in the surrounding area.

Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:
<ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment.
There is also a potential for assumed lead-containing paint which peels off of the building to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.
Worker Safety
<i>Could the release pose a threat to workers? If yes, please describe.</i>
Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.
Environmental Receptors
<i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i>
No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3029.
Mitigation
<i>What action(s) might be taken to abate/prevent release or impacts from release?</i>
<ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building. • Continue S&M activities per Procedure IP-900.
<i>What actions are currently being taken to abate/prevent release or impacts from release?</i>
Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination.

What actions are currently being taken to abate/prevent release or impacts from release? (Continued)

The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3029.

Current actions being taken to prevent further release and ensure worker safety in Building 3029 are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

No existing potential hazards requiring maintenance actions were identified to be associated with Building 3029.

Removal Actions

Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.

No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3029.

Remedial Site Evaluation

Is a Remedial Site Evaluation needed?

Areas of radiologic contamination associated with Building 3029 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.

ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.

Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.

No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3029 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.
Additional Comments
<p>The following documents and databases were referenced for historical and hazard information related to Building 3029:</p> <ul style="list-style-type: none"> • Phase I Safety Documentation, The Source Development Laboratory, Building 3029, Hazard Screening, Document No. HS/3029/F/RT-6 (Rev. 1). • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Building 3029 Occurrence Reports, 1989 to present. • Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1. • ORNL Hazardous Material Information System Database. • ORNL Drain System Survey Report for Building 3029. <p>The following personnel and offices were contacted and provided historical and current use/condition information for Building 3026-C:</p> <ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN


Todd R. Umant

Evaluator's Signature

6/18/96

Date


ORNL DWG 80-801



Building 3029

Fig. 6. Diagram of Building 3029.

**7. BUILDINGS 3030, 3031, AND 3118—ISOTOPES PRODUCTION
LABS C, D, AND H**



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3030/3031/3118 Radioisotopes Production Laboratories C, D, and H
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i> R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES	
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 40	
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in these buildings. Historical operations involving radioisotopes were performed in Buildings 3030 and 3031. Building 3118 was built in the early 1960s by enclosing the area between Buildings 3030 and 3031. Building 3118 was used primarily for temporary storage of radioactive sources and contaminated wastes and rear access to the hot cells in Building 3030 and 3031. Operations in Buildings 3030 and 3031 consisted of limited production and development work with radioisotopes used for industrial, medical, and research applications. Operations have included purifying, processing, dispensing, and storage of radioactive isotopes. The hot cell in Building 3030 has been used for processing isotopes such as ^{56}Co, ^{57}Co, ^{198}Au, ^{55}Fe, ^{24}Np, ^{75}Se, ^{90}Sr, $^{119\text{m}}\text{Sn}$, ^{237}U, ^{33}P, and ^{192}Ir. The hot cell in Building 3031 was utilized for the final separation of ^{153}Gd from europium targets. Radioisotope processing and handling was performed in contained hot cells, lab hoods, and glove boxes. Resulting primary waste streams included exhausted air and liquid process waste.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Buildings 3030 and 3031 were assumed to be constructed in the late 1940s, based on the documented construction date of surrounding buildings. Building 3118 was constructed in the early 1960s. The buildings are single-story, metal framed structures with metal siding. The exterior polyurethane cocooning process has only been partially completed on Building 3031; therefore, the buildings are not sealed. Buildings 3030, 3031, and 3118 are physically connected and share utilities (steam, electric, plant air). These buildings are located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facilities is paved for the most part with some grassy areas. Buildings 3030 and 3031 are single-room laboratories each consisting of a hot cell, a monitor, process hoods, and other laboratory equipment. Building 3118 is a single-room storage area consisting of rear access doors to each hot cell in Buildings 3030 and 3031. Floor drains in each building discharge to the process and low-level liquid waste (LLLW) (Tank WC10) systems. Cell, hood, and glove box hot drains discharge to the LLLW system (Tank WC10). The cells are currently shutdown. Work with radioactive materials was performed in the hot cells, hoods, and glove boxes. Generally, the interior of each building is in fair to good condition. Asbestos Containing Material (ACM), radiation (RAD) hazard areas, and polychlorinated bi-phenol (PCB) containing equipment are posted and/or labeled as appropriate. Buildings 3030 and 3031 are kept under slight negative pressure relative to atmosphere. Building space diagrams are attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>Very low levels of residual fixed radiologic surface contamination exist in areas of these facilities as a result of historical operations. The contamination exists primarily in the hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facilities and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facilities are very low and well isolated. The presence of this contamination is not considered a significant hazard in its current state.</p> <p>Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for these buildings. No current conditions were identified which present a potential for a significant HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Buildings 3030, 3031 and 3118 consist mainly of small amounts of residual fixed RAD surface contamination (α, β, γ), PCBs, and a small quantity of miscellaneous HAZMATs. Areas of fixed RAD contamination are associated primarily with the hot cells and process equipment. PCBs are present in electrical capacitors within the buildings. The Hazard Screening Report for these facilities indicates that small quantities of HAZMATs are currently used for S&M activities; however, an inventory list was not identified during this RmSE.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <ul style="list-style-type: none"> Quantities of β/γ and α contamination were reported as "residual contamination" and "traces (very low)", respectively, in the Hazard Screening Report for these facilities. \approx .5 gallons PCBs. <p>(Quantity estimates obtained from Building 3030, 3031, and 3118 Hazard Screening Report, and ORNL PCB Large High- and Low-Voltage and Small Capacitor Inventory database)</p>
<p><i>Other pollutants or contaminants:</i></p> <p>Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair-to-good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing.</p> <p>Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Paint on exterior surfaces was also found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration.</p>

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Buildings 3030, 3031, and 3118 are located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facilities. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including those common to the processes in Buildings 3030 and 3031. It is likely that liquid waste from activities involving radioisotopes in these buildings have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of these facilities.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. Surface water may have been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources. (Continued)

Additionally, if exterior painted surfaces do, in fact, contain lead, the potential exists for surface water to be impacted from deteriorated paint which washes off the buildings and finds its way to surface water with the storm water runoff.

Other than the potential for historical impact, no existing immediate threat to surface water was identified given the current status of these facilities.

Air
<i>Are there any suspected impacts due to air emissions? If yes, please describe.</i>
<p>The Hazard Screening Report prepared for Buildings 3030, 3031, and 3118 indicates a slight potential for radiation exposure to personnel working inside the facilities exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Because of the low levels and nature of RAD contamination within the facilities, impacts to persons or the environment surrounding the facilities are considered negligible. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facilities to protect against inadvertent exposure to personnel. Air in the buildings is controlled by a local exhaust system which exhausts laboratory hood air through high efficiency particulate air (HEPA) filters. Hot cells are exhausted through HEPA filters to the 3039 stack. Apart from catastrophic failure of the hot cells or ventilation system, it is unlikely that radioactive air emissions from these buildings would impact personnel or the environment.</p> <p>There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.</p>
Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
<p>As stated for groundwater, there is a potential for historical impact to soils in the area of Buildings 3030, 3031, and 3118 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in these building. An area of contaminated soil exists around the southwest corner of Building 3030. The area is well marked and covered with a protective barrier and river rock. Below-ground LLLW drains have been identified in this area. Information specific to this area was not identified during this RmSE; however, it is likely that this area of contamination is a result of leaks in the LLLW drain lines. As a result, it is also likely that operations in these facilities (at least Building 3030) have historically contributed to the Isotopes Circle soil contamination plume. This area of contamination is not considered an imminent hazard given the current status of the adjacent facility and the protective measures being taken to prevent contamination migration and personnel exposure.</p> <p>It is unlikely that the small quantities of chemicals used in these facilities have significantly impacted soil in the surrounding area.</p>
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
<p>The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:</p> <ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment. <p>There is also a potential for assumed lead-containing paint which peels off exterior surfaces of the buildings to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.</p>

<p style="text-align: center;">Worker Safety</p> <p><i>Could the release pose a threat to workers? If yes, please describe.</i></p> <p>Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facilities are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place in Buildings 3030 and 3031 to detect any radioactive release within the buildings. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of buildings.</p>
<p style="text-align: center;">Environmental Receptors</p> <p><i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i></p> <p>No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3030, 3031 or 3118.</p>
<p style="text-align: center;">Mitigation</p> <p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in these buildings. • Continue S&M activities per Procedure IP-900.
<p><i>What actions are currently being taken to abate/prevent release or impacts from release?</i></p> <p>Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facilities for worker and environmental protection. Warning signs and labels are posted throughout the facilities indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of each facility to detect the presence of radiologic contamination. The buildings are currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Buildings 3030, 3031, and 3118.</p> <p>Current actions being taken to prevent further release and ensure worker safety in Buildings 3030, 3031, and 3118 are considered adequate until D&D activities begin.</p>
<p style="text-align: center;">Other Environmental Authorities</p> <p><i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i></p> <p>If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).</p>

Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
No existing potential hazards requiring maintenance actions were identified to be associated with Buildings 3030, 3031, or 3118.
Removal Actions
<i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Buildings 3030, 3031, or 3118.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Buildings 3030, 3031, and 3118 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Buildings 3030, 3031, and 3118 contain substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Buildings 3030, 3031, and 3118:

- Phase I Safety Documentation, Radioisotope Production Laboratories C, D, and H, Buildings 3030, 3031, and 3118, Hazard Screening, Document No. Draft.
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3030, 3031, and 3118 Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Buildings 3030, 3031, and 3118.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3030, 3031, and 3118:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Armento
Evaluator's Signature

6/18/96
Date

Building 3030

ORNL DWG 80-587




Fig. 7. Diagram of Building 3030.

ORNL DWG 80-598

Building 3031





Fig. 8. Diagram of Building 3031.



**8. BUILDING 3032/(3099)—RADIOISOTOPES PRODUCTION
LABORATORY E**



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3032 (including Building 3099) Radioisotope Production Laboratory E
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
	<i>Years of Operation:</i> ≈ 40
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Information on historical operations identified for Building 3032 during this RmSE was not detailed. The building was originally built as part of the Isotopes Program, and it housed an analytical facility for radiochemical support of the isotopes production activities. Currently, all discrete items of radioactive material inventory have been removed. Radioisotope processing and handling was performed in lab hoods. Resulting primary waste streams included exhausted air and liquid process waste. Building 3099 is actually a concrete storage pad adjacent to the west side of Building 3032. This pad has been used for temporary storage of many different items including containerized radioactive materials and wastes.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3032 was originally constructed in the 1950s. The building is a single-story, metal framed structure with metal siding consisting of 1,200 sq. ft. of floor space. The building is not sealed by polyurethane cocooning. Paint observed on exterior surfaces is in good condition. Building 3032 is located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facilities is paved for the most part with some grassy areas. The building is basically a single-room laboratory consisting of a five process hoods and other laboratory equipment. Floor drains in the building reportedly discharge to the process waste system. Hood drains discharged to the low-level liquid waste (LLLW) system (Tank WC10). The Hazard Screening report for this building indicates that LLLW service is no longer available. Work with radioactive materials was performed in the process hoods. Generally, the interior of the building is in fair to good condition. Asbestos Containing Material (ACM) and radiation (RAD) hazard areas are posted and/or labeled as appropriate. No polychlorinated biphenols (PCBs) were identified to be associated with this building. Building 3032 is operated under normal atmospheric pressure. A building space diagram is attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>Small amounts of residual fixed radiologic surface contamination and a few isolated areas of transferable RAD contamination exist in areas of the facility as a result of historical operations. Accessible areas of RAD contamination have been decontaminated and are considered "clean", according to the Hazard Screening Report. Some small fixed and transferable hot spots remain in inaccessible areas, primarily in the process hoods and related equipment. This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are very low and well isolated. The presence of this contamination is not considered a significant hazard in its current state.</p> <p>It is assumed, based on the historical laboratory function of this building and operations in similar facilities, that hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations. Reportedly, no HAZMATs are currently used or stored in this facility. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Building 3032 consist mainly of small amounts of residual fixed and transferable RAD surface contamination (α, β, γ). Areas of fixed RAD contamination are associated primarily with the process hoods and associated equipment. No PCBs were identified to be present in within the building.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <p><400 μCi α <1,100 μCi β/γ</p> <p>(Quantity estimates obtained from Building 3032 Hazard Screening Report)</p>
<p><i>Other pollutants or contaminants:</i></p> <p>Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Paint on exterior surfaces was also found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration.</p>

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3032 is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples; however, because of the lack of specific information concerning radioisotope processes in Building 3032, it is not known whether any of these radionuclides were common to the processes in this building. It is likely, however, that liquid waste from activities involving radioisotopes in this building has historically contributed to WAG 1 groundwater contamination to some extent. However, the radionuclides detected in the groundwater were common to the processes and activities in many buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the assumed small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. Surface water may have been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are also groundwater discharge points; therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Additionally, if exterior painted surfaces do, in fact, contain lead, the potential exists for surface water to be impacted from deteriorated paint which washes off the building and finds its way to surface water with the storm water runoff.

Other than the potential for historical impact, no existing immediate threat to surface water was identified given the current status of this facility.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3032 indicates that there is no potential for significant radiation exposure to personnel working in or around this facility as a result of airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Radiologic contamination in the building is controlled by a local exhaust system which exhausts building and hood air through high efficiency particulate air (HEPA) filters. Because of the small amounts of RAD contamination present, it is highly unlikely that radioactive air emissions from this building would impact personnel or the environment.

There is, however, a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

As stated for groundwater, there is a potential for historical impact to soils in the area of Building 3032 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to many of the processes performed in the Isotopes Facilities. Even though specific radioisotopes processed in Building 3032 were not identified during this RmSE, it is likely that liquid waste from activities involving radioisotopes in this building has historically contributed to the Isotopes Circle contamination plume to some extent. However, the radionuclides detected in the soil were common to the processes and activities in many buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

It is unlikely that the assumed small quantities of chemicals used in Building 3032 have impacted soil in the surrounding area.

Release Beyond Facility or Reservation Boundaries

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).

Because of the small amount and inaccessibility of existing radiologic contamination in Building 3032, there is considered to be no potential for significant radiologic release beyond the facility or reservation boundaries.

There is, however, a potential for assumed lead-containing paint which peels off exterior surfaces of the building to be carried away with surface runoff during a rain event. Though this potential exists, it is considered slight and unlikely due to the current status and condition of the facility.

Worker Safety

Could the release pose a threat to workers? If yes, please describe.

Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facilities are required to "frisk" themselves to detect the presence of RAD contamination. ACM is appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked and workers are careless. This potential is not considered significant given the current status and level of activity of this building.

Environmental Receptors
<i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i>
No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3032.
Mitigation
<i>What action(s) might be taken to abate/prevent release or impacts from release?</i>
<ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in these buildings. • Continue S&M activities per Procedure IP-900.
<i>What actions are currently being taken to abate/prevent release or impacts from release?</i>
Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted as necessary indicating RAD and ACM hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3032.
Current actions being taken to prevent further release and ensure worker safety in Buildings 3032 are considered adequate until D&D activities begin.
Other Environmental Authorities
<i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i>
If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).
Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
No existing potential hazards requiring maintenance actions were identified to be associated with Building 3032.

Removal Actions
<i>Are Remedial Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3032.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Buildings 3032 are marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
ACM has also been identified, marked and documented. No further remedial investigation involving this hazards is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3032 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.
Additional Comments
The following documents and databases were referenced for historical and hazard information related to Building 3032:
<ul style="list-style-type: none"> • Phase I Safety Documentation, Radioisotope Production Laboratory E, Building 3032 Hazard Screening, Document No. HS/3032/F/RT-9 (Rev.0). • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Building 3032 Occurrence Reports, 1989 to present. • Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1. • ORNL Hazardous Material Information System Database. • ORNL Drain System Survey Report for Building 3032.
The following personnel and offices were contacted and provided historical and current use/condition information for Building 3032:
<ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant
Evaluator's Signature

6/18/96
Date





Fig. 9. Diagram of Building 3032/(3099).

9. BUILDING 3033/(3093)— KRYPTON AND TRITIUM FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3033 (Including 3093) The Krypton and Tritium Facility
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
	<i>Years of Operation:</i> ≈ 40
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Building 3033 was originally constructed to process ^{14}C, ^{85}Kr, and ^3H. It contains facilities that were historically utilized for storage, purification, processing, and dispensing of tritium (^3H) and krypton isotopes (mainly ^{85}Kr). Tritium operations involved the receipt of bulk tritium shipments followed by purification, loading of shipping containers, and shipment to numerous customers worldwide. Krypton operations included the purification of krypton in preparation for direct sale or as feed to the thermal diffusion columns in Building 3026-C. Radioisotope processing and handling was performed in contained enclosures and process hoods. Resulting primary waste streams included exhausted air. Reportedly, the processes in this building did not produce liquid process waste.</p> <p>Building 3093 is a permanent krypton storage enclosure located adjacent to Building 3033 to the northwest. For purposes of this report, reference to "the facility" or "the building" includes both Building 3033 and 3093, unless otherwise stated.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3033 and 3093 are assumed to have been constructed in the late 1940s, based on the documented construction date of surrounding buildings. Building 3033 is a single-story, metal framed structure with metal siding. The exterior of the building has been sealed by a polyurethane cocooning process, and it is operated under negative pressure. Building 3093 is a roofless, reinforced-concrete enclosure containing four charcoal-filled storage tanks which are currently empty. Building 3033 consists of approximately 1,200 sq ft and shares a common wall with Building 3033-A to the east. This facility is located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facility is paved for the most part with some grassy areas. Building 3033 is basically a single-room laboratory consisting of a krypton processing enclosure, a carbon reactor enclosure, a tritium process room consisting of a number of process hoods, and a utility area. Floor drains in the building discharge to the process system, and the cells drain to the low-level liquid waste (LLLW) system (WC-10). Reportedly, the processes in this building did not generate liquid waste. Work with radioactive materials was performed in the cells and hoods. The exterior of the building was observed to be in good condition. Generally, the interior of the building is in fair to good condition. Asbestos Containing Material (ACM) and radiation (RAD) hazard areas are posted and/or labeled as appropriate. A building space diagram is attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>The only significant area of radioactive contamination in this facility reportedly exists in the form of tritium in three traps and associated equipment (vessels, piping, vent ducts, etc.) in the Tritium Process Room. There are also a few small areas of fixed and transferable radiologic surface contamination located in other areas of the facility. Irretrievable amounts of krypton remain absorbed in the charcoal linings of the krypton storage tanks (Building 3093). Radiologic contamination in this facility has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are very low and well isolated. The presence of this contamination is not considered a significant hazard in its current state.</p> <p>It is assumed, based on the historical laboratory function of this building and operations in similar facilities, that hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations. Reportedly, no HAZMATs are currently used or stored in this facility. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Building 3033 consist mainly of small amounts of residual fixed and transferable RAD surface contamination (β, γ). Areas of RAD contamination are associated primarily with the hot cells and tritium process equipment. Reportedly, no HAZMATs are stored or used within this facility.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <p>< 500 Ci of ^3H (Quantity estimate obtained from Building 3033 Hazard Screening Report)</p>
<p><i>Other pollutants or contaminants:</i></p> <p>Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat given the status of this facility. Paint on exterior surfaces was also found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration.</p>

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3033 is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facilities. Reportedly, processes in Building 3033 did not generate liquid waste; however, since the building is serviced by the LLLW system there is a potential that historically radiologic waste of some sort may have been introduced into the system. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples. The WAG 1 Site Characterization Report indicates that high levels of tritium have been detected in a monitoring well just south of Building 3033. As a result, it is likely that liquid waste from activities involving radioisotopes in this building have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the small quantities of chemicals assumed to have been used historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. Surface water may have been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Additionally, if exterior painted surfaces do, in fact, contain lead, the potential exists for surface water to be impacted from deteriorated paint which washes off the building and finds its way to surface water with the storm water runoff.

Other than the potential for historical impact, no existing immediate threat to surface water was identified given the current status of this facility.

Air
<i>Are there any suspected impacts due to air emissions? If yes, please describe.</i>
<p>The Hazard Screening Report prepared for Building 3033 indicates that there is no potential for significant radiation exposure to personnel working in or around the facility due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Because of the low levels and nature of RAD contamination within the facilities, potential impacts to persons or the environment surrounding the facilities are considered negligible. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facilities to protect against inadvertent exposure to personnel. Air in the building is controlled by the isotopes area cell ventilation system which exhausts building and cell air to stack 3039. This also keeps Building 3033 under slight negative pressure relative to atmosphere. Apart from catastrophic failure of the hot cells, process areas, or ventilation system, it is unlikely that radioactive air emissions from this building would impact personnel or the environment.</p> <p>There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.</p>
Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
<p>As stated for groundwater, there is a potential for historical impact to soils in the area of Buildings 3033 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in this building (tritium). As a result, it is likely that operations in this facility have historically contributed to the Isotopes Circle soil contamination plume.</p> <p>There is also a potential for areas of soil adjacent to the facility to be impacted from lead if, in fact, exterior paint is found to be lead-containing. Deteriorating paint could dislodge from the surface and fall to the soil below. The exterior paint was observed to be good condition and does not pose an immediate threat in its current state.</p> <p>It is unlikely that the small quantities of chemicals assumed to have been used in Building 3033 have significantly impacted soil in the surrounding area.</p>
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
<p>The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:</p> <ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment. <p>There is also a potential for assumed lead-containing paint which peels off exterior surfaces of the buildings to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.</p>

<p style="text-align: center;">Worker Safety</p> <p><i>Could the release pose a threat to workers? If yes, please describe.</i></p> <p>Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. ACM is appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of building.</p>
<p style="text-align: center;">Environmental Receptors</p> <p><i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i></p> <p>No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3033.</p>
<p style="text-align: center;">Mitigation</p> <p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in this building. • Continue S&M activities per Procedure IP-900.
<p><i>What actions are currently being taken to abate/prevent release or impacts from release?</i></p> <p>Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facilities for worker and environmental protection. Warning signs and labels are posted throughout the facilities indicating RAD and ACM hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3033.</p> <p>Current actions being taken to prevent further release and ensure worker safety in Building 3033 are considered adequate until D&D activities begin.</p>
<p style="text-align: center;">Other Environmental Authorities</p> <p><i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i></p> <p>If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).</p>

Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
No existing potential hazards requiring maintenance actions per 40 CFR 300.415 were identified to be currently associated with Building 3033.
Removal Actions
<i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3033.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Building 3033 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
ACM has also been identified, marked and documented. No further remedial investigation involving this hazard is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3033 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Buildings 3033:

- Phase I Safety Documentation, The Krypton and Tritium Facility, Building 3033/3093, Hazard Screening, Document No. HS/3033/3093/F/RT-10/R-1.
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3033 Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Building 3033.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3033:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant
Evaluator's Signature

6/18/96
Date

ORNL DWG 80-596





Fig. 10. Diagram of Building 3033/3093.

10. BUILDING 3033-A—ACTINIDE FABRICATION FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3033-A The Actinide Fabrication Facility
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i> R.E. Eversole (576-7483), IFDP Project Manager, OER Program, LMES	
<i>Status (active/inactive):</i>	<i>Inactive, Standby Mode</i>
<i>Years of Operation:</i> ≈ 30	
<p><i>Description of Operation:</i></p> <p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Building 3033-A was used to house and contain the facilities for the production, loading, welding, and decontamination of neutron dosimeter materials as well as the weighing and packaging of milligram to gram quantities of actinide materials for research applications. The building included two operating areas; a small area for ^{14}C production at the south end of the building, and a larger main operating area for preparation of research materials. This building has been used almost exclusively for the preparation and distribution of highly enriched actinide isotopes, and for a period ^{14}C for the Isotopes Program. The following are some of the historical operations performed in this building: fabrication of ceramic oxide wires; loading of ceramic oxide wires, oxide powder, or metal into small metal capsules for use as in-core reactor neutron dosimeters; fabrication of monoenergetic gamma sources; weighing and packaging of milligram to gram quantities of actinide materials; preparation of nanogram to milligram actinide samples for alpha counting; decontamination of nuclear material shipping containers; and storage of radioactive materials. Additionally, many other small projects have been performed in this facility throughout the years.</p>	
<p><i>Physical description of area/facility:</i></p> <ul style="list-style-type: none"> • Building 3033-A was constructed in approximately 1960. • The facility is a single-story, metal framed structure with metal siding. The exterior of the building has been sealed by a polyurethane cocooning process, and the building is operated under negative pressure. • Building 3033-A consists of approximately 760 sq ft and shares common walls with Building 3033 to the west and Building 3034 to the east. • This facility is located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facility is paved for the most part with some grassy areas. • Building 3033-A is basically a single-room laboratory which consisted of a process hood, glove boxes, and various laboratory equipment. Floor, one hood, and sink drains discharge to the process waste system, and the drain in the hood which was located adjacent to the west wall discharged to the low-level liquid waste (LLLW) system (Tank WC-10). Work with radioactive materials was performed primarily in the hoods and glove boxes. Primary waste streams included exhausted air and liquid process waste. • The exterior of the building was observed to be in good condition. • Generally, the interior of the building is in fair to good condition. Asbestos Containing Material (ACM) and radiation (RAD) hazard areas are posted and/or labeled as appropriate. All equipment and hoods have been removed and the building has undergone general decontamination. • A building space diagram is attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>No significant areas of radioactive contamination were identified in this facility. Small localized areas of residual fixed and transferable RAD contamination exist in isolated areas throughout the facility; however, this contamination is not considered to represent a significant hazard due to the small amount of material involved. This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are very low and well isolated. The presence of this contamination is not considered a significant hazard in its current state.</p>
<p>It is assumed, based on the historical laboratory function of this building and operations in similar facilities, that hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations. Reportedly, no HAZMATs are currently used or stored in this facility. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Building 3033-A consist mainly of small amounts of residual fixed and transferable RAD surface contamination (α, β/γ). No significant β/γ material has been found other than the limited remains of ^{14}C contamination. Areas of RAD contamination are associated primarily with isolated surfaces throughout the facility. Reportedly, no HAZMATs are stored or used within this facility.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <p> $\approx 1,100 \mu\text{Ci } \alpha$ $\approx 2,160 \mu\text{Ci } \beta/\gamma$ $\approx 72 \mu\text{Ci } ^{14}\text{C}$ (located in the ^{14}C storage room) </p> <p>(Quantity estimates obtained from Building 3033-A Hazard Screening Report)</p>
<p><i>Other pollutants or contaminants:</i></p> <p>Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. Paint on exterior surfaces was also found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration.</p>

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3033-A is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facilities. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides common to many of the processes in the Isotopes Facilities have been detected in WAG 1 groundwater samples. As a result, it is possible that liquid waste from activities involving radioisotopes in this building have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the small quantities of chemicals assumed to have been used historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. No Drain Survey Report was available for Building 3033-A.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. Surface water may have been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Additionally, if exterior painted surfaces do, in fact, contain lead, the potential exists for surface water to be impacted from deteriorated paint which washes off the building and finds its way to surface water with the storm water runoff.

Other than the potential for historical impact, no existing immediate threat to surface water was identified given the current status of this facility.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3033-A indicates that there is no potential for significant radiation exposure to personnel working in or around the facility due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Because of the low levels and nature of RAD contamination within the facilities, potential impacts to persons or the environment surrounding the facilities are considered negligible. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facilities to protect against inadvertent exposure to personnel. Air within the building is controlled by the isotopes area cell ventilation system which exhausts building air to stack 3039 after passing through local roughing and high efficiency particulate air (HEPA) filters inside the building. This also keeps Building 3033-A under slight negative pressure relative to atmosphere. Apart from catastrophic failure of the structure or ventilation system, it is unlikely that radioactive air emissions from this building would impact personnel or the environment.

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

As stated for groundwater, there is a potential for historical impact to soils in the area of Building 3033-A due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to many of the processes performed in the Isotopes Facilities. As a result, it is possible that operations in this facility have historically contributed to the Isotopes Circle soil contamination plume.

There is also a potential for areas of soil adjacent to the facility to be impacted from lead if, in fact, exterior paint is found to be lead-containing. Deteriorating paint could dislodge from the surface and fall to the soil below. The exterior paint was observed to be good condition and does not pose an immediate threat in its current state.

It is unlikely that the small quantities of chemicals assumed to have been used in Building 3033-A have significantly impacted soil in the surrounding area.

Release Beyond Facility or Reservation Boundaries

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).

The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:

- A person becomes inadvertently contaminated and leaves the facility/reservation undetected.
- Catastrophic failure of the structure and/or contaminated equipment.

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors). (Continued)

There is also a potential for assumed lead-containing paint which peels off exterior surfaces of the buildings to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.

Worker Safety

Could the release pose a threat to workers? If yes, please describe.

Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. ACM is appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of this building.

Environmental Receptors

Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.

No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3033-A.

Mitigation

What action(s) might be taken to abate/prevent release or impacts from release?

- Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in these buildings.
- Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facilities for worker and environmental protection. Warning signs and labels are posted throughout the facilities indicating RAD and ACM hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3033-A.

Current actions being taken to prevent further release and ensure worker safety in Building 3033-A are considered adequate until D&D activities begin.

Other Environmental Authorities
<i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i>
If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).
Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
No existing potential hazards requiring maintenance actions were identified to be associated with Building 3033-A.
Removal Actions
<i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3033-A.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Building 3033-A have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
ACM has also been identified, marked and documented. No further remedial investigation involving this hazard is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3033-A contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Building 3033-A:

- Phase I Safety Documentation, The Actinide Fabrication Facility, Building 3033-A, Hazard Screening, Document No. HS/3033-A/3093/F/RT-11(Rev.1).
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3033-A Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Buildings 3030, 3031, and 3118.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3033-A:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant
Evaluator's Signature

6/18/96
Date

Building 3033-A




Fig. 11. Diagram of Building 3033-A.

**11. BUILDING 3034—RADIOISOTOPE AREA
SERVICES BUILDING**

ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3034 Radioisotope Area Services Building
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i> R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES	
<i>Status (active/inactive):</i> Inactive, Standby Mode	<i>Years of Operation:</i> ≈ 40
<p><i>Description of Operation:</i></p> <p>There are no current operations, other than surveillance and maintenance activities, on-going in this building. Information on historical operations identified for Building 3034 during this RmSE was not detailed. The building was originally built as part of the Isotopes Program. The facility was used as a field shop for the Plant and Equipment Division in supporting past isotope production operations in other facilities and it houses the central electrical distribution station for the Isotopes Circle area. Reportedly, no radioactive materials have been handled in this building. Currently, the building is being prepared to be used as office space in addition to continuing to house the electrical distribution station.</p>	
<p><i>Physical description of area/facility:</i></p> <ul style="list-style-type: none"> • Building 3034 was originally constructed in the 1950s. • The building is a single-story, metal framed structure with metal siding consisting of approximately 1,400 sq. ft. of floor space. The building is not sealed by polyurethane cocooning. Paint observed on exterior surfaces is in good condition. • Building 3034 is located in an industrial area of ORNL (Isotopes Circle). The immediate area surrounding the facilities is paved for the most part with some grassy areas. The building shares a common wall with Building 3033-A to the west. • The building consists of offices and a small warehouse area containing the electrical distribution station. Floor drains in the building reportedly discharge to the process waste system. Low-level liquid waste (LLLW) service has never been available in this building. Reportedly, no work associated with radioactive materials has been performed in this building. Information on drain locations and discharge points is available from the ORNL Engineering Support Office. • Generally, the interior of the building is in good condition. Asbestos Containing Material (ACM) is labeled as appropriate. No polychlorinated bi-phenols (PCBs) were identified to be associated with this building. • Building 3034 is operated under normal atmospheric pressure. • A building space diagram is attached to this form showing the layout of the facility. 	
Release Information	
<p><i>Description of release, or threatened release, and source:</i></p> <p>Despite the fact that no radioactive materials were reportedly handled in this facility (according to the IFDP Work Plan and facility personnel), the Hazard Screening report for the facility indicates that some small, fixed hot spots of residual radioactive surface contamination remain in inaccessible areas.</p>	

Description of release, or threatened release, and source: (Continued)

Perimeter walls within the facility have been decontaminated to a level of ten feet above the floor. The wall area above this point is presently identified as a fixed radiologic contamination area by postings. Since there is no record of radioactive material handling in this facility, the origin of this release and remaining contamination is uncertain. The remaining contamination is in small enough quantity to be considered insignificant.

It is assumed, based on the historical shop function of this building, that hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a HAZMAT release.

Hazardous substances present:

Hazardous substances remaining in Building 3034 consist mainly of small amounts of residual fixed RAD surface contamination (β/γ) and larger quantities of HAZMATs. Areas of fixed RAD contamination are associated with the interior perimeter wall surfaces above the ten-foot level. Because of the renovation work on-going in this building, a number of HAZMATs exist in this facility in various quantities. These materials are listed on the attached HAZMAT inventory sheets. No PCBs were identified to be present in within the building.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Since there has been no documented historical use of radioactive materials in this facility, it is uncertain where this contamination originated from. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

< 1,700 μCi β/γ
4,875 lbs HAZMATs (see attached HAZMAT sheet for detailed quantity breakdown).

(Quantity estimates obtained from Building 3034 Hazard Screening Report and ORNL Hazardous Material Information System database)

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in good condition and pose no immediate health threat. Paint on exterior surfaces was also found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration. There is, however, an area of deteriorating exterior paint on exposed piping adjacent to the east wall of the building which should be noted. Though this piping is not specific to Building 3034, it is peeling off and paint chips can be seen laying in the grassy area adjacent to the east side of the building.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3034 is located in Waste Area Grouping 1 at ORNL. Based on the information available regarding current and historical usage and operation of this facility, there is no reasonable evidence to suggest Building 3034 has significantly impacted groundwater in the area in any way.

Because of the depth to groundwater in the area of building 3034, soil characteristics, and nature and extent of potential lead-based paint (LBP) contamination, it is unlikely that lead from the paint chipping off of the exterior piping adjacent to the east side of the building has impacted groundwater through vertical migration if, in fact, the paint actually contains lead.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

The only identified potential for impact to surface water from Building 3034 was the exterior painted surfaces and piping adjacent to the building if, in fact, the paint does contain lead. The potential exists for paint which has chipped off the building or piping to find its way to surface water with the storm water runoff during a rain event. Numerous paint chips were observed in the grassy area adjacent to the east side of the building. This area runs along the side of the building, is approximately three feet wide, and slopes toward the pavement between Buildings 3034 and 3036. As a result, it is highly likely that a hard downpour could float the chips and carry them to the nearest storm drain.

Other than the potential for assumed lead paint impact, no existing immediate threat to surface water was identified given the current status of this facility.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3034 indicates that there is no potential for significant radiation exposure to personnel working in or around this facility as a result of airborne migration of radioactive particulates and physical contact with contaminated surfaces. Areas of RAD contamination are identified and marked within the facility to protect against inadvertent exposure to personnel. Air within the building is controlled by a local ventilation system. Because of the small amounts of RAD contamination present, it is highly unlikely that radioactive air emissions from this building would impact personnel or the environment.

There is, however, a potential for impact to indoor air quality due to the presence of ACM, assumed LBP, and usage of HAZMATs. ACM and lead-based paint pose a potential threat should these materials be disturbed and become airborne. Certain HAZMATs can pose a potential threat to indoor air quality if the area they are used in is not adequately ventilated. The ACM, assumed LBP, and HAZMATs remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

Based on the information available regarding historical usage and operation of this facility, there is no reasonable evidence to suggest Building 3034 has significantly impacted the soil below the building or in the immediate area in any way. Therefore, it is unlikely that activities in this building have contributed to the Isotopes Circle soil contamination plume identified in the Site Characterization Report for WAG 1.

Paint chips from the exterior piping adjacent to the east side of the building were observed in the grassy area below the piping. If the paint contains lead, there is a potential for lead impact to the soil in this area.

Release Beyond Facility or Reservation Boundaries

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).

Because of the small amount and inaccessibility of existing radiologic contamination in Building 3034, there is considered to be no potential for significant radiologic release beyond the facility or reservation boundaries.

There is, however, a potential for assumed lead-containing paint which peels off exterior surfaces of the building to be carried away with surface runoff during a rain event. This potential is considered slight for the exterior surfaces of the building current condition of the facility. However, this potential is greater for the piping exterior to the east side of the facility since paint chips have already fallen to the ground.

Worker Safety

Could the release pose a threat to workers? If yes, please describe.

The low levels of radiologic surface contamination existing in Building 3034 are inaccessible and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. ACM is appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked and workers are careless. This potential is not considered significant given the current status and level of activity of building.

Environmental Receptors

Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.

No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3034.

Mitigation

What action(s) might be taken to abate/prevent release or impacts from release?

- Continued utilization and enforcement of administrative controls that are currently in place to protect workers and monitor conditions and activities in this building.
- Exterior paint on piping adjacent to the east wall of the building should be tested for lead content. If the paint is found to be lead-containing, a maintenance action will be required to eliminate areas of deteriorating paint. In addition, a remedial site evaluation will be necessary to determine whether the soil in this area has been impacted by lead from the peeling paint.
- Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning tape and labels are used to identify RAD and ACM hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. The building is currently in surveillance and maintenance status awaiting usage as storage and office space and subsequent entry into the Decontamination and Decommissioning (D&D) Program. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3034.

Current actions being taken to prevent further release and ensure worker safety in Building 3034 are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

Samples should be taken of the exterior paint located on the piping adjacent to the east wall of the facility. The samples should then be analyzed to determine whether the paint does, in fact, contain lead. Such analysis should include TCLP (40 CFR 261, Appendix II) to determine whether the area qualifies as a RCRA generator point. If the paint is found to contain lead, abatement actions will be required to prevent deteriorated areas of paint from dislodging and falling to the ground below, potentially having a direct impact on soil in this area, and an indirect impact to surface water.

No further potential hazards requiring maintenance actions were identified to be associated with Building 3034.

Removal Actions

Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.

No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3034.

Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
<p>Pending confirmatory sampling and analysis results of the paint on exterior piping adjacent to the east wall of the facility, a remedial site evaluation (RSE) should be conducted to determine whether the soil in this area has been impacted by lead from chipping paint and whether remediation of the soil is necessary.</p> <p>Although no reasonable evidence was identified during this RmSE to suggest that Building 3034 has contributed to soil contamination in the area, it is possible that soil beneath the slab of this building may have been impacted from migration of contamination originating from leaking process and/or LLLW piping in the area. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.</p> <p>ACM has also been identified, marked and documented. No further remedial investigation involving this hazards is considered necessary given the current status and future plans of this facility.</p> <p>Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.</p>
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
<p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3034 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>
Additional Comments
<p>The following documents and databases were referenced for historical and hazard information related to Building 3034:</p> <ul style="list-style-type: none"> • Phase I Safety Documentation, Radioisotopes Area Services Building, Building 3034 Hazard Screening, Document No. HS/3034/F/RT-12 (Rev.0). • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Available Building 3034 Occurrence Reports, 1989 to present. • Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1. • ORNL Hazardous Material Information System Database. • ORNL Drain System Survey Report for Building 3034. <p>The following personnel and offices were contacted and provided historical and current use/condition information for Building 3034:</p> <ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant

Evaluator's Signature

6/18/96

Date




Fig. 12. Diagram of Building 3034.

Plant: 3 Division: Department: Control Area: Building: 3034 Room: Area: HAZ Rating: WA Code:
Item ID: Ingredient: Mix Comp: to HAZ Class: Phy State: Pressure Cd: Temp Cd: Cont Type Cd:
Date Expiration: MSDS Avail: Haz Mat Grp Cd: Inv Status: NISS

Building: 3034

RECID	** CASNO	Material Name	MMS	C R	Total LBS	Total KILOGRAMS	No of Items
00677	000067-64-1	ACETONE	---	---	0.8686	0.3940	1
00882	000074-86-2	ACETYLENE	---	---	16.6976	16.6976	1
81179	NISS	AJAX INSTITUTIONAL CLEANSER WITH OXYGEN BLEACH	---	---	0.2508	0.1136	4
01730	007440-37-1	ARGON	---	---	192.7890	87.4482	12
82571	NISS	ASHLAND PLIOBOND 20 BELT DRESSING #439-3490	---	---	1.6970	0.7700	10
89601	NISS	BOSTON INDUSTRIAL PRODUCTS STYLE 264 MOR SHEET	---	---	29.4298	13.3491	2
B1340	NISS	BOSTON INDUSTRIAL PRODUCTS STYLE 50 PACKING	---	---	32.0005	14.5153	1
B1343	NISS	CARBOLINE ALARA 1146 CAVITY DECON	---	---	89.2946	40.5037	1
A7206	NISS	CARBOLINE ALARA 1146 STRIPPABLE COATING	---	---	446.4730	202.5180	10
A7327	NISS	CHEMREX SONNEBORN SONOLASTIC NP-1 (ALL COLORS EXCE	---	---	85.2014	38.6444	62
A6677	NISS	CIMCOOL FIVE STAR 3.0	---	---	1.0431	0.4731	1
86418	NISS	CINCINNATI MILICRON CIMTAP (R)	---	---	0.4733	0.2888	1
92404	NISS	COPPERNATE PASTE SOLDERING FLUX	---	---	0.6250	0.2840	10
A0222	NISS	DEVCON 5-MINUTE EPOXY HARDENER (91081) AND RESIN (90	---	---	0.1953	0.0885	3
87236	NISS	DEVCON PLASTIC STEEL PUTTY (A) RESIN (B)	---	---	6.0000	2.7210	6
96137	NISS	DEVOE WONDER SHIELD EXTERIOR ACRYLIC LATEX SATIN P	---	---	16.6904	7.5706	2
A0795	NISS	DEXTER EPOXI-PATCH KIT 615 PART A (88069) AND PART B	---	---	0.2500	0.1136	4
91304	NISS	DOW CORNING SILICONE PLUS (TM) PREM 100% SIL SILNT,	---	---	0.6364	0.2888	8
87241	NISS	DOW CORNING (R) HIGH VACUUM GREASE	---	---	1.3820	0.6268	4
92595	NISS	EXXON KUTWELL 40	---	---	33.3812	15.1416	1
90652	NISS	EXXON TERRESTIC 33	---	---	399.3222	181.1313	1
82988	NISS	EXXON UNIREX N 2	---	---	9.4530	4.2880	10
90530	NISS	FEL-PRO C5-A HIGH TEMPERATURE ANTISEIZE COMPOUND	---	---	0.6572	0.2980	1
922228	NISS	FEL-PRO CLOVER SILICON CARBIDE GREASE MIX	---	---	1.0000	0.4535	1
91239	NISS	GARLOCK LOBALL WITH MOLY S-2	---	---	0.9375	0.4252	1
A7274	NISS	GARLOCK STYLE HTC-9800 COMPRESSED CARBON FIBER SHE	---	---	20.0025	9.0731	1
85527	NISS	GAVLON 510 ENAMEL, ANY COLOR	---	---	8.3452	3.7853	1
86113	NISS	GE SILICONE RUBBER SEALANT SCS2004	---	---	0.5224	0.2368	8
90866	NISS	GE SILICONE SEALANT GES090	---	---	26.8619	12.1844	1
89236	NISS	GLYPTAL 1202	---	---	4.1872	1.8926	2
91430	NISS	HANDY & HARMAN WHITE FLUX, SILVER BRAZING FLUX - L	---	---	0.5001	0.2268	1
01861	007440-59-7	HELIUM	---	---	4.0116	1.8196	2
B0509	NISS	HERCULES PVC CEMENT CLEAR MEDIUM	---	---	0.9492	0.4305	1
90215	NISS	HERCULES STA-PUT (R)	---	---	8.2148	3.7260	4
91493	** NISS	INSTA-FOAM OZONE FRIENDLY GREAT STUFF	---	---	1.1.7355	5.3230	4
B2783	NISS	ITW FLUID PRODUCTS GROUP TOLE STEEL BLUE DX-100	---	---	0.1956	0.0888	3
95267	NISS	J.W. HARRIS STAY-SILV 15	---	---	0.5215	0.2365	1
82454	NISS	JOHNSON COMPLETE FOR FLOORS	---	---	127.6827	57.9165	3
92010	NISS	JOHNSON FORTIFY	---	---	85.1218	38.6110	2
97209	NISS	JOHNSON GO-GETTER READY-TO-USE	---	---	15.2299	6.9079	7
87805	NISS	JOHNSON WAX FINISH JX-4000/CONCRETE SEALER	---	---	407.9177	185.0296	11
90647	NISS	K&W KNOCKER LOOSE	---	---	0.5867	0.2661	1
89862	NISS	KEL-SAN SUPER DRAIN OPENER	---	---	91.6312	41.5636	2
B3049	NISS	KULITE TUNGSTEN HEAVY METAL ALLOY (POWDER/METAL)	---	---	18.0000	8.1646	2

* indicates MSDS is not available
** indicates MSDS updated within last three months

**12. BUILDING 3038 (AHF, E, M)—ISOTOPE DEVELOPMENT
LABORATORY**

ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3038 (AHF, E, M) Isotope Development Laboratory
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 40	
<p><i>Description of Operation:</i></p> <p>There are no current operations on-going in this building, other than surveillance, maintenance, and deactivation activities required for facility stabilization. Building 3038 was constructed to house all the radioisotope shipping activities for ORNL. Originally, the entire facility was dedicated to radioisotope shipping as follows: the east portion (3038-E) contained the analytical chemistry laboratory to perform analyses of short-lived radioisotopes prior to shipment; the middle section (3038-M) housed the radioisotope handling and transfer barricade; and the west section (3038-AHF) housed the packaging, inspection, and shipping activities. During the 1960s, the volume of radioisotopes being shipped decreased and the shipping area was reduced. In the late 1960s, the west portion of the building was converted into the Alpha Handling Facility (AHF) by addition of water-shielded hot cells and glove boxes for target fabrication. The middle portion of the building (3038-M) has always been the center of radioactive isotope shipping operations for ORNL. The analytical chemistry laboratories supporting the isotopes shipping activities were located in the east end of the facility until 1976 when the analytical function was transferred to other ORNL facilities. That portion of the building (3038-E) was subsequently converted into an isotope production and development facility. During the late 1970s and early 1980s, research program activities involving plutonium alloys and compounds were conducted in this area of the building. The same glove boxes were used in the mid 1980s to perform research on ¹⁴⁷Pm-doped crystals and glasses for laser development studies. With these two exceptions, all work in the east end of the facility has been dedicated to isotopes efforts.</p>	
<p><i>Physical description of area/facility:</i></p> <ul style="list-style-type: none"> • Building 3038 was originally constructed in the late 1940s. • The facility is a single-story, metal frame building with brick siding consisting of approximately 7,250 sq. ft. of floor space. • Building 3038 is located in an industrial area of ORNL (Isotopes Circle). • Building utilities include electric, steam, and plant air. • The immediate area surrounding consists of a grassy area to the south and combination of pavement and grass skirting to the north, east, and west. • Building 3038 consists of a number of hot cells, glove boxes, process hoods, and related equipment and process areas for handling and packaging radioactive materials. Work involving radioactive materials was conducted primarily in the hot cells, glove boxes, process hoods, and Radioactive Materials Shipping and Packaging area located in 3038-M. • The building and hot cells are kept under negative pressure for containment purposes. Building ventilation is local and exhausts through high efficiency particulate air (HEPA) filters on the roof. Cell ventilation exhausts through HEPA filters to the cell ventilation system and stack 3039. The manipulator cells and the glove boxes in the AHF and AHF Annex exhaust through HEPA filters to the isotopes area process off-gas system. 	

Physical description of area/facility: (Continued)

- Building sinks and floor drains discharge to process waste system. Hot cell drains discharged to the low-level liquid waste (LLLW) system (Tank WC-10). In addition, hood and sink operations in 3038-E also discharged to the LLLW system.
- Exterior of the building appears to be sound with no visual evidence of significant damage or deterioration.
- Access to some of the interior portions of the building was restricted during the facility inspection. The interior areas of the building that were accessible were observed to be in fair to good condition without any significant areas of damage or deterioration. Asbestos containing material (ACM) and items containing poly chlorinated bi-phenols are labeled as appropriate.
- A building space diagram is attached to this form showing the location of the various process areas and equipment.

Release Information***Description of release, or threatened release, and source:***

Low levels of residual fixed and transferable radiologic surface contamination exist in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells, barricade area, a glove boxes, hoods and related process equipment (vessels, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD surface contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state according to the Building 3038 Hazard Screening Report.

The Hazard Screening Report does, however, indicate that a major potential hazard exists in the form of radiologic source material inventory remaining in the facility. This presents a potential for release of radiologic material from storage containers that might rupture during a natural phenomenon or other facility upset.

Hazardous materials (HAZMATS) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.

Hazardous substances present:

Hazardous substances remaining in Building 3038 consist mainly of residual RAD surface contamination (α , β , γ), radioactive source materials, PCBs, and a small quantity of miscellaneous HAZMATS. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells, barricade areas, glove boxes, hoods and related process equipment. Radioactive source materials are containerized in Department of Transportation (DOT) approved shipping containers and stored in the east and west ends of the facility. PCBs are reportedly present in the form fork lift hydraulic fluid within the building. Hazardous materials present in the building are listed on the attached HAZMAT inventory sheet.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

Residual Surface Contamination:

≈ 10 mCi β/γ as ^{90}Sr
 < 75 μCi α as ^{238}Pu
 < 2 μCi α as ^{239}Pu

Radiologic Material Inventory:

≈ 3,800 Ci α (the bulk as ^{238}Pu)
 ≈ 10 Ci β/γ (as ^{90}Sr equivalent)

Other Hazardous Substances:

PCB quantity not known (assumed to be less than 1 gallon).
 ≈ 11 pounds total miscellaneous HAZMATs (see attached HAZMAT inventory sheet).

(Radioactive material quantity estimates obtained from Building 3038 Hazard Screening Report; PCB quantity was not available in ORNL PCB Containing Equipment Inventory Database; HAZMAT quantity obtained from ORNL Hazardous Material Information System Database.)

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair to good condition and pose no immediate health threat. The exterior of this building is brick and is not painted; therefore, no suspect areas of exterior lead-containing paint are associated with this building.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3038 is located in Waste Area Grouping (WAG) 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility.

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources. (Continued)

Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3038. It is likely that liquid waste from activities involving radioisotopes in Building 3038 have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically and currently used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. Since the exterior surfaces of this building are not painted, no potential for direct impact to surface water from Building 3038 was identified in its current state.

Surface water may, however, have historically been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

No existing immediate threats to surface water were identified to be associated with Building 3038 during this RmSE.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 3038 indicates a slight potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility exists due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces.

Are there any suspected impacts due to air emissions? If yes, please describe. (Continued)

Also indicated is the greater potential of exposure due to catastrophic failure of containers of radioactive source material. Release of this material could pose a major airborne threat to personnel within and in the immediate vicinity of Building 3038. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air in the building is controlled by a combination of a local ventilation system which controls building air, the cell ventilation system which controls hot cell exhaust, and the process off-gas system which controls exhaust from manipulator cells and glove boxes in the AHF and AHF Annex. Apart from catastrophic failure of the hot cells, glove boxes, structure, ventilation systems, or other contaminated equipment, it is unlikely that radioactive air emissions from Building 3038 would impact personnel or the environment in its current state.

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.

Soil

Are there any suspected impacts to soil? If yes, please describe.

As stated for groundwater, there is a potential for historical impact to soils in the area of Building 3038 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in this building. An area of contaminated soil exists around the southeast corner of Building 3038. Reportedly this area is suspected to be the result of an abandoned waste tank and piping in the area that has leaked in the past. The area is well marked and covered with a protective barrier and river rock. Information specific to this area of contamination was not identified during this RmSE. As a result, it is likely that operations in this facility have historically contributed to the Isotopes Circle soil contamination plume. This area of contamination is not considered an imminent hazard given the current status of the adjacent facility (Building 3038) and the protective measures being taken to prevent contamination migration and personnel exposure.

It is unlikely that the small quantities of chemicals used in Building 3038 will, or have, significantly impact(ed) soil in the surrounding area.

Release Beyond Facility or Reservation Boundaries

Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).

The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:

- A person becomes inadvertently contaminated and leaves the facility/reservation undetected.
- Catastrophic failure of hot cells and/or contaminated equipment.

Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.

<h3 style="text-align: center;">Worker Safety</h3> <p><i>Could the release pose a threat to workers? If yes, please describe.</i></p> <p>Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.</p>
<h3 style="text-align: center;">Environmental Receptors</h3> <p><i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i></p> <p>No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3038.</p>
<h3 style="text-align: center;">Mitigation</h3> <p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building. • Continue S&M activities per Procedure IP-900.
<p><i>What actions are currently being taken to abate/prevent release or impacts from release?</i></p> <p>Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3038.</p> <p>Current actions being taken to prevent further release and ensure worker safety in Building 3038 are considered adequate until D&D activities begin.</p>
<h3 style="text-align: center;">Other Environmental Authorities</h3> <p><i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i></p> <p>If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).</p>

Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
No existing potential hazards requiring maintenance actions were identified to be associated with Building 3038.
Removal Actions
<i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3038.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Building 3038 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3038 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Building 3038:

- Phase I Safety Documentation, The Isotope Development Laboratory, Building 3038, Hazard Screening, Document No. HS/3038/F/RT-15 (Rev. 1).
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3038 Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Building 3038.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3038:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant
Evaluator's Signature

6/18/96
Date

ORNL DWG 80-591






Fig. 13. Diagram of Building 3038-AHF.

Building 3038



Building 3038-E



Building 3038-W





Fig. 14. Diagram of Building 3038-W.



Building 3038
N
W E
S






Fig. 15. Diagram of Building 3038-M.

ORNL DWG 80-594



Building 3038

ORNL-DWG 82-14970R



Building 3038-E

Fig. 16. Diagram of Building 3038-E.

MSR003C
13:42:49

03-28-1996

HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant: 3 Division: Department: Control Area: Building: 3038 Room: HAZ Class: HAZ Rating: WA Code:
Item ID: LIST: Ingredient: Mix Comp: to HAZ Nat Grp Cd: phy State: Pressure Cd: Temp Cd: Cont Type Cd:
Date Expiration: Inv Status: MSDS Avail: Haz Nat Grp Cd:

Building: 3038

RECID	**	CASNO	Material Name	MMES	C R	Total	Total	No of
-----	-----	-----	-----	-----	A T	LBS	KILOGRAMS	Items
87241	-----	NISS	DOW CORNING (R) HIGH VACUUM GREASE	-----	-----	-----	-----	-----
81193	-----	NISS	FORMULA 409 ALL PURPOSE CLEANER	-----	-----	-----	0.2070	1
89515	-----	NISS	HOUSEHOLD (HANDY) OIL	-----	-----	-----	0.3255	1
94226	-----	NISS	INSTA-GEL XF	-----	-----	-----	0.0887	1
97063	**	NISS	J. PENNER CRT CLEAN SOLUTION	-----	-----	-----	3.7854	1
00318	-----	000067-56-1	METHANOL	-----	-----	-----	0.0842	1
89448	-----	NISS	PPG QUICK DRY SPRAY ENAMELS, 55-B	-----	-----	-----	0.0296	1
92251	-----	NISS	SANFORD ROLL-ON STAMP PAD INKER	-----	-----	-----	0.3401	1
94032	-----	NISS	SELIG MASTER MECHANIC LIQUID	-----	-----	-----	0.0887	1
Building 3038 Totals:				11.3023	-----	5.1267	-----	10



**13. BUILDING 3047—RADIOISOTOPE DEVELOPMENT
LABORATORY**



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3047 The Radioisotope Development Laboratory (RDL)
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 30	
<i>Description of Operation:</i>	
<p>All isotopes activities within Building 3047 are shutdown with the exception of waste removal and transloading of radioactive material in the beta/gamma hot cells. There are currently a large number of different work items performed within this facility. Actual operations can involve temporary storage and movement of discrete items of inventory; trans-loading/shipment of items (transfer of items from on carrier or cask to another); receipt, packaging, repackaging, transfer, and shipment of radioactive material; and the unloading, opening, handling, repackaging, and shipment of liquid and solid radioactive materials including waste. The Health Sciences Research Division (HSRD) utilizes parts of this facility for processing medical radioisotopes and radiopharmaceutical research. The hot cells are used for opening High-Flux Isotopes Reactor target capsules and transloading highly radioactive materials. Laboratories 209 and 210 are currently not in use but are expected to be used by the Isotope Production and Distribution Program. Laboratory 208 is used by HSRD staff as an analytical and research facility. Laboratory 207 may also be used by the Isotope Production and Distribution Program.</p>	
<p>Historically, this facility has been used for research, development, and production of radioisotopes. The Medical Isotopes Section (now the Nuclear Medicine Group) of the HSRD has utilized several laboratories for nuclear medicine research. No specific descriptions can be given for past processing performed in RDL because of frequent changes not only in the processes themselves but also in the materials, operating procedures and parameters, and program requirements. Special safety summaries and approved procedures were required for each new experiment and operation. Before an operation could begin, all pertinent paperwork had to be reviewed and approved. If any potential hazard were identified, additional reviews and approvals were needed. Reviews identified and analyzed potential hazards that might be different in degree or type from those previously approved.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> • Building 3047 was originally constructed in the early 1960s. • The building is a three-story, steel frame structure with concrete block interior and exterior walls. • Building 3047 shares a common wall with the Isotopes Technology Building (Building 3047-A) to the east. Because they have individual ventilation systems and are separated by heavy walls and at least two sets of double doors, they are considered separate buildings. Building 3047-A, which contains administrative offices, is not considered a part of the RDL; nor is it included in the RDL programmatic missions and Isotopes Facilities Deactivation Project (IFDP). As of this writing, there remains speculation as to whether Building 3047 will itself remain in the IFDP. The building also shares a common wall with Building 3028 to the west. 	

Physical description of area/facility: (Continued)

- Building ventilation is divided into three zones; west, middle, and east. The west and middle zones operate under slight negative pressure, and the east zone is not contained. Exhaust ventilation of Hot Cells A, B, C, and D is provided by the cell ventilation system, exhaust ventilation of the Alpha Hot Cell is provided by the process off-gas system.
- The exterior of building is generally clean and in good condition with no visible areas of significant deterioration or damage.
- The interior portions of the building fair to good condition with no visible areas of significant deterioration or damage.
- Building 3047 is located in Isotopes Circle, an industrial area of ORNL. The immediate area surrounding the facility is paved.
- RDL houses four high-level beta/gamma hot cells (A-D), one alpha hot cell, seven laboratories for handling low-level materials, a decontamination room, a Health Physics (HP) area, offices, and service areas. Utilities include electrical power, steam, and plant air.
- Cell floor drains, some hood drains, and drains in the decontamination facility discharge to the LLLW system (Tank WC-10). The remaining floor, sink, and hood drains discharge to the process waste system.
- Work with radioactive materials was/is conducted primarily in the hot cells and laboratories within the building. Resulting primary waste streams included exhaust air and liquid process waste.
- A building space diagram is attached to this form showing the location of the various process areas and equipment.

Release Information*Description of release, or threatened release, and source:*

Low levels of residual fixed and transferable radiologic surface contamination exist in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state. The potential for release of additional radiologic contamination exists due to inventory of radioactive materials currently stored in the facility in limited quantities. The existing levels of residual RAD surface contamination in the facility are low, especially in comparison with the remaining radiologic material inventory, and the presence of this contamination is not considered a significant hazard in its current state.

Hazardous materials (HAZMATS) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) historically during facility operations and currently for surveillance and maintenance (S&M) activities. A large number of HAZMATS are currently used and stored within Building 3047, the majority of the individual items consist of less than one pound of material. Two of these materials were identified in the Hazard Screening Report to be potential significant hazard sources. These chemicals are chloroform and benzene, which are listed as human carcinogens by the Occupational Safety and Health Administration and the American Conference of Government Industrial Hygienists. These chemicals are used only in laboratory hoods while the containers are open and no more than 20 kg of each chemical is present in the facility at one time. A release of these chemicals within the building would result in minor effects on any personnel in the immediate vicinity of the accident. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release within the building.

There was a small diesel fuel spill identified around the pad of the emergency generator located adjacent to the northwest wall of the facility. This leak poses an immediate threat to surface water and is discussed in more detail in the Surface Water section of this report.

Hazardous substances present:

Hazardous substances remaining in Building 3047 consist mainly of residual RAD surface contamination (α , β , γ), radioactive materials in storage, PCBs, and a number of small quantities of miscellaneous HAZMATs including chloroform and benzene. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells and process equipment. PCBs are reportedly present in small electrical capacitors. Hazardous materials present in the building are listed on the attached HAZMAT inventory sheets.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

Residual Radiologic Surface Contamination:

< 1 mCi β/γ as ^{90}Sr
< 5 mCi α as ^{239}Pu

Radiologic Material Inventory:

\approx 3,000 Ci α (the bulk as ^{238}Pu)
 \approx 500,000 Ci β/γ (as ^{90}Sr equivalent)

Other Hazardous Substances:

\approx 1 gallon PCBs
 \approx 4,923 pounds total miscellaneous HAZMATs (see attached HAZMAT inventory sheet).

(Quantity estimates obtained from Building 3047 Hazard Screening Report, ORNL PCB Large High- and Low-Voltage and Small Capacitors Inventory database, ORNL Hazardous Material Information System database.)

Other pollutants or contaminants:

Asbestos containing material (ACM), primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in good condition and pose no immediate health threat. Paint on exterior surfaces was observed to be in good condition with no visible evidence of significant damage or deterioration.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3047 is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening the groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3047. It is likely that liquid waste from activities involving radioisotopes in Building 3047 have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically and currently used in this facility, it is unlikely that such usage has, or will, significantly contribute(d) to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified given the current status of the facility.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. An immediate, direct threat to surface water is associated with the emergency diesel generator located adjacent to the northwest wall of the building on the concrete apron. A portion of the concrete pad supporting the generator was found to be soaked with diesel fuel (an area of approximately four square feet). This area is susceptible to rainwater which can wash the fuel off the pad and channel it along the concrete apron into Fifth Creek to the east of the building. Though the area of fuel is small, continued leakage and subsequent rain events can compound the impact to Fifth Creek.

The only other potential for direct impact to surface water from Building 3047 in its current state would be from lead-containing paint chips which fall off the exterior painted surfaces and find their way into the storm water drainage system and eventually to WOC. Based on the age of this facility, it is assumed that painted surfaces contain lead. The exterior paint of Building 3047 is in good condition and there was no visible evidence of deterioration observed during the site inspection. Therefore, the potential for impact to surface water due to assumed exterior lead-based paint is considered slight.

Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.

Air
<i>Are there any suspected impacts due to air emissions? If yes, please describe.</i>
<p>The Hazard Screening Report prepared for Building 3047 indicates that the potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility as a result of potential airborne migration of radioactive particulates and physical contact with contaminated surfaces is considered insignificant. There is, however, a potential for significant radiation exposure to personnel as a result of airborne migration of particulates from the remaining inventory of radioactive material should containment of this material be compromised. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air in the building is controlled by the cell ventilation system (hot cells A-D), process off-gas system (alpha hot cell), and local ventilation systems (west, middle, and east building zones). Exhaust air from hot cells A-D, the alpha hot cell, the west building zone, and the middle building zone is filtered through high efficiency particulate air (HEPA) filtration units before discharge to local exhaust stacks or stack 3039. Apart from catastrophic failure of the hot cells, storage equipment, or ventilation systems, it is unlikely that radioactive air emissions from Building 3047 would impact personnel or the environment in its current state.</p> <p>There is also a potential for impact to indoor air quality due to the presence of ACM, assumed lead-based paint (LBP), chloroform, and benzene should these materials be disturbed or release within the facility. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state. Special handling procedures are implemented for usage of chloroform and benzene within the building to prevent release and personnel exposure.</p>
Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
<p>As stated for groundwater, there is also a potential for historical impact to soils in the area of Building 3047 due to leaking process and LLLW drain piping. Previous environmental studies have identified a soil contamination plume in the Isotopes Circle area and soil samples collected from the plume have detected radioisotopes common to the processes performed in Building 3047. Since, these radioisotopes were common to the processes in many of the other buildings in the area, it is difficult to determine whether waste from Building 3047 has actually contributed to the Isotopes area soil contamination plume based on the information reviewed during this RmSE.</p> <p>It is unlikely, however, that the small quantities of chemicals used in Building 3047 have, or will, significantly impact(ed) soil in the surrounding area.</p>
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
<p>The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:</p> <ul style="list-style-type: none"> • Leaking diesel fuel around the base of the emergency generator is washed away with storm water and is carried away from the facility and potentially the reservation via Fifth and White Oak Creeks. • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment. <p>There is also a potential for assumed lead-containing paint which peels off of the building to be carried away with surface runoff during a rain event. With the exception of the diesel fuel leak, these potential scenarios are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.</p>

<p style="text-align: center;">Worker Safety</p> <p><i>Could the release pose a threat to workers? If yes, please describe.</i></p> <p>Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. Asbestos containing material and PCB items are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.</p>
<p style="text-align: center;">Environmental Receptors</p> <p><i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i></p> <p>No significant immediate threat to environmental receptors within the area surrounding Building 3047 was found to exist as a result of contamination and conditions currently present in the facility.</p>
<p style="text-align: center;">Mitigation</p> <p><i>What action(s) might be taken to abate/prevent release or impacts from release?</i></p> <ul style="list-style-type: none"> • Clean up area of diesel fuel on concrete pad around emergency generator. Identify and repair source of leak. • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building. • Continue S&M activities per Procedure IP-900.
<p><i>What actions are currently being taken to abate/prevent release or impacts from release?</i></p> <p>Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status. The future long-term use of this facility was uncertain at the time of the writing and the building has currently been removed from the IFDP. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3047.</p> <p>Current actions being taken to prevent further release and ensure worker safety in Building 3047 are considered adequate given the current status and level of activity of the facility.</p>

Other Environmental Authorities
<i>Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.</i>
If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).
Maintenance Actions
<i>Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.</i>
One potential hazard requiring a maintenance action was identified to be associated with Building 3047. That is, the diesel fuel leak associated with the emergency generator located adjacent to the northwest wall of the building. The area of fuel around the generator should be cleaned up and the source of the leak should be identified and repaired to prevent further release.
Removal Actions
<i>Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.</i>
No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3047.
Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
Areas of radiologic contamination associated with Building 3047 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.
Asbestos containing material and PCB items have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.
Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3047 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.

Additional Comments

The following documents and databases were referenced for historical and hazard information related to Building 3047:

- Phase 1 Safety Documentation, Radioisotope Development Laboratory, Building 3047 - Hazard Screening, Document No. HS/3047/F/RI-16 (Rev. 1)
- Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2.
- Building 3047 Occurrence Reports, 1989 to present.
- Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1.
- ORNL Hazardous Material Information System Database.
- ORNL Drain System Survey Report for Building 3047.

The following personnel and offices were contacted and provided historical and current use/condition information for Building 3047:

- Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section.
- Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects.
- Ms. Swati Wilson, Manager, ORNL Lead Management Program.
- Mr. Nathan Dunn, Hazardous Material Information System Office.
- Mr. Jade Thomas, ORNL Environmental Compliance Office.
- Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Conant

Evaluator's Signature

6/18/96

Date




Fig. 17. Diagram of Building 3047.

Plant: 3 Division: Department: Building: 3047 Room: HAZ Class: HAZ Rating: WA Code:
Item ID: LIST: Inv Status: Max Comp: to Haz Mat Grp Cd: Phy State: Pressure Cd: Temp Cd: Cont Type Cd:
Date Expiration: MSDS Avail: ORNL

Building: 3047

RECID	** CASNO	Material Name	MMES	CR	Total AT	Total LES	Total KILOGRAMS	No of Items
96439	112246-73-8	(+)-DIP-CHLORIDE	N N	0.0551	0.0250	1		
96448	020439-47-8	(1R,2R)-(-)-1,2-DIAMINOCYCLOHEXANE	N N	0.0044	0.0019	1		
07699	028143-91-1	(1S,2S)-(+)-2-AMINO-1-PHENYL-1',3'-PROPANEDICL	N N	0.0204	0.1000	1		
07022	052075-14-6	(4S,5S)-(-)-4-METHOXYMETHYL-2-METHYL-5-PHENYL-2-OX	N N	0.0110	0.0050	1		
A2689	001099-45-2	(ETHOXCARBONYL)METHYLENE)TRIPHENYLPHOSPHORANE	N N	0.0110	0.0050	1		
96507	000623-82-5	(R)-(+)-3-METHYLGLIPIC ACID	N N	0.0440	0.0199	2		
00038	000079-00-5	1,1,2-TRICHLOROETHANE	N N	0.0431	0.4731	1		
08064	004637-24-5	1,1,1-DIMETHOXY-N,N-DIMETHYLMETHANAMINE	N N	0.2204	0.0999	1		
96469	016355-92-3	1,1,10-DIISODODECANE	N N	0.0551	0.0250	1		
07781	003314-70-5	1,1,12-DIBROMODODECANE	N N	0.0551	0.0249	1		
06499	001663-45-2	1,1-BIS(DIPHENYLPHOSPHINO) ETHANE, 97%	N N	0.0220	0.0100	1		
00098	** 000107-06-2	1,2-DICHLOROBUTANE	N Y N	0.0055	0.0024	1		
A7097	030314-71-5	1,2-DIPALMITOYL-SN-GLYCEROL	N N N	0.0005	0.0002	1		
A7543	001188-58-5	1,2-DISTEAROYL-RAC-GLYCEROL	N N N	0.0002	0.0001	1		
96455	000582-52-5	1,1',5,6-TETRACHLORO-3A,6A-DIPHENYLYGLUCURON	N N N	0.4408	0.1999	2		
96498	051592-06-4	1,1,3,4-ISOPROPYLIDENE-A-D-GLUCOFURANOSE	N N N	0.0022	0.0009	1		
N1SS		1,1,3,4,5,6,6-TETRACHLORO-3A,6A-DIPHENYLYGLUCURON	N N N	0.0004	0.0001	1		
A9590		1,1,3,4,5,6,6-TETRACHLORO-3,17-DICOL 17-ACETATE, 3-	N N N	0.1653	0.0749	1		
05751	000142-28-9	1,1,3-DICHLOROPROpane	N N N	2.2046	1.0000	2		
06199	000096-26-4	1,1,3-DIHYDROXY-2-PROPANONE	N N N	0.1102	0.0499	1		
08511	000627-31-6	1,1,3-DIISOPROPANE	N N N	0.0033	0.0015	2		
A3049	000502-52-3	1,1,3-DIPALMITIN	N N N	0.1102	0.0499	1		
A7432	000628-21-7	1,4-DILODOBUTANE	N N N	0.0551	0.0249	1		
00137	000123-91-1	1,4-DIOXANE	N N N	0.1102	0.0499	1		
07754	000886-66-8	1,1,4-DIBENZYLBUTADIENE	N N N	9.9207	4.5000	2		
96472	000628-77-3	1,1,5-DILODOPENTANE	N N N	0.0110	0.0049	1		
07663	000629-03-8	1,6-DIBROMOHEXANE	N N N	0.1102	0.0499	2		
96470	000629-09-4	1,6-DILODOHEXANE	N N N	0.0551	0.0250	1		
96461	004549-31-9	1,7-DIBROMOHEPTANE	N N N	0.0551	0.0249	1		
07783	004549-32-0	1,8-DIBROMOOCTANE	N N N	0.1102	0.0499	1		
96471	024772-63-2	1,8-DILODOHEPTANE	N N N	0.1102	0.0499	1		
07597	004549-33-1	1,9-DIBROMONONANE	N N N	0.0551	0.0249	1		
07675	002008-75-5	1-(2-CHLOROETHYL)PIPERIDINE MONOHYDROCHLORIDE	N N N	0.0440	0.0199	2		
96484	002252-63-3	1-(4-FLUOROPROPANE)PIPERAZINE	N N N	0.0440	0.0199	2		
03071	000078-77-3	1-BROMO-2-METHYLPROPANE	N N N	0.2204	0.0999	2		
96421	000637-59-2	1-BROMO-3-PHENYLPROPANE	N N N	0.2204	0.0999	2		
07691	006940-78-9	1-BROMO-4-CHLOROBUTANE	N N N	0.4408	0.1999	2		
07664	000693-58-3	1-BROMONONANE	N N N	0.2204	0.1000	1		
07170	000112-89-0	1-BROMOCTADECANE	N N N	0.2204	0.0999	1		
07723	000111-83-1	1-BROMOOCTANE	N N N	0.2204	0.0999	1		
03069	000106-94-5	1-BROMOPROPANE	N N N	0.2204	0.0999	1		
01002	000112-71-0	1-BROMOTRADECANE	N N N	0.2204	0.0999	1		
96431	000765-09-3	1-BROMOTRIDECA	N N N	0.2204	0.0999	1		
96433	000693-67-4	1-BROMOUNDECANE	N N N	0.1102	0.0499	1		
07594	006940-76-7	1-CHLORO-3-IODOPROPANE	N N N	0.2204	0.0999	1		
A4063	000107-84-6	1-CHLORO-3-METHYLBUTANE	N N N	0.2204	0.0999	1		

* indicates MSDS is not available
** indicates MSDS updated within last three months

Plant: 3	Division:	Department:	Building:	3047	Room:	Area:	HAZ Class:	Rating:	WA Code:	Installation:	ORNL
Item ID:	LIST:	Ingredient:	Mix Comp:	to	HAZ Mat	Phy State:	Pressure Cd:	Temp Cd:	Cont Type Cd:	Temp Cd:	WA Code:
Date Expiration:	MSDS Avail:	Inv Status:	MSDS Avail:	MSDS Avail:	MSDS Avail:	MSDS Avail:	MSDS Avail:				
B3404	015731-63-8	1-CHLORO-5-PHENYLPIENTANE			N N	N N	0.0220	0.0100	1		
B3405	071434-68-9	1-CHLORO-6-PHENYLHEXANE			N N	N N	0.0110	0.0050	1		
B3403	071434-47-4	1-CHLORO-7-PHENYLHEPTANE			N N	N N	0.0110	0.0050	1		
B3402	061440-32-2	1-CHLORO-8-PHENYLOCTANE			N N	N N	0.0110	0.0050	1		
B3401	027175-81-1	1-CHLORO-9-PHENYLNONANE			N N	N N	0.0110	0.0050	1		
B3401	*	NISS			N N	N N	0.0440	0.0200	2		
B3401	05851	1-DIETHYLPHOSPHINO-2-DIPHENYLPHOSPHINO-3-DIMETHYLAMINOPROPYL-CARBO DIIMIDE HY			N N	N N	0.0022	0.0110	1		
B3401	08007	1-ETHYL-3-(3-DIMETHYLAMINOPROPYL)-CARBO DIIMIDE HY			N N	N N	0.0010	0.0049	1		
B3401	05769	1-IDIODEDECANE			N N	N N	0.2204	0.0999	1		
B3401	06206	1-ISOPRENNALINE			N N	N N	0.0002	0.0000	1		
A2629	000051-31-0	1-METHYL-3-NITRO-1-NITROSOGUANIDINE			Y N	N N	0.0551	0.0249	1		
A2629	000070-25-7	1-MONOPALMITOYL-RAC-GLYCEROL (C16:0)			N N	N N	0.0046	0.0021	2		
A2629	019670-51-0	1-NITROSO-2-NAPHTHOL			N N	N N	0.4408	0.1998	2		
A2629	01021	100131-91-9			N N	N N	0.0551	0.0249	1		
96525	000104-72-3	1-PHENYLPYPERAZINE			N N	N N	0.0220	0.1000	1		
96525	000092-54-6	10-UNDECENOIC ACID			N N	N N	0.0220	0.1000	1		
A2665	002777-65-3	11-BROMO-1-UNDECANOL			N N	N N	0.1322	0.0599	2		
A2665	07672	11-BROMOUNDECANOIC ACID			N N	N N	0.4408	0.1998	2		
96432	002834-05-1	12-BROMODODECANOIC ACID			N N	N N	0.0330	0.0149	2		
96432	07805	071367-80-3			N N	N N	0.0000	0.0000	2		
96432	096512	14-METHYLPENTADECANOIC ACID			N N	N N	0.0551	0.0250	1		
B3358	004617-02-7	15-HYDROXYPENTADECANOIC ACID			N N	N N	0.044	0.0200	1		
B3444	004617-33-8	16-BROMO-9-HEXADECANOIC ACID			N N	N N	0.0551	0.0249	1		
96531	NISS	000979-02-2			N N	N N	0.0551	0.0250	1		
A2675	000506-13-8	16-DEHYDROREGNENOLONE ACETATE			N N	N N	0.0551	0.0250	1		
06124	017455-13-9	16-HYDROXYHEXADECANOIC ACID			N N	N N	0.0551	0.0250	1		
A2684	000434-22-0	18-CROWN-6			N N	N N	0.0551	0.0250	1		
A2684	0016373-93-6	19-NORTESTERONE			N N	N N	0.0220	0.0100	1		
08375	0016375-93-6	2'-DEOXYADENOSINE MONOHYDRATE			N N	N N	0.0005	0.0002	1		
07888	000951-77-9	2'-DEOXYCYTIDINE			N N	N N	0.0002	0.0000	1		
07499	000961-07-9	2'-DEOXYGUANOSINE			N N	N N	0.0000	0.0000	1		
96558	003709-18-0	2',2',5-TRIMETHYLPROPANE			N N	N N	0.0551	0.0249	1		
03117	000077-76-9	2',2',5-TRIMETHYLOCTANE			N N	N N	0.1023	0.0500	1		
96473	002033-24-1	2,2-DIMETHYL-1,3-DIOXANE-4,6-DIONE			N N	N N	0.0551	0.0249	1		
07750	017587-22-3	2,2-DIMETHYL-6,6,7,7,8,8,8-HEPTAFLUORO 3,5-OCTANED			N N	N N	0.1102	0.0500	1		
07750	000769-39-1	2,3,5,6-TETRAFLUOROPHENOL			N N	N N	0.1023	0.0500	1		
06171	054897-59-5	2,3,5-DIAMINOPROPIONIC ACID MONOHYDROCHLORIDE			N N	N N	0.0110	0.0050	1		
03128	000108-75-8	2,4,6-TRIMETHYLPYRIDINE			N N	N N	0.2204	0.1000	1		
01123	000092-71-7	2,5-DIPHENYL OXAZOLE			N N	N N	0.4408	0.1998	2		
07786	005452-83-5	2-(2-PIPERIDINOETHYL) PYRIDINE			N N	N N	0.0220	0.0100	1		
07696	013472-00-9	2-(4-AMINOPHENYL) ETHYLAMINE			N N	N N	0.0660	0.0299	3		
03154	000124-68-5	2-AMINO-2-METHYL-1-PROPANOL			N N	N N	1.1023	0.5000	1		
06941	007154-66-7	2-BROMOBENZOYL CHLORIDE			N N	N N	0.0220	0.0099	1		
07855	002576-47-8	2-BROMOTHIYLAMINE HYDROBROMIDE			N N	N N	0.2204	0.1000	1		
A6762	004781-83-3	2-IMINOTHIOLANE HYDROCHLORIDE			N N	N N	0.0002	0.0000	1		
96497	000088-67-5	2-LODOBENZOIC ACID			N N	N N	0.0224	0.0100	1		
A4683	NISS	2-IODOPHENYLACETIC ACID			N N	N N	0.0022	0.0099	1		
03214	** 000594-61-6	2-METHYL LACTIC ACID			N N	N N	0.4408	0.1998	3		
A2680	** 003433-37-2	2-PIPERIDINEMETHANOL			N N	N N	0.0551	0.0250	1		
06086	** 000098-03-3	2-THIOPHENECARBOXYLIC ACID			N N	N N	0.2204	0.1000	1		
06087	000527-72-0	2-THIOPHENEGLYOXYLIC ACID			N N	N N	0.0440	0.0204	1		
96550	004075-59-6	2-THIOPHENEGLYOXYLIC ACID			N N	N N	0.0199	0.0030	2		
B4034	** NISS	22,23-BIS(OR-SALPHA-CHOLANIC ACID-3BETA-OL ACETATE			N N	N N	0.0066	0.0030	1		

* indicates MSDS is not available

** indicates MSDS updated within last three months

HAZARDOUS MATERIALS INFORMATION SYSTEM

Management Inventory Summary Report (by Building)

Plant:	3 Division:	Department:	Building:	3047	Room:	Area:	HAZ	Rating:	Temp	Cd:	Cont	Type	Cd:	WA Code:
Item ID:		Control Area:	Mix Comp:	to	Phy State:	Pressure Cd:								UNCLASSIFIED
Date Expiration:		Ingredient:	MSDS Avail:	Haz Mat Grp Cd:										Page: 3 ORNL
		Inv Status:												Installation:
A9585	NISS	23-24-BIS(OR-5-CHOLENIC ACID-3B-OL ACETATE												1
A9586	NISS	23-24-BIS(OR-5-CHOLENIC ACID-3B-OL METHYL ESTER												1
07700	034841-35-5	3,-CHLOROPROPIONE												0.0250
07683	** 00416-82-1	3,-DIMETHYLGLUARIC ANHYDRIDE												0.0268
A4021	** 00016-87-6	3-AMINO-1-PROPANOL												0.0100
07442	000814-75-5	3-BROMO-2-BUTANONE												0.1998
06938	001711-09-7	3-BROMOBENZOYL CHLORIDE												0.2499
06537	000590-92-1	3-BROMOPROPIONIC ACID												0.0499
03253	000107-94-8	3-CHLOROPROPIONIC ACID												0.0249
07782	004166-53-4	3-METHYLGLUTARIC ANHYDRIDE												0.0249
07124	000641-70-3	3-NITROBUTHATIC ANHYDRIDE												0.0250
A2685	020231-57-6	3B-HYDROXYCHOL-5-EN-24-OIC ACID METHYL ESTER												0.0996
A9066	000070-69-9	4,-AMINOPROPIONE												0.0498
A7681	003647-69-6	4-(2-CHLOROETHYL)MORPHOLINE HYDROCHLORIDE												0.0230
08808	001083-48-3	4-(P-NITROBENZYL)PYRIDINE												0.0500
96517	000140-66-9	4-(TERT-OCTYL)PHENOL												0.0999
08820	000103-90-2	4-ACETAMIDOPHENOL												0.0999
A2690	000063-05-8	4-ANDROSTENE-3,17-DIONE												0.5000
08818	005728-52-9	4-BIPHENYLACETIC ACID												0.0498
96419	005162-44-7	4-BROMO-1-BUTENE												0.0250
96425	001122-91-4	4-BROMOBENZALDEHYDE												0.0100
06940	000586-75-4	4-BROMOBENZOYL CHLORIDE												0.0220
96426	000589-15-1	4-BROMOBENZYL BROMIDE												0.0249
96418	000627-00-9	4-CHLOROBUTYRIC ACID												0.0999
A7100	000352-32-9	4-FLUOROTOLUENE												0.0999
08572	000626-64-2	4-HYDROXYPYRIDINE												0.0299
07646	000100-11-8	4-NITROBENZYL BROMIDE												0.0250
96522	000591-80-0	4-PENTENOIC ACID												0.0249
96523	001200-03-9	4-PHENOXYBUTYL BROMIDE												0.0999
00261	005351-14-3	4-PHENYLTIOSEMICARBAZIDE												0.0250
00207	000104-15-4	4-TOLUENESULFONIC ACID												0.0249
06944	000917-23-7	5,10,15,20-TETRA(21H,23H-PORPHINE												0.0500
A2651	010325-79-8	5-ANDROSTEN-3B-OL-17B-CARBOXYLIC ACID												0.0204
A9583	NISS	5-ANDROSTEN-18B-OL; 17B-CARBOXYLIC ACID METHYL ESTE												0.0099
A2662	001119-51-3	5-BROMO-1-PENTENE												0.0100
06205	000901-57-5	5-BROMO-2'-DEOXYURIDINE												0.0050
A2688	014267-92-6	5-CHLORO-1-PENTENE												0.0500
A9580	019462-13-6	5-CHELONIC ACID-3B-OL ACETATE												0.0010
A9380	NISS	5-METHYLHYDANTOIN												0.0967
96532	001778-02-5	5-PREGNEN-3-B-OL-20-ONE ACETATE												0.0033
96533	000901-57-5	5-PREGNENE-3-B-20-B-DIOL												0.0220
A9578	002276-93-9	5A-CHOLANIC ACID-3B-OL												0.0551
96442	000566-88-1	5A-CHOLESTAN-3-ONE												0.0002
A9577	003110-99-4	5B-CHOLAN-24-OL												0.0110
96441	000546-18-9	5B-CHOLANIC ACID												0.0004
A9579	NISS	5B-CHOLANIC ACID-3A, 12A-DIOL DIACETATE												0.0308
A9581	NISS	5B-CHOLANIC ACID-3A, 12A-DIOL DIACETATE												0.0110
A9582	NISS	5B-CHOLANIC ACID-3A, 12A-DIOL METHYL ESTE												0.0050
B4032	** NISS	5BETA-CHOLAN-24-IODO												0.0030
B4033	** NISS	5BETA-CHOLANIC ACID-3-ALPHA, 7ALPHA, 12ALPHA-TRIOL												0.0002
														0.0551
														0.0250

* indicates MSDS is not available
** indicates MSDS updated within last three months

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)UNCLASSIFIED
Page: 4
Installation: ORNL

Plant: 3 Division: Item ID: Date Expiration:	Department: List: MSDS Avail:	Control Area: Inv Status: MSDS Avail:	Building: 3047 Mix Comp: to Haz Mat Grp Cd:	Room: HAZ Class: Phy State:	Area: HAZ Rating: Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:
96420	002695-47-8	6-BROMO-1-HEXENE	NN	0.1320	0.0599	6		
95719	004224-70-8	6-BROMOHEXANOIC ACID	NN	0.1102	0.0500	2		
96444	001175-06-0	6-KETOCHOLESTANOL	NN	0.0110	0.0049	1		
07462	002430-16-2	6-PHENYL-N-HEXYNOL	NN	0.0220	0.0099	1		
A9361	040228-90-8	7-PHENYLHEPTANOIC ACID	NN	0.0330	0.0150	2		
07677	002695-48-9	8-BROMO-1-OCTENE	NN	0.0551	0.0249	2		
07697	017696-11-6	8-BROMOOCOTANOIC ACID	NN	0.0440	0.0199	2		
00145	000148-24-3	8-HYDROXYQUINOLINE	NN	0.2204	0.1000	1		
03321	000103-84-4	ACETANILIDE	NN	0.0551	0.0249	1		
00015	000064-19-7	ACETIC ACID	NN	25.7847	11.6956	4		
07679	003483-11-2	ACETOACETIC ACID LITHIUM SALT	NN	0.0110	0.0049	1		
96395	000572-09-8	ACETOBROMO-A-D-GLUCOSE	NN	0.1102	0.0499	1		
00677	000067-64-1	ACETONE	NN	0.8686	0.3939	1		
00024	000075-05-8	ACETONITRILE	NN	12.2906	5.5749	2		
00683	000075-16-5	ACETYL CHLORIDE	NN	0.5511	0.2499	1		
01706	000107-02-8	ACROLEIN	NN	1.1023	0.5000	1		
90710	** NISS	ACTIVATED ALUMINA	NN	3.3069	1.5000	2		
05771	000073-24-5	ADENINE	NN	0.0573	0.0259	2		
A7728	020398-54-9	ADENOSINE 5'-DIPHOSPHATE SODIUM	NN	0.0002	0.0000	1		
07312	** 018422-03-4	ADENOSINE 5'-MONOPHOSPHATE MONOHYDRATE	NN	0.0110	0.0050	5		
06548	051963-61-2	ADENOSINE-5'-TRIPHOSPHATE DISODIUM CRYST	NN	0.0088	0.0039	2		
B0031	000622-91-8	ADIPIC ACID MONOMETHYL ESTER	NN	0.1102	0.0500	2		
96397	000488-81-3	ADONITOL	NN	0.0110	0.0049	1		
94664	NISS	AIRCOSIL 12 WHITE	NN	0.0625	14.2883	1		
89621	NISS	AJAX ALL PURPOSE CLEANER (NON- PHOSPHATE)	NN	31.5000	0.0283	1		
A4659	009006-59-1	ALBUMIN, EGG	NN	0.0022	0.0009	1		
08175	070024-90-7	ALBUMIN, HUMAN	NN	0.0110	0.0049	1		
A3183	009048-46-8	ALBUMINS, BLOOD SERUM	NN	0.2446	0.1107	3		
96399	001324-21-6	ALIZARIN, BLUE BLACK B	NN	0.0220	0.0099	1		
03359	000072-48-0	ALIZARINE	NN	0.0220	0.0099	1		
96400	002244-11-3	ALLOXAN MONOHYDRATE	NN	0.0220	0.0099	1		
00743	00411-38-3	ALPHA-BENZOIN OXIME	NN	0.2204	0.0999	1		
96422	005041-21-2	ALPHA-BRONO-GAMMA-BUTYROLACTONE	NN	0.2201	0.1000	10		
07745	000617-04-9	ALPHA-METHYL-D-MANNOPYRANOSIDE	NN	0.2204	0.0999	1		
A4017	007784-26-1	ALUMINUM AMMONIUM SULFATE DODECAHYDRATE	NN	5.2046	2.3605	4		
00269	007446-70-0	ALUMINUM CHLORIDE, ANHYDROUS	NN	5.1750	2.3462	13		
05796	021645-51-2	ALUMINUM HYDROXIDE	NN	2.2046	1.0000	1		
00355	** 007429-90-5	ALUMINUM NITRATE NONAHYDRATE	NN	10.3069	4.6745	10		
00356	** 007784-27-2	ALUMINUM NITRATE	NN	26.5345	12.0358	5		
06477	024304-00-5	ALUMINUM NITRIDE	NN	2.2046	1.0000	1		
00357	001344-28-1	ALUMINUM OXIDE	NN	12.9718	5.8836	11		
A4024	007784-30-7	AMBERLITE ADSORBENT RESINS	NN	1.1.1023	0.5000	1		
87294	NISS	AMERICAN CONTINENTAL MASTER MELT	NN	3.4250	1.5534	3		
A7664	** NISS	AMMONIA	NN	50.0717	22.7124	1		
002273	007664-41-7	AMMONIUM 1-PYRROLIDINECARBODITHIOATE	NN	30.0084	13.6115	4		
06390	005108-96-3	AMMONIUM ACETATE	NN	0.1102	0.0499	2		
00363	000631-61-8	AMMONIUM BICARBONATE	NN	5.0705	2.2999	1		
00364	001066-33-7	AMMONIUM BIFLUORIDE	NN	1.1023	0.5000	1		
00366	001341-49-7	AMMONIUM BROMIDE	NN	7.2046	3.2675	6		
00367	** 012124-97-9		NN	1.1023	0.5000	1		

* indicates MSDS is not available
** indicates MSDS updated within last three months

HAZARDOUS MATERIALS INFORMATION SYSTEM

Management Inventory Summary Report (by Building)

Plant: 3 Division: Department: Control Area: Building: 3047 Room: HAZ Class: Area: HAZ Rating: Page: 5

Item ID: L1SR: Ingredient: Mix Comp: Haz Mat Grp Cd: to Phy State: Pressure Cd: Temp Cd: Cont Type Cd:

Date Expiration: Inv Status: MSDS Avail: WA Code: Installation: ORNL

00369	012125-02-9	AMMONIUM CHLORIDE	N	N	3.5511	1.6104	4
00370	003012-65-5	AMMONIUM CITRATE, DIBASIC	N	N	4.2046	1.9070	3
00287	007789-09-5	AMMONIUM DICROMATE	N	N	1.1023	0.5000	1
02221	013826-83-0	AMMONIUM FLUOBORATE	N	N	5.2046	2.3605	4
02220	** 012125-01-8	AMMONIUM FLUORIDE	N	N	3.2046	1.4535	2
A3269	016919-19-0	AMMONIUM HEXAFLUOROSILICATE	N	N	1.1023	0.5000	1
A7102	007803-63-6	AMMONIUM HYDROGEN SULFATE	N	N	1.0000	0.4535	1
00372	** 001336-21-6	AMMONIUM HYDROXIDE	N	N	4.7674	6	
00374	012027-06-4	AMMONIUM IODIDE	N	N	0.8002	0.3629	2
00375	** 012027-67-7	AMMONIUM NOLYBDATE	N	N	0.7186	0.3259	3
00262	001113-38-8	AMMONIUM OXALATE, ANHYDROUS	N	N	7.2046	3.2675	6
00378	007727-54-0	AMMONIUM PERSULFATE	N	N	2.1023	0.9535	2
06098	007783-28-0	AMMONIUM PHOSPHATE, DIBASIC	N	N	1.1023	0.5000	1
07434	000528-94-9	AMMONIUM SALICYLATE	N	N	0.5511	0.2499	1
00380	007783-20-2	AMMONIUM SULFATE	N	N	2.2046	1.0000	2
00291	007803-55-6	AMMONIUM VANADATE	N	N	1.6014	0.7263	3
NISS	NISS	AMP-1	N	N	3.3069	1.5000	3
A2323	NISS	ANALTECH SILICA GEL GF UNIPATES	N	N	1.0000	0.4535	1
00007	000662-53-3	ANILINE	N	N	3.1023	1.4071	2
00383	** 007440-36-0	ANTIMONY METAL	N	N	1.1023	0.5000	1
00384	010025-91-9	ANTIMONY TRICHLORIDE	N	N	0.8002	0.3629	2
01726	001309-64-4	ANTIMONY TRIOXIDE	N	N	1.1023	0.5000	1
87736	NISS	APTEZON GREASE	N	N	0.0551	0.0250	1
94089	NISS	AREMCO CERAMA-BOND 569	N	N	0.0312	0.0141	1
01730	007440-37-1	ARGON	N	N	3.20	145.5423	10
00311	001332-21-4	ASBESTOS	N	N	0.8817	0.4000	4
92876	NISS	ASHLAND, BUFFER SOLUTION PH 4	N	N	2.2046	1.0000	2
07784	004648-54-8	AZIOTRIMETHYLSILANE	N	N	0.0551	0.0250	1
A3061	000492-61-5	B-D(+)-GLUCOSE	N	N	0.0220	0.0100	1
00386	000513-77-9	BARIUM CARBONATE	N	N	2.0987	0.9520	5
00303	010326-27-9	BARIUM CHLORIDE, DIHYDRATE	N	N	4.2046	1.9070	3
00306	017194-00-2	BARIUM HYDROXIDE	N	N	6.3069	2.8605	5
00293	** 010022-31-8	BARIUM NITRATE	N	N	4.1023	1.8605	4
00454	008012-89-3	BEESWAX	N	N	1.0000	0.4535	1
B0565	000929-77-1	BEHENIC ACID METHYL ACID	N	N	0.0220	0.0099	1
07762	001125-88-8	BENZALDEHYDE DIMETHYL ACETAL	N	N	0.4408	0.1999	2
00001	** 000071-43-2	BENZENE	N	N	8.8294	4.0050	2
06348	** 001076-43-3	BENZENE-D6	N	N	0.0110	0.0049	1
A7095	000531-85-1	BENZODINE DIHYDROCHLORIDE	N	N	0.2204	0.1000	1
00603	000065-85-0	BENZOIC ACID	N	N	0.2755	0.1249	1
00747	000098-88-4	BENZOYL CHLORIDE	N	N	0.5510	0.2498	3
00748	000094-36-0	BENZOYL PEROXIDE	N	N	0.3306	0.1499	2
00078	** 000100-39-0	BENZYL BROMIDE	N	N	0.2204	0.0999	1
00079	000100-44-7	BENZYL CHLORIDE	N	N	0.1102	0.0499	1
96416	000501-53-1	BENZYL CHLOROFORMATE	N	N	0.6613	0.2999	2
06037	000621-08-9	BENZYL SULFOXIDE	N	N	0.0551	0.0250	1
03544	000100-46-9	BENZYLAMINE	N	N	1.1023	0.5000	1
07748	000633-65-8	BERBERINE HYDROCHLORIDE	N	N	0.1100	0.0495	1
00391	007787-55-5	BERYLLIUM NITRATE TRIHYDRATE	N	N	0.2204	0.0998	1
07744	000604-69-3	BETA-D-GLUCOSE PENTAACETATE	N	N	0.4408	0.1998	2

* indicates MSDS is not available
** indicates MSDS updated within last three months

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant:	3 Division:	Department:	Control Area:	Building:	3047	Room:	Area:	HAZ Class:	HAZ Rating:	Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:
Item ID:		List:	Ingredient:	Mix Comp:	to								Installation: ORNL
Date Expiration:		Inv Status:	MSDS Avail:	Haz Mat	Grp Cd:	Phy State:							
00203	000103-63-9	BETA-PHENYLETHYL BROMIDE	NISS	N	N	0.4409	0.1999						
92250	NISS	BIG "D" WATER SOLUBLE DEODORANT	NISS	N	N	41.3100	18.7381						
95639	NISS	BIO-RAD AG 50W-X2, -X4, -X8, -X12, AND -X16	NISS	N	N	22.4717	10.1920						
93224	NISS	BIO-RAD AG 1-X2, -X4, -X8 RESIN AND MSZ-1	NISS	N	N	21.1570	9.5954						
93223	NISS	BIO-RAD AG11A8	NISS	N	N	1.0000	0.4535						
A4106	NISS	BIO-RAD ANION EXCHANGE RESIN (AG11 X10)	NISS	N	N	2.0000	0.9070						
A4108	NISS	BIO-RAD BIO-REX 9	NISS	N	N	1.0000	0.4535						
A0833	NISS	BIO-RAD BIO-REX 70	NISS	N	N	2.0000	0.9070						
A4107	NISS	CATION EXCHANGE RESIN (AG50W X1)	NISS	N	N	1.0000	0.4535						
A6571	NISS	BIO-RAD LABORATORIES AG 2-X8	NISS	N	N	1.0000	0.4535						
93342	NISS	BIO-RAD LABORATORIES AG MP-1	NISS	N	N	1.0000	0.4535						
93379	**	BIO-RAD LABORATORIES AG MP-50	NISS	N	N	3.2046	1.4535						
93543	**	BIO-RAD LABORATORIES AG MP-50	NISS	N	N	2.1023	0.9535						
92434	NISS	BIO-RAD LABORATORIES ALUMINA	NISS	N	N	5.4092	2.4535						
92390	NISS	BIO-RAD LABORATORIES AMINEX	NISS	N	N	4.1876	1.8999						
A4394	NISS	BIO-RAD LABORATORIES CHELEX 100	NISS	N	N	5.0000	2.2675						
96440	000821-48-7	BIS(2-CHLOROETHYL) AMINE HYDROCHLORIDE	007787-60-2	N	N	1.3227	0.6000						
00392	007440-69-9	BISMUTH CHLORIDE	00392	N	N	0.0551	0.0249						
06841	050632-95-4	BISMUTH METAL	06841	N	N	0.2204	0.0999						
00332	0010043-35-3	BOC-ON BORIC ACID	00332	N	N	0.2204	0.0999						
06045	000109-63-7	BORON TRIFLUORIDE ETHERATE	06045	N	N	0.0551	0.0249						
00395	007726-95-6	BROMINE	00395	N	N	3.3069	1.5000						
002032-35-1	002032-35-1	BROMOACETALDEHYDE DIETHYL ACETAL	002032-35-1	N	N	0.2204	0.0999						
A8942	NISS	BROMOACETONE	00338	N	N	0.0551	0.0250						
96424	022118-09-8	BROMOACETYL CHLORIDE	00338	N	N	0.3602	0.1633						
83616	000076-59-5	BROMOTHYMOL BLUE	003616	N	N	0.4408	0.1999						
86344	NISS	BUFFER SOLUTION PH 10.00	86344	N	N	0.0022	0.0009						
89878	NISS	BUFFER SOLUTION PH 7.00	89878	N	N	2.2046	1.0000						
00046	010108-64-9	BULLEN HI-SEPT	00046	N	N	2.2046	1.0000						
00397	007440-43-9	CADMIUM CHLORIDE	00397	N	N	10.4316	4.7317						
A4027	010124-36-4	CADMIUM METAL	A4027	N	N	0.8002	0.3629						
00400	000471-34-1	CADMIUM SULFATE ANHYDROUS	00400	N	N	1.6005	0.7260						
00401	**	CALCIUM CARBONATE	00401	N	N	0.2204	0.0999						
06406	010035-04-8	CALCIUM CHLORIDE DIHYDRATE	06406	N	N	3.2046	1.4535						
A7113	012007-99-7	CALCIUM HEXABORIDE	A7113	N	N	1.1023	0.5000						
00404	007778-54-3	CALCIUM HYPOCHLORITE	00404	N	N	0.3306	0.1500						
00405	**	CALCIUM METAL	00405	N	N	0.5511	0.2499						
00407	**	CALCIUM NITRATE	00407	N	N	3.9483	1.7910						
00409	001305-78-8	CALCIUM OXIDE	00409	N	N	5.1023	2.3140						
00410	007778-18-9	CALCIUM SULFATE, ANHYDROUS	00410	N	N	4.3148	1.9570						
00692	**	CARBON (GRAPHITE, SYNTHETIC)	00692	N	N	5.2046	2.3605						
00786	000075-15-0	CARBON DISULFIDE	00786	N	N	1.1023	0.5000						
00151	000558-13-4	CARBON TETRABROMIDE	00151	N	N	0.2204	0.0999						
07168	009000-11-7	CARBOXYMETHYL CELLULOSE ETHER	07168	N	N	0.2204	0.1000						
07931	009001-05-2	CATALASE	07931	N	N	0.0044	0.0019						
07658	000274-07-7	CATECHOLBORANE	07658	N	N	0.4408	0.1998						
07623	009004-34-6	CELLULOSE ACETATE	07623	N	N	1.1023	0.5000						
00790	009004-35-7	CELLULOSE ACETATE	00790	N	N	2.2046	1.0000						

* indicates MSDS is not available
** indicates MSDS updated within last three months

Plant: 3 Division: Item ID: Date Expiration:	Department: List:	Control Area: Ingredient: MSDS Avail:	Building: 3047 Inv Status:	Room: Comp: to Haz Mat Grp Cd:	HAZ Class: Phy State:	Area: Pressure Cd:	HAZ Rating: Temp Cd:	Installation: ORNL WA Code:	Cont Type Cd:
00412	016775-21-3	CERIUM AMMONIUM NITRATE	NN	NN	NN	NN	2-2046 1.0000	1	1.0000
03689	001306-38-3	CERIUM OXIDE	NN	NN	NN	NN	0.4535 1.1023	1	0.4535
00413	007790-86-5	CERIUM(II) CHLORIDE	NN	NN	NN	NN	0.5000 1.5621	1	0.5000
06217	010294-41-4	CERIUM(III) NITRATE, HEXAHYDRATE	NN	NN	NN	NN	0.7080 1.1023	6	0.7080
07049	013590-82-4	CERIUM(IV) SULFATE	NN	NN	NN	NN	0.5000 1.1023	1	0.5000
00415	007647-17-8	CERIUM(IV) CHLORIDE	NN	NN	NN	NN	0.5500 1.1023	1	0.5500
00416	007789-18-6	CERIUM NITRATE	NN	NN	NN	NN	0.0551 1.1023	1	0.0551
06558	010294-54-9	CERIUM SULFATE	NN	NN	NN	NN	0.0250 1.1023	1	0.0250
00792	000544-77-4	CETYL IODIDE	NN	NN	NN	NN	0.5000 1.1023	1	0.5000
A0869	07139	CETYLITE INDUSTRIES CETYLCLIDE	NN	NN	NN	NN	0.0249 1.1023	1	0.0249
06392	068647-86-9	CHARCOAL, ACTIVATED	NN	NN	NN	NN	16.0000 1.1023	3	1.4904
96436	006003-94-7	COCONUT CHELIDONIC ACID MONOHYDRATE	NN	NN	NN	NN	7-2046 1.1023	13	7.2564
00281	007782-50-5	CHLORINE	NN	NN	NN	NN	0.0551 1.1023	7	3.2675
A4028	000078-95-5	CHLOROACETONE	NN	NN	NN	NN	10.0000 1.1023	1	0.0249
00173	000079-04-9	CHLOROACETYL CHLORIDE	NN	NN	NN	NN	10.0000 1.1023	1	4.5359
00016	000067-66-3	CHLOROFORM	NN	NN	NN	NN	0.0999 1.1023	1	0.0999
05914	000865-49-6	CHLOROFORM-D	NN	NN	NN	NN	0.0500 1.1023	1	0.0500
07685	005293-84-5	CHLOROMETHYLTRIPHENYLPHOSPHONIUM CHLORIDE	NN	NN	NN	NN	10.4542 1.1023	2	4.7419
00108	016941-12-1	CHLOROPALATINIC ACID	NN	NN	NN	NN	0.2644 1.1023	2	0.1199
07670	001529-47-1	CHLOROTRIMETHYLGERMANE	NN	NN	NN	NN	0.0500 1.1023	2	0.0500
05772	** 000075-77-4	CHLOROTRIMETHYLSILANE	NN	NN	NN	NN	0.0036 1.1023	1	0.0036
03796	000057-88-5	CHOLESTEROL	NN	NN	NN	NN	0.0110 1.1023	1	0.0110
A2649	000516-91-6	CHOLESTERYL BROMIDE	NN	NN	NN	NN	0.081 1.1023	1	0.081
07151	000601-34-3	CHOLESTERYL PALMITATE	NN	NN	NN	NN	0.0110 1.1023	1	0.0110
00340	001787-61-7	CHROME BLACK T	NN	NN	NN	NN	0.0220 1.1023	1	0.0220
00319	007738-94-5	CHROMIC ACID	NN	NN	NN	NN	0.0049 1.1023	1	0.0049
00286	007789-02-8	CHROMIC NITRATE NONAHYDRATE	NN	NN	NN	NN	5.5114 1.1023	1	2.4999
007440-47-3	007440-47-3	CHROMIUM METAL	NN	NN	NN	NN	0.2204 1.1023	1	0.2204
02295	001308-38-9	CHROMIUM(III) OXIDE	NN	NN	NN	NN	5.5000 1.1023	1	0.5000
01813	015663-27-1	CIS-PLATIN	NN	NN	NN	NN	2.6454 1.1023	4	2.3605
03821	000077-92-9	CITRIC ACID	NN	NN	NN	NN	0.0000 1.1023	1	0.0000
00421	007440-48-4	COBALT METAL	NN	NN	NN	NN	23.8184 1.1023	9	10.8039
00422	017726-22-9	COBALT NITRATE HEXAHYDRATE	NN	NN	NN	NN	0.8000 1.1023	2	0.3629
00420	0017791-13-1	COBALT(II) CHLORIDE, HEXAHYDRATE	NN	NN	NN	NN	0.2204 1.1023	1	0.2204
95221	NISS	COLD KILL WASP/HORNET KILLER #297852	NN	NN	NN	NN	0.0999 1.1023	1	0.0999
86089	** NISS	COMPRESSED AIR	NN	NN	NN	NN	0.5000 1.1023	2	0.5000
02316	007758-42-6	COPPER CHLORIDE	NN	NN	NN	NN	1.0646 1.1023	2	1.0646
00424	007440-50-8	COPPER METAL	NN	NN	NN	NN	12.3102 1.1023	1	12.3102
00430	001317-38-0	COPPER(II) OXIDE	NN	NN	NN	NN	0.5000 1.1023	1	0.5000
81444	NISS	CRC-2-26 (AEROSOL)	NN	NN	NN	NN	1.4535 1.1023	2	1.4535
02326	000548-62-9	CRYSTAL VIOLET	NN	NN	NN	NN	0.0651 1.1023	1	0.0651
00257	007447-39-4	CUPRIC CHLORIDE	NN	NN	NN	NN	0.2204 1.1023	1	0.2204
00277	007758-98-7	CUPRIC SULFATE	NN	NN	NN	NN	0.9535 1.1023	2	0.9535
06450	007787-70-4	CUPROUS BROMIDE	NN	NN	NN	NN	2.2046 1.1023	1	2.2046
A4026	000108-85-0	CYCLOHEXYL BROMIDE	NN	NN	NN	NN	0.2204 1.1023	1	0.2204
05928	00065-46-3	CYTIDINE	NN	NN	NN	NN	0.1653 1.1023	1	0.1653
A4661	081012-87-5	CYTIDINE 5'-TRIPHOSPHATE SODIUM TYPE I	NN	NN	NN	NN	0.0002 1.1023	1	0.0002
A3048	034393-59-4	CYTIDINE 5'-DIPHOSPHATE TYPE I SODIUM SALT	NN	NN	NN	NN	0.0000 1.1023	1	0.0000
06693	000071-30-7	CYTOSINE	NN	NN	NN	NN	0.0000 1.1023	1	0.0000
		*	indicates MSDS is not available						
		**	indicates MSDS updated within last three months						

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant: 3 Division: Item ID: Date Expiration:	Department: List:	Control Area: Ingredient: MSDS Avail:	Building: 3047 Mix Comp: Haz Mat Grp Cd:	Room: HAZ Class: Phy State:	Area: HAZ Rating: Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:	Installation:	Page: 8 ORNL
A3050	005796-17-8	D-3,4-DIHYDROXYPHENYLALANINE		N N	0.0002	0.0000				1
96398	000138-69-2	D-ALANINE		N N	0.0002	0.0000				1
96404	009000-88-8	D-AMINO ACID OXIDASE		N N	0.0022	0.0009				1
96410	000488-82-4	D-ARABINOTOL		N N	0.0022	0.0009				1
96412	002058-58-4	D-ASPARAGINE MONOHYDRATE		N N	0.0022	0.0009				1
96413	001783-96-6	D-ASPARTIC ACID		N N	0.0002	0.0000				1
96446	000349-46-2	D-CYSTINE		N N	0.0002	0.0000				1
00825	000050-99-7	D-GLUCOSE		N N	0.0002	0.0000				1
A2626	006893-26-1	D-GLUTAMIC ACID		N N	5.7540	2.6099				5
96488	000351-50-8	D-HISTIDINE		N N	0.0002	0.0000				1
08811	000319-78-8	D-ISOLEUCINE		N N	0.0002	0.0000				1
96500	000328-38-1	D-LEUCINE		N N	0.0002	0.0000				1
96505	000348-67-4	D-METHIONINE		N N	0.0002	0.0000				1
96516	000327-56-0	D-NORLEUCINE		N N	0.0002	0.0000				1
A2627	000673-06-3	D-PHENYLALANINE		N N	0.0002	0.0000				1
96538	000312-84-5	D-SERINE		N N	0.0002	0.0000				1
96551	000632-20-2	D-THREONINE		N N	0.0002	0.0000				1
96564	000153-94-6	D-TRYPTOPHAN		N N	0.0002	0.0000				1
96566	000640-68-6	D-VALINE		N N	0.0002	0.0000				1
06794	000605-65-2	DANSYL CHLORIDE		N N	0.0002	0.0000				1
89518	NISS	DAP 33 GLAZING		N N	0.0044	0.0019				2
96450	012609-80-2	DEAE-SEPHADEX		N N	4.5899	0.8189				1
05884	009013-34-7	DEAE-CELLULOSE		N N	0.2204	0.0999				1
A2647	000053-43-0	DEHYDROISOANDROSTEROONE		N N	1.6534	0.7500				1
96454	000058-28-6	DESIPRAMINE HYDROCHLORIDE		N N	0.0551	0.0250				1
88011	NISS	DETEK FLUORESCENT PIGMENT		N N	0.02204	0.0999				1
A0222		DEVCON 5-MINUTE EPOXY HARDENER (91081) AND RESIN (90		N N	0.7161	0.3245				1
		DEVCON 5-MINUTE EPOXY RESIN		N N	0.0651	0.0295				1
09511	NISS	DI-N-PROPYLAMINE		N N	0.2204	0.0999				2
03916	000142-84-7	DI-N-PROPYLAMINE		N N	0.2204	0.0999				1
06153	000080-11-5	DIAZALD		N N	0.2204	0.0999				1
80834	000103-49-1	DIBENZYLAMINE		N N	0.2204	0.0999				1
96460	005671-55-1	DIBROMOBORANE-METHYL SULFIDE COMPLEX		N N	0.2204	0.0999				1
00177	000079-36-7	DICHLOROACETYL CHLORIDE		N N	0.2204	0.0999				1
A1865	000075-43-4	DICHLOROFUOROMETHANE		N N	0.2204	0.0999				1
A1022	000101-83-7	DICYCLOHEXYLAMINE		N N	2.5648	1.1634				2
01876	000111-42-2	DIETHANOLAMINE		N N	0.5511	0.2499				1
96463	029263-94-3	DIETHYL 2-BROMO-2-METHYLMALONATE		N N	0.2204	0.0999				1
06220	002049-80-1	DIETHYL ALYLMALONATE		N N	0.1653	0.0749				3
96464	000607-81-8	DIETHYL BENZYLALONATE		N N	0.0551	0.0249				1
A4018	000685-87-0	DIETHYL BROMOMALONATE		N N	0.0551	0.0249				1
A9379	NISS	DIETHYL BROMOMETHYLALONATE		N N	0.1210	0.0550				10
96468	000133-08-4	DIETHYL BUTYLMALONATE		N N	0.4408	0.1999				1
00883	000060-29-7	DIETHYL ETHER		N N	0.7863	0.3566				2
96465	001462-12-0	DIETHYL ETHYLIDENEMALONATE		N N	0.0110	0.0049				1
07725	000133-13-1	DIETHYL ETHYLALONATE		N N	0.2204	0.0999				1
96466	006326-44-9	DIETHYL FORMAMIDOMALONATE		N N	0.0551	0.0249				1
96467	000609-08-5	DIETHYL METHYLMALONATE		N N	0.4408	0.1999				2
B4113	* NISS	DIETHYL 5-BROMOPENTYLALONATE		N N	0.0440	0.0200				2
00116	000109-89-7	DIETHYLAMINE		N N	2.3658	1.0730				3
07372	038078-09-0	DIETHYLAminOSULFUR TRIFLUORIDE		N N	0.1102	0.0499				2

* indicates MSDS is not available
** indicates MSDS updated within last three months

Plant: 3 Division: Item ID: Date Expiration:	Department: List: Inv Status:	Control Area: Mix Comp: to Haz Mat Grp Cd:	Building: 3047	Room: HAZ Class: Rating:	Area: Temp Cd:	WA Code:
05922 020624-25-3		DIETHYLDITHIOPCARBAMATE SODIUM TRIHYDRATE	NN	0.2204	0.1000	1
06295 * 000111-46-6		DIETHYLENE GLYCOL	NY	8.8184	4.0000	1
01566 000111-96-6		DIETHYLENE GLYCOL DIMETHYL ETHER	NY	0.5511	0.2499	1
00888 000111-90-0		DIETHYLENE GLYCOL MONOETHYL ETHER	NN	0.2204	0.1999	1
05923 000111-43-6		DIETHYLENETRIAMINEPENTAACETIC ACID	NN	1.1023	0.5000	1
A2669 001605-53-4		DIETHYLPHENYLPHOSPHINE	NN	0.0110	0.0050	1
89999 NISS		DIFCO AGAR NOBLE 0142	NN	0.2500	0.1133	1
90685 NISS		DIFCO AGAR, BACTO 0140	NN	0.2204	0.1133	1
92147 000080-97-7		DIFCO MALTOSE 0168	NN	0.0551	0.1000	1
96443 001191-15-7		DIHYDROCHOLESTEROL	NN	0.2204	0.0249	1
96459 000108-18-9		DIISOBUTYLAUIMINUM HYDRIDE	NN	0.0999	0.0999	1
00875 000067-78-1		DIMETHYL SULFATE	NN	2.2046	1.0000	2
00034 000067-66-5		DIMETHYL SULFOXIDE	NN	1.1023	0.5000	1
00017 000128-04-1		DIMETHYLDITHIOPCARBAMATE, SODIUM SALT HYDRATE	NN	6.6448	3.0139	6
A7502 000068-12-2		DIMETHYLFORMAMIDE	NN	0.4408	0.2000	2
00850 000095-45-4		DIMETHYLGLYOXIME	NN	7.4713	3.8888	7
96475 000672-66-2		DIMETHYLPHENYLPHOSPHINE	NN	1.1030	0.5003	3
06141 000577-11-7		DIOMETHYL SODIUM SULFOSUCCINATE	NN	0.0220	0.0099	1
96476 001666-13-3		DIPHENYL DISILENIDE	NN	1.0000	0.4535	1
A7112 032294-60-3		DIPHENYL DITELLURIDE	NN	0.0660	0.0299	3
02580 007789-00-6		DIPOTASSIUM CHROMATE	NN	0.0440	0.0200	4
00679 003483-12-3		DITHIOTIORETTOL	NN	2.1023	0.9535	2
00873 * *	000086-10-6	DITHIZONE	NN	0.0110	0.0050	2
00579 001314-36-9		DIYTITRUM TRIOXIDE	NN	0.0771	0.0348	2
A3058 016742-48-6		DL-A-HYDROXYARACHIDIC ACID	NN	0.1100	0.0499	4
96494 00501-55-3		DL-A-HYDROXYMYRISTIC ACID	NN	0.0001	0.0000	1
A3057 00764-67-0		DL-A-HYDROXYPALMITIC ACID	NN	0.0001	0.0000	1
96493 000629-22-1		DL-A-HYDROXYSTEARIC ACID	NN	0.0001	0.0000	1
B1380 073548-70-6		DL-A-PHOSPHATIDYL-DL-GLYCEROL-DIPALMITOYL AMMONIUM	NN	0.0000	0.0000	1
96489 001927-25-9		DL-HOMOSERINE	NN	0.0000	0.0000	1
96539 005619-04-5		DL-SERINE METHYL ESTER HCL	NN	0.6613	0.2999	2
07668 001077-28-7		DL-THIOCTIC ACID	NN	0.3744	0.1699	9
07656 000123-01-3		DODECYLBENZENE	NN	0.0011	0.0004	1
07715 ** 000062-31-7		DOPAMINE CHLORIDE	NN	0.0330	0.0149	1
A5523 NISS		DOW CHEMICAL DOWEX (R) 2XB 50-100 MESH, CL ANION E	NN	0.0220	0.0099	1
85494 NISS		DOW CORNING SILICONE RUBBER PAINTABLE SEALANT 8644	NN	3.0000	1.3605	3
A1304 NISS		DOW CORNING (R) 111 COMPOUND	NN	0.1875	0.0850	1
81320 ** NISS		DOW CORNING (R) 3140 RTV CORTING	NN	0.3306	0.1500	1
88601 NISS		DOW CORNING (R) 321 DRY FILM LUBRICANT - AEROSOL	NN	0.1955	0.0887	1
82356 NISS		DOW CORNING (R) 705 DIFFUSION PUMP FLUID	NN	1.4342	0.6506	2
87241 NISS		DOW CORNING (R) HIGH VACUUM GREASE	NN	1.1023	0.5000	1
A3194 NISS		DOWEX 1 X 10	NN	1.4132	0.6407	8
89343 NISS		DOWEX 1-X 20-50 MESH IONIC FORM CL	NN	1.0000	0.4535	1
95243 NISS		DOWEX (R) 50WX4, 50-100 MESH, CL ANION EXCHANGE RES	NN	4.2046	1.9070	4
82358 NISS		DOWEX (R) 50WX8, 100-200 MESH, H CATION EXCHANGE RES	NN	1.1023	0.5000	1
82359 NISS		DOWEX (R) 50WX8, 100-200 MESH, H CATION EXCHANGE RES	NN	2.1023	0.4535	1
89342 NISS		DULCITOL	NN	10.4770	0.9535	2
96477 000608-66-2		DULCITOL	NN	0.0223	0.0099	23

* indicates MSDS is not available
** indicates MSDS updated within last three months

** indicates MSDS is not available
*** indicates MSDS updated within last three months

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant: 3	Division:	Department:	Control Area:	Building: 3047	Room:	Area:	HAZ Class:	Rating:	WA Code:	Installation: ORNL	Page: 12
Item ID:	Expiration:	Inv Status:	Ingredient: MSDS Avail:	Mix Comp: to Haz Mat Grp Cd:	Phy State:	Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:	UNCLASSIFIED	Page: 12
82459	NISS	KEL-SAN UTILITY CLEANER (AEROSOL)	N Y	1.4669	0.6654	1					
A8986	NISS	KEL-SAN UTILITY CLEANER (LIQUID)	N Y	10.2229	0.6371	1					
89624	NISS	KETANSERIN TARTARATE	N Y	11.7877	5.3468	1					
A2181	038345-83-7	KOH-I-NOOR 084 RAPIDRAW INK	N Y	0.0001	0.0000	1					
94012	NISS	L(+)-LACTIC ACID	N Y	0.5856	0.2652	12					
96499	000079-33-4	L(+)-ARGININE MONOHYDROCHLORIDE	N Y	0.0110	0.0049	1					
00733	001119-34-2	L-(+)-GLUTAMIC ACID	N Y	0.0022	0.0010	1					
04345	000056-86-0	L-A-PHOSPHATIDYLCHOLINE, DIMYRISTOYL	N Y	0.2226	0.1010	2					
A30952	018194-24-6	L-A-PHOSPHATIDYLETHANOLAMINE, TYPE I FROM BOVINE BRAIN	N Y	0.0002	0.0000	1					
B3995	** NISS	L-A-PHOSPHATIDYLINOSITOL AMMONIUM FROM BOVINE LIVER	N Y	0.0000	0.0000	1					
94808	NISS	L-ALANINE	N Y	0.0000	0.0000	1					
B3364	NISS	L-AMINO ACID OXIDASE	N Y	0.0022	0.0010	1					
08128	000056-41-7	L-ARABINOTOL	N Y	0.0002	0.0000	1					
05838	009000-89-9	L-ASPARAGINE	N Y	0.0022	0.0009	1					
96411	007643-75-6	L-ASPARTIC ACID	N Y	0.0022	0.0009	1					
06671	000070-47-3	L-CYSTEINE	N Y	0.0022	0.0009	1					
07652	000056-84-8	L-CYSTEINE	N Y	0.0022	0.0009	1					
06785	000052-90-4	L-GLUTAMINE	N Y	0.0022	0.0010	1					
04347	000056-89-3	L-GLUTIDINE MONOHYDROCHLORIDE MONOHYDRATE	N Y	0.0022	0.0010	1					
06393	000056-85-9	L-HISTIDINE MONOHYDROCHLORIDE MONOHYDRATE	N Y	0.0022	0.0009	1					
08129	007048-02-4	L-HOMOSERINE	N Y	0.0022	0.0010	1					
96490	000672-15-1	L-ISOLEUCINE	N Y	0.0550	0.0249	3					
08130	000073-32-5	L-LEUCINE	N Y	0.0022	0.0010	1					
07621	000061-90-5	L-METHIONINE	N Y	0.0022	0.0010	1					
07358	000056-87-1	L-PENICILLAMINE	N Y	0.0022	0.0010	1					
07716	000063-68-3	L-PHENYALANINE	N Y	0.0022	0.0010	1					
07761	001113-41-3	L-PROLINE	N Y	0.0022	0.0009	1					
07198	000063-91-3	L-SERINE	N Y	0.0022	0.0010	1					
07607	000147-85-3	L-SERINE METHYL ESTER HCL	N Y	0.0022	0.0010	1					
07606	000056-45-1	L-TYROSINE	N Y	0.0022	0.0010	1					
09650	005680-80-8	L-VALINE	N Y	0.0022	0.0010	1					
05880	000072-19-5	LACTIC ACID	N Y	0.2204	0.0999	1					
05883	000073-22-3	L-SERINE	N Y	0.0022	0.0010	1					
04346	000060-18-4	L-THEONINE	N Y	0.0022	0.0010	1					
08132	000072-18-4	L-TYROSINE	N Y	0.0022	0.0010	1					
00630	000050-21-5	LANTHANUM NITRATE HEXAHYDRATE	N Y	0.1023	0.5000	1					
00448	** 010277-43-7	LANTHANUM OXIDE	N Y	1.0000	0.4535	1					
04359	001312-81-8	LARYN BROMIDE	N Y	1.0023	0.5000	1					
00964	000143-15-7	LECITHIN	N Y	0.2204	0.0999	1					
08224	015082-28-7	LEAD ACETATE	N Y	0.2204	0.0999	1					
06322	000301-04-2	LEAD METAL	N Y	2.3523	1.0668	3					
00265	007439-92-1	LEAD NITRATE	N Y	1.1023	0.5000	1					
00302	010099-74-8	LEAD OXIDE	N Y	1.0000	0.4535	1					
06352	001335-25-7	LITHIUM ACETYLIDE, ETHYLENEDIAMINE COMPLEX	N Y	0.2204	0.0999	1					
04379	008002-43-5	LITHIUM ALUMINUM HYDRIDE	N Y	0.0551	0.0249	1					
07117	006867-30-7	LITHIUM AZIDE	N Y	0.0551	0.0249	1					
00250	016853-85-3	LITHIUM CARBONATE	N Y	7.3602	3.3185	5					
08060	019597-69-4	LITHIUM CHLORIDE	N Y	13.2046	5.9889	8					

* indicates MSDS is not available

** indicates MSDS updated within last three months

96501	004111-54-0	LITHIUM DIISOPROPYLAMIDE	NN	0.2204	0.1000	1
00457	** 007789-24-4	LITHIUM FLUORIDE	NN	1.1023	0.5000	1
05745	001310-66-3	LITHIUM HYDROXIDE	NN	10.0705	4.5678	2
00461	** 007790-69-4	LITHIUM NITRATE	NN	4.2046	1.3070	3
06833	** 012057-24-8	LITHIUM OXIDE	NN	0.1102	0.0499	1
04392	** 010377-18-7	LITHIUM SULFATE	NN	0.2204	0.0999	1
B3479	123334-21-4	LITHIUM TETRACHLOROPALLADATE (II) HYDRATE	NN	0.0110	0.0050	1
A2682	017476-04-9	LITHIUM TRI-TERT-BUTOXYALUMINOHYDRIDE, 0.5M SOLUTI	NN	0.0551	0.0250	1
07800	022560-16-3	LITHIUM TRIETHYLBOROHYDRIDE	NN	1.5429	0.6995	5
A2686	000434-13-9	LITHOCHOLIC ACID	NN	0.0771	0.3253	2
92963	NISS	LPS (R) 1 GREASELESS LUBRICANT	NY	0.7171	0.3844	1
82376	NISS	LUBRI-BOND(R) AEROSOL, 10-601	YY	0.8475	0.2068	4
82986	NISS	LUBRIPATE "130" SERIES	YY	0.4560	0.0022	1
07316	058366-64-6	LUTEINIZING HORMONE RELEASING HORMONE ACETATE GAMM	NN	5.3769	2.4389	6
00465	007439-95-4	MAGNESIUM METAL	NN	2.2125	0.9535	2
00466	** 010377-60-3	MAGNESIUM NITRATE DODECAHYDRATE	NN	1.1023	0.035	3
00467	001309-48-4	MAGNESIUM OXIDE	NN	10.0705	4.5678	2
00468	010004-81-8	MAGNESIUM PERCHLORATE ANHYDROUS	NN	15.1887	2.3534	4
04133	001343-88-0	MAGNESIUM SILICATE (FLORISIL)	NN	1.0000	0.4535	1
00469	007487-88-9	MAGNESIUM SULFATE ANHYDROUS	NN	0.0551	0.0249	1
06579	** 010034-99-8	MAGNESIUM SULFATE HEPTAHYDRATE	NN	0.1102	0.0500	1
00632	000110-16-7	MALEIC ACID	NN	0.044	0.0019	1
00633	000108-31-6	MALEIC ANHYDRIDE	NN	1.1023	0.1999	2
07738	000541-59-3	MALEIMIDE	NN	0.2204	0.5000	1
00227	000141-82-2	MALONIC ACID	NN	0.044	0.0019	1
00470	013446-34-9	MANGANESE CHLORIDE, TETRAHYDRATE	NN	0.4408	0.1023	1
00471	001313-13-9	MANGANESE DIOXIDE	NN	3.2046	1.4535	2
00473	010034-96-5	MANGANESE SULFATE, MONOHYDRATE	NN	1.1023	0.5000	1
94734	NISS	MARSH T- GRADE DYE TYPE MARKING PEN INK, ALL COLORS	NN	0.2334	0.1058	1
82978	NISS	MARVEL MYSTERY OIL	NN	0.2607	0.1182	1
00270	007487-94-7	MERCURIC CHLORIDE	NN	1.0493	0.4759	3
00300	010045-94-0	MERCURIC NITRATE	NN	1.1023	0.5000	1
04446	010415-75-5	MERCURUS NITRATE	NN	0.5511	0.2500	1
08296	007783-34-8	MERCURY(II) NITRATE MONOHYDRATE	NN	0.0661	0.0999	1
04443	021908-53-2	MERCURY(II) OXIDE	NN	0.044	0.0019	1
08227	000304-55-2	MESO-2,3-DIMERCAPTOsuccinic ACID	NN	0.2204	0.0249	1
01968	000072-33-3	METHANE	NN	0.044	0.0019	1
04464	000075-75-2	METHANESULFONIC ACID	NN	0.2204	0.0249	1
96504	007143-01-3	METHANESULFONIC ANHYDRIDE	NN	0.0551	0.0009	1
00318	008032-32-4	METHANOL	NN	16.6326	7.5444	3
04467	000625-45-6	METHOXYACETIC ACID	NN	0.1102	0.0499	1
A7241	NISS	METHYL 3-HYDROXYTETRADECANONATE	NN	0.0000	0.0000	1
07669	002905-65-9	METHYL 4-CHLOROBENZOATE	NN	0.4408	0.1998	2
07787	005454-83-1	METHYL 5-BROMOVALERATE	NN	0.0771	0.0349	2
00055	000096-33-3	METHYL ACRYLATE	NN	1.1023	0.5000	1
00197	000096-32-2	METHYL BROMOACETATE	NN	0.0551	0.0249	1
B3605	001120-28-1	METHYL EICOSANONE	NN	34.4295	0.0099	1
96508	** 000078-93-3	METHYL ETHYL KETONE	NN	0.022	0.6171	2
A2672	006064-90-0	METHYL HENEICOSANOATE	NN	0.0330	0.0009	1
	001731-92-6	METHYL HEPTADECANOATE	NN	0.0149	0.0149	3

** indicates MSDS is not available
** indicates MSDS is updated within last three months

HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)UNCLASSIFIED
Page: 14

Plant: 3 Division: Item ID: Date Expiration:	Department: List:	Control Area: MSDS Avail:	Building: 3047 Mix Comp: to Haz Mat Grp Cd:	Room: Class: Phy State:	Area: HAZ Rating: Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:	Installation: ORNL
04482	000106-70-7	METHYL-HEXANOATE							
00979	000108-10-1	METHYL ISOBUTYL KETONE							
B3361	000056-61-6	METHYL ISOTHOIACYANATE							
04473	000111-82-0	METHYL LAURATE							
B4112	** 000112-63-0	METHYL LINOLEATE							
04483	000124-10-7	METHYL MYRISTATE							
04485	001731-84-6	METHYL MYRISTATE							
04486	000111-11-5	METHYL OCTANOATE							
01911	000112-62-9	METHYL OLEATE							
00517	** 000547-58-0	METHYL ORANGE							
04474	000553-90-2	METHYL OXALATE							
04488	000112-39-0	METHYL PALMITATE							
00544	000493-52-7	METHYL PEG							
04475	** 000112-61-8	METHYL STEARATE							
A9198	001731-86-8	METHYL UNDECANOATE							
B4110	** 000111-81-9	METHYL UNDECYLENATE							
A9378	NISS	METHYL-11-BROMONONDECYLATE							
A7239	000141-23-1	METHYL-12-HYDROXYSTEARATE							
07719	000097-30-3	METHYL-12-HYDROXYSTEARATE							
00971	000109-83-5	METHYLAL- <i>D</i> -GLUCOPYRANOSIDE							
07065	** 000061-73-4	METHYLENE BLUE							
00025	000075-09-2	METHYLENE CHLORIDE							
05782	005137-55-3	METHYLTRIOCTYLAMMONIUM CHLORIDE							
07769	001779-49-3	METHYLTRIPHENYLPHOSPHONIUM BROMIDE							
A1291	NISS	MIDLAB DUST MOP & CLOTH TREATMENT							
06436	** 008042-17-5	MINERAL OILS							
04399	008020-83-5	MIXED BED RESIN M-614 16-50 MESH, IONIC FORM H/OH							
91821	08113-3-20-2	MIXED BED RESIN M-614 16-50 MESH, IONIC FORM H/OH							
00479	007439-98-7	MOLYBDENUM (VI) OXIDE							
04519	001313-27-5	MOLYBDENUM (VI) OXIDE (85%)							
00342	007782-91-4	MORPHOLINE							
00122	000110-91-8	N,N',N',N'-TETRAMETHYLDIAMINOMETHANE							
06118	000051-80-9	N,N-DIETHYLTRIMETHYLSILYLAMINE							
A5010	000996-50-9	N-AMYL BROMIDE							
00723	000110-53-2	N-BENZYL METHYLAMINE							
07655	000103-67-3	N-BROMOSUCCINIMIDE							
		N-BUTYL BENZENE							
		N-BUTYL BROMIDE							
		N-BUTYL CHLORIDE							
		N-BUTYL ETHER							
		N-CBZ-L-SERINE							
		N-HEPTADECANOYL COENZYME A							
		N-HEPTANE							
		N-HEPTYL BROMIDE							
		N-HEXYL BROMIDE							
		N-OCTYL ALCOHOL							
		N-PROPYLAMINE							
		NAFTON 117							
		NAPHTHALENE							
05717	066796-30-3								
00064	000091-20-3								
00064	0.5511								

* indicates MSDS is not available
** indicates MSDS updated within last three months

Plant: 3 Division:	Department:	Control Area:	Building:	3047	Room:	HAZ Class:	Area:	HAZ Rating:	Pressure Cd:	Temp Cd:	Cont Type Cd:	WA Code:
Item ID:	LIST:	Ingredient:	Mix Comp:	to	HAZ	Class:	HAZ	Rating:				
Date Expiration:	MSDS Avail:	Haz Mat Grp Cd:	to	Phy State:								
04605	012054-48-7	NICKEL-HYDROXIDE	Y	Y	Y	Y	Y	1.1023	0.5000	1		
00321	007440-02-0	NICKEL METAL	Y	Y	Y	Y	Y	5.0987	2.3125	8		
00485	013478-00-7	NICKELOUS NITRATE, HEXAHYDRATE	Y	Y	Y	Y	Y	1.1023	0.5000	1		
00641	000059-67-6	NICOTINIC ACID	Y	Y	Y	Y	Y	0.2204	0.0999	1		
88279	000485-47-2	NINHYDRIN SPRAY REAGENT, 0.2% NINHYDRIN IN ETHANOL	Y	Y	Y	Y	Y	0.0551	0.0249	1		
04619	007440-03-1	NIOBIUM METAL	Y	Y	Y	Y	Y	0.0022	0.0009	1		
04624	007697-37-2	NITRIC ACID	Y	Y	Y	Y	Y	128.9579	58.4940	17		
00648	000088-99-3	NITROGEN	Y	Y	Y	Y	Y	51.7651	23.1803	4		
00054	000095-53-4	O-PHTHALIC ACID	Y	Y	Y	Y	Y	1.1022	0.5000	2		
00644	** 000112-80-1	O-TOLUIDINE	Y	Y	Y	Y	Y	0.2204	0.0999	1		
06164	000370-81-1	OLEIC ACID	Y	Y	Y	Y	Y	0.2204	0.0999	1		
01144	006153-56-6	OXALIC ACID, BIS(CYCLOHEXYLIDENEHYDRAZIDE)	Y	Y	Y	Y	Y	0.1102	0.0498	2		
01133	007782-44-7	OXYGEN	Y	Y	Y	Y	Y	6.6138	2.9999	2		
89735	000150-13-0	P-10 NUCLEAR COUNTER MIXTURE	Y	Y	Y	Y	Y	30.2575	13.7246	2		
00595	000106-38-7	P-AMINOBENZOIC ACID	Y	Y	Y	Y	Y	34.2255	15.5245	5		
A4682	NISS	P-BROMOTOLUENE	Y	Y	Y	Y	Y	0.2314	0.1048	2		
00705	000619-73-8	P-iodophenylacetic acid	Y	Y	Y	Y	Y	0.8816	0.3999	4		
07682	004124-41-8	P-NITROBENZYL ALCOHOL	Y	Y	Y	Y	Y	0.0022	0.0010	1		
01093	000098-59-9	P-TOLUENESULFONIC ANHYDRIDE	Y	Y	Y	Y	Y	0.1653	0.0749	2		
00669	000099-94-5	P-TOLUENESULFONYL CHLORIDE	Y	Y	Y	Y	Y	0.0220	0.0100	1		
0093	** 000105-49-0	P-TOLUIC ACID	Y	Y	Y	Y	Y	1.3226	0.5998	3		
A2631	006865-14-1	P-TOLUIDINE	Y	Y	Y	Y	Y	1.1023	0.5000	1		
06629	009001-73-4	PALMITOL-DL-CARNITINE CHLORIDE	Y	Y	Y	Y	Y	0.4408	0.1998	2		
00795	008002-74-2	PAPAIN, LYOPHILIZED	Y	Y	Y	Y	Y	0.0022	0.0010	1		
06233	001002-84-2	PARAFFIN	Y	Y	Y	Y	Y	0.0088	0.0039	1		
06511	086508-42-1	PENTADECANOIC ACID	Y	Y	Y	Y	Y	1.0000	0.4535	1		
86793	** NISS	PERFLUORO COMPOUNDS, C5-18	Y	Y	Y	Y	Y	0.0551	0.0250	1		
00111	000108-95-2	PERMATEX(R) HYDRAULIC JACK OIL	Y	Y	Y	Y	Y	140.0000	63.5034	2		
00387	000143-74-8	PHENOL, RED	Y	Y	Y	Y	Y	2.0863	0.9463	1		
00388	000077-09-8	PHENOLPHTHALEIN	Y	Y	Y	Y	Y	1.0000	0.4535	1		
A2397	NISS	PHENOMENEX PHENOGLIC LINEAR/MIXED BED	Y	Y	Y	Y	Y	0.0044	0.0018	1		
A3059	068332-77-4	PHENOXYACETYLCELLULOSE	Y	Y	Y	Y	Y	0.7473	0.3387	2		
07765	001464-44-4	PHENYL-BETA-D-GLUCOPYRANOSIDE	Y	Y	Y	Y	Y	0.2204	0.1000	1		
06500	0000536-74-3	PHENYLACETYL CHLORIDE	Y	Y	Y	Y	Y	0.0551	0.0250	1		
06795	000064-04-0	PHENYLETHYLAMINE, 98%	Y	Y	Y	Y	Y	0.2204	0.1000	1		
B2593	001124-19-2	PHENYLTRIM TRICHLORIDE	Y	Y	Y	Y	Y	0.1653	0.0750	3		
02081	007664-38-2	PHOSPHORIC ACID	Y	Y	Y	Y	Y	0.0551	0.0249	1		
05801	012067-99-1	PHOSPHOTUNGSTIC ACID	Y	Y	Y	Y	Y	0.2204	0.1000	1		
00649	000085-44-9	PHthalic anhydride	Y	Y	Y	Y	Y	12.7544	5.7853	2		
93402	** NISS	POLYMERIC SYSTEMS DSi-601 SILICONE SEALANT	Y	Y	Y	Y	Y	0.2204	0.0999	1		
0373	** 009005-64-5	POLYOXYETHYLENESORBITAN MONOLAURATE TWEEN 20	Y	Y	Y	Y	Y	0.5247	0.2379	3		
01046	001806-34-4	POPOP	Y	Y	Y	Y	Y	0.0551	0.0249	1		
04903	** 000298-14-6	POTASSIUM BICARBONATE	Y	Y	Y	Y	Y	0.0220	0.0099	2		
00288	007789-29-9	POTASSIUM BIFLUORIDE	Y	Y	Y	Y	Y	2.0000	0.9070	2		
00493	** 007758-01-2	POTASSIUM BROMATE	Y	Y	Y	Y	Y	1.1023	0.5000	1		
00494	** 007758-02-3	POTASSIUM BROMIDE	Y	Y	Y	Y	Y	1.1023	0.5000	1		
00495	000581-08-7	POTASSIUM CARBONATE	Y	Y	Y	Y	Y	0.1102	0.0500	2		
								15.4207	6.9947	5		

* indicates MSDS is not available
** indicates MSDS updated within last three months

HAZARDOUS MATERIALS INFORMATION SYSTEM Management Inventory Summary Report (by Building)

UNCLASSIFIED Page: 17 Installation: ORNL

Cont. Type Cd: WA Code:

*** indicates MSDS updated within last three months

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant:	3	Division:	Department:	Control Area:	Building:	3047	Room:	Area:	HAZ Class:	HAZ Rating:	WA Code:	Installation:	ORNL
Item ID:		Expiration:	LIST:	Ingredient:	Mix Comp:	to	Haz Mat	Grp Cd:	Phy State:	Pressure Cd:	Temp Cd:	Cont	Type Cd:
05099		013600-98-1		SODIUM-COBALTINTRITE						4-4092	2.0000	2	
00538	000143-33-9			SODIUM CYANIDE						3.3069	1.5000	3	
06258	025895-60-7			SODIUM CYANOBOROHYDRIDE						0.6612	0.2997	3	
95149	NISS			SODIUM CYCLOCOPENTADIENIDE, 2-3 M IN TETRAHYDROFURAN						0.0005	0.0002	1	
00047	**	010588-01-9		SODIUM DICHROMATE						1.1023	0.5000	1	
07136	**	013601-19-9		SODIUM FERROCYANIDE						0.0220	0.0099	1	
00540		007681-49-4		SODIUM FLUORIDE						1.1023	0.5000	1	
07378	000149-44-0			SODIUM FORMALDEHYDEDESULFOXYLATE						4-4092	2.0000	1	
06489	016721-80-5			SODIUM HYDROXIDE HYDRATE						0.1102	0.0499	1	
00543	001310-73-2			SODIUM HYDROXIDE SOLUTIONS (>10%)						12.7161	5.7679	3	
06411	**	001310-73-2		SODIUM HYDROXIDE, <10%						8.5818	3.8926	4	
06414		001310-73-2		SODIUM HYPOCHLORITE SOLUTION						2.2046	1.0000	1	
06410	007681-52-9			SODIUM HYPOPHOSPHITE, MONOHYDRATE						46.0367	20.8820	4	
00545	010039-56-2			SODIUM HYPOPHOSPHITE, ANHYDROUS						1.1023	0.5000	1	
00528	007681-57-4			SODIUM METABISULFITE, ANHYDROUS						0.5511	0.2499	1	
00548	010102-40-6			SODIUM MOLYBDATE, DIHYDRATE						0.2204	0.0999	1	
00549	**	007631-99-4		SODIUM NITRATE						0.1102	0.0500	1	
00550		007632-00-0		SODIUM NITRITE						0.9818	0.3999	1	
05114	**	013755-38-9		SODIUM NITROPRUSSIDE DIHYDRATE						0.2500	0.1133	1	
00155		000062-76-0		SODIUM OXALATE						0.2500	0.1133	1	
07796	007790-28-5			SODIUM PERIODATE						0.2204	0.0999	1	
05682	**	013472-33-8		SODIUM PERPHENATE						0.0022	0.0010	1	
05115	**	007775-27-1		SODIUM PHOSPHATE, DIBASIC						1.1023	0.5000	1	
02351		013472-36-1		SODIUM PHOSPHATE, DECAHYDRATE						0.2491	0.1129	1	
02612	**	013472-36-1		SODIUM PHOSPHATE, DECAHYDRATE, DECAHYDRATE						1.1023	0.5000	1	
06172	012209-98-2			SODIUM STANNATE, TRIHYDRATE						3.3069	1.5000	3	
00558	007757-82-6			SODIUM SULFATE						32.4076	14.6998	19	
00560	001313-84-4			SODIUM SULFIDE, NONAHYDRATE						3.3069	1.5000	1	
00559		007757-83-7		SODIUM SULFIDE, ANHYDROUS						3.2046	1.4535	3	
00529	**	001330-43-4		SODIUM TETRABORATE						4.4092	2.0000	2	
00562		00142-66-8		SODIUM TETRAPHENYLBORON						0.1102	0.498	2	
00555	007722-88-5			SODIUM TETRAPHYDROPHOSPHATE						1.0000	0.4535	1	
02614	000540-72-7			SODIUM THIOLCYANATE						1.0000	0.4535	1	
00564		007772-98-7		SODIUM THIOSULFATE						0.0001	0.0000	1	
06417	**	NISS		SODIUM TRIPHOSPHOPYRIDINE NUCLEOTIDE HYDRATE IN AC						3.6510	1.6561	1	
94501	NISS			SODIUM TUNGSTATE, DIHYDRATE						0.0002	0.0000	1	
89036	NISS	053125-86-3		SOLDIER SEAL LIQUID WRENCH NO. 1, POUR						1.1023	0.5000	1	
B0466	NISS	000749-02-0		SPHINGOSINE						0.0651	0.0295	1	
96542		02124		SPIPERONE SPRAYON LUBRICANTS, RUST PREVENTIVES & MAINTENAN						0.0001	0.0000	1	
A8223		002272		STANNIC CHLORIDE						0.0110	0.0050	1	
05155	**	018282-10-5		STANNIC OXIDE						0.7823	0.3548	1	
07264		007772-99-8		STANNOUS CHLORIDE, DIHYDRATE						1.5511	0.7034	2	
00567		01025-69-1		STARCH						0.0551	0.4535	1	
02124		009005-25-8		STERAROLIC ACID						2.2046	0.0250	1	
05705		000506-24-1		STERAMINE TABLETS 1-G						1.1023	0.5000	1	
89876		00568	**	STRONTIUM CARBONATE						0.0551	0.0250	1	
05166		01633-05-2		STRONTIUM HYDROXIDE						3.0000	1.3608	1	
		018480-07-4								7.2495	1.4740	3	
										7.2046	3.2679	2	

* indicates MSDS is not available
** indicates MSDS updated within last three months

HAZARDOUS MATERIALS INFORMATION SYSTEM

Management Inventory Summary Report (by Building)

Plant: 3	Division:	Department:	Control Area:	Building:	3047	Room:	Area:	HAZ Class:	HAZ Rating:	Page: 19
Item ID:	LIST:	Ingredient:	Mix Comp:	to	Haz Mat Grp Cd:	Phy State:	Pressure Cd:	Temp Cd:	Cont Type Cd:	Installation: ORNL
Date Expiration:	MSDS Avail:	Inv Status:								WA Code:
00570	**	0100012-76-9	STRONTIUM NITRATE							1-4040
01074	0000057-50-1	SUCROSE								3-5000
00349	005329-14-6	SULFAMIC ACID								1-0000
A9043	034071-95-9	SULFOSUCCINIMIDYL-3-(4-HYDROXYPHENYL) PROPIONATE								2
00572	007704-34-9	SULFUR TETRAFLUORIDE								1-0000
02134	007783-60-0	SULFURIC ACID, >40%								1-0000
00351	007664-93-9	SYNTECH PRODUCTS TOUCH IT UP DE-CONTAMINANT								2-2046
94248	NISS	TALC (POWDER) CONTAINING NO ASBESTOS FIBERS								1-0000
00869	014807-96-6	TANTALUM NITRIDE								0-0002
96543	012033-62-4	TANTALUM PENTOXIDE								0-0049
00573	001314-61-0	TANTALUM(IV) CHLORIDE								1-3632
06858	007721-01-9	TAP MAGIC CUTTING FLUID								2-2046
87084	NISS	TAUROCHENODEOXYCHOLIC ACID SODIUM								1-0000
05214	000107-35-7	TAUROCHOLIC ACID SODIUM								1-0431
A3051	006009-98-9	TAUROCHOLIC ACID SODIUM								0-0551
96544	000145-42-6	TAUROBIOXYCHOLIC ACID SODIUM								0-0249
96545	001180-95-6	TELLURIUM								0-0000
02140	013494-80-9	TELLURIUM CHLORIDE								1-196
07440	010026-07-0	TEMPERATUR INDICATOR CRAYONS (300 DEG								1-7780
A0048	NISS	TERPENTINE								1-749
00032	000075-65-0	TERT-BUTYL ALCOHOL								0-5669
B4108	**	TERT-BUTYL AZIDOFORMATE								1-2499
B4108	**	TERT-BUTYL HYPOCHLORITE								2-7557
00570	000507-40-4	TESTOSTERONE								0-0300
A0707	000058-22-0	TETRABUTYLAMMONIUM FLUORIDE TRIHYDRATE								0-02204
A7104	087749-50-6	TETRABUTYLAMMONIUM HYDROGEN SULFATE								0-01102
A2863	032503-27-8	TETRABUTYLAMMONIUM HYDROXIDE								0-0440
01077	002052-49-5	TETRABUTYLAMMONIUM IODIDE								0-0200
A4038	000311-28-4	TETRAETHYLAMMONIUM FLUORIDE HYDRATE								0-0250
07705	098330-04-2	TETRAETHYLAMMONIUM HYDROXIDE								0-0500
08894	00077-98-5	TETRAETHYLAMMONIUM IODIDE								0-0249
A2667	002138-24-1	TESTHYDROFURAN								0-0250
00117	000109-99-9	THIOPHENYLARSONIUM CHLORIDE								0-0500
07196	000075-76-3	THIOPHENYLARSONIUM CHLORIDE								1-1023
05252	0000507-28-8	THIOPHENYLPHOSPHONIUM CHLORIDE								0-02204
96548	002001-45-8	THIOPHENYLTRIFLUOROACETONE								0-0999
07204	NISS	THIOPHENE								1-1023
07450	023586-53-0	THIOPHENE TRIFLUOROACETATE								0-3452
B3643	034822-90-7	THIOLIC CYCLOPENTADIENIDE								0-2204
00100	001314-32-5	THIOLYL SESQUIOXIDE								0-0551
01085	000325-51-0	THIOLYLTRIFLUOROACETONE								0-1102
A4495	000123-93-3	THIODIGLYCOLIC ACID								0-16612
00113	000110-02-1	THIOPHENONE								0-12204
00112	000108-98-5	THIOPHENOL								1-1023
00012	000062-56-6	THIOUREA								0-5000
C5273	**	THIUMIUM OXIDE								2-2046
C6782	000050-89-5	THYMIDINE								1-1023
06692	000065-71-4	THYMINE								0-0022
00389	000076-61-9	THYMOL BLUE								0-0099
00574	**	TIN METAL								1-1023
02158	013463-67-7	TITANIUM DIOXIDE								0-0099
										3.2675
										6

* indicates MSDS is not available
** indicates MSDS updated within last three months

HMISR003C
13:48:12


03-28-1996

HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)

Plant: 3	Division:	Department:	Control Area:	Building:	3047	Room:	Area:	HAZ Class:	Rating:	Instalation:	Page:
Item ID:	Item Expiration:	LiSr:	Ingredient:	Mix Comp:	to	HAZ Mat	State:	Pressure Cd:	Temp Cd:	WA Code:	20
Date:	Expiriation:	MSDS Avail:	MSDS	Grp Cd:	Phy	State:	Pressure Cd:	Temp Cd:	Cont	Type Cd:	ORNL
05288	013860-02-1	TITANIUM NITRATE				NN	NN	1.1023	0.5000	1	
05289	007705-07-9	TITANIUM TRICHLORIDE				NN	NN	1.1454	0.9731	2	
A1154	NISS	TODAY & BEYOND				NN	NN	24.3018	24.3018	6	
07107	000108-88-3	TOLUENE				NN	NN	24.8004	11.2493	3	
A1025	001576-35-8	TOLUENE-4-SULFONHYDRAZIDE				NN	NN	0.2204	0.0999	1	
057557	000538-81-8	TORSENE, PART A (82645) AND PART B (89492)				NN	NN	0.3911	0.1774	1	
057552	000110-57-6	TRANS, TRANS-1,4-DICHLORO-2-BUTENE				NN	NN	0.0551	0.0250	1	
07649	000051-35-4	TRANS-4-HYDROXY-L-PROLINE				NN	NN	0.0551	0.0249	1	
00909	000078-50-2	TRI-N-OCTYLPHOSPHINE OXIDE				NN	NN	0.0022	0.0010	1	
965553	000998-40-3	TRIBUTYLTIN HYDRIDE				NN	NN	0.0551	0.0249	1	
05777	000688-73-3	TRIBUTYLTIN HYDRIDE				NN	NN	0.2204	0.0999	1	
000033	000076-03-9	TRICHLOROACETIC ACID				NN	NN	0.0660	0.0298	2	
000039	** 000079-01-6	TRICHLOROETHYLENE				NN	NN	1.1023	0.5000	1	
07657	000123-02-4	TRIDECYL BENZENE				NN	NN	12.2251	5.5452	1	
07724	000115-80-0	TRIETHYL ORTHOPROPIONATE				NN	NN	0.0551	0.0249	1	
00131	000121-44-8	TRIETHYLAMINE				NN	NN	0.4408	0.1998	2	
05330	000078-39-7	TRIETHYLORTHOACETATE				NN	NN	0.5511	0.2499	1	
05335	000076-05-1	TRIFLUOROMETHYLIC ACID				NN	NN	0.4408	0.1999	2	
07448	000358-23-6	TRIFLUOROMETHANE SULFONIC ANHYDRIDE				NN	NN	0.6612	0.2997	3	
965557	000149-73-5	TRIMETHYL ORTHOFORMATE, ANHYDROUS				NN	NN	0.0770	0.0346	4	
00028	000075-50-3	TRIMETHYLAMINE				NN	NN	1.1023	0.5000	1	
965559	0000503-30-0	TRIMETHYLENE OXIDE				NN	NN	0.2204	0.0999	1	
96562	000555-44-2	TRIPALMITIN				NN	NN	1.1574	0.5249	2	
02172	000603-34-9	TRIPHENYLAMINE				NN	NN	0.0110	0.0049	1	
07430	000603-36-1	TRIPHENYLANTIMONY				NN	NN	0.0551	0.0249	1	
06339	000603-35-0	TRIPHENYLPHOSPHINE				NN	NN	0.5511	0.2499	1	
A0606	000892-20-6	TRIPHENYLTIN HYDRIDE				NN	NN	0.6612	0.2998	3	
00680	000077-86-1	TRIS(HYDROXYMETHYL)AMINOMETHANE				NN	NN	0.0220	0.0100	1	
06128	000072-57-1	TRYPSIN BLUE				NN	NN	1.1023	0.5000	1	
00861	000902-07-7	TRYPSIN				NN	NN	0.2204	0.0999	1	
A2583	NISS	TURTLE WAX MINUTE DE-ICER, T-297				NN	NN	0.2204	0.0999	1	
A2621	000051-67-2	TYRAMINE				NN	NN	10.3672	4.7017	11	
00672	000112-18-9	UNDECYLENIC ACID				NN	NN	0.0551	0.0250	1	
05770	** 000066-22-8	URACIL				NN	NN	0.2204	0.0999	1	
00908	000057-13-6	UREA				NN	NN	0.0110	0.0050	1	
07714	000058-96-8	URIDINE				NN	NN	14.9207	6.7675	10	
A2632	000058-97-9	URIDINE 5-MONOPHOSPHATE				NN	NN	0.0002	0.0000	1	
00577	007440-62-2	VANADIUM METAL				NN	NN	0.0000	0.0000	1	
00578	001314-62-1	VANADIUM PENTOXIDE				NN	NN	0.4408	0.1999	2	
05410	** 027774-13-6	VANADYL SULFATE				NN	NN	1.1647	0.5282	3	
00866	000121-33-5	VANILLIN				NN	NN	1.1022	0.4999	2	
B4098	*	VINYL MAGNESIUM CHLORIDE				NN	NN	0.2204	0.0999	1	
05264	000067-03-8	VITAMIN B1				NN	NN	0.1984	0.0900	1	
07539	** 000083-88-5	VITAMIN B2				NN	NN	0.0110	0.0049	1	
06175	** 008032-32-4	VM & P NAPHTHA				NN	NN	0.0110	0.0049	1	
89881	NISS	WESTLAND STIHL TWO-CYCLE ENGINE OIL				NN	NN	8.8184	4.0000	1	
82916	NISS	WINDSHIELD DE-ICER				NN	NN	0.8345	0.3785	2	
06689	000069-89-6	XANTHINE				NN	NN	1.4994	0.6802	1	
00049	001330-20-7	XYLENE				NN	NN	0.0022	0.0009	1	
						NN	NN	1.1023	0.5000	1	

* indicates MSDS is not available
** indicates MSDS updated within last three months

**14. BUILDING 3517—FISSION PRODUCTS DEVELOPMENT
LABORATORY**



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 3517 Fission Products Development Laboratory (FPDL)
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	
R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES	
<i>Status (active/inactive):</i>	<i>Years of Operation:</i> ≈ 30
<i>Description of Operation:</i>	
<p>Activities involving the processing of radioactive source material have ceased in Building 3517. Current operations are limited to surveillance, maintenance, and deactivation activities and storage of most of ORNL's inventory of ⁹⁰Sr and ¹³⁷Cs. Some over packing, packaging, and transfer/transport activities are also planned for the facility for removal of remaining inventory and subsequent facility stabilization. Historical operations included recovery of long-lived fission products from aqueous waste, purification and pelletization of radiation source materials, and testing of new procedures for source fabrication. Large quantities of ¹³⁷Cs, ⁹⁰Sr, ¹⁴⁴Ce, and ¹⁴⁷Pm have been processed from liquid, high-level waste streams each year. Many Curies (Ci) of fission product materials have also been processed through the FPDL over the years. Until 1989, the FPDL processed ⁹⁰Sr and ¹³⁷Cs from Hanford, Washington for production of sources for distribution through the Isotope Distribution Program. Radioisotope processing continued in the manipulator cells between 1975 and 1989 at reduced levels of operation. This process equipment has been placed in standby for possible utilization in the future.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> Building 3517 was originally constructed in the late 1950s. The building is a two-story, concrete block structure containing operating areas, service areas, offices, and personnel access areas. There is also an aluminum sided superstructure designated as the third story which houses a 20-ton crane, which services the operating cells. The building consists of approximately 14,400 sq. ft. of floor space. Building utilities include electric power, steam, and plant air. The building is maintained as an active storage area for radioisotopes, although the processing hot cells are in standby mode. Building 3517 is located in an industrial area of ORNL to the southwest of Isotopes circle. The immediate area surrounding the facility is paved for the most part with some grassy areas. The operating area consists of nine process cells (cell 1 through 9), ten manipulator and service cells (cell 10 through 20 - there is no longer a cell numbered 19), four tank farm cells (cell 21 through 24), a ventilation filter pit, an old and a newly installed filtration housing, and several service/pipe tunnels. (Some of the cells and one of the tunnels are presently inactive.) The four tank farm cells (listed as numbered cells) and the two pipe tunnels are located underground adjacent to the northwest corner of the building. The FPDL includes two cell ventilation buildings, a new filter housing (no building number), and a storage building. Building 3547 and 3548 are filtration facilities for the FPDL. Building 3542 is a storage building for the facility, containing no radioactive materials. 	

Physical description of area/facility: (Continued)

- An concrete pad exposed to the weather is located at the northeast corner of the facility and used for storage of casks containing radiologically contaminated material (⁹⁰Sr).
- Cell floor drains and the electropolisher glove box drain discharge to stainless steel collection tanks (S-223, S-324, and S-523) located in shielded underground cells adjacent to the northwest corner of the facility. Liquid waste is discharged from these tanks to the low-level, liquid waste (LLLW) system as necessary. Building floor and sink drains, steam condensate, and emergency cooling water for the storage well is monitored at Manhole 209 before discharge to the process waste system.
- Work with radioactive materials was performed primarily in the hot cells and electropolisher.
- Some interior portions of the building are restricted access areas due to radiologic contamination. Interior portions of the building observed were found to be in good condition. Many surfaces have been recently painted. Asbestos Containing Material (ACM), radiation (RAD) hazard areas, and polychlorinated bi-phenol (PCB) containing equipment are posted and/or labeled as appropriate.
- The building is operated in a "contained" state and kept under negative pressure relative to atmosphere.
- A building space diagram is attached to this form showing the locations of the various process areas and equipment.

Release Information*Description of release, or threatened release, and source:*

Low levels of residual fixed and transferable radiologic surface contamination exist in areas of the facility as a result of historical operations. The contamination exists primarily in the hot cells and process equipment (vessels, hoods, piping, ventilation ducts, etc.). This contamination has accumulated from activities involving a variety of materials throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are low and the presence of this contamination is not considered a significant hazard in its current state. The potential for release of additional radiologic contamination exists due to the large quantities of radioactive materials (primarily ²⁴⁴Cm, ⁹⁰Sr, and ¹³⁷Cs) currently stored in the facility.

Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used, for the most part, in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. A few materials are currently used in quantities that exceed 100 pounds. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.

Hazardous substances present:

Hazardous substances remaining in Building 3517 consist mainly of residual RAD surface contamination (α , β , γ), radioactive materials in storage, PCBs, and quantities of miscellaneous HAZMATs. Areas of fixed and transferable RAD contamination are associated primarily with the hot cells and process equipment. PCBs are reportedly present in the form of forklift hydraulic fluid. Hazardous materials present in the building are listed on the attached HAZMAT inventory sheets.

Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:

The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.

90,000 Ci ^{90}Sr .
 350,000 Ci ^{137}Cs .
 \approx 3,500 Ci ^{154}Eu .
 \approx 2,500 Ci ^{152}Eu .
 \approx 16,000 Ci ^{60}Co .
 \approx 36,000 Ci ^{244}Cm .

Quantity of PCBs unknown (assumed to be less than 1 gallon).
 \approx 1,686 pounds total miscellaneous HAZMATs (see attached HAZMAT inventory sheet).

(Quantity estimates obtained from Building 3517 Hazard Screening Report, ORNL PCB Hydraulic Equipment Inventory database, ORNL Hazardous Material Information System database.)

Other pollutants or contaminants:

Asbestos containing material, primarily in the form of thermal system insulation, has been confirmed present in this building. ACM observed is in fair to good condition and poses no immediate health threat. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in good condition and pose no immediate health threat. Many of the interior surfaces have been recently painted which leaves the potential for lead-containing underlayers of paint. Paint on exterior surfaces was observed to be in good condition with no visible evidence of significant damage or deterioration.

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 3517 is located in Waste Area Grouping 1 at ORNL. Although no specific adverse spills or releases of hazardous substances threatening to groundwater were identified during this RmSE, it is suspected, based on available environmental studies conducted in WAG 1, that process and LLLW drains and associated piping may have leaked over the life of the facility. Buried process and LLLW piping and some drains have been found to be deteriorated and leaking in other facilities and areas of WAG 1. Studies have determined that groundwater in WAG 1 has been both radiologically and chemically contaminated. Numerous man-made radionuclides have been detected in WAG 1 groundwater samples including many of those processed in Building 3517. It is likely that liquid waste from activities involving radioisotopes in Building 3517 have historically contributed to WAG 1 groundwater contamination. However, the radionuclides detected in the groundwater were common to the processes and activities in many other buildings in the area which makes it difficult to determine exactly which building is, or was, the source of contamination.

Because of the reported small quantities of chemicals historically used in this facility, it is unlikely that such usage has significantly contributed to WAG 1 groundwater contamination. As part of the facility shutdown process, inactive process and LLLW drains within the building have reportedly been plugged to prevent further release. However, no documentation was available at the time of this report to verify which drains have actually been plugged and which have not. Information on drain locations and discharge points is available from the ORNL Engineering Support Office.

Other than the potential for historical impact to groundwater in WAG 1 via leaking process and LLLW lines external to the building, no existing immediate threat to groundwater was identified to be associated with this facility given its current status.

Surface Water
<p><i>Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.</i></p> <p>WAG 1 is essentially bound by Fifth Creek to the east, White Oak Creek (WOC) to the south, and First Creek to the west. First and Fifth creeks flow south into (WOC) which flows to the west and exits WAG 1 at the southwest corner. Storm water (from surface runoff and storm water drainage system) and treated water from the process waste system discharges into WOC. The only potential for direct impact to surface water from Building 3517 in its current state would be from lead-containing paint chips which fall off the exterior painted surfaces and find their way into the storm water drainage system and eventually to WOC.</p> <p>Surface water may have also been indirectly impacted by leaking process and LLLW lines external to the building. Some of these lines are known to have shared a common trench with storm water drainage piping. Contamination from leaking waste lines could potentially enter deteriorated storm water piping and migrate to WOC. The three creeks bordering WAG 1 are groundwater discharge points. Therefore, groundwater contaminated by leaking waste lines could also potentially impact surface water in the area.</p> <p>Other than the potential for historical impact, no existing immediate threats to surface water were identified to be associated with facility.</p>
Air
<p><i>Are there any suspected impacts due to air emissions? If yes, please describe.</i></p> <p>The Hazard Screening Report prepared for Building 3517 indicates that the potential for radiation exposure to personnel working inside and within the immediate vicinity of the facility as a result of potential airborne migration of radioactive particulates and physical contact with contaminated surfaces is considered insignificant. There is, however, a potential for significant radiation exposure as a result airborne migration of particulates from the remaining inventory of radioactive material should containment of this material be compromised. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air flows from the interior of the building into the cells which exhaust through underground ducts to three stages of high efficiency particulate air (HEPA) filtration units and eventually to the stack 3039. Apart from catastrophic failure of the hot cells, storage equipment, or cell ventilation system, it is unlikely that radioactive air emissions from Building 3517 would impact personnel or the environment in its current state.</p> <p>There is also a potential for impact to indoor air quality due to the presence of ACM and assumed lead-based paint (LBP) should these materials be disturbed. The ACM and assumed LBP remaining in the building are not considered to be immediate threats to indoor quality in their current state.</p>
Soil
<p><i>Are there any suspected impacts to soil? If yes, please describe.</i></p> <p>As stated for groundwater, there is a potential for historical impact to soils in the area of Building 3517 due to leaking process and LLLW drain piping. Previous environmental studies have identified areas of soil contamination throughout WAG 1 and soil samples collected have detected radioisotopes common to the processes performed in this building. Since, these radioisotopes were common to the processes in many of the other buildings in the area, it is difficult to determine whether waste from Building 3517 has actually contributed to WAG 1 soil contamination based on the information reviewed during this RmSE.</p> <p>There is also a potential for areas of soil adjacent to the facility to be impacted from lead if, in fact, exterior paint is found to be lead-containing. Deteriorating paint could dislodge from the surface and fall to the soil below. The exterior paint was observed to be good condition and does not pose an immediate threat in its current state.</p> <p>It is unlikely that the quantities of chemicals that have been, and are being, used in Building 3517 have, or will, significantly impact(ed) soil in the surrounding area.</p>

Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries: <ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of hot cells and/or contaminated equipment.
There is also a potential for assumed lead-containing paint which peels off of the building to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.
Worker Safety
<i>Could the release pose a threat to workers? If yes, please describe.</i>
Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. Monitors and alarms are in place to detect any radioactive release within the building. PCB containing equipment and ACM are appropriately labeled. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of the building.
Environmental Receptors
<i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i>
No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 3517.
Mitigation
<i>What action(s) might be taken to abate/prevent release or impacts from release?</i>
<ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in the building. • Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facility for worker and environmental protection. Warning signs and labels are posted throughout the facility indicating RAD, ACM, and PCB hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status undergoing facility stabilization activities pursuant to acceptance into the Decontamination and Decommissioning (D&D) Program. Inactive waste drains are reportedly plugged in contaminated areas to prevent inadvertent discharge of contamination beyond the facility. A groundwater monitoring program is in place to monitor contamination levels and migration in groundwater underlying WAG 1. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 3517.

Current actions being taken to prevent further release and ensure worker safety in Building 3517 are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

No potential hazards requiring maintenance actions were identified to be associated with Building 3517.

Removal Actions

Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.

No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 3517.

Remedial Site Evaluation
<i>Is a Remedial Site Evaluation needed?</i>
<p>Areas of radiologic contamination associated with Building 3517 have been identified and marked as appropriate. However, it is suspected that process and LLLW drains and associated piping may have leaked beneath the slab of the building as a result of past practices. As a result, it is recommended that some type of remedial investigation be performed to assess the condition of the soil in this area before conducting any S&M or D&D activities which involve disturbing the slab.</p> <p>ACM and PCB-containing equipment have also been identified, marked and documented. No further remedial investigation involving these hazards is considered necessary given the current status and future plans of this facility.</p> <p>Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.</p>
No Further Investigation
<i>Is a finding of No Further Investigation appropriate? Please explain.</i>
<p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 3517 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>
Additional Comments
<p>The following documents and databases were referenced for historical and hazard information related to Building 3517:</p> <ul style="list-style-type: none"> • Phase I Safety Documentation, The Fission Product Development Laboratory, Building 3517, Hazard Screening, Document No. HS/3517/F/RT-29 (Rev. 0). • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Building 3517 Occurrence Reports, 1989 to present. • Site Characterization Summary Report for Waste Area Grouping 1 at Oak Ridge National Laboratory, Oak Ridge, Tennessee, Volumes 1 and 2, Document Nos. DOE/OR-1043/V1&D1 and DOE/OR-1043/V2&D1. • ORNL Hazardous Material Information System Database. • ORNL Drain System Survey Report for Building 3517. <p>The following personnel and offices were contacted and provided historical and current use/condition information for Building 3517:</p> <ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program.

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Grant

Evaluator's Signature

6/18/96

Date





Fig. 18. Diagram of Building 3517.

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)UNCLASSIFIED
Page: 1
Installation: ORNLPlant: 3 Division: Department: Control Area: Building: 3517 Room: Area: HAZ Rating:
Item ID: LIST: Ingredient: Mix Comp: To HAZ Mat Grp Cd: Phy State: Class: Pressure Cd: Temp Cd:
Date Expiration: MSDS Avail: HAZ Mat Grp Cd: Cont Type Cd: WA Code:
Cont Type Cd:

Building: 3517

RECID	**	CASNO	Material Name	MMECS	Total LBS	Total LBS	Total KILOGRAMS	No of Items
87321	**	NISS	AEROSOL LACQUER	N N	2.5425		1.1532	3
89621	NISS	NISS	AJAX ALL PURPOSE CLEANER (NON-PHOSPHATE)	N N	31.5000	14.2883	1	
01730	007440-37-1	NISS	ARGON (95%) /METHANE (5%)	N N	277.9816	126.0909	13	
91793	**	96317	ASHLAND PLIOBOND 8003	N N	46.3860	21.0405	13	
96317	**	00303	BARIUM CHLORIDE, DIHYDRATE	N N	2.2818	1.0350	2	
00303	010326-27-9	82250	BIG "D" WATER SOLUBLE DEODORANT	N N	0.4188	0.1900	1	
82250	NISS	89878	BULLEN HI-SEPT	N N	41.3092	18.7377	1	
89878	NISS	00415	CESTUM CHLORIDE	N N	10.4316	4.7317	1	
00415	007647-17-8	95221	COLD KILL WASP/HORNET KILLER #297852	N Y	1.1023	0.5000	1	
95221	NISS	86440	DURABOND D-500 CLEAR THIN SPREAD ADHESIVE	N Y	8.2145	3.7261	7	
86440	NISS	00436	FERRIC SULFATE, ANHYDROUS	N Y	8.3452	3.7853	1	
00436	**	010028-22-5	FERRIC SULFATE, ANHYDROUS	N N	0.8818	0.4000	1	
85495	NISS	85396	GE RTV SILICONE SEALANT	N N	0.6715	0.3046	1	
85396	NISS	00870	HIGH-PURITY NITROGEN AS NANO3	N N	61.8480	28.8942	4	
00870	**	007647-01-0	HYDROCHLORIC ACID	N N	1.9626	0.8942	1	
00956	005470-11-1	02549	HYDROXYLAMINE HYDROCHLORIDE	N N	50.8818	22.6798	1	
02549	000144-62-7	93928	J.T. BAKER OXALIC ACID, 0.1N VOLUMETRIC SOLUTION	N N	41.7264	18.9269	1	
93928	NISS	82454	JOHNSON BRAVO EXTRA HEAVY DUTY STRIPPER 04587	N N	42.5609	19.3055	1	
82454	NISS	87950	JOHNSON COMPLETE FOR FLOORS	N N	10.4316	4.7317	1	
87950	NISS	90355	JOHNSON CREW SHOWER ROOM CLEANER	N N	10.4316	4.7317	1	
90355	NISS	89659	JOHNSON LIQUID ENVY INSTANT CLEANER	N N	41.7264	18.9269	1	
89659	NISS	822906	JOHNSON SNAPBACK LIQUID	N N	42.1437	19.1162	1	
822906	NISS	92502	JOHNSON SOFT CARE LOTIONIZED SOAP	N N	41.8930	19.0024	4	
92502	NISS	93930	JOHNSON WAX VIEW QUICK CLEANER	N N	7.2527	3.2527	1	
93930	NISS	90647	K&W KNOCKER LOOSE	N Y	10.2229	4.6371	1	
90647	NISS	89896	KEL-SAN UTILITY CLEANER (LIQUID)	N Y	11.7877	5.3468	1	
89896	NISS	89624	KELSAN CONCENTRATED BOWL CLEANER	N Y	11.5646	5.0646	2	
89624	NISS	90007	LUBRI BOND A (10 600)	N Y	9.1273	4.1398	2	
90007	NISS	A1291	MASTER MECHANIC AEROSOL	N Y	10.7445	4.8737	1	
A1291	NISS	007697-37-2	MIDLAB DUST MOP & CLOTH TREATMENT	N N	140.2170	63.6020	1	
007697-37-2	NISS	04624	NITRIC ACID	N N	161.3126	73.1702	10	
04624	007727-37-9	89735	P-10 NUCLEAR COUNTER MIXTURE	N N	33.3811	15.1415	1	
89735	NISS	95731	PLANISOL M	N N	134.0000	60.7816	4	
95731	NISS	007722-64-7	POTASSIUM PERMANGANATE	N Y	18.7500	9.7439	1	
007722-64-7	NISS	85508	PPG CUSTOM BULK COLORANTS, 96 LINE	N Y	0.8818	0.5049	1	
85508	NISS	A5892	Premier CLEAN LUBE II	N N	2.0863	0.3968	1	
A5892	NISS	00323	PROPANE	N N	0.5652	0.2564	1	
00323	000074-98-6	89646	SANI-FRESH 10-10	N N	134.0000	60.7816	4	
89646	NISS	92144	SBS BAR SOAP	N Y	21.4816	9.7439	1	
92144	NISS	91432	SILICONE SPRAY LUBRICANT (AEROSOL) M9-14	N Y	0.8750	0.3968	1	
91432	NISS	00543	SODIUM HYDROXIDE	N Y	229.7621	104.2193	7	
00543	001310-73-2	06410	SODIUM HYPOCHLORITE SOLUTION	N Y	41.7264	18.9269	1	
06410	007681-52-9	00658	STEARIC ACID	N Y	1.1023	0.5000	1	
00658	**	000057-11-4	STERAMINE TABLETS 1-G	N N	3.0000	1.3607	1	

* indicates MSDS is not available
** indicates MSDS updated within last three months

HMISR003C
15:44:15

03-28-1996

03-28-1996
HAZARDOUS MATERIALS INFORMATION SYSTEM
Management Inventory Summary Report (by Building)


Plant: 3 Division: Department: Control Area: Building: 3517 Room: Area: Installation: ORNL
 Item ID: List: Ingredient: Mix Comp: to HAZ Class: HAZ Rating: WA Code:
 Date Expiration: Inv Status: MSDS Avail: Haz Mat Grp Cd: Phy State: Pressure Cd: Cont Type Cd:
 05685 007783-48-4 STRONTIUM FLUORIDE N N 0.4409 0.2000 1
 80848 NISS TURCO DECON 4502 Y N 65.0000 29.4838 1
 Building 3517 Totals: 1686.1799 761.9428 1
 Building Summary Report (by Building)

14-13

* indicates MSDS is not available
** indicates MSDS updated within last three months



15. BUILDING 7025—TRITIUM TARGET FACILITY



ORNL FACILITY RmSE INFORMATION FORM

General Information	
<i>Area/Facility Name (and aliases):</i>	Building 7025 Tritium Target Facility
<i>Organization responsible for area/facility (include specific person and phone number if possible):</i>	
R.E. Eversole (576-7483), IFDP Project Manager, ER Program, LMES	
<i>Status (active/inactive):</i>	Inactive, Standby Mode
<i>Years of Operation:</i> ≈ 20	
<i>Description of Operation:</i>	
<p>There are no current operations, other than surveillance, maintenance, and deactivation activities, on-going in this building. Building 7025 was originally installed in support of tritium target needs for neutron generation and special metallurgical studies. The building housed equipment for preparing tritium targets made of titanium and diffusing of tritium into metallurgical samples. The metallurgical samples were utilized for helium embrittlement studies. Other equipment, since removed, was necessary for preparation of thin films of thorium oxide and/or uranium oxide. All tritium process activities within the Tritium Target Facility were halted in October 1989. All natural-thorium/natural-uranium operations ended in late 1992.</p>	
<i>Physical description of area/facility:</i>	
<ul style="list-style-type: none"> • Building 7025 is a TVA surplus building which was installed at ORNL during the late 1960s. • The facility is a single-story, prefabricated metal structure consisting of approximately 590 sq. ft. of floor space. • This facility is remotely located in the East Support Area of ORNL and is basically isolated from other buildings in this area. The immediate area surrounding the facility is gravel and dirt with some grassy areas. • Building 7025 is a small single-room laboratory which consisted of a tritium process hood and various related process equipment. The hot sink located at the east end of the tritium hood drained to a small underground collection tank adjacent to the east side of the facility. Wastewater from the lavatory sink was reportedly bottled for disposal away from the facility. There is no other drainage service available for this building. • Building utilities include plant air and electrical service. • Work with radioactive materials was performed primarily in the tritium hood and uranium evaporator. • The exterior of the building was observed to be in fair to good condition with no visible areas of significant deterioration or damage. • All tritium traps, cylinders, and sources of bulk material have been removed from the facility, as well as all thorium/uranium equipment. Basically, all equipment except for the tritium hood and ventilation equipment has been removed and the facility is being cleaned. The tritium hood is in the process of being decontaminated and dismantled. • Generally, the interior of the building is in fair condition. Wall surfaces are deteriorating in areas as a result of the on-going removal work. Asbestos Containing Material (ACM) and radiation (RAD) hazard areas are posted and/or labeled as appropriate. • A building space diagram is attached to this form showing the locations of the various process areas and equipment. 	

Release Information
<p><i>Description of release, or threatened release, and source:</i></p> <p>Low levels of residual fixed and transferable radiologic surface contamination exist in areas of this facility as a result of historical operations. The contamination exists primarily in the tritium hood and associated process equipment. This contamination has accumulated from various activities throughout the operating history of the facility and, therefore, cannot be attributed to a single release episode. The existing levels of RAD contamination in the facility are low and well isolated or controlled. The presence of this contamination is not considered a significant hazard in its current state.</p> <p>Hazardous materials (HAZMATs) (e.g., acids, hydraulic fluids, and other chemicals) were reportedly used in small quantities (i.e., less than 5 gallons or 100 pounds) during facility operations and currently for surveillance and maintenance (S&M) activities. According to available spill/release records and facility personnel interviews, no significant HAZMAT spills (i.e., spills having the potential to adversely affect human health and/or the environment) have been reported for this building. No current conditions were identified which present a potential for a significant HAZMAT release.</p>
<p><i>Hazardous substances present:</i></p> <p>Hazardous substances remaining in Building 7025 consist mainly of small amounts of residual fixed and transferable RAD surface contamination (α, β/γ). Areas of RAD contamination are associated primarily with the tritium hood and process equipment remaining in the building. These areas are marked and isolated and building access is restricted.</p> <p>No polychlorinated bi-phenol (PCB) items were identified to be associated with this building.</p>
<p><i>Estimate (if possible) of quantities of hazardous substances that have been released and that could be released:</i></p> <p>The following represents the known quantities of substances currently existing in the facility. Radiologic surface contamination has accumulated from a legacy of many different programs and processes and cannot be attributed to a single release episode. It is only possible to quantify release amounts from contamination which currently exists in the facility and/or has been historically documented from past activities.</p> <p><2 μCi α <20 μCi β/γ as ^3H</p> <p>(Quantity estimates obtained from Building 7025 Hazard Screening Report)</p>
<p><i>Other pollutants or contaminants:</i></p> <p>Asbestos containing material in the building has been identified, documented, and marked as appropriate. There is no immediate threat from the presence of ACM in this building. Based on the age of the facility, interior and exterior painted surfaces are assumed to be lead-containing. Verification samples are taken by ORNL Lead Management Program personnel on an "as-needed" basis to confirm the presence of lead in the paint (i.e., when work activities will disturb the paint, or paint is found to be deteriorating and poses a health or environmental threat). Interior painted surfaces observed are in fair condition with some localized areas of deterioration and pose no immediate health threat given the status of this facility. Paint on exterior surfaces was found to be in good condition, posing no immediate hazard to the surrounding area due to deterioration.</p>

Groundwater

Are there any suspected impacts to groundwater? If yes, please describe. Include any impacts to drinking water sources.

Building 7025 is located in a fairly remote area of ORNL, approximately 1.5 miles east of Isotopes Circle. The building is not serviced by a common drainage system. A small local underground collection tank adjacent to the east side of the building was used to collect liquid waste from the hot sink in the tritium hood. Reportedly, no liquid waste streams were generated by the processes in this building, and this sink was only used by personnel for washing and decontamination. Although it was not confirmed, it is assumed that wastewater from the water fountain in the building also drained to this tank. Wastewater from the lavatory sink was reportedly bottled and disposed of away from the facility. The integrity of the existing collection tank is unknown. Reportedly, the contents have been pumped out and it currently sits empty. However, no information was identified during this RmSE to indicate the size of this tank, its historical content, or to confirm or deny whether the tank may have leaked. Due to the lack of information concerning this tank, there is a potential, which is common to all tanks of this age, that they may have leaked in the past. If the tank has leaked and did contain hazardous substances there is a high potential that groundwater in the immediate area may have been impacted. However, this potential could not be substantiated based on information identified during this RmSE.

Aside from the historical potential for groundwater impact, no existing immediate threat to groundwater was identified to be associated with this building.

Surface Water

Are there any suspected impacts to surface water? If yes, please describe. Also describe the most likely surface water migration route(s), if applicable. Include any impacts to drinking water sources.

The only potential threat to surface water identified during this RmSE is related to exterior painted surfaces if, in fact, the paint does contain lead. The potential exists for surface water to be impacted from deteriorated paint which washes off the building and finds its way to surface water with the storm water runoff.

Other than the potential for lead-based paint (LBP) impact, no existing immediate threat to surface water was identified to be associated with this building.

Air

Are there any suspected impacts due to air emissions? If yes, please describe.

The Hazard Screening Report prepared for Building 7025 indicates that there is a slight potential for radiation exposure to personnel working in or around the facility due to potential airborne migration of radioactive particulates and physical contact with contaminated surfaces. Because of the low levels and nature of RAD contamination within this facility, potential impacts to persons or the environment surrounding the facility are considered insignificant. Areas of RAD contamination are identified, marked, and controlled as appropriate throughout the facility to protect against inadvertent exposure to personnel. Air within the building is controlled by a local exhaust system. Exhaust air from the now-removed uranium evaporator was filtered through a high efficiency particulate air (HEPA) filter inside the building before being discharged to atmosphere. No HEPA filtration was used in the tritium hood exhaust since the processes in the hood involved only radioactive gases.

Are there any suspected impacts due to air emissions? If yes, please describe. (Continued)

Apart from catastrophic failure of the structure which could disturb existing contaminated surfaces, it is unlikely that radioactive air emissions from this building would impact personnel or the environment.

There is also a potential for impact to indoor air quality due to the presence of ACM and assumed LBP should these materials be disturbed. These hazards are not considered to be an immediate threat to indoor air quality given the current status of this facility.

Soil
<i>Are there any suspected impacts to soil? If yes, please describe.</i>
As stated for groundwater, there is a potential for historical impact to soils in the area of Buildings 7025 if, in fact, the collection tank adjacent to the building has leaked. No evidence of soil contamination such as staining, stressed vegetation, odor, etc. were observed in the area of the UST. This potential for soil contamination could not be substantiated based on information identified during this RmSE.
There is also a potential for areas of soil adjacent to the facility to be impacted from lead if, in fact, exterior paint is found to be lead-containing. Deteriorating paint could dislodge from the surface and fall to the soil below. The exterior paint was observed to be good condition and does not pose an immediate threat in its current state.
Release Beyond Facility or Reservation Boundaries
<i>Has or will the release migrate beyond the boundaries of the facility or reservation? If yes, please describe (including possible human or environmental receptors).</i>
The following are considered potential scenarios where radiologic contamination could migrate beyond the facility or reservation boundaries:
<ul style="list-style-type: none"> • A person becomes inadvertently contaminated and leaves the facility/reservation undetected. • Catastrophic failure of the structure and/or contaminated equipment.
There is also a potential for assumed lead-containing paint which peels off exterior surfaces of the buildings to be carried away with surface runoff during a rain event. Though these potentials exist, they are considered slight and unlikely due to the current status of the facility and the engineering/administrative controls that are in place to protect again such an event.
Worker Safety
<i>Could the release pose a threat to workers? If yes, please describe.</i>
Radiologically contaminated areas are isolated and well marked. Good radiation practices and standard operating procedures are enforced for worker safety. Personnel exiting the facility are required to "frisk" themselves to detect the presence of RAD contamination. However, even with these safeguards in place, a potential threat to workers exists if safety measures are overlooked. This potential is not considered significant given the current status and level of activity of building.
Environmental Receptors
<i>Does the release pose a potential threat to environmental receptors? If yes, please describe. Include natural resources impacts.</i>
No existing conditions posing an immediate significant threat to environmental receptors, including natural resources, were identified to be currently existing or associated with Building 7025.
Mitigation
<i>What action(s) might be taken to abate/prevent release or impacts from release?</i>
<ul style="list-style-type: none"> • Continued utilization and enforcement of engineering and administrative controls that are currently in place to protect workers and monitor conditions and activities in these buildings. • Continue S&M activities per Procedure IP-900.

What actions are currently being taken to abate/prevent release or impacts from release?

Engineering and administrative controls are in place to control access to contaminated areas and to monitor conditions and activities within the facilities for worker and environmental protection. Warning signs and labels are posted throughout the facilities indicating RAD hazard areas. Standard operating procedures are in place for building access and surveillance and maintenance activities to protect against inadvertent contact and disturbance of contaminated areas and materials. Radiologically contaminated areas are monitored periodically by ORNL health physics personnel. Personnel are "frisked" upon exit of the facility to detect the presence of radiologic contamination. The building is currently in surveillance and maintenance status awaiting entry into the Decontamination and Decommissioning (D&D) Program. The building is inspected for structural changes after each natural incident (earthquake, tornado, or other severe storm), fire and/or man induced activity which could cause cracking, failure, or deterioration of the facility and/or equipment that may allow contamination to be released. No such conditions have been reported for Building 7025. The building remains locked and secured to limit access.

Current actions being taken to prevent further release and ensure worker safety in Building 7025 are considered adequate until D&D activities begin.

Other Environmental Authorities

Is the release or threatened release potentially subject to other environmental statutory actions? If yes, please explain.

If paint is found to be lead-containing and samples fail the Toxicity Characteristic Leaching Procedure (TCLP) analysis, the building could qualify as a hazardous waste generator point under the Resource Conservation and Recovery Act (RCRA).

Maintenance Actions

Are maintenance actions necessary to eliminate potential threats to human health and the environment? If so, explain.

No existing potential hazards requiring maintenance actions were identified to be associated with Building 7025.

Removal Actions

Are Removal Actions necessary to eliminate immediate threats to human health and the environment? If so, explain.

No imminent hazards requiring removal actions per 40 CFR 300.415 were identified to be currently associated with Building 7025.

Remedial Site Evaluation

Is a Remedial Site Evaluation needed?

It is recommended that a Remedial Site Evaluation (RSE) be conducted at Building 7025 to determine whether the collection tank located adjacent to the building has leaked and whether a remedial investigation is necessary.

Building 7025 has reportedly been surveyed for asbestos containing material (ACM); therefore, no further remedial investigation involving this hazard is considered necessary given the current status and future plans of this facility.

Based on the age of the facility, painted surfaces are assumed to contain lead. Samples of the paint should be taken and analyzed to verify the presence of lead prior to conducting any S&M or D&D activities which may disturb these assumed areas.

No Further Investigation	
<p><i>Is a finding of No Further Investigation appropriate? Please explain.</i></p> <p>A finding of No Further Investigation implies that a facility or area is free from hazardous substances or contaminants that may threaten human health and the environment. Since Building 7025 contains substances and materials which may become threatening if not properly controlled, handled and managed during the S&M cycle, a finding of No Further Investigation is inappropriate in this case.</p>	
Additional Comments	
<p>The following documents and databases were referenced for historical and hazard information related to Building 7025:</p> <ul style="list-style-type: none"> • Phase I Safety Documentation, Tritium Target Facility, Building 7025, Hazard Screening, Document No. HS/7025/3093/F/RT-33 (Rev. 0). • Work Plan for the Isotopes Facilities Deactivation Project at Oak Ridge National Laboratory, Document No. ORNL/ER-249/R2. • Building 7025 Occurrence Reports, 1989 to present. • ORNL Hazardous Material Information System Database. <p>The following personnel and offices were contacted and provided historical and current use/condition information for Building 7025:</p> <ul style="list-style-type: none"> • Mr. Karl Haff, Radiochemical Processing Department Head, ORNL Radiochemical Technology Section. • Mr. Herman Phillips, Assistant Facilities Manager, ORNL Special Projects. • Ms. Swati Wilson, Manager, ORNL Lead Management Program. • Mr. Nathan Dunn, Hazardous Material Information System Office. • Mr. Jade Thomas, ORNL Environmental Compliance Office. • Mr. Joe Armento, ORNL Chemical Technology Division, Isotopes Facilities Shutdown Program. 	

The RmSE of this facility was conducted for LMES under contract by:

Advanced Sciences, Inc.
800 Oak Ridge Turnpike, Suite C-102
Oak Ridge, TN

Todd R. Grant

Evaluator's Signature

6/18/96

Date

Building 7025

ORNL DWG 90A-606

15-9




Fig. 19. Diagram of Building 7025.

DISTRIBUTION

1. L. V. Asplund
2. T. W. Burwinkle
3. K. W. Cook
4. R. E. Eversole
5. L. L. Kaiser
- 6-8. D. M. Matteo (3)
9. P. T. Owen
10. L. D. Owens
11. P. A. Schrandt
12. Central Research Library
13. ER Central Doc. Mgmt. Center—RC
14. R. L. Nace, Team Leader, Fernald/Ohio Team, Office of Environmental Restoration, U.S. Department of Energy, Cloverleaf Building, EM-425, 19901 Germantown Road, Germantown, MD 20874
15. J. W. Wagoner II, Team Leader, Portsmouth/Paducah/Weldon Spring Team, Office of Environmental Restoration, U.S. Department of Energy, Cloverleaf Building, EM-424, 19901 Germantown Road, Germantown, MD 20874
16. V. F. Boston, DOE Oak Ridge Operations Office, P.O. Box 2001, Oak Ridge, TN 37831-8541
- 17-18. R. C. Sleeman, Director, Environmental Restoration Division, DOE Oak Ridge Operations Office, P.O. Box 2001, Oak Ridge, TN 37831-8541 (2)
- 19-20. Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831 (2)
21. T. R. Conant, Advanced Sciences, Inc., 800 Oak Ridge Turnpike, Suite C-102, Oak Ridge, TN 37830-6927