Predicting the Reliability of Package-on-Package-Package (PoPoP) Interconnections Based on Accelerated Aging Experiments and Computational Modeling

P. Vianco, J. Rejent, M. Grazier, B. McKenzie, A. Kilgo, and M. Neilsen,

Sandia National Laboratories*
Albuquerque, NM 87185

Contact: ptvianc@sandia.gov





*Sandia National Laboratories is a multi-program laboratory operated by Sandia Corporation, a Lockheed Martin Company, for the U.S. Department of Energy's National Nuclear Security Administration under contract DE-AC04-94AL85000.

Acknowledgements

- ◆ The authors would like to thank the engineers and supporting staff at STI Electronics (Madison, AL) for developing and executing the processes used to assemble the test vehicles.
- ♦ The authors wish to and Brian Wroblewski of Sandia for his thorough review of the proceedings.

- The high-reliability electronics community ...
 - Military systems,
 - Space vehicles
 - Satellite hardware

... is demanding increased functionality from products, which must also meet stricter size, weight, and power (SWaP) requirements.



- Three-dimensional (3-D) packaging ...
 - Stacked packages
 - Stacked die

... provides an effective approach to meet these objectives in the next generation of flight and ground systems.



Currently, the high-reliability community favors stacked package technology based upon the "known good package" concept.



Package-on-Package (PoP)



Package-on-Package (PoPoP)


- The qualification of 3-D packaging must consider temperature cycling conditions, including assembles that may also have these unique features:
 - Backwards compatible, second-level interconnections
 - Underfill and/or staking
 - Conformal coatings






- A multi-year study is developing both the empirical database and computational modeling tools for predicting the long-term reliability of stacked package interconnections.
- The project began with a package-on-package (PoP) investigation* †:








^{*}P. Vianco, J. Grazier, J. Rejent, A. Kilgo, F. Verdi, and C. Meola, Proc. Surf. Mount. Tech. Assoc. Inter. (2009)

[†]P. Vianco, M. Neilsen, J. Rejent, J. Grazier, and A. Kilgo, *Proc. Surface Mount Tech. Assoc. Inter.* (2013)


The results of the PoP study were not intuitively obvious – e.g., the effect of underfill on thermal mechanical fatigue (TMF) behavior:



The synergistic effects between multiple materials results in the complex response of PoP interconnections to thermal cycles.

The test vehicle details are listed below:


- Printed circuit board:
 - 1 mm thick
 - High temperature FR-4 laminate ($T_g = 180$ °C)
 - Organic solderability preservative (OSP) surface finish




Test vehicle

Packages:


- Top package. bottom: 128 I/O; 0.65 mm pitch; ENIG finish; SAC305 balls
- Middle package. top: 128 I/O; 0.65 mm pitch; ENIG finish;
 bottom: 128 I/O; 0.65 mm pitch; ENIG finish; SAC105 balls
- Bottom package. top: 128 I/O; 0.65 mm pitch; ENIG finish; bottom: 305 I/O; 0.50 mm pitch; bare Cu; SAC305 balls



- A two-step, assembly process was used to build the test vehicles.
- Step (1): construct the individual PoPoP component (stacks):




The stack reflow step creates the first-level, Pb-free interconnections that stacks individual packages into the PoPoP component.



- The solder reflow step forms the second-level interconnections between the PoPoP component to the printed circuit board (PCB).
- There are two solder reflow profiles:

1/31/2017

- Low-temperature, Sn-Pb reflow profile for backwards compatibility.
- High-temperature, Pb-free reflow profile.




10

- Thermal cycling provided the accelerated aging environment.
 - Temperature extremes -55°C / 125°C.
 - Hold times 15 min.
 - Ramp rates 10°C / min.
- Sample counts:
 - N = 20 backwards compatibility
 - N = 20 Pb-free solder joints
 - In each group of 20 PWAs:
 - N = 8, no underfill
 - N = 4, underfill; bottom gap only
 - N = 4, underfill; bottom and middle gaps
 - N = 4, underfill; bottom, middle and top gaps
- Duplicate PWAs were monitored to capture failures in the three levels of solder joints.

2. Top joints

3. Middle joints ———


1. Bottom joints (PCB) —




1/31/2017 SMTAI 2016 11

Failure analysis steps included (a) extraction of a PoPoP package;
 (b) cross section; and (c) microanalysis techniques (SEM, EDX, etc.).













Section 3

- An objective of the backwards compatible test vehicles was to assess the TMF of the inhomogeneous microstructure.
- This microstructure was observed on only one (1) test vehicle.



S/N05: as-fabricated; underfill, middle and bottom gaps


The dual microstructure is illustrated by this optical micrograph:




S/N05: as-fabricated; underfill, middle and bottom gaps


Excessive voids and cracks were not observed in any joints.

Understanding the mixed-metallurgy microstructure is critical to the execution of PoPoP technology in high-reliability electronics.






Energy dispersive x-ray (EDX) analysis indicate that both the Pb-rich and Ag₃Sn phases are distributed nonhomogeneously in the "mixed" Sn-Pb/SAC 305" region.




The remaining, backwards compatible test vehicles exhibited homogeneous distributions of Pb-rich phase in the solder joints.





S/N07: as-fabricated; underfill, middle gap

This optical micrograph shows the homogeneous microstructure.




Although the Ag₃Sn particles were not uniformly distributed across the entire joint, this trend did not affect TMF performance.







A direct correlation was not observed between the Pb-rich and Ag₃Sn phases within either the homogeneous or the inhomogeneous microstructures.



The microstructure analysis also confirmed the excellent integrity of the SAC105 solder joints that attached middle package to the bottom package ...







19

S/N05: as-fabricated; underfill, middle and bottom gaps

 ... as well as SAC305 interconnections that joined the middle package to the top package.





S/N05: as-fabricated; underfill, middle and bottom gaps

Recall that the middle and top solder joints had undergone two soldering steps: initial stack reflow and subsequent, solder reflow.

Mixed SnPb/SAC305 bottom joints; no underfill: The 2P Weibull data indicated that all three solder joints had nearly identical behaviors despite the different solder compositions.

Top joints:

 $\eta = 2600 \pm 200$ cycles $\beta = 8.7 \pm 4.0$

Middle joints:


 $\eta = 2500 \pm 300$ cycles $\beta = 6.6 \pm 3.4$

Bottom joints:

 $\eta = 2600 \pm 200$ cycles $\beta = 7.6 \pm 3.5$


Combined joints:

 $η = 2600 \pm 100$ cycles $β = 7.5 \pm 2.1$



S/N22 and S/N23: Mixed SnPb/SAC305; No underfill


Mixed SnPb/SAC305 bottom joints; no underfill: Failure of the top solder joints was caused by the "100% crack" at the top pad.



S/N22, U10A, top; No underfill; Failed: 3068 cycles


Partial cracks were observed at the bottom pad (middle package).

Mixed SnPb/SAC305 bottom joints; no underfill: The "100% crack" exhibited the expected TMF morphology of having developed in the SAC305 solder near to, but not at, the solder/pad interface.




S/N22, U10A, top; No underfill; Failed: 3068 cycles

Mixed SnPb/SAC305 bottom joints; no underfill: The "100% crack" of the middle solder joints was near the bottom pad.




S/N22, U10A, top; No underfill; Failed: > 3068 cycles

Mixed SnPb/SAC305 bottom joints; no underfill: An example of the "100% crack" was not captured for the bottom solder joints in this particular cross section; the partial TMF crack is evident.



S/N22, U10A, top; No underfill; Failed: > 3068 cycles

 Mixed SnPb/SAC305 bottom joints; no underfill: The data show a slight preference for failures to occur at low temperatures.



100% SAC305 bottom joints; no underfill: The 2P Weibull data show that the TMF was more distinct vis-a-vis the three solder joint types.

Top joints:

 $\eta = 2400 \pm 200$ cycles $\beta = 10.6 \pm 6.0$

Middle joints:


 $\eta = 2600 \pm 500$ cycles $\beta = 5.0 \pm 2.0$

Bottom joints:

 $\eta = 2200 \pm 200$ cycles $\beta = 5.2 \pm 2.0$

Combined joints:

 $\eta = 2400 \pm 200$ cycles $\beta = 5.0 \pm 1.2$



S/N44 and S/N45: 100% SAC305; No underfill

• 100% SAC305 bottom joints; no underfill: The outliers that caused the small β terms for the middle and bottom joints occurred at the high-cycle counts rather than the typical, "early failures".

Cumulative Failure Fraction

Top joints:

 $\eta = 2400 \pm 200$ cycles $\beta = 10.6 \pm 6.0$


Middle joints:


 $\eta = 2600 \pm 500$ cycles $\beta = 5.0 \pm 2.0$

Middle joints, censored: $\eta = 2400 \pm 500$ cycles $\beta = 8.2 \pm 4.7$

Bottom joints:

 $η = 2200 \pm 200$ cycles $β = 5.2 \pm 2.0$





S/N44 and S/N45: 100% SAC305; No underfill

1/31/2017 SMTAI 2016 28

- 100% SAC305 vs. Mixed SnPb/SAC305 bottom joints; no underfill:
- The SnPb/SAC305 bottom joints exhibited a slightly "better" fatigue behavior (higher values of η and β) than the 100% SAC305 joints.
- The SnPb/SAC305, bottom joints exhibited higher values of both η and β:
 - Mixed SnPb/SAC305:

Bottom joints:


 $\eta = 2600 \pm 200 \text{ cycles}$ $\beta = 7.6 \pm 3.5$

100% SAC305:


Bottom joints:

 $\eta = 2200 \pm 200$ cycles

 $\beta = 5.2 \pm 2.0$



- 100% SAC305 bottom joints; no underfill:
 - The top and middle solder joints showed the same, slight preference for failure towards the low temperatures.
 - The bottom joints exhibited failures at the high and low temperatures to relatively a similar degree.



The TMF performance of the PoPoP is not coupled between the three levels of interconnections in the absence of underfill.

Mixed SnPb/SAC305 bottom joints; Underfill, bottom gap, only:

 Failure data were collected only for the middle joints and top joints because the bottom joints "outlived" the other joints.

Top joints:

 $\eta = 3100 \pm 300$ cycles $\beta = 5.5 \pm 2.0$

Middle joints:


 $\eta = 3000 \pm 400$ cycles $\beta = 5.3 \pm 2.1$

Combined joints:

 $\eta = 3200 \pm 300$ cycles $\beta = 4.8 \pm 1.2$

·

Bottom joints (N = 1): n = 4506 cycles




Mixed SnPb/SAC305 bottom joints; Underfill, bottom gap ... versus ...


Mixed SnPb/SAC305 bottom joints; No underfill.

	No underfill		Underfill, bottom	
Solder Joint Level	η	β	η	β
Top solder joints	2600 <u>+</u> 200	8.7 <u>+</u> 4.0	3100 <u>+</u> 300	5.5 <u>+</u> 2.1
Middle solder joints	2500 ± 300	6.6 <u>+</u> 3.4	3000 <u>+</u> 400	5.3 <u>+</u> 2.1
Bottom solder joints	2600 <u>+</u> 200	7.6 <u>+</u> 3.5	3500 (N = 1)	

◆ The presence of underfill in the bottom gap, only, improved the TMF resistance of all three levels of interconnections.




Mixed SnPb/SAC305 bottom joints; Underfill, bottom gap, only:
 The top solder joints failed by a "100% crack" at the top pad.



S/N10, U10A, top; Underfill, bottom; Failed: ≥ 4506cycles

A partial crack was observed at the bottom pad (middle package).


Mixed SnPb/SAC305 bottom joints; Underfill, bottom gap, only: The middle joints failed by a "100% crack" at the bottom pad.



S/N10, U10A, top; Underfill, bottom; Failed: ≥ 4506cycles

A partial crack was observed at the top pad (top package).

- Mixed SnPb/SAC305 bottom joints; Underfill, bottom gap, only:
- The bottom solder joints had not failed; but, they did exhibited the development of the Pb-rich layer ahead of IMC growth (blue arrows.)




- 100% SAC305 bottom joints; Underfill, bottom gap, only:
- The bottom solder joints were the life-limiting interconnections.
 - 2P Weibull failure statistics are shown for the bottom joints.

Bottom joints:

 $\eta = 1600 \pm 200 \text{ cycles}$ $\beta = 2.7 \pm 0.8$


- The interconnections had a relatively low η value very wide failure distribution (low β).
- A "knee" is observed at a cumulative failure fraction (CFF) ≈ 0.6, or 1300 cycles.



S/N33 and S/N36: 100% SAC305; Underfill, bottom, only


- 100% SAC305 bottom joints; Underfill, bottom gap, only:
- A "knee" CFF plot suggests that the solder joint TMF is governed by two failure mechanisms.
- The 2P Weibull failure statistics were recalculated, assuming that there were two populations:


```
CFF < 0.6 (N = 16):</th>CFF < 0.6 (N = 12):</th>\eta = 1000 \pm 100 cycles\eta = 2100 \pm 200 cycles\beta = 6.3 \pm 2.5\beta = 6.0 \pm 2.6
```



- The "high-η" mechanism must avoid the "low-η" mechanism.
- Since both failure regimes had similar populations, it is inferred that any solder joint has roughly an equal chance of failing under either mechanism.

- 100% SAC305 bottom joints; Underfill, bottom gap, only:
- The microstructures were examined, which belonged to both "high-η" and "low-η" mechanisms.





100% SAC305; S/N33, U14 Underfill, bottom, only

100% SAC305; S/N33, U01 Underfill, bottom, only


"Low-n" mechanism


"High-η" mechanism

The "high-η"mechanism included cracks at the Cu pad (red arrows).


Results – Statistics versus Failure Mode

- 100% SAC305 bottom joints; Underfill, bottom gap, only:
- Several observations were compiled along with their consequences:
 - The T_{max}. of the cycle, 125°C, exceeds the underfill T_q of 120°C
 - Tensile stresses due to the sharp increase of CTE generate the Cu pad cracks.
 - Greater solder joint damage was associated with a longer fatigue life.
 - "Early" damage can reduce fatigue strain by decoupling the structures (PCB, solder joint, and package) from one-another.
 - Yet, only 43% of PoPoPs were "high-η".
 - The glass transition "zone," coupled with the complex construction of the PoPoP, caused this bimodal failure behavior to prevail as an "edge-of-the-cliff" behavior.





- 100% SAC305 bottom joints; Underfill, bottom gap, only:
- The temperature-at-failure data indicate that tensile stresses due to underfill thermal expansion affected bottom solder joint TMF.



Summary

- A long-term study is underway to develop a toolset for predicting the reliability of stacked package technology.
 - Package-on-package (PoP).
 - Package-on-package-on-package (PoPoP).
 - Thermal mechanical fatigue (TMF).
 - Accelerated aging empirical data.
 - Computational modeling codes and software.
- ◆ Some constructions are unique to high-reliability applications:
 - Backwards compatibility.
 - Test environments.
 - Use of underfill materials and staking compounds.
 - Conformal coatings on PWA.

Summary (con't)

- The backwards compatible, mixed SnPb/SAC305 bottom solder joints had a longer TMF lifetime than did the 100% SAC305 joints.
 - The middle and top interconnections exhibited comparable TMF lifetimes for both test vehicle genres.
- Placement of underfill in the bottom gap increased the characteristic lifetimes (η) of top, middle, and bottom for the mixed Sn-Pb/SAC305 solder joints.
 - The slope parameter (β) decreased with the addition of underfill to the bottom gap.
- The presence of underfill in the bottom gap caused the 100% SAC305 bottom solder joints to exhibited a bimodal failure mode a "high-η" mechanism and a "low-η" mechanism.
 - No underfill: $\eta = 2200 \pm 200$ cycles
 - Underfill, "low- η " mechanism: $\eta = 1000 \pm 100$ cycles
 - Underfill, "high- η " mechanism: η = 2100 \pm 200 cycles

1/31/2017

Summary (con't)

◆ The bimodal failure mode of the 100% SAC305 bottom solder joints with underfill was correlated to different fracture microstructures...