

27
8/14/79
23 OPN/NTS

MASTER

UCID- 18129

Lawrence Livermore Laboratory


TECHNICAL EVALUATION OF THE SUSCEPTIBILITY OF SAFETY-RELATED SYSTEMS
TO FLOODING CAUSED BY THE FAILURE OF NON-CATEGORY I SYSTEMS
FOR TURKEY POINT NUCLEAR POWER PLANT, UNITS 3 AND 4

E. Kejka Collins

August 1979



This is an informal report intended primarily for internal or limited external distribution. The opinions and conclusions stated are those of the author and may or may not be those of the laboratory.
This work was supported by the U.S. Nuclear Regulatory Commission under Interagency Agreement DOE 40-550-75 with the U.S. Department of Energy.



DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

ABSTRACT

This report documents the technical evaluation of the Florida Power and Light Company's Turkey Point nuclear power plants, Units 3 and 4, to determine whether the failure of any non-Category I (seismic) equipment could result in a condition, such as flooding, that might potentially adversely affect the performance of safety-related equipment required for the safe shutdown of the facilities or to mitigate the consequences of an accident. Criteria developed by the U. S. Nuclear Regulatory Commission were used to evaluate the acceptability of the existing protection as well as measures taken by Florida Power and Light Company to minimize the danger of flooding and to protect safety-related equipment.

NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Department of Energy, nor any of their employees, or any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

FOREWORD

This report is supplied as part of the Selected Electrical, Instrumentation, and Control Systems Issues (SEICSI) Program being conducted for the U. S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, Division of Operating Reactors, by the Lawrence Livermore Laboratory, Field Test Systems Division.

The Nuclear Regulatory Commission funded the project under the authorization entitled "Electrical, Instrumentation, and Control System Support," No. B&R 20-19-04-031, FIN A-0231.

This work was performed by EG&G, San Ramon Operations, for Lawrence Livermore Laboratory under U. S. Department of Energy Contract No. DE-AC08-76NV01183.

TABLE OF CONTENTS

	<u>Page</u>
1. INTRODUCTION	1
2. EVALUATION OF TURKEY POINT UNITS 3 AND 4	3
2.1 Introduction	3
2.2 Sources of Flooding.	3
2.3 Safety-Related Equipment Subject to Flooding Damage	4
2.4 Evaluation	4
2.4.1 General Considerations	4
2.4.2 Diesel Generator Room.	5
2.4.3 Residual Heat Removing System Pumps	5
2.4.4 Switchgear Rooms	6
2.4.5 Safety Injection Pumps	7
2.4.6 Motor Control Centers.	7
2.4.7 Charging Pumps, Containment Spray Pump Rooms, and Boric Acid Transfer Pump Room.	8
2.4.8 Component Cooling Water Pumps	8
2.4.9 Auxiliary Feedwater Pumps.	9
2.4.10 Control Room, Reactor Protection Equipment Rooms, and Battery Rooms	9
3. CONCLUSIONS	11
APPENDIX.	13
REFERENCES.	17

TECHNICAL EVALUATION OF THE
SUSCEPTIBILITY OF SAFETY-RELATED SYSTEMS TO FLOODING
CAUSED BY THE FAILURE OF NON-CATEGORY I SYSTEMS
FOR
TURKEY POINT NUCLEAR POWER PLANT, UNITS 3 AND 4

E. Kejka Collins
EG&G, Energy Measurements Group
San Ramon Operations

1. INTRODUCTION

By letter to the Florida Power and Light Company (FPLCO) dated September 26, 1972, the Nuclear Regulatory Commission (NRC) requested a review of nuclear power plants to determine whether the failure of any non-Category I (seismic) equipment, particularly in the circulating water system and fire protection system, could result in a condition, such as flooding, that might adversely affect the performance of safety-related equipment required for safe shutdown of the facilities or which might be required to limit the consequences of an accident [Ref. 1]. By letter dated November 6, 1972 [Ref. 2], and subsequent letters, the Florida Power and Light Company submitted the additional information requested by the NRC, as well as descriptions of various plant changes implemented to mitigate the effects of failure of some non-Category I systems on safety-related equipment. The NRC guidelines [Ref. 3] are provided as an Appendix to this report.

The purpose of this technical evaluation is to determine, on the basis of the information provided (refer to References), whether the licensee's response and equipment/plant modifications seem to be adequate to preclude the flooding/damage of equipment important to safety.

2. EVALUATION OF TURKEY POINT UNITS 3 AND 4

2.1 INTRODUCTION

Three separate reviews of the Turkey Point Units 3 and 4 were conducted by the FPLCO between 1972 and 1975. Initially, at the request of NRC in 1972, the FPLCO reviewed several water systems as sources of flooding. Subsequently, as a result of an abnormal occurrence, the drainage system was reviewed. Finally, the facilities were again reviewed at NRC's request and both the potential sources of flooding and safety-related equipment which could be damaged by flooding were identified. The sources of flooding and the appropriate safety equipment are discussed in Sections 2.2 and 2.3. Section 2.4 provides an evaluation of measures that were taken by FPLCO to minimize the danger of flooding and to protect safety-related equipment.

2.2 SOURCES OF FLOODING

During the Licensee's three reviews of Turkey Point Units 3 and 4, the following potential sources of flooding were identified:

- (1) Circulating water system
- (2) Fire protection system
- (3) Component cooling system
- (4) Drainage system
- (5) Chemical and volume control system (holdup tanks)
- (6) Primary and service water tanks

2.3 SAFETY-RELATED EQUIPMENT SUBJECT TO FLOODING DAMAGE

The following safety-related systems, equipment, or locations were considered by the Licensee to require protection from flooding:

- (1) Diesel generator room
- (2) Residual heat removing system
- (3) Switchgear rooms
- (4) Safety-injection pumps
- (5) Motor control centers
- (6) Charging pumps, containment spray pump rooms, and boric acid transfer pump room
- (7) Component cooling water pumps
- (8) Auxiliary feedwater pumps
- (9) Control room, reactor protection equipment rooms, and battery rooms

2.4 EVALUATION

2.4.1 General Considerations

Turkey Point Units 3 and 4 are outdoor nuclear power plants. As a result, flooding problems are, in general, minimized. Flooding occurring outdoors at grade elevation (18 feet) in the turbine area generally free-flows into the yard where it is drained off to the circulating water intake canal immediately east of the plants or to the discharge canal just west of the plants. Protection from flooding for equipment located in the Auxiliary Building is generally provided by the arrangement of the equipment [Ref. 4]. All safety-related equipment with the exception of the residual heat removal system is located in rooms at grade elevation or above. Furthermore, equipment that could be damaged by flooding is located above the floor (a minimum of 18 inches) in these rooms.

The Auxiliary Building has a considerable amount of free volume below grade level. The non-Category I tanks whose rupture could result in the flooding of the Auxiliary Building have negligible volume when compared to the free volume of the building that would have to be flooded before the rooms housing safety equipment and located at grade elevation were reached.

The chemical and volume control system holdup tanks are located, below grade elevation, in individual compartments which can be isolated to contain the tank volume in the event of a tank rupture. Only the piping connecting the holdup tanks, the primary water tank, and the service water tank to the Auxiliary Building could cause flooding if a rupture occurred. The Licensee has indicated that the piping is small, and that its rupture would be detected and isolated sufficiently early to prevent serious flooding.

Pipe trenches are blocked to prevent flow into the Auxiliary Building. Entrances into the Auxiliary Building are closed by doors with water-tight sills. These doors are maintained closed by administrative procedure. In addition, there is also at least one operator in the area who would become aware of any flooding problems emanating from the turbine area. We consider these measures adequate.

2.4.2 Diesel Generator Room

The diesel generator room is at grade elevation. The generators are located on pedestals, and any water in the room from ruptures in the 1 1/2-inch piping (which carries water used for washdown) would run out the door through a large vent opening in the door at floor level [Ref. 5]. We consider this measure to be adequate in mitigating the consequences of flooding.

2.4.3 Residual Heat Removing System Pumps

The residual heat removing pump rooms, located below grade elevation in the Auxiliary Building, could be subject to flooding should a fire protection system piping break occur [Ref. 4]. The pump rooms, however, contain sump level alarms which sound in the control room to apprise the operator of an abnormal condition in the room [Ref. 2]. In addition, each pump room is equipped with a sump and automatic pumping system. The motors of the pumps and valves are positioned at least 30 inches above the floor [Ref. 6]. Water entering the rooms from the rupture of piping would be

pumped out, or the alarm would be received in time for the operator to take action before serious flooding could occur. These measures are considered adequate in mitigating the consequences of flooding.

2.4.4 Switchgear Rooms

The 4160-volt switchgear rooms are located at grade elevation in the Turbine Building. These rooms are subject to several possible sources of flooding, thereby causing damage to the redundant 4-kV buses located inside.

The first possible source of flooding (and one which resulted in an abnormal occurrence at the facility in 1972) is rainwater backing up floor drainpipes and entering the switchgear rooms by seeping under the doors during a heavy rain storm. Since that occurrence, the drains have been blocked off [Ref. 10]. The Licensee has further indicated that two sumps were installed in each of the switchgear rooms. Each sump is equipped with a high water-level alarm and a sump pump which would automatically begin to pump out any water flooding the rooms [Ref. 6]. In addition, grating-covered drains have been installed outside the switchgear rooms in front of the main door leading to the rooms to preclude rainwater from entering under the doors again [Ref. 6]. We consider these measures adequate.

A second possible source of flooding is a circulating water system piping rupture which would flood the condenser pit and possibly subsequently overflow into the switchgear area. As mentioned in relation to the motor control centers (Section 2.4.5), the Licensee believes that the water from this type of overflow would run off without achieving any level to speak of and without impairing the operation of the 4-kV buses.

Steam and water pipes which pass (or passed) through the switchgear rooms were considered as the third possible source of flooding. These pipes have been modified or re-routed. Specifically, the fire main riser pipe in Unit 3 and the low pressure steam lines in unit 4 were re-routed

outside the switchgear rooms, while several small, low-energy cooling water pipes which carry water to the generator exciter and to priming air ejector coolers for both Units 3 and 4 were encased in sheet steel boxes so that any leakage would run outside the structure through the annular space between pipes and the wall penetration holes [Ref. 8, 9]. We consider these measures adequate to mitigate the consequences of flooding.

2.4.5 Safety Injection Pumps

The safety injection pumps are located, at grade elevation, in a separate compartment which is not in communication with non-Category I systems which could flood the pumps [Ref. 4]. Pipe trenches leading to or from the room are blocked to prevent water flow. These measures are considered adequate to prevent flooding of the safety injection pumps.

2.4.6 Motor Control Centers

All safety-related motor control centers are located at grade elevation, are physically separated from each other, and are mounted on 6-inch pedestals [Ref. 4].

Two of the motor control centers (3C and D), which are located in the east-west corridor of the Auxiliary Building, might be subject to wetting should a failure of the fire protection system piping occur. These control centers, however, are backed up by redundant equipment in other locations [Ref. 4]. The possibility of a common mode failure of these redundant systems due to fire protection system piping failure does not exist according to the licensee [Ref. 2]. These centers could, however, be flooded by the flooding of the free volume of the Auxiliary Building below grade elevation. It is believed that flooding of this nature would be detected in sufficient time to mitigate the flooding problem. We concur with this evaluation.

Two additional motor control centers (3B and 4B) are located in separate rooms and are not in contact with any non-Category I systems which would result in flooding [Ref. 4]. We concur with this evaluation.

One motor control center (4A) is located in an open area in the vicinity of the Unit 4 switchgear room (refer to Section 2.4.4). This area could receive water from the condenser pit in the event the pit floods from a rupture in the main circulating water system piping. The water, however, would run off on the ground without achieving any level and without impairing the operation of the motor control center [Ref. 4].

2.4.7 Charging Pumps, Containment Spray Pump Rooms, and Boric Acid Transfer Pump Room

The charging pump rooms, containment spray pump rooms, and the boric acid transfer pump room are located at grade elevation and are in contact with the Auxiliary Building at or below grade elevation. For flooding to occur in any of these rooms, it would be necessary for the entire Auxiliary Building below grade level to be flooded [Ref. 4].

The charging pump motors are located at least 24 inches above the floor and the containment spray and boric acid transfer pump motors are at least 17 inches above the floor [Ref. 6]. These measures are considered adequate to mitigate the consequences of flooding.

2.4.8 Component Cooling Water Pumps

The component cooling water pumps are located, at grade elevation, in an outdoor area. Any piping failure in this area (specifically in the intake of cooling water discharge piping) would result in the water running off as does rain-water [Ref. 4]. Pipe trenches leading to or from the component cooling system rooms are blocked to prevent water flow into the Auxiliary Building [Ref. 2]. These measures are considered adequate to mitigate the consequences of flooding.

2.4.9 Auxiliary Feedwater Pumps

The auxiliary feedwater pumps are located outside the Auxiliary Building at grade elevation. The pumps and controls are elevated above grade, and the Licensee has stated that water will run off on the ground to the discharge or intake canal [Ref. 4]. We concur with that evaluation.

2.4.10 Control Room, Reactor Protection Equipment Rooms, and Battery Rooms

The control room, the reactor protection equipment rooms, and the battery rooms, while located above grade level, do have service water piping which passes through the rooms or through adjoining non-water-tight rooms. The reactor protection equipment rooms and the battery rooms have floor drains which are part of the storm drain system [Ref. 6]. The Licensee states that the drainage system and operator action to isolate ruptures in the piping would be sufficient to protect the rooms from flooding should a rupture in one of the lines occur because the lines are small (less than 1 inch in diameter) [Ref. 4]. We concur with this evaluation.

3. CONCLUSIONS

Based on our review of the documentation provided by the Licensee (refer to the References), the existing equipment/proposed modifications for Turkey Point Units 3 and 4 are acceptable insofar as they prevent or mitigate the consequences of the failure of a non-Category I system which would result in the flooding of safety-related systems that are required for the safe shutdown of the facilities.

APPENDIX

APPENDIX

NRC GUIDELINES FOR PROTECTION FROM FLOODING OF EQUIPMENT IMPORTANT TO SAFETY

Licensees are required to investigate their facilities or review their designs to assure that equipment important to safety will not be damaged by flooding due to rupture of a non-Class I system component or pipe such that engineered safety features will not perform their design function. No single incident of a non-Class I system component or pipe failure shall prevent safe shutdown of the facility.

Further guidelines:

1. Separation for redundancy - single failures of non-Class I system components or pipes shall not result in loss of a system important to safety. Redundant safety equipment shall be separated and protected to assure operability in the event a non-Class I system or component fails.
2. Access doors and alarms - watertight barriers for protection from flooding of equipment important to safety shall have all access doors or hatches fitted with reliable switches and circuits that provide an alarm in the control room when the access is open.
3. Sealed water passages - passages or piping and other penetrations through walls of a room containing equipment important to safety shall be sealed against water leakage from any postulated failure of non-Class I water systems. The seals shall be designed for the SSE, including seismically indicated wave action of water inside the affected compartments during the SSE.
4. Class I watertight structures - walls, doors, panels, or other compartment closures designed to protect equipment important to safety from damage due to flooding from a non-Class I system rupture shall be designed for the SSE, including seismically induced wave action of water inside the affected compartment during the SSE.
5. Water level alarms and trips - rooms containing non-Class I system components and pipes whose rupture could result in flood damage to equipment important to safety shall have level alarms and pump trips (where necessary) that alarm in the control room and limit flooding to within the design flood volume. Redundance of switches is required. Critical pump (i.e.,

high volume flow, such as condenser circulating water pumps) trip circuits should meet IEEE 279 criteria.

6. Class I equipment should be located or protected such that rupture of a non-Class I system connected to a tower containing water or body of water (river, lake, etc.) will not result in failure of the equipment from flooding.
7. The safety analysis shall consider simultaneous loss of offsite power with the rupture of a non-Class I system component or pipe.

The licensees' responses should include a listing of the non-Class I systems considered in their analysis. These should include at least the following systems:

Firewater	Demineralized Water
Service Water	Drains
Condensate	Heating Boiler Condensate
Feedwater	Condenser Circulating Water
Reactor Building Cooling Water	Makeup
Turbine Building Cooling Water	Potable Water

REFERENCES

- [1] R. C. DeYoung, Nuclear Regulatory Commission (NRC), Wash., D.C., private communication to James Coughlin of the Florida Power and Light Company (FPLCO), Miami, FLA (September 26, 1972).
- [2] James Coughlin, FPLCO, Miami, FLA, private communication to R. C. DeYoung, NRC, Wash., D.C. (November 6, 1972).
- [3] George Lear, NPC, Wash., D.C., private communication to Robert E. Uhrig of FPLCO, Miami, FLA (December 5, 1974).
- [4] Robert E. Uhrig, FPLCO, Miami, FLA, private communication to George Lear, NRC, Wash., D.C. (January 7, 1975).
- [5] E. Kejka Collins of EG&G, San Ramon, CA, private communication to John F. Burdoin, NRC, Wash., D.C. (December 5, 1978).
- [6] Turkey Point Flooding Review response to NRC questions (March 6, 1979).
- [7] A. D. Schmidt, FPLCO, Miami, FLA, private communication to John F. O'Leary, NRC, Wash., D.C. (November 17, 1972).
- [8] James Coughlin, FPLCO, Miami, FLA, private communication to R. C. DeYoung, NRC, Wash., D.C. (January 5, 1973).
- [9] Robert E. Uhrig, FPLCO, Miami, FLA, private communication to George Lear, NRC, Wash., D.C. (August 18, 1975).
- [10] J. F. Burdoin, NRC, Wash., D.C., private communication to E. Kejka Collins, EG&G, San Ramon, CA (July 13, 1979).