


Nevada
Environmental
Restoration
Project

DOE/NV--795



Post-Closure Inspection Report
for Corrective Action Unit 453:
Area 9 UXO Landfill Tonopah Test
Range, Nevada
Calendar Year 2001

Controlled Copy No.: UNCONTROLLED

Revision: 0

January 2002

Environmental Restoration
Division

U.S. Department of Energy
National Nuclear Security Administration
Nevada Operations Office

DISCLAIMER STATEMENT

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the U.S. Government or any agency thereof or its contractors or subcontractors.

AVAILABILITY STATEMENT

Available for sale to the public from-
U.S. Department of Commerce
National Technical Information Service
5285 Port Royal Road
Springfield, VA 22161-0002
Telephone: 800.553.6847
Fax: 703.605.6900
E-mail: orders@ntis.fedworld.gov
Online ordering: <http://www.ntis.gov/ordering.htm>

Available electronically at <http://www.doe.gov/bridge>

Available for a processing fee to U.S. Department of Energy and its contractors, in paper, from-
U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62
Oak Ridge, TN 37831-0062
Telephone: 865.576.8401
Fax: 865.576.5728
E-mail: reports@adonis.osti.gov

**POST-CLOSURE INSPECTION REPORT FOR
CORRECTIVE ACTION UNIT 453:
AREA 9 UXO LANDFILL
TONOPAH TEST RANGE, NEVADA
CALENDAR YEAR 2001**

Prepared for
U. S. Department of Energy
National Nuclear Security Administration
Nevada Operations Office
Work Performed Under Contract No.
DE-AC08-96NV11718

Controlled Copy No.: _____

Revision: 0

January 2002

UNCONTROLLED

THIS PAGE INTENTIONALLY LEFT BLANK

**POST-CLOSURE INSPECTION REPORT FOR
CORRECTIVE ACTION UNIT 453:
AREA 9 UXO LANDFILL
TONOPAH TEST RANGE, NEVADA
CALENDAR YEAR 2001**

Approved by: Janet L. Appenzeller-Wing
Janet L. Appenzeller-Wing, Project Manager
Industrial Sites Project

Date: 1/23/02

Approved by: Runore C. Wycoff
Runore C. Wycoff, Division Director
Environmental Restoration Project

Date: 1-28-02

THIS PAGE INTENTIONALLY LEFT BLANK

TABLE OF CONTENTS

1.0 INTRODUCTION	1
2.0 INSPECTION RESULTS	1
2.1 May 15, 2001 Inspection	1
2.2 November 6, 2001 Inspection	3
2.3 November 15, 2001 Maintenance and Repair Activities	3
3.0 CONCLUSIONS AND RECOMMENDATIONS	3

FIGURES

FIGURE 1 - AREA 9 UXO LANDFILL CAU 453 LOCATION MAP	2
---	---

ATTACHMENTS

ATTACHMENT A - INSPECTION CHECKLISTS

ATTACHMENT B - FIELD NOTES

ATTACHMENT C - PHOTOGRAPH LOG AND PHOTOGRAPHS

DISTRIBUTION LIST

THIS PAGE INTENTIONALLY LEFT BLANK

1.0 INTRODUCTION

Post-closure monitoring requirements for the Area 9 Unexploded Ordnance Landfill (Corrective Action Unit [CAU] 453) (Figure 1) are described in Closure Report for Corrective Action Unit 453: Area 9 UXO Landfill, Tonopah Test Range, Nevada, report number DOE/NV--284, August 1999. The Closure Report (CR) was submitted to the Nevada Division of Environmental Protection (NDEP) on August 5, 1999. The CR (containing the Post-Closure Monitoring Plan) was approved by the NDEP on September 10, 1999.

As stated in Section 5.0 of the NDEP-approved CR, post-closure monitoring at CAU 453 consists of the following:

- Visual site inspections are conducted twice a year to evaluate the condition of the cover.
- Verification that the site is secure and the condition of the fence and posted warning signs.
- Notice of any subsidence, erosion, unauthorized excavation, etc., deficiencies that may compromise the integrity of the unit.
- Remedy of any deficiencies within 90 days of discovery.
- Preparation and submittal of an annual report.


Site inspections were conducted on May 15, 2001 and November 6, 2001. Both site inspections were conducted in accordance with the Post-Closure Monitoring Plan in the NDEP-approved CR.

This report includes copies of the inspection checklists, photographs, recommendations, and conclusions. The Post-Closure Inspection Checklists are found in Attachment A, a copy of the field notes is found in Attachment B, and inspection photographs are found in Attachment C.

2.0 INSPECTION RESULTS

2.1 May 15, 2001 Inspection

The first inspection was completed on May 15, 2001. The perimeter fence and concrete monuments marking the landfill cells were in excellent condition. One sign had become detached from the fence, and a second sign had come loose at two corners. The remainder of the signs were securely attached to the fence and in excellent condition. Several small mammal burrows were observed inside the fence, but have not compromised the integrity of the waste cell covers. An area measuring approximately 3 by 6 meters (10 by 20 feet), located at the eastern end of trench number A9-1, appears to have subsided approximately 25.4 centimeters (10 inches). No cracks, erosion features, or settling were observed at the other landfill cell covers. Although closure activities did not include revegetation at the site, sparse plants were



TONOPAH TEST RANGE




FIGURE 1
AREA 9 UXO LANDFILL CAU 453
LOCATION MAP

observed inside the fenced area, both on and off the landfill cover area. No maintenance or repairs to the site were made during this site inspection. Repair activities for the A9-1 cover subsidence area were scheduled for November 2001.

2.2 November 6, 2001 Inspection

The inspection was completed on November 6, 2001. The perimeter fence, concrete monuments, and site postings were in excellent condition. Two unattached warning sign were reattached to the fence using steel hog rings. Numerous small mammal burrows were observed inside the fence and were filled in by hand. The burrows have not compromised the integrity of the waste cell covers. The subsidence area in Landfill Cell A9-1 observed in the May 16, 2001 site inspection was still present. Repair work was scheduled for November 15, 2001. No cracks, erosion, or settling features were observed in the other landfill cover areas. Plant growth on the landfill cover was limited to sparse native grasses and halogeton. No further site maintenance or repairs were recommended.

2.3 November 15, 2001 Maintenance and Repair Activities

On November 15 and 16, 2001, the area of subsidence located at the east end of Landfill Cell A9-1 was repaired. Ninety-one cubic meters (120 cubic yards) of clean fill was placed in the area and compacted by back-dragging the area with the backhoe bucket. Final touch-up grading was made to bring the cover up to the pre-existing grade.

3.0 CONCLUSIONS AND RECOMMENDATIONS

The perimeter fence, monuments, and site postings are in excellent condition. Repair work to the eastern end of Landfill Cell A9-1 was completed and no other cracks, erosion features, or settling were observed in the other landfill cover area. Plant growth on the landfill cover is sparse and is limited to native grasses and shrubs.

No modifications or repairs to the cover, or changes in the frequency of site inspections, are recommended at this time.

THIS PAGE INTENTIONALLY LEFT BLANK

ATTACHMENT A
INSPECTION CHECKLISTS

THIS PAGE INTENTIONALLY LEFT BLANK

CAU 453: AREA 9 UXO LANDFILL, POST-CLOSURE INSPECTION CHECKLIST

Date of Last Inspection: 21 November 2000

Reason for Last Inspection: Biannual

Responsible Agency: NNSA/INV BN ER

Project Manager: Wayne Johnson

Inspection Date: 15 May 01

Inspector (name, title, organization): Brad Jackson, Task Manager, BN

Assistant Inspector (name, title, organization): Kevin Cabbie, Task Manager, DOE

A. GENERAL INSTRUCTIONS

1. All checklist items must be completed and detailed comments made to document the results of the site inspection. The completed checklist is part of the field record of the inspection. Additional pages should be used as necessary to ensure that a complete record is made. Attach the additional pages and number all pages upon completion of the inspection.
3. Any checklist line item marked by an inspector in a SHADED BOX, must be fully explained or an appropriate reference to previous reports provided. The purpose of this requirement is to provide a written explanation of inspector observations and the inspector's rationale for conclusions and recommendations. Explanations are to be placed on additional attachments and cross-referenced appropriately. Explanations, in addition to narrative, will take the form of sketches, measurements, annotated site maps.
4. The site inspection is a walking inspection of the entire site including the perimeter and sufficient transects to be able to inspect the entire surface and all features specifically described in this checklist.
5. A standard set of color 35 mm photographs (or equivalent) is required. In addition, all anomalous features or new features (such as changes in adjacent area land use) are to be photographed. A photo log entry will be made for each photograph taken.
6. This unit will be inspected biannually with formal reporting to the Nevada Division of Environmental Protection to be done annually. The annual report will include an executive summary, this inspection checklist with field notes and photo log attached, and recommendations and conclusions.

B. PREPARATION (To be completed prior to site visit)

YES NO EXPLANATION

1. Site as-built plans and site base map reviewed.

✓

2. Previous inspection reports reviewed.

✓

a. Were anomalies or trends detected on previous inspections?

✓

b. Was maintenance performed?

✓

3. Site maintenance and repair records reviewed.

✓

a. Has site repair resulted in a change from as-built conditions?

✓

N/A

b. Are revised as-builts available that reflect repair changes?

✓

N/A

C. SITE INSPECTION (To be completed during inspection)

YES NO EXPLANATION

1. Adjacent off-site features within watershed areas.

- a. Have there been any changes in use of adjacent area?
- b. Are there any new roads or trails?
- c. Has there been a change in the position of nearby washes?
- d. Has there been lateral excursion or erosion/deposition of nearby washes?
- e. Are there new drainage channels?
- f. Change in surrounding vegetation?

	✓	
	✓	
	✓	
	✓	
	✓	
	✓	

2. Security fence, signs.

- a. Displacement of fences, site markers, boundary markers, or monuments?
- b. Have any signs been damaged or removed?
(Number of signs replaced: 0)
- c. Were gates locked?

	✓	
	✓	
	✓	

CAU 453: AREA 9 UXO LANDFILL, POST-CLOSURE INSPECTION CHECKLIST

3. Waste Unit cover.

- a. Is there evidence of settling?
- b. Is there cracking?
- c. Is there evidence of erosion around the cap (wind or water)?
- d. Is there evidence of animal burrowing?
- e. Have the site markers been disturbed by man or natural processes?
- f. Is vegetation present?
- g. Do natural processes threaten to integrity of any cover or site marker?
- h. Other?

YES	NO	EXPLANATION
	✓	
	✓	
	✓	
✓		Shallow - small animal
	✓	
✓		
	✓	
	✓	
	✓	

4. Photo Documentation

- a. Has a photo log been prepared?
- c. Number of photos exposed ()

✓	
---	--

D. FIELD CONCLUSIONS

1. Is there an imminent hazard to the integrity of the unit?
(Immediate report required)

	✓
--	---

Person/Agency to whom report made:

2. Are more frequent inspections required?

3. Are existing maintenance/repair actions satisfactory?

4. Is other maintenance/repair necessary?

5. Is current status/condition of vegetative cover satisfactory?

	✓
	✓
	✓
	✓

Several signs of slope need repair (vegetation, no fence)

See note below:

6. Rationale for field conclusions:

Note for D.4. - an area (approx 15' x 20') along the northern portion of trench A9-1 appears to be noticeably lower than the surrounding ground surface and may be a result of subsidence in the landfill.

E. CERTIFICATION

I have conducted an inspection of the Area 9 UXO Landfill, CAU 453, at the TTR in accordance with the Post-Closure Inspection Plan (see Closure Report) as recorded on this checklist, attached sheets, field notes, photo logs, and photographs.

Chief Inspector's Signature: Brad Jackson

Printed Name: BRAD JACKSON

Title: TASK MANAGER

Date: 15 May 01

CAU 453: AREA 9 UXO LANDFILL, POST-CLOSURE INSPECTION CHECKLIST

Date of Last Inspection: 15 May 2001

Reason for Last Inspection: Bi annual

Responsible Agency: BNER NNSA/NV

Project Manager: Wayne Johnson BNER

Inspection Date: 6 November 2001

Inspector (name, title, organization): Kevin B. Campbell Technical Lead BNER

Assistant Inspector (name, title, organization): NA

A. GENERAL INSTRUCTIONS

1. All checklist items must be completed and detailed comments made to document the results of the site inspection. The completed checklist is part of the field record of the inspection. Additional pages should be used as necessary to ensure that a complete record is made. Attach the additional pages and number all pages upon completion of the inspection.
2. Any checklist line item marked by an inspector in a SHADED BOX, must be fully explained or an appropriate reference to previous reports provided. The purpose of this requirement is to provide a written explanation of inspector observations and the inspector's rationale for conclusions and recommendations. Explanations are to be placed on additional attachments and cross-referenced appropriately. Explanations, in addition to narrative, will take the form of sketches, measurements, annotated site maps.
3. The site inspection is a walking inspection of the entire site including the perimeter and sufficient transects to be able to inspect the entire surface and all features specifically described in this checklist.
4. A standard set of color 35 mm photographs (or equivalent) is required. In addition, all anomalous features or new features (such as changes in adjacent area land use) are to be photographed. A photo log entry will be made for each photograph taken.
5. This unit will be inspected biannually with formal reporting to the Nevada Division of Environmental Protection to be done annually. The annual report will include an executive summary, this inspection checklist with field notes and photo log attached, and recommendations and conclusions.

B. PREPARATION (To be completed prior to site visit)

YES

NO

EXPLANATION

1. Site as-built plans and site base map reviewed.

✓

2. Previous inspection reports reviewed.

✓

a. Were anomalies or trends detected on previous inspections?

✓

Small area (20x15') of subsidence near trench AG-1 noted on last inspo

b. Was maintenance performed?

✓

Scheduled for 11/14/01

3. Site maintenance and repair records reviewed.

✓

a. Has site repair resulted in a change from as-built conditions?

✓

N/A

b. Are revised as-builts available that reflect repair changes?

✓

Will be following 11/14/01 repairs

C. SITE INSPECTION (To be completed during inspection)

YES

NO

EXPLANATION

1. Adjacent off-site features within watershed areas.

- Have there been any changes in use of adjacent area?
- Are there any new roads or trails?
- Has there been a change in the position of nearby washes?
- Has there been lateral excursion or erosion/deposition of nearby washes?
- Are there new drainage channels?
- Change in surrounding vegetation?

	✓	
	✓	
	✓	
	✓	
	✓	
	✓	
	✓	

2. Security fence, signs.

- Displacement of fences, site markers, boundary markers, or monuments?
- Have any signs been damaged or removed?
(Number of signs replaced: 0)
- Were gates locked?

	✓	
	✓	2 signs were reattached to fence
	✓	no lock present

CAU 453: AREA 9 UXO LANDFILL, POST-CLOSURE INSPECTION CHECKLIST

3. Waste Unit cover.

- a. Is there evidence of settling?
- b. Is there cracking?
- c. Is there evidence of erosion around the cap (wind or water)?
- d. Is there evidence of animal burrowing?
- e. Have the site markers been disturbed by man or natural processes?
- f. Is vegetation present?
- g. Do natural processes threaten to integrity of any cover or site marker?
- h. Other?

YES	NO	EXPLANATION
✓		near trench A9-1
	✓	
	✓	
✓		small burrows present
	✓	
✓		
	✓	
	✓	

4. Photo Documentation

- a. Has a photo log been prepared?

✓		
---	--	--

- c. Number of photos exposed ()

D. FIELD CONCLUSIONS

- 1. Is there an imminent hazard to the integrity of the unit? (Immediate report required)

	✓	
--	---	--

Person/Agency to whom report made:

- 2. Are more frequent inspections required?

	✓	
--	---	--

- 3. Are existing maintenance/repair actions satisfactory?

✓		Scheduled repair of subsidence feature for 11/14/01 will be
---	--	---

- 4. Is other maintenance/repair necessary?

	✓	
--	---	--

- 5. Is current status/condition of vegetative cover satisfactory?

✓		
---	--	--

- 6. Rationale for field conclusions:

Based on observations minor repair work to the eastern end of landfill cell A9-1 is needed. All other areas, all fencing, signs, and monuments are in excellent condition.

reserve following repair

E. CERTIFICATION

I have conducted an inspection of the Area 9 UXO Landfill, CAU 453, at the TTR in accordance with the Post-Closure Inspection Plan (see Closure Report) as recorded on this checklist, attached sheets, field notes, photo logs, and photographs.

Chief Inspector's Signature: <i>Kevin B. Campbell</i>	Printed Name: <i>Kevin B. Campbell</i>
Title: BNER Technical Lead	Date: 6 November 2001

ATTACHMENT B

FIELD NOTES

THIS PAGE INTENTIONALLY LEFT BLANK

Work continued from Page N/A TTR Post Closure Inspe. BOOK NO.

15 May 01

630 - receive clearance from ASI to access Area 9.

1645 - arrive at CAV Area 9 UXO Landfill

- walk the perimeter of fence and visually inspect the site.

The fence was in good condition but one sign was

5 on the ground and one sign was not connected

to the fence at two corners. There were numerous

burrows within the fenced area. All concrete

monuments were in good shape and visible.

- An area approximately 15'-20' in length and approximately 10' in width

0 in the Northeast end of trench A9-1 has apparently
subsided. This area was noticeably lower than the surface
grade of the remainder of the site.

16 May 01

5 - 1400 - Five-Points Landfill

- Walk the perimeter of fencing and visually inspect the site.

The fenced area is well covered by vegetation and shows
no signs of erosion. Numerous burrows are present along
the fence line and within the fencing. Some surface debris
0 is present along the south east margin of the site
within the fencing.

Last /one

Work continued from Page N/A TTR Post Closure Inspection, 6 November 2001

Clear, cool 60°, winds from south 5-10 mph.

9:35 Arrive at 5 points land fill for inspection. Walk perimeter of fence/cover
Gate in excellent condition no lock present

5 Fence line in excellent condition

Bunny fencing looks good all of bottom edge buried no obvious breaches/breaks

Vegetation inside fence looks excellent, healthy, plant density is at least as good
or better than outside fence line.

Several small mammal burrows present along base of fence outside fenced area.

0 Only very few small mammal burrows present inside fence line.

Small burrows outside fence backfilled by hand

10:20 Depart site for Area 3 to meet Berry Elliston. Bomblet site

10:38 Arrive at Bomblet for site inspection (CAU400)

Numerous small mammal burrows present at base of fence both inside and outside
fence line

Vegetation healthy but sparse less vegetation inside fence than outside

Numerous bomblet fragments inside & outside fence

Fence & gate in excellent condition, no lock or signs present

10:54 Depart site for Area 3 compound. Berry E. at lunch

0 11:20 Arrive at Area 9 UXO site (CAU453)

Fence in excellent condition, no lock on gate. No bunny fencing present.

Healthy mix of vegetation inside fence.

Concrete above grade monuments all in excellent condition

Large rabbit observed inside fence

5 Numerous small mammal burrows present inside fence

Two signs on north fence line were unattached/had blow down - and were
reattached to fence with hog rings.

Pictures of soil pile and subsidence area were taken

12:02 Depart site for Area 3

Work continued to Page 22

SIGNATURE



DISCLOSED TO AND UNDERSTOOD BY

DATE

WITNESS

DATE

11/6/01

DATE

ATTACHMENT C
PHOTOGRAPH LOG AND PHOTOGRAPHS

THIS PAGE INTENTIONALLY LEFT BLANK

PHOTOGRAPH LOG

PHOTO NUMBER	DATE	DESCRIPTION
1	05/15/2001	View to northwest from outside of perimeter fence near gate. Concrete monuments indicate locations of the northeast and southwest ends of Landfill Cells A9-1, A9-2, and A9-3. Signs on south fence line visible and in good condition
2	05/15/2001	View to west from outside the southeast corner of perimeter fence. Concrete monuments indicate locations of the landfill cells.
3	05/15/2001	View to west from inside of the perimeter fence showing the A9-1 Landfill Cell cover subsidence area in the foreground. Concrete monuments indicate locations of the landfill cells.
4	05/15/2001	View to east from inside of perimeter fence. Concrete monuments indicate locations of the corners of the Landfill Cells A9-1, A9-2, and A9-3. Sparse vegetation inside fence is healthy native grass and brush species.
5	11/06/2001	View to the north from outside perimeter fence. Gate signs and landfill cell corner monuments are visible and in excellent condition.
6	11/06/2001	View to west from outside perimeter fence.
7	11/06/2001	View to east of subsidence area at eastern end of A9-1 Landfill Cell. Sparse vegetation of native grasses, shrubs, and halogeton are present inside the fenced area.
8	11/06/2001	View to northeast from outside perimeter fence at southwest corner.

THIS PAGE INTENTIONALLY LEFT BLANK



1



2



3



4



11/06/2001

5



11/06/2001

6



7



8

DISTRIBUTION LIST

THIS PAGE INTENTIONALLY LEFT BLANK

DISTRIBUTION LIST

*Provide copy of initial distribution of Revision 0; remainder of list gets Revision 0 if approved without changes. The entire list receives Revision 1, if issued.

Nevada Department of Environmental Protection

Paul Liebendorfer Bureau of Federal Facilities Division of Environmental Protection 333 W. Nye Lane, Room 138 Carson City, NV 89706-0866	2 (Controlled)*
Supervisor, Las Vegas Office Bureau of Federal Facilities Division of Environmental Protection 555 E. Washington, Suite 4300 Las Vegas, NV 89010-1043	1 (Controlled)*

U.S. Department of Energy

Janet Appenzeller-Wing Project Manager Environmental Restoration Division U.S. Department of Energy National Nuclear Security Administration Nevada Operations Office P.O. Box 98518 M/S 505 Las Vegas, NV 89193-8518	1 (Uncontrolled)*
Kevin Cabble Environmental Restoration Division U.S. Department of Energy National Nuclear Security Administration Nevada Operations Office P.O. Box 98518 M/S 505 Las Vegas, NV 89193-8518	1 (Uncontrolled)*
Sabrina Lawrence Environmental Restoration Division U.S. Department of Energy National Nuclear Security Administration Nevada Operations Office P.O. Box 98518 M/S 505 Las Vegas, NV 89193-8518	1 (Controlled)*

DISTRIBUTION LIST (Continued)

U.S. Department of Energy (continued)

U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62
Oak Ridge, TN 37831-0062

1 (electronic copy)

U.S. Department of Energy
National Nuclear Security Administration
Nevada Operations Office
Public Reading Facility
P.O. Box 98521 M/S NLV040
Las Vegas, NV 89193-8521

1 (Controlled) &
1 (Uncontrolled)

U.S. Department of Energy
National Nuclear Security Administration
Nevada Operations Office
Technical Information Resource Center
P.O. Box 98521 M/S 505
Las Vegas, NV 89193-8521

1 (Uncontrolled)

Bechtel Nevada

Correspondence Control
Bechtel Nevada
P.O. Box 98521 M/S NLV008
Las Vegas, NV 89193-8521

1 (Uncontrolled)*

Environmental Management Library
Bechtel Nevada
P.O. Box 98521 N/S NLV080
Las Vegas, NV 89193-8521

1 (Uncontrolled)*

Kevin Campbell
Bechtel Nevada
P.O. Box 98521 M/S NTS306
Las Vegas, NV 89193-8521

1 (Uncontrolled)*

Ann Heidema
Bechtel Nevada
P.O. Box 98521 M/S NLV022
Las Vegas, NV 89193-8521

1 (Uncontrolled)

DISTRIBUTION LIST (Continued)

Bechtel Nevada (continued)

Ronald Jackson Bechtel Nevada P.O. Box 98521 M/S NTS306 Las Vegas, NV 89193-8521	1 (Uncontrolled)*
Wayne Johnson Bechtel Nevada P.O. Box 98521 M/S NTS306 Las Vegas, NV 89193-8521	1 (Uncontrolled)*
Steve Nacht Bechtel Nevada P.O. Box 98521 M/S NTS306 Las Vegas, NV 89193-8521	1 (Uncontrolled)*

IT Corporation

Lynn Kidman IT Corporation P.O. Box 93838 M/S 439 Las Vegas, NV 89193-8521	1 (Uncontrolled)*
Garry Romano IT FFACO Support Office IT Corporation P.O. Box 93838 M/S 439 Las Vegas, NV 89193-8521	1 (Controlled)

State Of Nevada

Manager, Northern Nevada FFACO Public Reading Facility Nevada State Library and Archives Federal Publications 100 North Stewart Street Carson City, NV 89701-4285	1 (Controlled) & 1 (Uncontrolled)
---	--------------------------------------