

CONFIDENTIAL

U. S. S. CREE (ATF-84)
% FLEET POST OFFICE
SAN FRANCISCO, CALIFORNIA

ATF 84/AJP:tjp

A-4

Ser: 143-58

411009

12 June 1958

CONFIDENTIAL

From: Commanding Officer, U.S.S. CREE (ATF 84)

To: Commander, Task Group 7.3

Via: CTU 7.3.1 Technical Coordinating Unit

Subj: Final report of Operation Hardtack

Station

Approved

Distribution

Ref: (a) CTG 7.3 Instruction 03401.1A

(b) CTG 7.3 Message 162218Z of April 1958

(c) CTG 7.3 Operation Plan No. 1-58

Paul Brown
DNA 5/11/58

Encl: (1) Final Radiological Safety Report

1. In compliance with references (a) and (b) the final report of Operation Hardtack for period 15 March 1958 to 10 June 1958 is herewith submitted.

(1) PLANNING

Planning information received was adequate. With the exception of wash-down system, no ship modifications were necessary. Installation of wash-down system was slow due to late arrival of material, and thus had to be installed while enroute EPG. No other special equipment was necessary, except a radio transmitter and receiver, which were delivered to CREE upon arrival Eniwetok. This involved no installation problems.

(2) TRAINING

Training programs were adequate. Only special programs were required in Rad-Safe and Security training. 60% of crew attended Rad-Safe schools before leaving CONUS. Security lectures were given prior to leaving for EPG and while enroute. No outside lectures or instructions were received upon arrival Eniwetok.

(3) MOVEMENT TO FORWARD AREA

Problems encountered on movement to forward area were due primarily to inclement weather. Between CONUS and Hawaii, sea action on Squaw 29 caused opening of flooding ports on vent valves resulting in partial flooding. It is also believed that improper design of the bullnose contributed to the parting of bridle chain on Squaw. A delay of approximately 8 days was thus required in Pearl Harbor where redesign of the bullnose and other necessary repairs were made. No other problems were encountered while enroute. CHOP date to CTG 7.3 was 17 April 1958.

CONFIDENTIAL

01637

UNCLASSIFIED

CONFIDENTIAL

(4) OPERATIONS

(a) Navigation

No problems were encountered, available charts were adequate. Holding ability was good in all anchorages. Aero Beacon on FRED was found to be out of position on all charts.

(b) Track charts

None were used.

(c) Surface water transportation

Adequacy of inter - atoll surface transportation for freight and personnel was considered to be good. Boat pool personnel were found to be friendly and courteous at all times.

(d) Operational area

No unauthorized craft were encountered in the danger area.

(e) Search and rescue

No SAR missions were performed.

(f) Radiological safety

(Enclosure one (1))

(5) LOGISTICS

No problems were encountered in replenishment of provisions, stores and fuel. It was felt the problem of obtaining spare parts was kept to a minimum due to the fine cooperation of all ships present in the immediate area. SOPA administrative functions were adequate. Recreation facilities were as good as could be expected. TV was good and helped moral. The three (3) day tender availability was of great value and felt to be adequate in most cases. The time for ships' force maintenance was very limited, although no major problems occurred.

(6) ADMINISTRATION AND PERSONNEL

(a) No problems occurred in Personnel stabilization. One man was lost due to emergency leave just prior to leaving CONUS. A second man was lost due to necessary hospitalization while in EPG.

(b) Personnel allowance was adequate.

(c) No changes in discipline were noted.

(d) Mail service was satisfactory, although many delays were noted due to operating schedule. Guard mail was also adequate.

~~CONFIDENTIAL~~

April 27 Released BC 6529 due to apparent sinking condition
April 28 Arrived Bikini and released BC 6528, returned to
area of BC 6529.

29 - 4 May Enroute Eniwetok towing barge BC 6529.
5 Refueled from USS CACAPON (AO 52).
12 - 16 Towed EC - 2 to target array and remained in vicinity.
17 Towed EC - 2 from target array to anchorage.
20 - 21 Recovered mooring buoys from array.
22 Assisted USS ARIKARA and USS GRASP in salvage of YC 1345.
23 - 26 Laid two mooring buoys in target array.
27 Recovered two mooring buoys from WAHOO site.
28 Commenced three (3) day availability alongside USS HOOPER
ISLAND. Also took on fuel from HOOPER ISLAND.

31 - 1 JUNE Remained alongside YFNB 12 in target array.
2 - 3 Towed EC - 2 to target array.
5 Proceeded to assigned anchorage for rehearsal.
6 - 7 Remained alongside YFNB 12 in target array.
9 Proceeded to target array. Towed USS BONITA to anchorage
near ELMER.
10 Recovered 3 anchors and towed barge YC 1415 to anchorage.

J. M. Reid
J. M. REID, LT, USN

U. S. S. CREE (ATF-84)
% FLEET POST OFFICE
SAN FRANCISCO, CALIFORNIA

ATF 84/JMR:tjp
A-4
Ser: 144-58

ENCLOSURE ONE (1)

12 June 1958

CONFIDENTIAL

From: Commanding Officer, U.S.S. CREE (ATF 84)
To: Commander, Task Group 7.3

Subj: Final Radiological Safety Report; submission of

Ref: (a) CTG 7.3 INST 03401.1A
(b) CTG 7.3 Operation Plan No. 1-58

1. In accordance with references (a) and (b) the final Radiological Safety Report is hereby submitted as enclosure (1) to the final Report of Operation Hardtack.

(1) Evaluation of performance and efficiency of water washdown system. Actual use of the system was only necessary once, and in this case was found to be 95% effective. Performance was good.

(2) Radiac Equipment performance. The only equipment used by this vessel was the 27F. No operational difficulties occurred and the training methods were satisfactory. Reading requirements were felt to be a little high (while in port) thus battery supply was a problem.

(3) Effectiveness of decontamination materials, equipment and procedures. Necessary decontamination was almost non existent. Materials, equipment and procedures were all found to be adequate.

(4) Evaluation of radiological safety training. At least 60% of this vessels crew attended shore based Rad-Safe schools prior to leaving CONUS. Lectures were also given by ships personnel while enroute EPG, but no training was received from CTG 7.3 upon arrival Eniwetok. Training was found to be adequate for all phases of the operation.

J. M. REID, LT, USN