

**This document was too large to scan
as a single document. It has
been divided into smaller sections.**

Section 1 of 4

Document Information			
Document #	ARH-02132 SEP	Revision	
Title	PUREX SOURCE DATA – FY1972 SEPTEMBER 1971		
Date	09/01/1971		
Originator	J.G. MURPHY	Originator Co.	ARHCO
Recipient		Recipient Co.	
References			
Keywords			
Projects			
Other Information			

BEST AVAILABLE COPY

~~SECRET~~

LITERATURE ACCESS CATEGORIES

C-65

DOCUMENT NO.

ARH-2132 SEP

SERIES AND COPY NO.

DATE

September, 1, 1971

(CLASSIFICATION)

PROJECT

DECLASSIFIED

Atlantic Richfield Hanford Company
Richland, Washington 99352

ISSUING FILE

TITLE AND AUTHOR

CIRCULATING COPY
RECEIVED

AUG 11 1971

RETURN TO AFMCO
DOCUMENT CONTROL
271-U Bldg., 200 West

PUREX - SOURCE DATA - FY 1972

September 1, 1971

DECLASSIFIED

DECLASSIFIED BY CG-SS-4
SEPT. 2000 AND APPROVED
FOR PUBLIC RELEASE

NAME/DATE Buzz Lammay 12.9.02

NAME/DATE [Signature] 12/10/02

JG Murphy

☒ RESTRICTED DATA

THIS DOCUMENT CONTAINS RESTRICTED DATA AS DEFINED
IN THE ATOMIC ENERGY ACT OF 1954. ITS TRANSMITTAL
OR THE DISCLOSURE OF ITS CONTENTS IN ANY MANNER TO
AN UNAUTHORIZED PERSON IS PROHIBITED.

☐ OTHER OFFICIAL CLASSIFIED INFORMATION

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE
NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE
MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECS.
793 AND 794, THE TRANSMISSION OR REVELATION OF
WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS
PROHIBITED BY LAW

ORG. PNNL NSAT

THIS DOCUMENT MUST NOT BE LEFT UNATTENDED OR WHERE AN
UNAUTHORIZED PERSON MAY HAVE ACCESS TO IT. WHEN NOT IN
USE, IT MUST BE STORED IN AN APPROVED LOCKED REPOSITORY
WITHIN AN APPROVED GUARDED AREA. WHILE IT IS IN YOUR
POSSESSION AND UNTIL YOU HAVE RETURNED IT TO YOUR
CLASSIFIED DOCUMENT RESPONSIBILITY STATION, IT IS YOUR
RESPONSIBILITY TO KEEP IT AND ITS CONTENTS WITHIN THE
LIMITS OF THIS PROJECT AND FROM AN UNAUTHORIZED PERSON.
ITS TRANSMITTAL TO AND STORAGE AT YOUR PLACE OF
RESIDENCE IS PROHIBITED. IT WILL BE DUPLICATED ONLY IN
ACCORDANCE WITH EXISTING SECURITY REGULATIONS. ALL
PERSONS RECEIVING THIS DOCUMENT ARE REQUESTED TO SIGN
IN THE SPACE BELOW.

ROUTE TO:

PAYROLL NO.

LOCATION

FILES ROUTE
DATE

SIGNATURE AND DATE

JG Murphy

61633

271-U Bldg.

AUG 11 1971

[Signature] 8-11-71

795-70000 61522 2701-2

MAY 19 1976

REVIEW FOR DECLASSIFICATION
ON 9/1/85
BY [Signature]
CLASSIFICATION UNCHANGED

GROUP 1

EXEMPTED FROM AUTOMATIC DOWNGRADING
AND DECLASSIFICATION

~~SECRET~~

DECLASSIFIED

1

10. Date of Transfer if Financial Responsibility						No.	Day	Yr.	
						(23-30)	(31-32)	(33)	
									9
									10

12. Transfer Authority—SNM Draft Number, Reference, or Order Number (34-50)
DUN # 104

Loads 2108 thru 2238

7
3
9
10

ASSIFIED

Loads 2108 thru 2238

[illegible]

CLASSIFIED

7-14-61
K
9 627.90
RECEIVER'S DATA

A. Date Received		B. For File (25)		C. Signature of Authorized Official and Date Signed	
No. (20-1)	Day (1-3)	Mo. (1-12)	Yr. (00-99)		
91	16	71		4	
ORIGINAL SIGNED BY					
G. B. KUKLINSKI					
G. B. Kuklinski 9/22/71					

G. B. Kuklinski 9/2

[illegible]

GPO-857-815

2

TRANSFER SERIES			
From (5-7)	To (9-11)	No. (13-18)	(119)
HXA	HVA	119	

13

SHIPPER'S DATA

A. Date Shipped			B. Form No. (75)		C. Gross Weight		D. Net Weight		E. Grams		F. Weight %		G. Activity		H. Limits of Error	
Mo. (70-71)	Day (72-73)	Yr. (74)	Form No. (75)													
Line No. (20-21)	AEC Project Number and Identification (22-31)	Material Type (22-33)	Material Descr. Code (24-25)	Owner Code (37)	Gross Weight (40-50)	Net Weight (40-50)	Grams (40-50)	Weight % (40-50)	Activity (40-50)	Activity (40-50)	Estimate (66-70)	Activity (71-75)				
50				G			38 661.69	5.298	36 613.39							
"				"			13 595.93	7.249	12 610.36							
"				"			42 673.36	5.121	40 488.06							
"				"			20 821.89	5.349	19 708.13							
"				"			32 605.47	6.001	30 648.81							
"				"			11 402.30	4.292	10 912.91							
Total						159 760.64			150 981.66							

[illegible]

DECLASSIFIED

DECLASSIFIED

DECLASSIFIED

DECLASSIFIED

3

54-3520-1119-62

DONT SAY IT --- Write it: UNCLASSIFIED

ABH-2132 SEP 17 9-17-71

TO Juanita Murphy, ARHCO FROM C. Thomsen, DUN

Please refer to the following load #s and change the 741 Ref. to 120 instead of 119:
2160, 2164, 2167, 2170, 2173, 2176, 2179, 2182, 2185, 2188, 2191, 2194, 2197, 2200, 2203,
2206, and A well only on 2207.

Thank you.

"SAFETY IS NO ACCIDENT"

DOCUMENTATION (only if document is classified Secret)

Page 1 of 2 Pages Copy 2 of 5 Copies, Series

DECLASSIFIED

A. Project Number and Identification		B. Form No. (75)		C. Signature of Project Director and Date Signed		9-30-71					
Project Number and Identification (72-31)	Affected Area (72-33)	Material Design Code (72-35)	Composition Code (72-36)	Owner Code (72-37)	Test Weight	Grams Element Weight (72-50)	Weight % Isotope (72-54)	Grams Isotope Weight (72-55)	Limits of Error		
20	82	284	G		269	880	457	.865	2 334 466	1 349 402	1.1672
50	253	G			153	054			Pu 239/241	143 990	6 122
Sept MSR					Cost Memo lbs.	594	987.67	514664 lbs.			

A. Date Received			B. Form No. (75)		C. Signature of Authorized Official and Date Signed						
No. (70-71)	Date (72-73)	Yr. Day									
9	07	72-73	30	7A	4						
Material Type (72-73)	Material Description Code (74-75)	Compositional Code (76-77)	Owner Code (78)	Gross Weight (79)	Net Weight (80)	Elemental Weight (81-82)	Weight % Isotope (83-84)	Isotope Weight (85-86)	Limits of Error Element (87-90) Isotope (91-92)		
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	100 100 100	
100 100 100	100 100 100	100 100 100	100								

19 U.S.C., SECTION 1001; ACT OF JUNE 25, 1949, 62 STAT. 749; MAKES IT A CRIMINAL OFFENSE TO MAKE A WILLFULLY FALSE STATEMENT OR
 REFERRATION TO ANY BODY
 MEET OR AGENCY OF THE UNITED STATES AS TO ANY MATTER WITHIN ITS JURISDICTION.

10-4-11

U.S. ATOMIC ENERGY COMMISSION
NUCLEAR MATERIAL TRANSFER REPORT
(CONTINUATION PAGE)

SECRET

~~DECLASSIFIED~~

DECLASSIFIED						Form No. (75)		Limits of Error				
No.	Date Shipped	Day (2-73)	Yr. (04)	71		Force No. (75)						
Line No. (1-21)	AEC Project Number and Identification (22-31) ^E	Material Type (32-39) ^F	Material Descrip. Code ^G	Dumpe- sition Code (34-36) ^H	Omerit Code (37) ^I	Gross Weight ^J	Net Weight ^K	Grams Element Weight (40-50) ^L	Weight % Isotope (51-54) ^M	Grams Isotope Weight Pu239/241 ^N	Element (55-70) ^O	Isotope (71-75) ^P
		50		253	G			14 985.66	4.026	34 382.34		
		"		"	"			4 915.63	4.292	4 704.65		
		"		"	"			65 541.47	7.906	60 359.76		
		"		"	"			4 676.07	4.949	4 444.65		
		"		"	"			11 643.13	7.906	10 722.62		
		"		"	"			5 972.05	5.310	5 654.93		
		"		"	"			11 958.18	4.198	11 456.18		
		"		"	"			8 884.08	1.934	8 712.26		
		"		"	"			11 395.16	4.023	10 936.73		
		"		"	"			13 082.94	3.573	12 615.49		
						Total		153 054.37		143 989.61		

RECEIVING DATA

[illegible]

DECLASSIFIED

4

—

TRANSFER SERIES NO.

ARH-2102 SEP 2

DECLASSIFIED

(9-68)

AEC-RL RICHLAND, WASH

CPD -- INTERPLANT TRANSFER FORM

ARH-212 SEP

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

Shipper Signature _____

Receiver Signature _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

From Tank, ~~Truck~~, etc. TANK CAR ATX 100 To Tank, ~~Truck~~, etc.

Date 9-3-71

Time 10 40

13 14

Dispatching Tank ☐

Receiving Tank ☒

Level at Start

13 14
8" 8"

Amount Received _____

Level at Completion

13
9' 9"

14
9' 9"

Sample Serial No. 6242

Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

DECLASSIFIED

RRH-21.2 SEP

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

UNCLASSIFIED

Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

From Tank, Truck, etc. 18623

Date 9-4-71

To Tank, Truck, etc. P-13 & 14

Time 1630

Dispatching Tank ☒

Receiving Tank ☐

Level at Start 13' 10" 14' 10"

Level at Completion 8' 6" 8' 4"

Amount Received _____

Sample Serial No. 6911

Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-212 SEP 7

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

DECLASSIFIED

Shipper Signature _____

Receiver Signature _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

From Tank, Truck, etc. 18622 Date 9-5 To Tank, Truck, etc. P-13P14 Time 1130

Dispatching Tank ☒

Receiving Tank ☐

Level at Start 8" 8" Amount Received ✓

Level at Completion 8'2" 8' 2"

Sample Serial No. 7039 Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

DECLASSIFIED

10

NUCLEAR MATERIAL TRANSFER RECORD
CHEMICAL PROCESSING DIVISION *403 Acid* OPERATION

TRANSFER SERIES NO.

DATE	9-10-71	9-10-71	9-11-71	9-11-71					
TANK	SHIPPING 100	100	18623	18623					
	RECEIVING 13	14	13	14					
TYPE MATERIAL	403 Acid	403 Acid	403	403					
BATCH NUMBER	72-1-24	72-1-24	72-1-25	72-1-25					
TIME START	2120	2120	1300	1300					
TIME END	2330	2330	1500	1500					
WEIGHT FACTOR	BEFORE 8"	8"	8"	9"					
	AFTER 114	114	99"	98					
BOARD	SP. GR.								
	TEMP.								
	CORR. SP. GR.								
LAB. SERIAL NUMBER	7710	7710	7760	7760					
LAB. SP. GR.	1.310	1.310	1.318	1.318					
U LBS./GAL.	8.99 ²	8.99 ²	8.68 ²	8.68 ²					
PU GMS./GAL.	6.30	6.30	5.33	5.33					
SUPV. APPROVAL									
Liquid Level	BEFORE 6.14	6.14	6.14	6.84					
	AFTER 8.20	8.70	7.51	7.44					
GALLONS	BEFORE 3.37	3.87	3.37	4.22					
	AFTER 4.34	4.41	3.75	3.78					
GALLONS TRANSFERRED	400	402	341	336					
U LBS. TRANSFERRED	3600	3620	2960	2920					
GRAMS PU TRANSFERRED									
GRAMS NP TRANSFERRED									
Na OH	JURED								
	25244	25376	18197	17919					
	4.2		4.15						

UNCLASSIFIED

DECLASSIFIED

1310

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-2102 SEP

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

Date 9-10-71 Time 2:00

From Tank, Truck, etc. X-100 To Tank, Truck, etc. 13 & 14

Dispatching Tank ☐

Receiving Tank ☐

Level at Start 8" Amount Received _____

Level at Completion _____

Sample Serial No. _____ Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

DECLASSIFIED

ARH-21L2 SEP 12

CPD -- INTERPLANT TRANSFER FORM

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Shipper Signature

Receiver Signature

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

Date 9-10-71 Time 1300

From Tank, Truck, etc. 18623 To Tank, Truck, etc. 13414

Dispatching Tank ☒

Receiving Tank ☐

Level at Start 13-8" Amount Received _____

Level at Completion ~~14-8"~~ 13-8'3"

Sample Serial No. 2760 Total Lbs U _____

Analysis - Lbs U Per Gallon _____

UNCLASSIFIED

DECLASSIFIED

CHEMICAL PROCESSING DIVISION 403 Acid OPERATION

TRANSFER SERIES NO.

CHEMICAL PROCESSING DIVISION 403 Acid OPERATION

NUCLEAR MATERIAL TRANSFER RECORD

[illegible]

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

DECLASSIFIED

ASH-2132 SEP

14

ESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☒

Carrier No. # 18622

Batch No. 9-3

(E)

Mary

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/15/71

Time 0825

BELOW -- FOR PUREX USE ONLY

Date 9-15-71

Time 1245

From Tank, Truck, etc. 18622

To Tank, Truck, etc. 13 & 14

Dispatching Tank ☐

TK13 TK14

Receiving Tank ☒

Level at Start 10" 10"

Amount Received

Level at Completion 7'9" 7'9"

Sample Serial No. 8332

Total Lbs U

Analysis - Lbs U Per Gallon

UNCLASSIFIED

DECLASSIFIED

DECLASSIFIED

ARH-2132 SEP

DECLASSIFIED

CHEMICAL PROCESSING DIVISION

TRANSFER SERIES NO.

DATE		9-17-71	9-17-71	9-18-71	9-18-71	OPERATION			
TANK	SHIPPING	ATMX-100	ATMX-100	1862-3	1862-3				
	RECEIVING	13	14	13	14				
TYPE MATERIAL		403-acid	403-acid	403	403				
BATCH NUMBER		72-1-27	72-1-27	72-1-28	72-1-28				
TIME START				1830	1830				
TIME END									
WEIGHT FACTOR	BEFORE	10"	10"	10"	10"				
	AFTER	114"	114"	114"	114"				
BOARD	SP. GR.								
	TEMP.								
	CORR. SP. GR.								
LAB. SERIAL NUMBER		NO	Sample	NO	Sample				
LAB. SP. GR.		1.320		1.320					
U LBS./GAL.		.069		.069					
LAB. SP. GR. HNO ₃ 16/94		5.54		5.54					
NP GMS./GAL.									
SUPV. APPROVAL									
LIQUID LEVEL	BEFORE	7.6"	7.6"	7.6"	7.6"				
	AFTER	86.4"	86.4"	86.4"	86.4"				
GALLONS	BEFORE	413	462	413	462				
	AFTER	4314	4385	4314	4385				
GALLONS TRANSFERRED		3901	3923	3901	3923				
U LBS. TRANSFERRED		269	271	269	271				
GRAMS PU TRANSFERRED									
GRAMS NP TRANSFERRED									
HNO ₃ Transferred		21,612	21,733	21,612	21,733				
Na OH REQUIRED		9-5	9-4						

ESTIMATES BASED ON HISTORICAL EXPERIENCE

DECLASSIFIED

1080

See # 2

CPD -- INTERPLANT TRANSFER FORM

DECLASSIFIED

DATE 212 SEP

ESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☒

Carrier No. ATMY-100

Batch No. 9-5

E

Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/17/71

Time 0840

BELOW -- FOR PUREX USE ONLY

Date 9-17-71 Time _____

From Tank, Truck, etc. 100 To Tank, Truck, etc. 13 1/4

Dispatching Tank ☐

Receiving Tank ☒

Level at Start 10" 10"

Level at Completion 9'6" 9'6"

Amount Received _____

Sample Serial No. _____ Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-21C2 SEP 17

DECLASSIFIED

E

ESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☒

Carrier No. 18623

Batch No. 9-4

Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/16/71

Time 0840

BELOW -- FOR PUREX USE ONLY

From Tank, Truck, etc. 18623

Date 9-18-71

Time 1830

To Tank, Truck, etc. 13E14

Dispatching Tank ☐

TK13

TK14

Receiving Tank ☒

Level at Start 10"

10"

Amount Received

Level at Completion 9'-6"

9'-6"

Sample Serial No. _____ Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

DECLASSIFIED

UNCLASSIFIED

CHEMICAL PROCESSING DIVISION

TRANSFER SERIES NO.

TRANSFER RECORD

403 HNO₃

OPERATION

DATE		9-21-71	9-21																	
TANK	SHIPPING	18622	18622																	
	RECEIVING	P-13	P-14																	
TYPE MATERIAL																				
BATCH NUMBER		72-1-29	72-1-29																	
TIME START																				
TIME END																				
WEIGHT FACTOR	BEFORE	8"	8"																	
	AFTER	9 1/2"	9 1/2"																	
BOARD																				
CORR. SP. GR.																				
AB. SERIAL NUMBER		9136	9136																	
AB. SP. GR.		9112	9112																	
LBS./GAL.		1.317	1.317																	
GMS./GAL.		.04	.04																	
GMS./GAL.		5.86	5.86																	
SUPV. APPROVAL																				
LIQUID LEVEL	BEFORE	6.1	6.1																	
	AFTER	6.1	6.1																	
GALLONS	BEFORE	69.1	69.1																	
	AFTER	337.4	387.4																	
GALLONS TRANSFERRED		345.2	351.9																	
U LBS. TRANSFERRED		3115	3132																	
GRAMS PU TRANSFERRED		125	125																	
GRAMS NP TRANSFERRED		9.6																		
Na OH REQUIRED		18.254	18.353																	

DECLASSIFIED

250

CPD -- INTERPLANT TRANSFER FORM

AKR-12 SEP

19

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☐

Carrier No. 18622

Batch No. 9-6

DECLASSIFIED

Shipper Signature [Signature]

Receiver Signature _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/21/71

Time 0900

BELOW -- FOR PUREX USE ONLY

From Tank, Truck, etc. Can # 18622

Date 9/21/71

Time 2210

To Tank, Truck, etc. _____

Dispatching Tank ☐

Receiving Tank ☐

Level at Start TK13 0'8" 7'7"

Amount Received TK14 0'8" 7'7"

Level at Completion _____

Sample Serial No. 9136

Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

CHEMICAL PROCESSING DIVISION 403 H/103 OPERATION

NUCLEAR MATERIAL TRANSFER RECORD

TRANSFER SERIES NO.

[illegible]

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-21.2 SEP 71

21

DECLASSIFIED

E

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☒

Carrier No. ATMX-100

Batch No. 9-7

Shipper Signature [Signature]

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/22/71

Time 1310

BELOW -- FOR PUREX USE ONLY

Date 9-25-71 Time 0700

From Tank, Truck, etc. X-100 To Tank, Truck, etc. 13-14

Dispatching Tank ☐

Receiving Tank ☐

Level at Start 10" Amount Received

Level at Completion direct to #15

Sample Serial No. 9563

Total Lbs U

Analysis - Lbs U Per Gallon

DECLASSIFIED

UNCLASSIFIED

1537

CHEMICAL PROCESSING DIVISION 403 Acid OPERATION

TRANSEFER SERIE NO.

[illegible]

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-21-2 SEP 23

DESTINATION - Check One

Purex to U Plant ☐

U Plant to Purex ☒

Carrier No. 18622

Batch No. 7-8

DECLASSIFIED

[Signature]
Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9-27-71

Time 1330

BELOW -- FOR PUREX USE ONLY

Date 9-28-71 Time 0230

From Tank, Truck, etc. 18622 To Tank, Truck, etc. P-13-14

Dispatching Tank ☐

Receiving Tank ☐

Level at Start 0' 8" Amount Received _____

Level at Completion 7' 10"

Sample Serial No. 9898 Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

DECLASSIFIED

CHEMICAL PROCESSING DIVISION 4423 ACID OPERATION

TRANSFER SERIES NO.

[illegible]

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

ARH-2102 SEP

25

DESTINATION - Check One

Purex to U Plant ☒

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

DECLASSIFIED

Shipper Signature _____

Receiver Signature _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

From Tank, Truck, etc. _____

Date 9-28-71

Time 2130

To Tank, Truck, etc. _____

Dispatching Tank ☐

Receiving Tank ☐

Level at Start

13 14
9" 9"

Amount Received _____

Level at Completion

9'5" 9'5"

Sample Serial No. 24

Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

24
APR 14 1971

DESTINATION - Check One

Purex to U Plant

U Plant to Purex ☒

Carrier No. ATMX-100

Batch No. 9-10

DECLASSIFIED

M. J. [Signature]
Shipper Signature

Receiver Signature

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☒

Date 9/29/71

Time 1445

BELOW -- FOR PUREX USE ONLY

Date 9-30-71

Time 0715

From Tank, Truck, etc. Atmx 100

To Tank, Truck, etc. P13 - P14

Dispatching Tank ☐

Receiving Tank ☐

Level at Start 0'8" 0'8"

Amount Received _____

Level at Completion 13'4" 14'4"
7'11" 8'0"

Sample Serial No. _____ Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

CPD -- INTERPLANT TRANSFER FORM

25
ARH-2102 SEP

DESTINATION - Check One

Purex to U Plant ☒

U Plant to Purex ☐

Carrier No. _____

Batch No. _____

Shipper Signature _____

Receiver Signature _____

MATERIAL TYPE - Check One

Depleted U ☐

Waste Material ☐

Recovered Acid - UO_3 ☐

Date _____

Time _____

BELOW -- FOR PUREX USE ONLY

Date 9-28-71 Time 2130

From Tank, Truck, etc. _____ To Tank, Truck, etc. _____

Dispatching Tank ☐

Receiving Tank ☐

Level at Start

13 14
9" 9"

Amount Received _____

Level at Completion

9'5" 9'5"

Sample Serial No. 24 Total Lbs U _____

Analysis - Lbs U Per Gallon _____

DECLASSIFIED

UNCLASSIFIED

DON'T SAY IT ---

Write It

ARH-21.2 SEP 1959

27

a. u.o.o.

~~SECRET~~ DECLASSIFIED

DATE

September

FROM

Personnel

Shurpung

Acid

5550

-688 bias

4862

4.235

42.06

DECLASSIFIED

~~SECRET~~

"SAFE LIVING IS A LIFETIME PROPOSITION"

DECLASSIFIED

OFFICIAL USE ONLY

AND 12 SEP 28

28

INTERDEPARTMENTAL SS MATERIAL TRANSFER

UNCLASSIFIED

NUMBER

6711-71-31

ALLOTMENT NO.

FROM (DEPT., SECTION, SUB-SECTION OR UNIT)

CPD TSS STANDARDS LAB

TO (DEPT., SECTION, SUB-SECTION OR UNIT)

~~CPD TSS~~ PUREX ~~LAB~~

ALLOTMENT NO.

AEC TRANSFER AUTHORITY

☐ NORMAL U
☐ DEPLETED U☐ ENRICHED U { 75%
☐ ENRICHED U { 75%☐ PLUTONIUM
☒ NP

TYPE AND IDENTIFICATION

☐ NO. OF PCS.
☐ NET WT.
☐ VOL.FAC. WT.
OR ANALYT.
FACTOR

SS WT.

IN gms
NP

SS WT.

IN U-235

SS WT.


IN PU

125B4 NP STD (3XN)

.482

.482

TOTAL

negl.
.482

SHIPPED BY

DECLASSIFIED

DATE

9/28/71

SHIPPER'S INSTRUCTIONS

WHITE — TO RECEIVER
YELLOW — TO RECEIVER
BLUE — TO RECEIVER
PINK — TO RECEIVER
GOLDENROD — TO SHIPPER'S SS ACCOUNT, OFF. (WITHIN 24 HRS)
GREEN — RETAIN

RECEIVED BY

DATE

R H James 9-30-71

RECEIVER'S INSTRUCTIONS

WHITE — TO RECEIVER'S SS ACCOUNT, OFF.
YELLOW — TO SHIPPER'S SS ACCOUNT, OFF.
BLUE — IPD PRODUCTION PLANNING & SCHEDULING
PINK — RETAIN

DECLASSIFIED

OFFICIAL USE ONLY

ARH 2182 SPLE 29

INTERDEPARTMENTAL SS MATERIAL TRANSFER

FROM (DEPT., SECTION, SUB-SECTION OR UNIT)

CPD TSS STANDARDS LAB

TO (DEPT., SECTION, SUB-SECTION OR UNIT)

PUREX

☐ NORMAL U☐ ENRICHED U { 75%☒ PLUTONIUM☐ DEPLETED U☐ ENRICHED U { 75%☐

NUMBER

6711-71-32

ALLOTMENT NO.

ALLOTMENT NO.

AEC TRANSFER AUTHORITY

TYPE AND IDENTIFICATION

☐ NO. OF PCS.
☐ NET WT.
☐ VOL.FAC. WT.
OR ANALYT.
FACTOR

SS WT.

IN _____
U

SS WT.

IN _____
U-235

SS WT.

IN gms
PU6087 FES 18 (PuNO₃)₄

1.13

TOTAL

SHIPPED BY

DATE

9/28/71

RECEIVED BY

DATE

9-30-71

SHIPPER'S INSTRUCTIONS

RECEIVER'S INSTRUCTIONS

WHITE — TO RECEIVER
YELLOW — TO RECEIVER
BLUE — TO RECEIVER
PINK — TO RECEIVER
GOLDENROD — TO SHIPPER'S SS ACCOUNT. OFF. (WITHIN 30 DAYS)
GREEN — RETAIN

WHITE — TO RECEIVER'S SS ACCOUNT. OFF.
YELLOW — TO SHIPPER'S SS ACCOUNT. OFF.
BLUE — IPD PRODUCTION PLANNING & SCHEDULING
PINK — RETAIN

SECRET
AFTER FILING

SS MATERIAL TRANSFER

LOAD NO.

2106

CAR NO.

ARH-2102 SEP 30

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.							
A	684	9	1	3	3	1	5	2	0	3	0	0	5	2	2	7	8	9			
B	683	9	1	3	3	1	5	2	2	3	0	0	5	2	2	7	8	9			
C	682	9	1	3	3	1	5	2	2	3	0	0	5	2	2	7	8	9			

CAR LOADED

8-31-71

DATE

1015

TIME

AND MUST BE UNLOADED BY

9-2-71

DATE

1015

TIME

CAR SHIPPED

8-31-71 1020

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

JW #3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2106

CAR NO.

ABH-212 SEP 3

47

SEDS.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	64	9 1 3 3					
B	65	9 1 3 3					
C	66	9 1 3 3					

CAR LOADED

8-31-71

1015

AND MUST BE UNLOADED BY

9-2-71

1015

CAR SHIPPED

8-31-71

1020

CAR TO BE DELIVERED TO

Purser

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72R-1-65	9-1	07:5	
B								
C								

DECLASSIFIED

~~SECRET~~
AFTER TAIL-IN

SS MATERIAL TRANSFER

LOAD NO.

2101

CAS NO.

ARH-212 SE 105KW

AREA
KW

WELL	STATION	KEY NO.			NET WT.			NO. PIECES			FACTOR WT.			MWDS			DECLASSIFIED		
A	2133-KE																		
	714-KW	9	2	4	4	1	6	1	2	3	0	0	5	5	2	6	3	4	4894.50
B	2134-KE																		12.73
	715-KW	9	2	4	4	2	6	1	3	0	0	5	5	1	6	3	4		1419.67
C	2136-KE																		#118
	717-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4	1907

CAR LOADED 8-30-71 1400
DATE TIME

AND MUST BE UNLOADED BY

9-1-71 1400
DATE TIME

CAR SHIPPED

8/30/71 2200
DATE TIME

CAR TO BE DELIVERED TO

Purex
BUILDING

LOADING SUPERVISOR

J. Wickstrom

SHIPPING SUPERVISOR

J. S. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2102

CAR NO.

38

ARH-212 SEP

BLDG.
109KVAREA
KV

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2133-KK					
	734-KV	9 2 4 4				
B	2134-KK					
	725-KV	9 2 4 4				
C	2135-KK					
	724-KV	9 2 4 4				

CAR LOADED

8-30-71

1100

AND MUST BE UNLOADED BY

9-1-71

1100

CAR SHIPPED

8/31/71

1100

CAR TO BE DELIVERED TO

Purcell

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

REMARKS:

AREA

BLDG.

IF REMOVED FROM KV BASIN
DECLASSIFIED




→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72B-1-63	9-1	0915	
B					/	/	/	
C					/	/	/	

DECLASSIFIED

DECLASSIFIED

THIS FORM IS TO BE USED FOR THE RECORDING OF UNLOADING AND CHARGING OPERATIONS. IT IS TO BE FILLED OUT BY THE OPERATOR AND SUBMITTED TO THE SUPERVISOR FOR REVIEW AND SIGNATURE. THE RECORDING OF UNLOADING AND CHARGING OPERATIONS IS A CRITICAL PART OF THE MAINTENANCE OF THE SYSTEM AND MUST BE DONE CAREFULLY AND ACCURATELY.

~~SECRET~~
AFTER FILING

SS MATERIAL TRANSFER

ARH-2102 SEP 71 34

LOAD NO.

2104

CAR NO.

144

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTORY	WELL	NO. PIECES	FACTORY	WELL	NO. PIECES	FACTORY	WELL	NO. PIECES	FACTORY	WELL	NO. PIECES	FACTORY	WELL	NO. PIECES	FACTORY
A	2123 KE																			
	705 KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4		
B	2122 KE																			
	706 KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4		
C	2121 KE																			
	707 KW	9	2	4	4	1	6	1	2	3	0	0	5	5	1	6	3	4		

CAR LOADED

8/30/71

DATE

1830

TIME

AND MUST BE UNLOADED BY

9/1/71

DATE

1830

TIME

CAR SHIPPED

8/30/71

DATE

2200

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

D. J. Winton

SHIPPING SUPERVISOR

D. J. Winton

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE metal from KW basin
DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

-5000-265 (4-66)

NUCLEAR MATERIALS

~~SECRET~~
AFTER FILING

SS MATERIAL TRANSFER

LOAD NO.

2105

CAR NO.

45

BLDG.

105 KW

AREA

100 K

ARH-2182 SEP 7

36

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	NWD														
A	2126 KW																			
	702 KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4	4894.50	
B	2125 KE																		12.73	
	703 KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4	1419.67	
C	2124 KE																		#118	
	704 KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4	1402	

CAR LOADED 8/30/71 2315 AND MUST BE UNLOADED BY 9/1/71 2315
DATE TIME DATE TIME

CAR SHIPPED 8-31-71 1020 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

D. S. Winston

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE metal from KW basin
DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2104

CAR NO.

44

BLDG.

105 NW

AREA

100 E

AR-1-2132 SEP 1 1971

35

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2223 EE					
	705 NW	9 2 4 4				
B	2222 EE					
	705 NW	9 2 4 4				
C	2221 EE					
	705 NW	9 2 4 4				

CAR LOADED

8/30/71

1130

TIME

AND MUST BE UNLOADED BY

9/1/71

DATE

1330

TIME

CAR SHIPPED

8/30/71

2200

TIME

CAR TO BE DELIVERED TO

PUEBLO

BUILDING

LOADING SUPERVISOR <i>E. J. Wright</i>		SHIPPING SUPERVISOR <i>E. J. Wright</i>			
RECEIVED FOR SHIPPING <i>[Signature]</i>		DATE 8-30-71	TIME		
RECEIVED BY <i>Wright</i>		DATE 8-30-71	TIME 2300	AREA 200E	BLDG. 202A
REMARKS:					

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					725-1-65	9-1	5:45	pd
B					/	/	/	/
C					/	/	/	/

DECLASSIFIED

DECLASSIFIED

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2105

CAR NO.

45

BLDG.

105 KW

AREA

100 K

AR 1-2162 SEP 7 37

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2126 KW					
	702 KW	9 2 4 4				
B	2125 KE					
	703 KW	9 2 4 4				
C	2124 KE					
	704 KW	9 2 4 4				

CAR LOADED 8/30/71 2315

AND MUST BE UNLOADED BY 9/1/71 2315

CAR SHIPPED 8-31-71 1120

CAR TO BE DELIVERED TO PEREX BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000 265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A				72-B-1-65	72-B-1-65	4-1-71		WCP
B								
C							1200	

DECLASSIFIED

~~SECRET~~
AFTER ALL-IN

SS MATERIAL TRANSFER

LOAD NO.

2107

CAR NO.

36

BLDG.

105-KW

AREA

KW

ARH-2182 SEP 7 38

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	2120 KE																				
	701-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4			4894.50
B	2119-KE																				12.73
	700-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4			1419.67
C	2118-KE																				#118
	699-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4			1907

CAR LOADED

8-31-71

0915

DATE

TIME

AND MUST BE UNLOADED BY

9-2-71

0915

DATE

TIME

CAR SHIPPED

8-31-70

1020

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2107

CAR NO.

ARH-6132 S-P-39
36 105-KW KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2120 KE					
	702-KW	9 2 4 4				
B	2119-KE					
	700-KW	9 2 4 4				
C	2118-KE					
	699-KW	9 2 4 4				

CAR LOADED

8-31-71

0915

AND MUST BE UNLOADED BY

9-2-71

0915

CAR SHIPPED

8-31-71

2000

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-68)

ACCOMPANY SHIPMENT

DECLASSIFIED

39 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	2100	11-2-65			72-8-1-65	11-2-65		WEB
B								
C								

DECLASSIFIED

DECLASSIFIED

THIS FORM CANNOT BE RELOADED BY DATE. IT IS TO BE USED FOR RECORDING OR PROVISION FOR COORDINATION OF THE RECEIVING POINT OR ORIGIN.

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

ARM-2162 SEP 40

LOAD NO.

2108

CAR NO.

46

BLDG.

105KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	2115KE								
	698KW	92441609300551634					4894.50		
B	2116KE						12.73		
	697KW	92441609300551634					1419.67		
C	2117KE								
	696KW	92441605300551634					1902		#119

CAR LOADED 9H 8-31-71 1100 AND MUST BE UNLOADED BY 9-2-71 1100
DATE TIME DATE TIME

CAR SHIPPED 9-1-71 1015 CAR TO BE DELIVERED TO Gurex
DATE TIME BUILDING

LOADING SUPERVISOR <u>J. Wickstrom</u>	SHIPPING SUPERVISOR <u>J. Wickstrom</u>
RECEIVED FOR SHIPPING BY	DATE TIME
RECEIVED BY	DATE TIME AREA BLDG.

REMARKS:

KE metal from KW Basin

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2108

CAR NO.

46

ARH-2132

S-P-7

BLDG.

105KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2115KE					
	698KW	92 #4				
B	2115KE					
	698KW	92 #4				
C	2115KE					
	698KW	92 #4				

CAR LOADED 8-31-71 1100

AND MUST BE UNLOADED BY

9-2-71 1100

CAR SHIPPED

9-1-71 1015

CAR TO BE DELIVERED TO

BUILDING

Gurex

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE metal from KW Basin

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

WATERIAL TRANSFER

TESTIFIED

41A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-65	9-1-71		WCP
B								
C							1200	

THIS RECORD IS TO BE USED TO DETERMINE THE LOCATION OF THE POINT OF ORIGIN

~~SECRET~~
AFTER PHASIN

SS MATERIAL TRANSFER

LOAD NO.
2066

CAR NO.

46

BLDG.

105KW

AREA

100 K

ARH-2132 SEP 7 42

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.			NO. PIECES			FACTOR WT.			MWDS			
A	169KW	9	0	5	8	1	6	1	3	2	0	5	5	15	9	1	2	
B	170KW	9	0	5	8	1	6	1	3	2	0	5	5	15	9	1	2	
C	171KW	9	0	5	8	1	6	1	6	3	0	0	5	5	15	9	1	2

DECLASSIFIED

4947.67
18.53
1871.48
#118
2736

CAR LOADED ⁹⁴ 8/26/71 1730 AND MUST BE UNLOADED BY 8/28/71 1730
DATE TIME DATE TIME

CAR SHIPPED 8-26-71 19⁰⁰ CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

Je #3

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

34-5000-265 (4-66)

NUCLEAR MATERIALS

ARM-2132 SEP 43

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2066

CAR NO.
46

BLDG.
205W

AREA
200 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	205W	9058				
B	205W	9058				
C	205W	9058				

EX-METAL

DECLASSIFIED

CAR LOADED 8/26/71 1730

AND MUST BE UNLOADED BY 8/28/71 1730

CAR SHIPPED 8-26-71 1900

CAR TO BE DELIVERED TO PURLEY BUILDING

LOADING PROVIDED BY [Signature]

SHIPPING SUPERVISOR [Signature]

RECEIVED FOR SHIPMENT BY [Signature]

DATE 8-26-71

TIME

RECEIVED BY R.A. Falk

DATE 8/26/71

TIME 2140

AREA 200-E

BLDG. 202-H

REMARKS:

EX METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

43A.

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	C7	8-26-64	2200	OB	72A-1-64	9-1-64	540	[Signature]
B	C8	[Signature]	[Signature]	[Signature]	/	/	/	/
C	C9	[Signature]	[Signature]	[Signature]	/	/	/	/

DECLASSIFIED

DECLASSIFIED

SECRET
AFTER TELL-IN

SS MATERIAL TRANSFER

LOAD NO.

1931

CAR NO.

37

BLDG.

105

AREA

C

ARM-2102 SEP - 44

DECLASSIFIED

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	129 KE								
	2609C	92171609	300	55	1900				
B	130 KE								
	2608C	92171608	300	55	1900				
	201 KE								
C	2607C	92171615	300	55	1900				

CAR LOADED 8-11-71 2230
DATE TIME

AND MUST BE UNLOADED BY 8-13-71 2230
DATE TIME

CAR SHIPPED 8-12-71 1040
DATE TIME

CAR TO BE DELIVERED TO Building

LOADING SUPERVISOR

R. R. R.

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE TIME

RECEIVED BY

DATE TIME

AREA

BLDG.

REMARKS:

KE metal out of C Basin

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

1931

CAR NO.

37

BLDG.

105

AREA

C

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	129 KE					
	2609C	9217				
B	129 KE					
	2609C	9217				
	201 KE					
C	2609C	9277				

KE-METAL

9836
DECLASSIFIED

CAR LOADED 8-11-71 2:30

AND MUST BE UNLOADED BY 8-12-71 2:30

CAR SHIPPED 8-12-71 10:40

CAR TO BE DELIVERED TO

BUILDING

LOADING SUPERVISOR

B. Beck

SHIPPING SUPERVISOR

Wickstrom

RECEIVED FOR SHIPPING BY

Wright

DATE

8-12-71

TIME

RECEIVED BY

Wright

DATE

9-12-71

TIME

11:20

AREA

200E

BLDG.

202A

REMARKS:

KE metal out of C Basin

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

NS-3000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

22 MATERIAL JAN 22 1971

45A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	C-1	8-12-71	8-4 1400	QCS	72A-1-64	4-1	0540	QCS
B	C-2	✓	8-4 1400	✓	8-3	8-3/71	0900	QCS
C	C-3	✓	8-4 1400	✓	A-3	8/31/71	1500	QCS

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF THE DISSEMINATION AND INFORMATION CONTROL, AND IS TO BE DESTROYED WHEN THE INFORMATION CONTAINED HEREIN IS NO LONGER REQUIRED FOR OFFICIAL USE.

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2062

CAR NO.

44

BLDG.

105

AREA

B

AR 1-2102 SEP 74

44

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	609KE					
	1427B	9564	1610	300	555355	
B	608KE					
	1426B	9564	1608	300	555355	
C	607KE					
	1425B	9564	1610	300	555355	

DECLASSIFIED

4884.24
7.39
901.03
#118

CAR LOADED 8-26-71 1030

AND MUST BE UNLOADED BY 8-28-71 1030

CAR SHIPPED 8-26-71 1900

CAR TO BE DELIVERED TO

LOADING SUPERVISOR

R. J. Beach

SHIPPING SUPERVISOR

E. E. Quinn

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE Metal from "B" Basin
DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2062

CAR NO.

44

BLDG.

105

AREA

B

AR-2132 SEP

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	609KE					
	1427B	9564				
B	609KE					
	1426B	9564				
C	609KE					
	1425B	9564				

DECLASSIFIED

CAR LOADED 8-26-71 1020

AND MUST BE UNLOADED BY

8-28-71

1030

CAR SHIPPED 8-26-71

CAR TO BE DELIVERED TO

J. J. J.

LOADING SUPERVISOR

E. J. J.

SHIPPING SUPERVISOR

E. J. J.

RECEIVED FOR SHIPPING BY

M. J. J.

DATE

8-26-71

TIME

RECEIVED BY

R. A. Palk

DATE

8/26/71

TIME

2140

AREA

200-E

BLDG.

202-A

REMARKS:

KE Metal from 'B' Basin

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-65)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

32 MATERIAL TRANSFER

47A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	10	8-26-64	2:20	OB	72A1-64	9-1	0:54	
B	11							
C	12							

DECLASSIFIED

DECLASSIFIED

DO NOT BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT PERMISSION IN WRITING FROM THE NATIONAL ARCHIVES AND RECORDS ADMINISTRATION.

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

ARM-2132 SEP 71

LOAD NO.

1970

CAR NO.

40

BLDG.

105-B

AREA

100B

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	114KE 1524 B	9 5 3 5	1 6 0 0	5 0 0	5 5 1 5	4 8 1	4957.30
B	115KE 1523 B	9 5 3 5	1 6 0 0	5 0 0	5 5 1 5	4 8 1	9.29 111000 #117
C	116KE 1522 B	9 5 3 5	1 6 1 0	3 0 0	5 5 1 5	4 8 1	

CAR LOADED 8/16/71 1030

DATE

TIME

AND MUST BE UNLOADED BY

8/18/71

1030

DATE

TIME

CAR SHIPPED 8/16/71 1140

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

G. S. Winston

SHIPPING SUPERVISOR

G. S. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE Metal from B basin

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

1970

CAR NO.

40

BLDG.

105-B

AREA

100B

AR-2132 SEP 7 49

WELLS	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	114KE 1524 B	9 5 3 5				
B	114KE 1523 B	9 5 3 5				
C	114KE 1522 B	9 5 3 5				

CAR LOADED

8/16/71

1030

AND MUST BE UNLOADED BY

8/16/71

1030

CAR SHIPPED

DATE

TIME

CAR TO BE DELIVERED TO

Purcell

BUILDING

LOADING SUPERVISOR

E. J. Winston

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

[Signature]

DATE

8-16-71

TIME

RECEIVED BY

[Signature]

DATE

8-16-71

TIME

1245

AREA

800E

BLDG.

202A

REMARKS:

KE Metal from B begin
DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

94-5000-255 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

49A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	C-4	8-16-71	1735	[Signature]	72-A-1-64	9-1	0540	[Signature]
B	C-5	/	/	/	/	/	/	/
C	C-6	/	/	/	/	/	/	/

DECLASSIFIED

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2021

CAR NO.

45

BLDG.

105-B

AREA

100-B

WELL

STATION

KEY NO.

NET WT.

NO. PIECES

FACTOR WT.

MWDS

DECLASSIFIED

A

2008-B

9 4 5 5 1 6 1 0 3 0 0 5 5 1 5 3 0 8

2624-KE

2007-B

4959.48

5.73

B

9 4 5 5 1 6 1 3 0 0 5 5 1 5 3 0 8

2623-KE

2006-B

731.06

#117

C

9 4 5 5 1 6 1 3 3 0 0 5 5 1 5 3 0 8

2622-KE

CAR LOADED

8-21-71

DATE

TIME

AND MUST BE UNLOADED BY

8-23-71

DATE

TIME

1345

CAR SHIPPED

8-23-71

DATE

TIME

CAR TO BE DELIVERED TO

BUILDING

LOADING SUPERVISOR

E. J. Roach

SHIPPING SUPERVISOR

E. J. Roach

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE metal from "B" Basin

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 Sep 7

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2021

CAR NO.

45

BLDG.

105-B

AREA

100-B

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2008-B	9455				
B	2624-KE 2007-B	9455				
C	2623-KE 2006-B	9455				

CAR LOADED

8-21-71

DATE

TIME

1345

AND MUST BE UNLOADED BY

8-23-71

DATE

TIME

1345

CAR SHIPPED

8-23-71

DATE

TIME

0650

CAR TO BE DELIVERED TO

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

8-21-71

71.50

200E

202A

DECLASSIFIED

KE metal from "B" Basin

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

51A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	B-3	8.22.71	1020	<i>[Signature]</i>	72A-1-64	9-1	0340	<i>[Signature]</i>
B	B-7	/	/	/	/	/	/	/
C	B-1	/	/	/	/	/	/	/

DECLASSIFIED

THIS DOCUMENT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOUR AGENCY. IT AND ITS CONTENTS ARE NOT TO BE DISTRIBUTED OUTSIDE YOUR AGENCY.

APR 12 1972 SEP 1

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO. 2092	CAR NO. 46	BLDG. 105-KW	AREA KW
------------------	---------------	-----------------	------------

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS				
A	1101																					

DECLASSIFIED

CAR LOADED	8-29-71	1330	AND MUST BE UNLOADED BY	8-31-71	1330
	DATE	TIME		DATE	TIME
CAR SHIPPED	8-29-71	1400	CAR TO BE DELIVERED TO	Purex	
	DATE	TIME		BUILDING	

LOADING SUPERVISOR <i>J. Wickstrom</i>	SHIPPING SUPERVISOR <i>J. Wickstrom</i>			
RECEIVED FOR SHIPPING BY	DATE	TIME		
RECEIVED BY	DATE	TIME	AREA	BLDG.

DECLASSIFIED

REMARKS:

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2092

CAR NO.

16

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1101	9 1 1 9				
B	1100	9 1 1 9				
C	1099	9 1 1 9				

DECLASSIFIED

CAR LOADED 8-29-71 1330 AND MUST BE UNLOADED BY 8-31-71 1330

CAR SHIPPED 8-29-71 1400 CAR TO BE DELIVERED TO Purax BUILDING

LOADING SUPERVISOR <i>Wickstrom</i>	SHIPPING SUPERVISOR <i>Wickstrom</i>			
RECEIVED FOR SHIPPING BY <i>R. H. H.</i>	DATE <i>8-28-71</i>	TIME <i>1400</i>		
RECEIVED BY <i>Blackburn</i>	DATE <i>8-28-71</i>	TIME <i>1500</i>	AREA <i>200 E</i>	BLDG. <i>202A</i>

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

53A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	B4	8-29	2100	OS	12A-1-64	9-1	0540	
B	B5							
C	B6							

DECLASSIFIED

NOT BE RECHARGED TO THE SAME OR TO ANY OTHER RECEIVER. IF IT IS RETURNED TO POINT OF ORIGIN.

ARM-2132 SEP 2

5Y

SECRET
AFTER ALL-IN

SS MATERIAL TRANSFER

LOAD NO.

2099

CAR NO.

46

BLDG.

105

AREA

105

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	DECLASSIFIED	REMARKS
A	825	9 1 1 9 1 6 1 8	0 2 9 5 2 2 0 6 4	2 7 1 5 5 15 5 2 1	4911.70	1637.23		Real # 62
B	826	9 1 1 9 1 6 1 7	0 2 9 5 2 2 0 6 4	2 7 1 5 5 15 5 2 1	11.81	3.94		
C	827	9 1 1 9 1 6 1 4	0 2 9 5 2 2 0 6 4	2 7 1 5 5 15 5 2 1	1351.12	450.37		#118

CAR LOADED 8-30-71 0930
DATE TIMEAND MUST BE UNLOADED BY 9-1-71 0930
DATE TIMECAR SHIPPED 8-30-71 1040
DATE TIMECAR TO BE DELIVERED TO Purex
BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

NUCLEAR MATERIALS

ARH-2132 SEP 53

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2099

CAR NO.

16

BLDG.

305-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	825	9 1 1 9				
B	826	9 1 1 9				
C	827	9 1 1 9				

DECLASSIFIED

FE-METAL

CAR LOADED 8-30-71 0930 AND MUST BE UNLOADED BY 9-1-71 0930

CAR SHIPPED 8-30-71 1040 CAR TO BE DELIVERED TO PARROT

LOADING SUPERVISOR <i>J. Wickstrom</i>	SHIPPING SUPERVISOR <i>J. Wickstrom</i>
RECEIVED FOR SHIPPING BY <i>J. Wickstrom</i>	DATE <u>8-30-71</u> TIME <u>1030</u>
RECEIVED BY <i>J. C. Blackburn</i>	DATE <u>8-30-71</u> TIME <u>1450</u>
REMARKS:	AREA <u>200E</u> BLDG. <u>202A</u>

DECLASSIFIED

1637.23
3.94
150.27

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

55A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A		8-30-71			72-1A-62	8-30	1230	LEB
B					72-1A-62	8-30	1230	LEB
C	C-3	8-30-71	1230	LEB	72-1A-64	9-1	0540	✓

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF THE CHIEF OF THE DIVISION FOR THE RECORDS AND COMMUNICATIONS SECTION. IT IS TO BE RETAINED FOR A PERIOD OF 10 YEARS FROM THE DATE OF THE LAST ENTRY.

~~SECRET~~
AFTER PLANNING

SS MATERIAL TRANSFER

LOAD NO.

2118

CAR NO.

42

BLDG.

105/KW100/K

AREA

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	678	9133	152430	0522788			DECLASSIFIED
B	677	9133	152330	0522788			4743.99 17.76 1699.49 #119
C	676	9133	152130	0522788			2364

CAR LOADED

9-1-71

DATE

2130

TIME

AND MUST BE UNLOADED BY

9-3-71

DATE

2130

TIME

CAR SHIPPED

9-1-71

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

E. J. Roach

SHIPPING SUPERVISOR

E. J. Roach

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW metal from KW basin.

DECLASSIFIED

JL # 3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2118

CAR NO.

42

BLDG.

105/KW100K

AREA

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	678	9133				
B	677	9133				
C	676	9133				

DECLASSIFIED

CAR LOADED 9-1-71 2130 AND MUST BE UNLOADED BY 9-2-71 2130
DATE TIME DATE TIME

CAR SHIPPED 9-1-71 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW metal from KW basin.

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

57A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					A-3	9.2.71	1430	CCB
B					A-3	"	"	CCB
C					A-3	"	"	CCB

DECLASSIFIED

DECLASSIFIED

THIS DOCUMENT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOU BY THE NATIONAL ARCHIVES. IT IS TO BE RETURNED TO THE NATIONAL ARCHIVES WHEN REQUESTED. IT IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT PERMISSION IN WRITING FROM THE NATIONAL ARCHIVES.

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2115

CAR NO.

47

BLDG.

105-KW

AREA

100-K.

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWD	DECLASSIFIED
A	2333 KE 405KW	9 2 4 4	1 6 0 8 3 0	0 5 5 1	6 3 4		4894.50
B	2334 KE 404KW	9 2 4 4	1 6 1 0 3 0	0 5 5 1	6 3 4		12.73 1419.67
C	2335 KE 403KW	9 2 4 4	1 6 1 1 3 0	0 5 5 1	6 3 4		#119

CAR LOADED

94

9-1-71

1700

AND MUST BE UNLOADED BY

9-3-71

1700

CAR SHIPPED

9-1-71

TIME

CAR TO BE DELIVERED TO

BUILDING

Purcell

LOADING SUPERVISOR

R. J. Roach.

SHIPPING SUPERVISOR

R. J. Roach.

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE metal from KW basin.

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2115

CAR NO.

47

BLDG.

105-KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2333 KE 405 KW	9 2 4 4				
B	2334 KE 404 KW	9 2 4 4				
C	2335 KE 403 KW	9 2 4 4				

DECLASSIFIED

KE METAL

98 38
92 44
5

CAR LOADED 9-1-71 1700 AND MUST BE UNLOADED BY 9-3-71 1700

CAR SHIPPED 9-1-71 CAR TO BE DELIVERED TO P. 100-K

LOADING SUPERVISOR

R. K. Kach

SHIPPING SUPERVISOR

R. K. Kach

RECEIVED FOR SHIPPING BY

M. A. F.

DATE

9-1-71

TIME

2215

RECEIVED BY

J. Beck

DATE

9-2-71

TIME

0930

AREA

200 E

BLDG.

202 A

REMARKS:

KE metal from KW review.

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

59 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0011				A-3	9-2-71	1430	CCF
B					A-3	"	"	CCF
C					A-3	"	"	CCF

DECLASSIFIED

UNLOADING OR CHARGING RECORDS ARE TO BE MAINTAINED IN THE BUILDING DISPATCHER'S OFFICE AND SHALL BE AVAILABLE TO THE READER.

~~SECRET~~
AFTER 1-1-71

SS MATERIAL TRANSFER

LOAD NO.

2116

CAR NO.

44

BLDG.

105-KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2315 KE 428 KW	92441535300522631																		
B	2314 KE 427 KW	92441535300522631																		
C	2313 KE 426 KW	92441530300522631																		

DECLASSIFIED

CAR LOADED 94 9-1-71 1750 AND MUST BE UNLOADED BY 9-3-71 1750
DATE TIME DATE TIME

CAR SHIPPED 9-1-71 1750 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR

R. J. Beach

SHIPPING SUPERVISOR

R. J. Beach

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE metal from KW basin.

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

CAR NO.

BLDG.

AREA

2116

44

105-KW

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2315 KE	9244				
B	2314 KE	9244				
C	2313 KE	9244				

CAR LOADED 9-1-71 1750

AND MUST BE UNLOADED BY 9-3-71 1750

CAR SHIPPED 9-1-71

CAR TO BE DELIVERED TO Parcel

LOADING SUPERVISOR
RECEIVED FOR SHIPPING BY
RECEIVED BY
REMARKS:

SHIPPING SUPERVISOR
DATE 9-1-71 TIME 2215
DATE 9-2-71 TIME 0930
AREA 208E BLDG. 202A

UNCLASSIFIED KE metal from KW basin.

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

61 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					A-3	9.27	1430	004
B					A-3	"	"	"
C					A-3	"	"	"

DECLASSIFIED

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE

SECRET AFTER DECLASSIFICATION		SS MATERIAL TRANSFER				LOAD NO. 2117	CAR NO. 45	BLDG. 105-KW	AREA 100/K
WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	411 KW 2330	9244	161030	055163	4894.50				
B	410 KW 2331	9244	161230	0551634	12.73				
C	409 KW 2332	9244	161030	0551634	1419.67				
CAR LOADED		9-1-71	1945	AND MUST BE UNLOADED BY		9-3-71	1945		
CAR SHIPPED		9-1-71		CAR TO BE DELIVERED TO		Durex			
LOADING SUPERVISOR R. J. Roach.				SHIPPING SUPERVISOR R. J. Roach.					
RECEIVED FOR SHIPPING BY				DATE		TIME			
RECEIVED BY				DATE		TIME		AREA	BLDG.
REMARKS: KE metal from KW basin.									

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2117

CAR NO.

45

BLDG.

105-KW/60K

AREA

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	#11 KW 2330	9244				
B	#10 KW 2331	9244				
C	#09 KW 2332	9244				

METAL

DECLASSIFIED

CAR LOADED 9-1-71 1945 AND MUST BE UNLOADED BY 9-3-71 1945

CAR SHIPPED 9-1-71 1945 CAR TO BE DELIVERED TO Bureau

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED
KE metal from KW basin.

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

63A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					A-3	9.2.71	1540	CCJ
B					A-3	4		CCJ
C					A-3	4		CCJ

DECLASSIFIED

REPRODUCED FROM THE RECORDS OF THE U.S. DEPARTMENT OF COMMERCE, BUREAU OF MINES, WASHINGTON, D.C. 20230

~~SECRET~~
AFTER DILL-IN

SS MATERIAL TRANSFER

LOAD NO.

21129

CAR NO.

46

BLDG.

100-KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2327 KE	9 2 4 4	1 6 0 9 3 0 0 5 5 1 6 3 4																	
	407 KW																			
B	2328 KE	9 2 4 4	1 6 0 8 3 0 0 5 5 1 6 3 4																	
	408 KW																			
C	2329 KE	9 2 4 4	1 6 0 8 3 0 0 5 5 1 6 3 4																	
	406 KW																			

CAR LOADED

9-1-71
DATE2310
TIME

AND MUST BE UNLOADED BY

9-3-71
DATE2310
TIME

CAR SHIPPED

9-2-71
DATE1330
TIME

CAR TO BE DELIVERED TO

BUILDING

Purex

LOADING SUPERVISOR

E. J. Roach

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE metal from KW Basin

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 1 65

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

21119

CAR NO.

46

BLDG.

105-KW

AREA

100-K.

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2327 KE	9 2 4 4																		
	407 KW																			
B	2328 KE	9 2 4 4																		
	408 KW																			
C	2329 KE	9 2 4 4																		
	406 KW																			

CAR LOADED 9-1-71 2310 AND MUST BE UNLOADED BY 9-3-71 2310

CAR SHIPPED 9-2-71 1230 CAR TO BE DELIVERED TO Purex

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED from KW Basin

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

65A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	01	11-2-66			72-A1-66	9-2	1745	ZRD
B					0	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED BY THE BUILDING DISPATCHER AND IS TO BE USED FOR THE PURPOSE OF PROVING OR DISPROVING THE CHARGING OR UNLOADING OF THE DISSOLVER.

SECRET
--AFTER DECLASS--**SS MATERIAL TRANSFER**

LOAD NO.

2121

CAR NO.

38

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	2316-KE																				
	422-KW	9	2	4	4	1	5	3	5	5	0	0	5	2	2	6	3				
B	2317-KE																				
	421-KW	9	2	4	4	1	5	3	2	3	0	0	5	2	2	6	3	1			
C	2318-KE																				
	418-KW	9	2	4	4	1	5	3	5	3	0	0	5	2	2	6	3	1			

CAR LOADED

9-2-71

DATE

1200

TIME

AND MUST BE UNLOADED BY

9-4-71

DATE

1200

TIME

CAR SHIPPED

9-2-71

DATE

1330

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2121

CAR NO.

38

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2316-KB																			
	422-KW	9	2	4	4															
B	2317-KB																			
	421-KW	9	2	4	4															
C	2318-KB																			
	418-KW	9	2	4	4															

CAR LOADED

9-2-71

1200

AND MUST BE UNLOADED BY

9-4-71

1200

CAR SHIPPED

9-2-71

1330

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS

DECLASSIFIED

SS METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

A 67

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	1051	7-1-66			72-A-1-66	9-2-74		LRD
B								
C								

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF THE CHIEF OF THE BUREAU OF THE ARMY CORP OF ENGINEERS, WASHINGTON, D.C. 20315. IT IS TO BE KEPT FOR A PERIOD OF 10 YEARS FROM THE DATE OF THE LAST ENTRY. IT IS TO BE DESTROYED BY THE BUREAU OF THE ARMY CORP OF ENGINEERS, WASHINGTON, D.C. 20315. IT IS TO BE REPRODUCED BY THE BUREAU OF THE ARMY CORP OF ENGINEERS, WASHINGTON, D.C. 20315.

~~SECRET~~
AFTER DECLASSIFICATION

SS MATERIAL TRANSFER

LOAD NO.

2124

CAR NO.

41

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	673	9	1	3	3	1	5	2	6	3	0	0	5	2	2	7	8	8			
B	674	9	1	3	3	1	5	2	3	3	0	0	5	2	2	7	8	8			
C	675	9	1	3	3	1	5	2	4	3	0	0	5	2	2	7	8	8			

DECLASSIFIED

CAR LOADED 9-2-71 1515 AND MUST BE UNLOADED BY 9-4-71 1515
DATE TIME DATE TIME

CAR SHIPPED 9-2-71 TIME CAR TO BE DELIVERED TO Purex BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

R. J. Roach

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

J#3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 7 69

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2124

CAR NO.

41

BLDG.

305-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS				
A	673	9 1 3 3								
B	674	9 1 3 3								
C	675	9 1 3 3								

DECLASSIFIED

CAR LOADED

9-2-71

DATE

1515

TIME

AND MUST BE UNLOADED BY

9-4-71

DATE

1515

TIME

CAR SHIPPED

9-2-71

DATE

TIME

CAR TO BE DELIVERED TO

BUILDING

Perex

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

JA-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

69A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-67	9-2	2340	LRD
B					✓	✓	✓	✓
C					✓		✓	✓

DECLASSIFIED

DECLASSIFIED

THIS FORM CANNOT BE UNLOADED BY BARGE AND MUST BE UNLOADED BY TUG BOAT. IT IS TO BE USED FOR THE RECORD OF UNLOADING AND CHARGING OF DISSOLVER.

~~SECRET~~
AFTER TALL-IN

SS MATERIAL TRANSFER

LOAD NO.
2120

CAR NO.
37

BLDG.
105-KW

AREA
KW

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
------	---------	---------	--	--	--	---------	--	--	--	------------	--	--	--	------------	--	--	--	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

CAR LOADED 9-2-71 1000 AND MUST BE UNLOADED BY 9-4-71 1000
DATE TIME DATE TIME
CAR SHIPPED 9-2-71 1330 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR
J. Wickstrom
RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR
J. Wickstrom
DATE TIME

RECEIVED BY

DATE TIME AREA BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 71

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2120

CAR NO.

37

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2312-KS					
	425-KW	9 2 4 4				
B	2311-KS					
	424-KW	9 2 4 4				
C	2310-KS					
	423-KW	9 2 4 4				

CAR LOADED

9-2-71

DATE

1000

TIME

AND MUST BE UNLOADED BY

9-4-71

DATE

1000

TIME

CAR SHIPPED

9-2-71

DATE

1330

TIME

CAR TO BE DELIVERED TO

Parex

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

A-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

70A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0001	9-2-40			72-B-1-67	9-2-40		LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

NOT BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, WITHOUT PERMISSION IN WRITING FROM THE NATIONAL ARCHIVES. THIS RECORD IS THE PROPERTY OF THE NATIONAL ARCHIVES AND IS LOANED TO YOU. IT IS TO BE RETURNED TO THE NATIONAL ARCHIVES WHEN REQUESTED.

~~SECRET~~
AFTER TALL-IN

SS MATERIAL TRANSFER

LOAD NO.
2122

CAR NO.
36

BLDG.
105-KW

AREA
KW

ARH-2132 SEP 72

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	2326-KE																				
	417-KW	9	2	4	4	1	6	1	0	0	0	0	0	0	0	0	0	6	3	4	4894.50
B	2319-KE									1	1	9	5	2	2	2	2	9	6		12.73
	419-KW	9	2	4	4	1	5	8	0	1	6	1	5	5	1	3	1	8			1419.67
C	2320-KE																				
	420-KW	9	2	4	4	1	5	7	2	3	0	0	5	2	2	6	3	1			479

CAR LOADED 9-2-71 1200 AND MUST BE UNLOADED BY 9-4-71 1200
DATE TIME DATE TIME

CAR SHIPPED 9-2-71 1330 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR

J. Wickstrom
RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom
DATE TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 73

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2122CAR NO.
36BLDG.
105-KWAREA
KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2326-KE																			
	417-KW	9	2	4	4															
B	2319-KE																			
	419-KW	9	2	4	4															
C	2320-KE																			
	420-KW	9	2	4	4															

CAR LOADED 9-2-71 1200 AND MUST BE UNLOADED BY 9-4-71 1200
DATE TIME DATE TIME

CAR SHIPPED 9-2-71 1230 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

J. Beck

DATE

9-2-71

TIME

1710

AREA

200E

BLDG.

202A

REMARKS

UNCLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

0.5000.203 (4-65)

ACCOMPANY SHIPMENT

ARM-315-229

108-28

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

73A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0003	11-1-40			72-B-F-67	9-2-11-40		LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

RECEIVED BY RECEIVER
DATE OF RECEIPT
ORIGIN

~~SECRET~~
AFTER PICK UP

SS MATERIAL TRANSFER

LOAD NO.

2123

CAR NO.

39

BLDG.

105-KW

AREA

KW

ARH-2132 SEP 7

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS													
A	2323-KE																		
	414-KW	9	2	5	4	1	5	2	8	5	0	0	5	2	2	6	3	1	4894.50
B	2324-KE																		12.73
	415-KW	9	2	4	4	1	5	3	0	3	0	0	5	2	2	6	3	1	1419.67 #119
C	2325-KE																		
	416-KW	9	2	4	4	1	5	3	0	3	0	0	5	2	2	6	3	1	993

CAR LOADED 9-2-71 1515 AND MUST BE UNLOADED BY 9-4-71 1515
DATE TIME DATE TIME
CAR SHIPPED 9-2-71 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR <i>J. Wickstrom</i>	SHIPPING SUPERVISOR <i>R. J. Roach</i>		
RECEIVED FOR SHIPPING BY	DATE	TIME	
RECEIVED BY	DATE	TIME	AREA
			BLDG.

REMARKS:

KE METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2123

CAR NO.

39

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2323-K3																			
	414-KW	9	2	8	4															
B	2321-K3																			
	415-KW	9	2	4	4															
C	2325-K3																			
	416-KW	9	2	4	4															

CAR LOADED

9-2-71

DATE

1515

TIME

AND MUST BE UNLOADED BY

9-4-71

DATE

1515

TIME

CAR SHIPPED

9-2-71

DATE

TIME

CAR TO BE DELIVERED TO

Purco

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

1-5000-285 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

22 MATERIAL TRANSFER

75 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	2022	11-2-67			72-B-1-67	9-2	2340	LRD
B								
C								

DECLASSIFIED

DECLASSIFIED

RECEIVED BY DATE AND TIME AND BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELL MUST BE MADE BY RECEIVER

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2125

CAR NO.

42

BLDG.

AREA

ARH-2132 SEP 7 1976

1051 KW

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	DECLASSIFIED
A	2322 KE	9244	161030	0551	634	3263.07	
	413 KW					8.3	
B	2321 KE	9244	1563	0052	2631	946.51	
	412 KW						
C		9226	01520	1505	15153	1637.03	
	936 KW					4.08	
	94					440.28	#119

CAR LOADED

9-2-71

DATE

1845

TIME

AND MUST BE UNLOADED BY

9-4-71

DATE

1845

TIME

CAR SHIPPED

9-2-71

DATE

TIME

CAR TO BE DELIVERED TO

BUILDING

Purep.

LOADING SUPERVISOR

R. J. Roach.

SHIPPING SUPERVISOR

R. J. Roach

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

2 buckets of KE metal
1 bucket of KW metal } from KW basin

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2125

CAR NO.

42

BLDG.

105-KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2322 KE	9244				
	413 KW					
B	2321 KE	9244				
	412 KW					
C	936 KW	9260				

CAR LOADED 9-2-71 1845

AND MUST BE UNLOADED BY

9-4-71 1845

CAR SHIPPED 9-2-71

CAR TO BE DELIVERED TO

Piney.

LOADING SUPERVISOR

R. P. Roach

SHIPPING SUPERVISOR

R. P. Roach

RECEIVED FOR SHIPPING BY

m.d.f.

DATE

9-2-71

TIME

1930

RECEIVED BY

J. W. Beck

DATE

9-2-71

TIME

2145

AREA

200E

BLDG.

202A

REMARKS:

2 buckets of KE metal
 1 bucket of KW metal } from KW basin.

UNCLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

77A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	2481	11-11			72-B-107	9-2	2300	LRP
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

THIS DOCUMENT IS TO BE RETURNED TO POINT OF ORIGIN

~~SECRET~~
AFTER FILING

SS MATERIAL TRANSFER

LOAD NO.

2126

CAR NO.

45

BLDG.

105-KW

AREA

100-K

APR 102 SEP 71

78

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	935	9260	1525	1505	529225	310	4911.35
B	934	9260	1516	1505	529225	310	11.64 1321.16 #119
C	933	9260	1520	1505	529225	310	160

DECLASSIFIED

94
CAR LOADED 9-2-71 1920
DATE TIME

AND MUST BE UNLOADED BY 9-4-71 1920
DATE TIME

CAR SHIPPED 9-2-71
DATE TIME

CAR TO BE DELIVERED TO

Purep
BUILDING

LOADING SUPERVISOR

R. J. Roach.

SHIPPING SUPERVISOR

R. Roach.

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW metal from KW basin.
DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2126

CAR NO.

45

BLDG.

105-KW

AREA

100-K

ARH-2132 SEP

88

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	935	9260																		
B	934	9260																		
C	933	9260																		

CAR LOADED

9-2-71 1920

DATE

TIME

AND MUST BE UNLOADED BY

9-4-71 1920

DATE

TIME

CAR SHIPPED

9-2-71

DATE

TIME

CAR TO BE DELIVERED TO

BUILDING

Pursey

LOADING SUPERVISOR

R. J. Ruck

SHIPPING SUPERVISOR

P. Ruck

RECEIVED FOR SHIPPING BY

M. G. F.

DATE

9-2-71

TIME

1930

RECEIVED BY

J. Ruck

DATE

9-2-71

TIME

2145

AREA

200E

BLDG.

202A

REMARKS:

KW metal from KW basin.

UNCLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

J4-5000-205 (4-68)

ACCOMPANY SHIPMENT

DECLASSIFIED

22 MATERIAL TRANSFER

80 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0841	11-11-55			72-B-1-67	9-2	1340	BRD
B								
C								

DECLASSIFIED

THIS RECORD IS TO BE USED FOR THE PURPOSE OF RECORDING THE UNLOADING AND CHARGING OF MATERIALS. IT IS TO BE RETURNED TO THE POINT OF ORIGIN.

~~SECRET~~
AFTER PLAIN

SS MATERIAL TRANSFER

LOAD NO.

2130

CAR NO.

38

BLDG.

105

AREA

KV

ARTE-2132 SEP 81

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	670	9	1	3	3	1	5	2	4	3	0	0	5	2	2	7	8	8			
B	671	9	1	3	3	1	5	2	3	0	0	5	2	2	7	8	8				
C	672	9	1	3	3	1	5	2	2	3	0	0	5	2	2	7	8	8			

DECLASSIFIED

E-METAL

4743.99
17.76
1699.49
#119

2364

CAR LOADED

9-3-71

0915

DATE

TIME

AND MUST BE UNLOADED BY

9-6-71

0915

DATE

TIME

CAR SHIPPED

9-3-71

0915

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

J# 3

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2130

CAR NO.

38

BLDG.

105

AREA

IV

AR11-2132 SEP 7

82

ELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	670	9 1 3 3				
B	672	9 1 3 3				
C	672	9 1 3 3				

DECLASSIFIED

E-METAL

CAR LOADED

9-3-71

0915

AND MUST BE UNLOADED BY

9-6-71

0915

CAR SHIPPED

9-3-71

0915

CAR TO BE DELIVERED TO

Furco

BUILDING

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

82A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	4100				72-A-168	9-3-77	7000	LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

25

AREA
KW

KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
E-METAL				
DECLASSIFIED				
4	2	4	1	6
4	1	6	1	1
3	0	0	5	5
1	6	3	4	

NUCLEAR MATERIALS

AMH-2132 SEP 89

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2100

CAR NO.

47

BLDG.

105KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A						
B						
C						

CAR LOADED

8-30-71

DATE

1030

TIME

AND MUST BE UNLOADED BY

9-1-71

DATE

1030

TIME

CAR SHIPPED

8-30-71

DATE

1040

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

10

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-255 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

84A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00-1	8-1-77						
B								
C	B-7 A-7	8-30	2200	288	75-A-168	9-3	4-12	LR2

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED BY THE BUILDING DISPATCHER AND MUST BE RETURNED TO POINT OF ORIGIN
NO OTHER DISPOSITION FOR THIS RECORD IS TO BE MADE BY THE BUILDING DISPATCHER

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2102

CAR NO.

42

BLDG.

105-KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	2130-KE						
	711-KW	9 2 4 4 1 6 1 0 5 0 5 5 2 6 3 4					4894.50 12.73 1419.67 #118
B	2131-KE						
	712-KW	9 2 4 4 1 6 1 2 3 0 0 5 5 1 6 3 4					
C	2132-KE						
	713-KW	9 2 4 4 1 6 1 2 3 0 0 5 5 1 6 3 4					100V

CAR LOADED 8-30-71 1400
DATE TIMEAND MUST BE UNLOADED BY 9-1-71 1400
DATE TIMECAR SHIPPED 8/30/71 2200
DATE TIMECAR TO BE DELIVERED TO Purex
BUILDING

LOADING SUPERVISOR

J. Wickham
RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. S. Winston

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2102

CAR NO.

12

BLDG.

105-KV

AREA

KV

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2130-KE					
	711-KV	9 2 4 4				
B	2131-KE					
	712-KV	9 2 4 4				
C	2132-KE					
	713-KV	9 2 4 4				

CAR LOADED

8-30-71

DATE

11:00

TIME

AND MUST BE UNLOADED BY

9-1-71

DATE

11:00

TIME

CAR SHIPPED

8/30/71

DATE

11:00

TIME

CAR TO BE DELIVERED TO

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

8-30-71

TIME

RECEIVED BY

DATE

8-30-71

TIME

2300

AREA

202 E

BLDG.

202 A

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

86A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D1	8-31	2135	QTB	72-A-144	9-3	4-12	F.R.D
B	D2							
C	D3							

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF ORIGIN AND NOT BE UNLOADED BY HAND. IT IS TO BE RETURNED TO POINT OF ORIGIN.

SECRET
AFTER DECLASSIFICATION

SS MATERIAL TRANSFER

LOAD NO.

2103

CAR NO.

39

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	2127 KE						
	710 KW	9 2 4 4	1 6 1 0	3 0 0 5	5 2 6 3	4	894.50
B	2128 KE						
	709 KW	9 2 4 4	1 6 1 0	3 0 0 5	5 1 6 3	4	12.23 1419.67 #118
C	2129 KE						
	708 KW	94 2 4	1 6 1 2	3 0 0 5	5 1 6 3	4	1402

DECLASSIFIED

CAR LOADED 8/30/71 1745 AND MUST BE UNLOADED BY 9/1/71 1745
DATE TIME DATE TIME

CAR SHIPPED 8/30/71 2200 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR L. B. Winston

SHIPPING SUPERVISOR L. B. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED
KE metal from KW basin

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2103

CAR NO.

39

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2127 K2																			
	710 KW	9	2	4	4															
B	2128 K2																			
	709 KW	9	2	4	4															
C	2129 K2																			
	708 KW	9	2	4	4															

CAR LOADED

8/30/71

1745

DATE

TIME

AND MUST BE UNLOADED BY

9/1/71

DATE

1745

TIME

CAR SHIPPED

8/30/71

2300

DATE

TIME

CAR TO BE DELIVERED TO

PO BOX

BUILDING

200E

202A

LOADING SUPERVISOR

L.S. Winston

SHIPPING SUPERVISOR

L.S. Winston

RECEIVED FOR SHIPPING BY

Wright

DATE

8-30-71

TIME

RECEIVED BY

Wright

DATE

8-30-71

TIME

2300

AREA

200E

BLDG.

202A

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

88A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D4	8-31	2135	DB	72-A-1-88	9-31	4-12	LRO
B	D5				✓	✓	✓	✓
C	D6				✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE BUILDING DISPATCHER'S OFFICE AND NOT BE LOANED TO ANY OTHER OFFICE. IT SHALL BE RETURNED TO POINT OF ORIGIN.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2109

CAR NO.

37

BLDG.

105 KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	210 KE 695 KW	9 2 4 4				
B	2110 KE 694 KW	9 2 4 4				
C	2111 KE 693 KW	9 2 4 4				

METAL

DECLASSIFIED

CAR LOADED 8-31-71 1200

AND MUST BE UNLOADED BY 9-2-71 1200

CAR SHIPPED 9-1-71 1015

CAR TO BE DELIVERED TO Parex

LOADING SUPERVISOR

J. Wickstrom

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

9-1-71

TIME

1115

RECEIVED BY

J. Beck

DATE

9-1-71

TIME

1115

AREA

200 E

BLDG.

202 H

REMARKS:

DECLASSIFIED metal from KW Basin

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

90 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-7	9-1-71		WCP	A-3	9-3	4-12	LRD
B	D-8				-	✓	✓	✓
C	D-9		1400		✓	✓	✓	✓

DECLASSIFIED

THIS DOCUMENT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOU BY THE NATIONAL ARCHIVES. IT IS TO BE RETURNED TO THE NATIONAL ARCHIVES AT COLLEGE PARK, MARYLAND 20740.

ARH-2102 SEP 91

~~SECRET~~
AFTER TALL-IN

SS MATERIAL TRANSFER

LOAD NO.
2110CAR NO.
42BLDG.
105-KWAREA
KW

DECLASSIFIED

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	2114-KB																			
	692-KW	9	2	4	4	1	6	0	8	3	0	0	5	5	2	6	3	4	4894.50	
B	2113-KB																		12.73	
	691-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4	1419.67	
C	2112-KB																		#119	
	690-KW	9	2	4	4	1	6	1	0	3	0	0	5	5	1	6	3	4		

CAR LOADED

9-1-71

1000

DATE

TIME

AND MUST BE UNLOADED BY

9-3-71

1000

DATE

TIME

CAR SHIPPED

9-1-71

1015

DATE

TIME

CAR TO BE DELIVERED TO

BUILDING

Purex

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2110

CAR NO.
42

BLDG.
105-KW

AREA
KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2114-KW					
	692-KW	9 2 4 4				
B	2113-KW					
	692-KW	9 2 4 4				
C	2112-KW					
	690-KW	9 2 4 4				

DECLASSIFIED

KE-METAL

CAR LOADED 9-1-71 1000 AND MUST BE UNLOADED BY 9-3-71 1000
DATE TIME DATE TIME
CER SHIPPED 9-1-71 1115 CAR TO BE DELIVERED TO Purax
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS

DECLASSIFIED

KE METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

AREA
IN

BDDG
102-40

IS

22 MATERIAL TRANSFER

102-40

DECLASSIFIED

DECLASSIFIED

42 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-10	4-1		WED	A-3	9-5-74	12-12	260
B	D-11				✓	✓	✓	✓
C	D-12				✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED BY THE BUILDING DISPATCHER AND RETURNED TO THE POINT OF ORIGIN BY THE RECEIVER.

~~SECRET~~
~~AFTER ALL-IN~~

SS MATERIAL TRANSFER

LOAD NO.

2127

CAR NO.

44

BLDG.

ARF

DECLASSIFIED

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	930	92601535	1505	29225	1515310	4911.35	
B	931	92601523	1505	29225	1515310	11.64	
C	932	92601523	1505	29225	1515310	1321.16	#119

97 CAR LOADED 9-2-71 2115 AND MUST BE UNLOADED BY 9-4-71 2115
DATE TIME DATE TIME

CAR SHIPPED 9-3-71 0915 CAR TO BE DELIVERED TO Purey
DATE TIME BUILDING

LOADING SUPERVISOR

RECEIVED BY
SUPERVISOR
R. J. Beach
SHIPPING BY

SHIPPING SUPERVISOR

SHIPPING SUPERVISOR

J. Wickstrom

DATE	TIME

RECEIVED FOR SHIPPING BY

RECEIVED BY

DATE _____

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2127

CAR NO.

44

BLDG.

105RW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	930	9260				
B	931	9260				
C	932	9260				

DECLASSIFIED

CAR LOADED 9-2-71 2115 AND MUST BE UNLOADED BY 9-4-71 2115

CAR SHIPPED 9-3-71 0915 CAR TO BE DELIVERED TO Purex

LOADING SUPERVISOR

D. J. Back

SHIPPING SUPERVISOR

J. Wickham

RECEIVED FOR SHIPPING BY

[Signature]

DATE

9-1-71

TIME

RECEIVED BY

Wright

DATE

9-3-71

TIME

1000

AREA

200E

BLDG.

202A

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

102M 100-K

72 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

94 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	211	11-11-68			72-A-1-68	9-3-71	1000	PRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS DOCUMENT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOUR AGENCY. IT AND ITS CONTENTS ARE NOT TO BE DISTRIBUTED OUTSIDE YOUR AGENCY. IT IS TO BE RETURNED TO THE U.S. GOVERNMENT ON REQUEST.

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2128

CAR NO.

47

BLDG.

105-KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	927	9260	1568	1505	29225	225	4911.35
B	928	9260	1555	1505	29225	225	11.64
C	929	9260	1555	1505	29225	225	1321.16
							#119

DECLASSIFIED

CAR LOADED 9-2-71 2200 AND MUST BE UNLOADED BY 9-4-71 2200
DATE TIME DATE TIME

CAR SHIPPED 9-3-71 0915 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR

R. J. Roach

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED
H

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2188

CAR NO.

47

BLDG.

105KW

AREA

100-K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	927	9260				
B	928	9260				
C	929	9260				

METAL

DECLASSIFIED

CAR LOADED 9-2-71 2:00 AND MUST BE UNLOADED BY 9-4-71 2200

CAR SHIPPED 9-3-71 0915 CAR TO BE DELIVERED TO Purex

LOADING SUPERVISOR

R. J. Rogers

SHIPPING SUPERVISOR

Wichatrom

RECEIVED FOR SHIPPING BY

174

DATE

9-3-71

TIME

RECEIVED BY

Wright

DATE

9-3-71

TIME

1000

AREA

200E

BLDG.

202A

REMARKS

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DATE OF RECEIPT

SECRET
AFTER FULL-IN

SS MATERIAL TRANSFER

LOAD NO.

2129

CAR NO.

36

BLDG.

105KW

AREA

100K.

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	924	92601615	2705515559	30529	45		
B	925	92601583	150529225	505515310			
C	926	92601616	2605515559	40529	72		

DECLASSIFIED

94
CAR LOADED 9-2-71 2310
DATE TIME

AND MUST BE UNLOADED BY 9-4-71 2310
DATE TIME

CAR SHIPPED 9-3-71 0915
DATE TIME

CAR TO BE DELIVERED TO Purex
BUILDING

LOADING SUPERVISOR

R. J. Roach

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2102 SEP 78

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2129

CAR NO.

36

BLDG.

105KW

AREA

100K.

CELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MODE
A	924	9260				
B	925	9260				
C	926	9260				

CAR LOADED

9-2-71

2310

AND MUST BE UNLOADED BY

9-4-71

2310

CAR SHIPPED

9-3-71

0915

CAR TO BE DELIVERED TO

BUILDING

Puray

LOADING SUPERVISOR

P. J. Roach

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

J. Wickstrom

DATE

9-3-71

TIME

RECEIVED BY

Wright

DATE

9-3-71

TIME

1000

AREA

200E

BLDG.

202A

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

34-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

98A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A		11-4			72-A-1-48	9-3-71	1000	L.R.D.
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE BY RECORDS MANAGEMENT DIVISION OF THE NATIONAL ARCHIVES

SECRET AFTER FILL-IN		SS MATERIAL TRANSFER				LOAD NO.	CAR NO.	BLDG.	AREA
						2113	36	105KW	KW
WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	2108KE								
	397KW	9 2 4 4 1 6 0 8 3 0 0 5 5 1 6 3 4	4894.50						
B	2107KE								
	398KW	9 2 4 4 1 6 0 8 3 0 0 5 5 1 6 3 4	12.73 1419.67 #119						
C	2106KE								
	399KW	9 2 4 4 1 6 0 8 3 0 0 5 5 1 6 3 4	607						
CAR LOADED		9-1-71 1445		AND MUST BE UNLOADED BY		9-3-73 1445			
CAR SHIPPED		9-1-71 1515		CAR TO BE DELIVERED TO		Burex			
LOADING SUPERVISOR					SHIPPING SUPERVISOR				
J. Wickstrom					J. Wickstrom				
RECEIVED FOR SHIPPING BY					DATE		TIME		
RECEIVED BY					DATE		TIME		BLDG.
REMARKS:									
<p>DECLASSIFIED</p> <p>KE metal, KW Basin</p> <p>Ju # 3</p>									
<p>IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.</p>									

ARH-2102 SEP 7

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2113

CAR NO.

36

BLDG.

105KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	2108KE					
	397KW	9 2 4 4				
B	2107KE					
	398KW	9 2 4 4				
C	2106KE					
	399KW	9 2 4 4				

CAR LOADED

DATE

9-1-71

TIME

1445

AND MUST BE UNLOADED BY

DATE

9-3-73

TIME

1445

CAR SHIPPED

DATE

9-1-71

TIME

1515

CAR TO BE DELIVERED TO

BUILDING

Bureau

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

Wickstrom

DATE

9-1-71

TIME

1515

RECEIVED BY

R. A. Palk

DATE

9/1/71

TIME

1730

AREA

200E

BLDG

202-A

REMARKS:

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

100A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	C-7	9.2	0710	[Signature]	B-3	9-4-77	0530	[Signature]
B	C-8	/	/	/	B-3	/	/	/
C	C-9	/	/	/	B-3	/	/	/

DECLASSIFIED

CONFIDENTIAL

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE

SECRET AFTER FILL-IN		SS MATERIAL TRANSFER				LOAD NO. 2114		CAR NO. 38		BLDG. KW		AREA KW	
--------------------------------	--	-----------------------------	--	--	--	----------------------	--	-------------------	--	-----------------	--	----------------	--

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWD						
A	233LKE											
	402KW	92441610300551634					4894.50					
B	2101KE											
	401KW	92441610300551634					12.73 1419.67 #119					
C	2102KE											
	400KW	92441608300551634					402					

94
CAR LOADED 9-1-71 1505
DATE TIME

CAR SHIPPED 9-1-71 1515
DATE TIME

AND MUST BE UNLOADED BY 9-1-71 1515
DATE TIME

CAR TO BE DELIVERED TO Shurex
BUILDING

LOADING SUPERVISOR <i>J. Wickstrom</i>		SHIPPING SUPERVISOR <i>J. Wickstrom</i>	
RECEIVED FOR SHIPPING BY	DATE	TIME	
RECEIVED BY	DATE	TIME	AREA BLDG.

REMARKS:

KE metal KW Basin

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2114

CAR NO.

38

BLDG.

105KW

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	233LKE					
	402KW	9 2 4 4				
B	2101KE					
	401KW	9 2 4 4				
C	2102KE					
	400KW	9 2 4 4				

CAR LOADED

9-1-71

15 05

AND MUST BE UNLOADED BY

9-1-71

15 15

CAR SHIPPED

9-1-71

15 15

CAR TO BE DELIVERED TO

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

102A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	C-10	9-6-71	0910	CCF	B.3	9-9-71	0550	CCF
B	C-11	"	"	"	"	"	"	CCF
C	C-12	"	"	"	"	"	"	CCF

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED AT THE POINT OF ORIGIN AND SHOULD NOT BE REPRODUCED OR COPIED WITHOUT THE AUTHORITY OF THE ORIGINATING OFFICE.

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2131

CAR NO.

37

BLDG.

105

AREA

105

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS				
A	921									2	7	0	5	5	15	5	5	9				
		9	2	6	0	1	6	1	4	0	3	0	5	2	9	0	4	5	4911.35			
B	922									2	7	0	5	5	15	5	5	9				
		9	2	6	0	1	6	1	4	0	3	0	5	2	9	0	4	5	11.64	1321.16		
C	923									2	7	0	5	5	15	5	5	9				
		9	2	6	0	1	6	1	7	0	3	0	5	2	9	0	4	5	1817			

CAR LOADED 9-3-71 1000 AND MUST BE UNLOADED BY 9-6-71 1000
 DATE TIME DATE TIME
 CAR SHIPPED 9-3-71 1345 CAR TO BE DELIVERED TO Purex
 DATE TIME BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

AMH-2132 SEP 7 1971

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2131

CAR NO.

37

BLDG.

105

AREA

IV

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	921	9 2 6 0				
B	922	9 2 6 0				
C	923	9 2 6 0				

CAR LOADED 9-3-71 1000 AND MUST BE UNLOADED BY 9-6-71 1000
DATE TIME DATE TIME

CAR SHIPPED 9-3-71 1345 CAR TO BE DELIVERED TO Perex
DATE TIME BUILDING

LOADING SUPERVISOR

J. Wickstrom
RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE 9-3-71

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

104A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0001	72-13-1			72-13-1-69	9-4	0430	FE8
B					72-13-1-69	9-4	0430	FE8
C					72-13-1-69	9-4	0430	FE8

DECLASSIFIED

03/17/2013

105

ARH-2132 SEP

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.
2132

CAR NO.
46

SEDS.
105
AREA
KV

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	918									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	6	0	3	0	5	2	9	0	4	5			
B	919									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	6	0	3	0	5	2	9	0	4	5			
C	920									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	7	0	3	0	5	2	9	0	4	5			

DECLASSIFIED

SECRET

94
CAR LOADED 9-3-71 1100 AND MUST BE UNLOADED BY 9-6-71 1100
DATE TIME DATE TIME
CAR SHIPPED 9-3-71 1345 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR <i>J. Wickstrom</i>		SHIPPING SUPERVISOR <i>J. Wickstrom</i>	
RECEIVED FOR SHIPPING BY		DATE	TIME
RECEIVED BY		DATE	TIME
		AREA	BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARM-21C2 SEP 7

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2132

CAR NO.

46

BLDG.
105AREA
KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	928	9 2 6 0																		
B	929	9 2 6 0																		
C	920	9 2 6 0																		

CAR LOADED

9-3-71
DATE1100
TIME

AND MUST BE UNLOADED BY

9-6-71
DATE1100
TIME

CAR SHIPPED

9-3-71
DATE1345
TIME

CAR TO BE DELIVERED TO

BUILDING

Purax

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

RECEIVED BY

SHIPPING SUPERVISOR

DATE

DATE

TIME

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

106 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0011	7-1-			72-B-1-69	9-4	0430	828
B	0012				72-B-1-69	9-4	0430	828
C					72-B-1-69	9-4	0430	828

DECLASSIFIED

DECLASSIFIED

THIS UNLOADING RECORD IS TO BE RETURNED TO POINT OF ORIGIN
IF THE UNLOADING IS NOT COMPLETED BY THE RECEIVER
OR IF THE UNLOADING IS COMPLETED BY THE RECEIVER
BUT THE MATERIAL IS NOT RELOADED BY THE RECEIVER

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2133

CAR NO.

45

BLDG

AREA

KW

ARH-2102 S-P

107.

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS				
A	917									2	7	0	5	5	15	5	5	9				
		9	2	6	0	1	6	1	6	0	3	0	5	2	9	0	4	5	4911.35			
B	916									2	7	0	5	5	15	5	5	9	11.64			
		9	2	6	0	1	6	2	0	0	3	0	5	2	9	0	4	5	1321.16			
C	915									2	7	0	5	5	15	5	5	9	#19			
		9	2	6	0	1	6	2	0	0	3	0	5	2	9	0	4	5	1817			

94
CAR LOADED

9-3-71

DATE

1300

TIME

AND MUST BE UNLOADED BY

9-3-71

DATE

1300

TIME

CAR SHIPPED

9-3-71

DATE

1345

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

J. Wickstrom

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-21C2 SEP 1 1971

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2133

CAR NO.

45

BLDG.

105

AREA

EW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	927	9 2 6 0																		
B	926	9 2 6 0																		
C	925	9 2 6 0																		

CAR LOADED

9-3-71

DATE

1300

TIME

AND MUST BE UNLOADED BY

9-3-71

DATE

1300

TIME

CAR SHIPPED

9-3-71

DATE

1345

TIME

CAR TO BE DELIVERED TO

PAPER

BUILDING

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

108A

UNLOADING AND CHARGING RECORD								
WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	001	-			72-B-1-69	9-4	0430	LES
B					72-B-1-69	9-4	0430	LES
C					72-B-1-68	9-4	0430	LES

DECLASSIFIED

Don't know

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-01-2001 BY 60322 UCBAW

SECRET
- AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO. 2134

CAR NO. 42

BLDG. 105 AREA

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	912									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	2	2	0	3	0	5	2	9	0	4	5			
B	913									2	7	0	5	5	15	5	5	9			
		9	2	6	0	2	6	2	0	0	3	0	5	2	9	0	4	5			
C	914									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	2	0	0	3	0	5	2	9	0	4	5			

CAR LOADED 9-3-71 1345 AND MUST BE UNLOADED BY 906071 1345
 DATE TIME DATE TIME
 CAR SHIPPED 9-3-71 1345 CAR TO BE DELIVERED TO Purex
 DATE TIME BUILDING

LOADING SUPERVISOR <i>J. Wickstrom</i>	SHIPPING SUPERVISOR <i>J. Wickstrom</i>		
RECEIVED FOR SHIPPING BY	DATE	TIME	
RECEIVED BY	DATE	TIME	BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2134

CAR NO.
42

BLDG.
105

AREA
KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	912	9 2 6 0																		
B	913	9 2 6 0																		
C	914	9 2 6 0																		

CAR LOADED 9-3-71 1345 AND MUST BE UNLOADED BY 906071 1345
DATE TIME DATE TIME
CAR SHIPPED 9-3-71 1345 CAR TO BE DELIVERED TO Perex
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

110 A

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	101	72-11-1-64	9-4	2645	288			
B	102	72-11-1-64	9-4	0645	288			
C	103	72-11-1-64	9-4	0645	288			

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE RETURNED TO POINT OF ORIGIN

AREA
100 X

DECLASSIFIED

AREA	BLDG.
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

CP#3

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2142

CAR NO.

42

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	464	9 8 4 1					
		9 1 3 3					
		7 1 8					
B	665	9 1 3 3					
C	466	9 1 3 3					

DECLASSIFIED

 CAR LOADED 9/4/71 1515 AND MUST BE UNLOADED BY 9/6/71 1515
 DATE TIME DATE TIME

 CAR SHIPPED 9/4/71 1 CAR TO BE DELIVERED TO PUREX
 DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

 IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

112A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					A-3	9-5-71	0700	007
B					"	"	"	"
C					"	"	"	"

DECLASSIFIED

DECLASSIFIED

THIS FORM IS TO BE RETURNED TO POINT OF ORIGIN
AS CANNOT BE RECHARGED BY DATA
UNLESS ORIGINATOR PROVIDES FOR COOLING
AND RECHARGING MADE BY RECEIVER

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2140

CAR NO.

47

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	897	9	2	6	0	1	6	1	7	0	3	0	5	5	15	5	5	9	4	911.35	
																			1164		
B	896	9	2	6	0	1	6	1	6	0	3	0	5	5	15	5	5	9	1321.16		
																			#119		
C	895	9	2	6	0	1	6	1	6	0	3	0	5	5	15	5	5	9			

CAR LOADED

9/4/71
DATE1315
TIME

AND MUST BE UNLOADED BY

9/6/71
DATE1315
TIME

CAR SHIPPED

9/4/71
DATE1400
TIME

CAR TO BE DELIVERED TO

PUREX
BUILDING

LOADING SUPERVISOR

S. B. Winston

SHIPPING SUPERVISOR

S. B. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

94#3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2152 SEP

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2110

CAR NO.

47

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	097	9 2 6 0				
	096	9 2 6 0				
	095	9 2 6 0				

CAN LOADED

9/4/71

DATE

1315

TIME

AND MUST BE UNLOADED BY

9/6/71

DATE

1315

TIME

CAR SHIPPED

9/11/71

DATE

1400

TIME

CAR TO BE DELIVERED TO

PURA
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

9-4-71

TIME

RECEIVED BY

DATE

9-4-71

TIME

1430

AREA

200E

BLDG.

202A

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

114A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	10010	9-5-4	1800	2000	A-3	9-5-4	0930	001
B	✓	✓	✓	✓	A-3	✓	✓	001
C	✓	✓	✓	✓	A-3	✓	✓	001

DECLASSIFIED

DECLASSIFIED

THIS RECORD CANNOT BE UNLOADED BY DATE AND TIME SHOWN. IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR LOADING OF NEW RECORD.

ARH 112 SEP 7

~~SECRET~~
AFTER 11/1/71

SS MATERIAL TRANSFER

LOAD NO.
2113

CAR NO.
37

BLDG.
105

AREA
100 K

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	879																				
		9	2	6	0	1	5	2	0	1	5	0	5	2	9	2	2	5	4	9	
B	878																				
		9	2	6	0	1	5	2	0	1	5	0	5	2	9	2	2	5	11.64		
C	877																				
		9	2	6	0	1	5	2	0	1	5	0	5	2	9	2	2	5	11.35		

CAR LOADED 9/4/71 17:00 AND MUST BE UNLOADED BY 9/7/71 17:00
DATE TIME DATE TIME

CAR SHIPPED 9-4-71 19:00 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR <u>[Signature]</u>	SHIPPING SUPERVISOR <u>[Signature]</u>	
RECEIVED FOR SHIPPING BY	DATE	TIME
RECEIVED BY	DATE	TIME
	AREA	BLDG.

REMARKS: **KW METAL FROM KW BASIN**

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2113

CAR NO.

37

BLDG.

105 EN

AREA

100 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	879	9 8 4 1 9 2 6 0																		
B	878	5 8 9 2 6 0																		
C	877	9 2 6 0																		

CAR LOADED 9/4 9/4/71 17:00 AND MUST BE UNLOADED BY 9/7/71 17:00

CAR SHIPPED 9-4-71 17:00 CAR TO BE DELIVERED TO PERM BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

9-4-71

TIME

1830

RECEIVED BY

DATE

9/4/71

TIME

2000

AREA

200 E

BLDG.

202 A

REMARKS:

EN METAL FROM EN BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

116 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00:11	9-5-71	0600		A-3	9-5-71	0600	CCJ
B		9-5-71	0600		A-3	9-5-71	0600	CCJ
C	AREA	9-5-71	0600		A-3	9-5-71	0600	CCJ

DECLASSIFIED

THIS DOCUMENT IS UNCLASSIFIED BY DATE 03/11/2011 AND IS BEING RETURNED TO POINT OF ORIGIN
UNLESS OTHERWISE INDICATED BY THE RECEIVING OFFICE

~~SECRET~~
AFTER FILING

SS MATERIAL TRANSFER

LOAD NO.
2145CAR NO.
46BLDG.
105 KWAREA
300 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	DECLASSIFIED			
A	885	9 2 6 0	1 5 2 2	1 5 0 5	2 9 2 2	5				
B	884	9 2 6 0	1 5 2 2	1 5 0 5	2 9 2 2	5				
C	883	9 2 6 0	1 5 2 2	1 5 0 5	2 9 2 2	5				

94 CAR LOADED 9/4/71 19:00 AND MUST BE UNLOADED BY 9/6/71 19:00
DATE TIME DATE TIME

CAR SHIPPED 9-4-71 19:00 CAR TO BE DELIVERED TO PUREX BUILDING
DATE TIME

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS: KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARRH-2102 SEP 7 1971

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2145

CAR NO.
46

BLDG.
105 KW

BLDG.
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	805	9 2 6 0				
B	811	9 2 6 0				
C	808	9 2 6 0				

E-METAL

DECLASSIFIED

CAR LOADED 9/4/71 19:00 AND MUST BE UNLOADED BY 9/6/71 19:00
DATE TIME DATE TIME
CAR SHIPPED 9-4-71 19:00 CAR TO BE DELIVERED TO PIREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BLDG

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

118 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00:01	10/11			A-3	9-5201	0601	00-1
B					"	"	"	"
C					"	"	"	"

DECLASSIFIED

UNLOADING OR CHARGING RECORD FOR BUILDING DISPATCHER TO BE COMPLETED BY THE DISPATCHER AND RETURNED TO POINT OF ORIGIN

SECRET AFTER FILL-IN		SS MATERIAL TRANSFER										LOAD NO. 2146				CAR NO. 38				BLDG. 105		AREA 100 K	
WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWD					
A	892									2	7	0	5	5	5	15	5	5	9				
		9	2	6	0	1	6	1	6	3	0	5	2	9	4	5	4911.35						
B	893									2	7	0	5	5	5	15	5	5	9	11.64			
		9	2	6	0	1	6	1	6	3	0	5	2	9	4	5	1321.16						
C	894									2	7	0	5	5	5	15	5	5	9				
		9	2	6	0	1	6	1	6	3	0	5	2	9	4	5	#119						
CAR LOADED 94		DATE 9/4/71				TIME 21:00				AND MUST BE UNLOADED BY DATE 9/6/71 TIME 21:00													
CAR SHIPPED		DATE 9-4-71				TIME 22:30				CAR TO BE DELIVERED TO PUREX													
LOADING SUPERVISOR <i>[Signature]</i>										SHIPPING SUPERVISOR <i>[Signature]</i>													
RECEIVED FOR SHIPPING BY										DATE					TIME								
RECEIVED BY										DATE					TIME					AREA		BLDG.	
REMARKS: KW METAL FROM KW BASIN																							

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

SS MATERIAL TRANSFER

2146

38

105 EW

100 K

DECLASSIFIED

CAR LOADED

9/4/71
PAGE

21:00
TIME

AND MUST BE UNLOADED BY

9/6/71
DATE

21:00
TIME

CAN SHIPPED

DATE

TIME

CAR TO BE DELIVERED TO

PERIOD
BUILDING

~~LOADING SUPERVISOR~~

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE 11-7

RECEIVED BY

DATE _____

TIME

AREA

BLDG.

REMARKS:

KN METAL FROM KN BASH

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARRIVAL 9-5-70

22 MATERIAL TRANSFER

170A

DECLASSIFIED

DECLASSIFIED

170A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-A-1-70	9-5	0915	Feb
B					72-A-1-70	9-5	0915	Feb
C					72-A-1-70	9-5	0915	Feb

DECLASSIFIED

DECLASSIFIED

RECEIVED BY DATE AND TIME AND MUST BE RETURNED TO POINT OF ORIGIN

~~SECRET~~
AFTER FULL-IN

SS MATERIAL TRANSFER

LOAD NO.
2147CAR NO.
36BLDG.
105 KWAREA
100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	889									1	5	0	5	2	9	2	2	5			
		9	2	6	0	1	5	2	2	1	5	0	5	5	15	3	1	0			
B	890									1	5	0	5	2	9	2	2	5			
		9	2	6	0	1	5	2	1	1	5	0	5	5	15	3	1	0			
C	891									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	6	3	0	5	2	9		4	5				

DECLASSIFIED

CAR LOADED 9/4/71 22:15 AND MUST BE UNLOADED BY 9/6/71 22:15
DATE TIME DATE TIME

CAR SHIPPED 9/4/71 22:30 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 7 1971

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2147CAR NO.
36BLDG.
105 EWAREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	889	9 2 6 0				
B	890	9 2 6 0				
C	891	9 2 6 0				

CAR LOADED 9/4/71 22:15 AND MUST BE UNLOADED BY 9/6/71 22:15
DATE TIME DATE TIME

CAR SHIPPED 9/4/71 22:30 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR <i>[Signature]</i>		SHIPPING SUPERVISOR <i>[Signature]</i>		
RECEIVED FOR SHIPPING BY <i>M. G. Funderburg</i>		DATE 9-4-71	TIME 2220	
RECEIVED BY <i>Wright</i>		DATE 9-5-71	TIME 0900	AREA 280E
REMARKS: KW METAL FROM KW BASIN				BLDG. 202A

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

122A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A		11/1/70			72-A-1-70	9-5	0945	828
B					72-A-1-70	9-5	0945	828
C		11/1/70			72-A-1-70	9-5	0945	828

DECLASSIFIED

DECLASSIFIED

THIS FORM CANNOT BE UNLOADED BY DATE AND TIME WHEN IT MUST BE RETURNED TO POINT OF ORIGIN
UNLOADING OR PROVISION FOR CO. OR RE. MUST BE MADE BY RECEIVER

SECRET
AFTER DOWNGRADE

SS MATERIAL TRANSFER

LOADING NO.
2148

CAR NO.
44

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	661																				
		9	1	3	3	1	6	1	5	2	5	0	5	5	15	8	1	4	7	43.99	
B	662																				
		9	1	3	3	2	6	1	5	2	5	0	5	5	15	8	1	17.96	1699.49		
C	663																				
		9	1	3	3	1	6	1	5	2	5	0	5	5	15	8	1	#119			

CAR LOADED 9/4/71 23:00 AND MUST BE UNLOADED BY 9/6/71 23:00
DATE TIME DATE TIME

CAR SHIPPED 9/5/71 11:30 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

96#3

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARRH-2132 SEP 7 1971

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2148

CAR NO.
44

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	661	9 1 3 3				
B	662	9 1 3 3				
C	663	9 1 3 3				

CAR LOADED 9/4/71 23:00 AND MUST BE UNLOADED BY 9/6/71 23:00

CAR SHIPPED 9/5/71 11:30 CAR TO BE DELIVERED TO PUREX BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLOG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

1-5000-268 (4-66)

ACCOMPANY SHIPMENT

ARR-H-315 SEP

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

124 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00:25	10/10			72-13-1-71	9-5	1430	888
B					72-13-1-71	9-5	1430	888
C					72-13-1-71	9-5	1430	888

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE RETURNED TO POINT OF ORIGIN
AND NOT BE REPRODUCED OR COPIED BY ANY OTHER PARTY
WITHOUT THE WRITTEN PERMISSION OF THE ISSUING OFFICE

~~SECRET~~
AFTER DILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2141

CAR NO.

45

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES			FACTOR WT.			MWDS				
A	876									2	7	0	5	5	15	5	5	9		
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5	4911.35	
B	875									2	7	0	5	5	15	5	5	9	11.64	
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5	1321.16	
C	874									2	7	0	5	5	15	5	5	9	#119	
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5		

CAR LOADED

9/4/71

DATE

1400

TIME

AND MUST BE UNLOADED BY

9/6/71

DATE

1400

TIME

CAR SHIPPED

9/4/71

DATE

1400

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

D. S. Winston

SHIPPING SUPERVISOR

D. S. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2141

CAR NO.

45

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	876	9 2 6 0																		
B	875	9 2 6 0																		
C	874	9 2 6 0																		

CAR LOADED 9/4/71 1400 AND MUST BE UNLOADED BY 9/6/71 1400

CAR SHIPPED 9/4/71 1400 CAR TO BE DELIVERED TO POREX BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

126 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	100	12-1-71	11:55		72-B-1-26	9-5	11:55	828
B					72-B-1-71	9-5	12:55	828
C					72-B-1-71	9-5	12:55	828

DECLASSIFIED

DECLASSIFIED

THIS FORM IS TO BE RETURNED TO POINT OF ORIGIN
 IF NOT LOADED OR UNLOADED BY DATE
 AND NOT BY RECEIVER

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.
2144

CAR NO.
39

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	882	9 2 6 0	1 5 2 0	1 5 0 5 2 9	2 2 5				
B	881	9 2 6 0	1 5 2 3	1 5 0 5 5 15	3 1 0				
C	880	9 2 6 0	1 6 1 6	2 7 0 5 5 15	5 5 9				

DECLASSIFIED

CAR LOADED **94** **9/4/71** **18:00** AND MUST BE UNLOADED BY **9/6/71** **18:00**
DATE TIME DATE TIME

CAR SHIPPED **9-4-71** **19:00** CAR TO BE DELIVERED TO **PUREX**
DATE TIME BUILDING

LOADING SUPERVISOR *E. E. Jones*

SHIPPING SUPERVISOR *E. E. Jones*

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS: **KW METAL FROM KW BASIN**

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO. **214**

CAR NO. **39**

BLDG. **105 NW**

AREA **100 K**

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	802	9 2 6 0				
B	802	9 2 6 0				
C	800	9 2 6 0				

EW METAL

DECLASSIFIED

CAR LOADED **9/4/71** **18:00** AND MUST BE UNLOADED BY **9/6/71** **18:00**
DATE TIME DATE TIME

CAR SHIPPED **9-4-71** **19** CAR TO BE DELIVERED TO **PURKX**
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

EW METAL FROM KW 983TV

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

128A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00:85	7-1-71			72-B-1-71	9-5	12:05	888
B					72-B-1-71	9-5	12:55	888
C					72-B-1-71	9-5	12:55	888

DECLASSIFIED

DECLASSIFIED

NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM.

~~SECRET~~
AFTER DECLASSIFICATION

SS MATERIAL TRANSFER

LOAD NO.

2149

CAR NO.

47

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	886									1	5	0	5	2	9	2	2				
		9	2	6	0	1	5	2	3	1	5	0	5	5	15	3	1	0			
B	887									1	5	0	5	2	9	2	2	5			
		9	2	6	0	1	5	2	3	1	5	0	5	5	15	3	1	0			
C	888									1	5	0	5	2	9	2	2	5			
		9	2	6	0	1	5	2	4	1	5	0	5	5	15	3	1	0			

DECLASSIFIED

94
 CAR LOADED 9/5/71 0900 AND MUST BE UNLOADED BY 9/7/71 0900
 DATE TIME DATE TIME

CAR SHIPPED 9/7/71 1130 CAR TO BE DELIVERED TO PUREX
 DATE TIME BUILDING

LOADING SUPERVISOR

D. G. Winston

SHIPPING SUPERVISOR

D. G. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2149

CAR NO.

47

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	886	9 2 6 0				
B	887	9 2 6 0				
C	888	9 2 6 0				

CAR LOADED 9/5/71 0900 AND MUST BE UNLOADED BY 9/7/71 0900

CAR SHIPPED 9/7/71 1130 CAR TO BE DELIVERED TO PUREX BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED
DECLASSIFIED

22 MATERIAL TRANSFER

130 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-71		1430 0230	888
B					72-B-1-71		1430 0230	888
C					72-B-1-71		1430 0230	888

DECLASSIFIED

DECLASSIFIED

RECEIVED BY DATE AND TIME. IT MUST BE RETURNED TO POINT OF ORIGIN. NO CHARGES FOR COPIES OR FOR DELIVERY TO RECEIVER.

SECRET
AFTER TAIL-IN

SS MATERIAL TRANSFER

LOAD NO. **2151** CAR NO. **46** BLDG. **205** AREA **100 K**

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS							
A	1150																								
																				</					

4911.35
11.64
1321.16
#119

1812

CAR LOADED 9/5/71 1115 AND MUST BE UNLOADED BY 9/7/71 1115
DATE TIME DATE TIME
CAR SHIPPED 9/5/71 1130 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR <i>D. B. Winston</i>		SHIPPING SUPERVISOR <i>D. B. Winston</i>			
RECEIVED FOR SHIPPING BY		DATE	TIME		
RECEIVED BY		DATE	TIME	AREA	BLDG.

REMARKS:
DECLASSIFIED
KW Metal from KW basin

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2151

CAR NO.

46

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	1150	9 2 6 0																		
B	1151	9 2 6 0																		
C	1152	9 2 6 0																		

CAR LOADED 9/5/71 1115 AND MUST BE UNLOADED BY 9/7/71 1115
 DATE TIME DATE TIME
 CAR SHIPPED 9/7/71 1130 CAR TO BE DELIVERED TO PURIST
 DATE TIME BUILDING

LOADING SUPERVISOR <i>[Signature]</i>		SHIPPING SUPERVISOR <i>[Signature]</i>			
RECEIVED FOR SHIPPING BY <i>[Signature]</i>		DATE 9-5-71	TIME T		
RECEIVED BY <i>[Signature]</i>		DATE 9-5-71	TIME 1330	AREA 200E	BLDG. 201A

REMARKS:
 DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

22 MATERIAL TRANSFER

132A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-71	9-5	1525	888
B					72-B-1-71	9-5	1525	888
C					72-B-1-71	9-5	1525	888

DECLASSIFIED

DECLASSIFIED

THIS RECORD CANNOT BE UNLOADED BY DATE AND WHEN KNOWN IT BE RETURNED TO POINT OF ORIGIN
ON UNLOADING OR PROVISION FOR COPIES OF RECORDS TO BE MADE BY RECEIVER

SECRET
AFTER 1-1-71

SS MATERIAL TRANSFER

LOAD NO.

2150

CAR NO.

BLOG

AREA

100 x

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	1119																			
		9 2 6 0	1 6 1 8	2 7 0	5 5 15	5 5 9														
B	1118																			
		9 2 6 0	1 6 1 8	2 7 0	5 5 15	5 5 9														
C	1117																			
		9 2 6 0	1 4 5 8	2 2 0	5 2 9	3 3 0														

CAR LOADED 9/5/71 1030 AND MUST BE UNLOADED BY 9/7/71 1030
DATE TIME DATE TIME

CAR SHIPPED 9/5/71 1130 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

D. S. Winston

SHIPPING SUPERVISOR

D. S. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLOG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED		SS MATERIAL TRANSFER				LOAD NO. 2150		CAR NO. 42		BLDG. 205 KW		AREA 200 K	
WELL	STATION	KEY NO.				NET WT.		NO. PIECES		FACTOR WT.		MWDS	
A	1119	9	2	6	0								
B	1118	9	2	6	0								
C	1117	9	2	6	0								

DECLASSIFIED

EL-METAL

CAR LOADED 9/5/71 1030 AND MUST BE UNLOADED BY 9/7/71 1030
DATE TIME DATE TIME

CAR SHIPPED 9/7/71 1130 CAR TO BE DELIVERED TO PARC
DATE TIME BUILDING

LOADING SUPERVISOR S. S. Winston SHIPPING SUPERVISOR S. S. Winston

RECEIVED FOR SHIPPING BY Wright DATE 9-5-71 TIME 1330

RECEIVED BY Wright DATE 9-5-71 TIME 1330 AREA 200E BLDG. 202A

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

AREA 100 E
BLDG 100 E
100 E

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

134 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0001 2MU	9-5			72-13-1-71	9-5	1430 0230	228
B					72-13-1-71	9-5	1430 0230	228
C			15		72-13-1-71	9-5	1430 0230	228

DECLASSIFIED

THIS FORM IS TO BE USED BY THE RECEIVER TO RECORD THE UNLOADING AND CHARGING OF MATERIAL. IT MUST BE RETURNED TO POINT OF ORIGIN.

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2154

CAR NO.

36

BLDG.

105 KW

AREA

100 K

ARH-2132 SEP 7 1971 135

WELL	STATION	KEY NO.			NET WT.			NO. PIECES			FACTOR WT.			MWDS		
A	658	9	1	3	3	1	6	1	5	0	5	5	15	8	1	7
B	659	9	1	3	3	1	6	1	5	0	5	5	15	8	1	7
C	660	9	1	3	3	1	6	1	5	0	5	5	15	8	1	7

DECLASSIFIED

4744.00

17.76

1699.50

#119

844

CAR LOADED

9/5/71

17:00

DATE

TIME

AND MUST BE UNLOADED BY

9/7/71

17:00

DATE

TIME

CAR SHIPPED

9-5-71

18:00

DATE

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

4#3

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-68)

NUCLEAR MATERIALS

ARH-2132 SEP 7 1973

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2152

CAR NO.

36

BLDG.

105 NW

AREA

200 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	658	9 1 3 3				
B	659	9 1 3 3				
C	660	9 1 3 3				

DECLASSIFIED

E-METAL

CAR LOADED

9/5/71

DATE

17:00

TIME

AND MUST BE UNLOADED BY

9/7/71

DATE

17:00

TIME

CAR SHIPPED

9-5-71

DATE

18:00

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

NW METAL FROM NW BATTERY

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

136A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-7A	9-6	1750	RRR
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

~~SECRET~~
AFTER TALL-IN

SS MATERIAL TRANSFER

LOAD NO.

2152

CAR NO.

37

BLDG.

105 KW

AREA

100 K

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1122									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5			
B	1121									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5			
C	1120									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	7	0	3	0	5	2	9	0	4	5			

CAR LOADED 9/4 9/5/71 1400 AND MUST BE UNLOADED BY 9/7/71 1400
DATE TIME DATE TIME

CAR SHIPPED 9-5-71 1800 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

D. B. Winston

SHIPPING SUPERVISOR

E. E. Jones

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2152

CAR NO.

37

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1122	9 2 6 0				
B	1121	9 2 6 0				
C	1120	9 2 6 0				

CAR LOADED

9/5/71

1400

AND MUST BE UNLOADED BY

9/7/71

1400

CAR SHIPPED

DATE

TIME

CAR TO BE DELIVERED TO

PURCH

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0001	11-11-72	9:45		11-B-1-72	9-6	1750	LRD
B					✓			
C					✓			

DECLASSIFIED

UNCLASSIFIED OR PROVISION FOR THAT. IT CANNOT BE UNLOADED BY DATE. IT BE SHOWN THAT IT RETURNED TO POINT OF ORIGIN

~~SECRET~~
AFTER FALL-IN

SS MATERIAL TRANSFER

LOAD NO. 2153

CAR NO. 45

BLDG. 105 KW

AREA 100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						</
------	---------	---------	--	--	--	---------	--	--	--	------------	--	--	--	------------	--	--	--	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

CAR LOADED 9/5/71 1500 AND MUST BE UNLOADED BY 9/7/71 1500
DATE TIME DATE TIME

CAR SHIPPED 9-5-71 18:00 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR D. S. Winston

SHIPPING SUPERVISOR E. E. Jones

RECEIVED FOR SHIPPING BY

DATE TIME

RECEIVED BY

DATE TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-205 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2153

CAR NO.

45

ARH-3152 SEP 3 1971

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.				NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1147	9	2	6	0				
B	1148	9	2	6	0				
C	1149	9	2	6	0				

CAR LOADED

9/5/71

DATE

1500

TIME

AND MUST BE UNLOADED BY

9/7/71

DATE

1500

TIME

CAR SHIPPED

9-5-71

DATE

1500

TIME

CAR TO BE DELIVERED TO

PIL-EX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

9-5-71

TIME

1800

RECEIVED BY

DATE

9-5-71

TIME

1830

AREA

200E

BLDG.

202A

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

22 MATERIAL TRANSFER

140A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-72	9-6	1750	LRL
B					✓	✓	-	✓
C					✓	✓	6	✓

DECLASSIFIED

DECLASSIFIED

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE

SECRET
AFTER PHASIN

SS MATERIAL TRANSFER

LOAD NO.
2155

CAR NO.
38

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	1125			2 7 0 5 5 15					
		9 2 6 0 1 6 1 5		3 0 5 2 9		4 5			
B	1124			2 7 0 5 5 15		5 5 9			
		9 2 6 0 1 6 1 5		3 0 5 2 9		4 5			
C	1123			2 7 0 5 5 15		5 5 9			
		9 2 6 0 1 6 1 6		3 0 5 2 9		4 5			

DECLASSIFIED

SECRET

CAR LOADED 9/5/71 18⁰⁰ AND MUST BE UNLOADED BY 9/7/71 18⁰⁰

CAR SHIPPED 9/5/71 18⁰⁰ CAR TO BE DELIVERED TO Purex

LOADING SUPERVISOR E. C. Jones

SHIPPING SUPERVISOR E. C. Jones

RECEIVED FOR SHIPPING BY

DATE TIME

RECEIVED BY

DATE TIME AREA BLDG.

REMARKS: **KW METAL FROM KW BASIN**

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2155

CAR NO.

38

ARH-2132

BLDG:

105 EW

AREA:

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1125	9 2 6 0				
B	1124	9 2 6 0				
C	1123	9 2 6 0				

CAR LOADED

9/5/71

DATE

TIME

AND MUST BE UNLOADED BY

9/7/71

DATE

TIME

CAR SHIPPED

9/5/71

DATE

TIME

CAR TO BE DELIVERED TO

Purvis

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-68)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

142 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A		11-11-71			72-B-1-71	9-6	1844	LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF THE CHIEF OF THE BUREAU OF MINERAL INVESTIGATION AND RESEARCH, U.S. GEOLOGICAL SURVEY, WASHINGTON, D.C. 20508. IT IS TO BE KEPT IN THE OFFICE OF THE CHIEF OF THE BUREAU OF MINERAL INVESTIGATION AND RESEARCH, U.S. GEOLOGICAL SURVEY, WASHINGTON, D.C. 20508. IT IS TO BE KEPT IN THE OFFICE OF THE CHIEF OF THE BUREAU OF MINERAL INVESTIGATION AND RESEARCH, U.S. GEOLOGICAL SURVEY, WASHINGTON, D.C. 20508.

~~SECRET~~
AFTER ALL-IN

SS MATERIAL TRANSFER

LOAD NO.
2156

CAR NO.

39

BLDG.

105 KW

AREA

200 K

ARH-2162 SEP 1/4

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1128																				
		9	2	6	0	1	6	1	6	2	7	0	5	5	15	5	5	9			
B	1127																				
		9	2	6	0	1	6	1	6	2	7	0	5	5	15	5	5	9			
C	1126																				
		9	2	6	0	1	6	1	6	2	7	0	5	5	15	5	5	9			

CAR LOADED 9/5/71 19:00
DATE TIME

AND MUST BE UNLOADED BY 9/7/71 19:00
DATE TIME

CAR SHIPPED 9-5-71 22:45
DATE TIME

CAR TO BE DELIVERED TO PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2156

CAR NO.

39

BLDG.

105 KW

AREA

100 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1128	9 2 6 0				
B	1127	9 2 6 0				
C	1126	9 2 6 0				

CAR LOADED

9/5/71

DATE

19:00

TIME

AND MUST BE UNLOADED BY

9/7/71

DATE

19:00

TIME

CAR SHIPPED

9/5/71

DATE

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

M. G. F.

DATE

9-5-71

TIME

2245

RECEIVED BY

R.A. Palk

DATE

9/6/71

TIME

1800

AREA

200-E

BLDG.

202-A

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

144A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	1001	7/1/55			72-B-172	7-6-55		LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE MAINTAINED IN THE OFFICE OF THE RECEIVING OFFICE AND NOT BE UNLOADED BY DATE AND TIME OF RETIREMENT TO POINT OF ORIGIN

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.
2157

CAR NO.
46

BLDG.
105 KW

AREA
100 K

ARH-2132 SEP 14

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	1131	9 2 6 0 1 6 1	2 7 0 5 5 15	3 0 5 2 9	5 5	4 5	DECLASSIFIED
B	1130	9 2 6 0 1 6 1	2 7 0 5 5 15	3 0 5 2 9	5 5 9	4 5	4911.35 11.64 1321.16 #119
C	1129	9 2 6 0 1 6 1 4	2 7 0 5 5 15	3 0 5 2 9	5 5 9	4 5	1812

CAR LOADED 94 9/5/71 20:45 AND MUST BE UNLOADED BY 9/7/71 20:45
DATE TIME DATE TIME

CAR SHIPPED 9-5-71 22:45 CAR TO BE DELIVERED TO POREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2257

CAR NO.

46

ARH-2132 SEP 1971

BLDG.

105 KW

AREA

100 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1131	9 2 6 0				
B	1130	9 2 6 0				
C	1129	9 2 6 0				

CAR LOADED

94
9/5/71
DATE20:45
TIME

AND MUST BE UNLOADED BY

9/7/71
DATE20:45
TIME

CAR SHIPPED

9-5-71
DATE22:30
TIME

CAR TO BE DELIVERED TO

PULLEX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

9-5-71

TIME

2245

RECEIVED BY

DATE

9/6/71

TIME

1900

AREA

200-K

BLDG.

202-14

REMARKS:

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

ARM-2125 SEP

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

146A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	2455	9-6	1955	LRD	73-B-1-A	9-6	1955	LRD
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

THIS FORM IS TO BE USED FOR RECORDING THE UNLOADING AND CHARGING OF MATERIALS FROM THE DISSOLVER TO THE POOL. IT IS TO BE FILLED OUT BY THE OPERATOR AT THE TIME OF UNLOADING OR CHARGING. IT IS TO BE KEPT IN THE RECORD BOOK FOR THE DISSOLVER.

~~SECRET~~
AFTER FILING

SS MATERIAL TRANSFER

LOAD NO.

2160

CAR NO.

ARH-2132 SEP 1 1971

105 KW

100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	687	9	1	5	7	1	6	1	5	3	0	0	5	5	1	1	0	06			
B	686	9	1	5	7	1	6	1	5	3	0	0	5	5	1	1	0	06			
C	685	9	1	5	7	1	6	1	7	3	0	0	5	5	1	1	0	06			

DECLASSIFIED

CAR LOADED 9/6/71 0915 AND MUST BE UNLOADED BY 9/8/71 0915
DATE TIME DATE TIME

CAR SHIPPED 9-6-71 21:10 CAR TO BE DELIVERED TO POREX -
DATE TIME BUILDING

LOADING SUPERVISOR

J. B. Winston

SHIPPING SUPERVISOR

[Signature]

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO. 2160

CAR NO. 14

ARH-2132 SEP 7 1971

BLDG. 105 KW

AREA 100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	687	9 1 5 7				
B	686	9 1 5 7				
C	685	9 1 5 7				

CAR LOADED 9/6/71 0915
DATE TIMEAND MUST BE UNLOADED BY 9/8/71 0915
DATE TIMECAR SHIPPED 9-6-71 2110
DATE TIMECAR TO BE DELIVERED TO PERLEX
BUILDING

LOADING SUPERVISOR S. S. Winton	SHIPPING SUPERVISOR C. J. D.
RECEIVED FOR SHIPPING BY M. H. J.	DATE 9-6-71 TIME 2110
RECEIVED BY R. A. Salk	DATE 9/6/71 TIME 2245 AREA 100-E BLDG. 202-A

REMARKS:

DECLASSIFIED

FW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

J4-5000-265 (4-68)

ACCOMPANY SHIPMENT

APPROXIMATE 22 MATERIAL TRANSFER

22 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

148A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	0535	9-2-71			72-A-1-73	9-2-71	0550	1139
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS FORM CANNOT BE REPRODUCED BY DATA AND WILL BE RETURNED TO POINT OF ORIGIN
RECORDING OR PROVISION FOR RECORD AND WILL BE RETURNED TO THE CY REPAIR

SECRET
AFTER DECLASSIFICATION

SS MATERIAL TRANSFER

LOAD NO.

2138

CAR NO.

36

BLDG.

105 KW

AREA

100 K

ARH-2132 SEP 14 1971

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	900									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5			
B	899									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	0	3	0	5	2	9	0	4	5			
C	898									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	2	0	0	3	0	5	2	9	0	4	5			

CAR LOADED

9/4/71
DATE

1045
TIME

AND MUST BE UNLOADED BY

9/6/71
DATE

1045
TIME

CAR SHIPPED

9/4/71
DATE

1400
TIME

CAR TO BE DELIVERED TO

PUREX
BUILDING

LOADING SUPERVISOR

J. S. Winston

SHIPPING SUPERVISOR

J. S. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

JH #3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED	SS MATERIAL TRANSFER	LOAD NO. 2138	CAR NO. 36	BLDG. 105 KW	AREA 100 K
---------------------	-----------------------------	-------------------------	----------------------	------------------------	----------------------

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	900	9 2 6 0				
B	899	9 2 6 0				
C	898	9 2 6 0				

E-METAL

DECLASSIFIED

CAR LOADED	9/4/71	1015	AND MUST BE UNLOADED BY	9/6/71	1015
	DATE	TIME		DATE	TIME
CAR SHIPPED	9/4/71	1400	CAR TO BE DELIVERED TO	PIREX	
	DATE	TIME		BUILDING	

LOADING SUPERVISOR <i>G. B. Winston</i>	SHIPPING SUPERVISOR <i>G. B. Winston</i>	
RECEIVED FOR SHIPPING BY <i>L. M.</i>	DATE 9-4-71	TIME
RECEIVED BY <i>Wright</i>	DATE 9-4-71	TIME 1430
	AREA 200E	BLDG. 202A

REMARKS: *Wright*

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

DECLASSIFIED

150A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-4	9-4	1800	LRD	72-A-1-73	9-7-71	1830	JS
B	D-5	9-4	1800	✓	✓	✓	✓	✓
C	D-6	9-4	1800	✓	✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO. 2139

CAR NO. 44

BLDG. 105 KW

AREA 100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	871									2	7	0	5	5	15	5	5				
		9	2	6	0	1	6	1	6	0	3	0	5	2	9	0	4	5			
B	872									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	6	0	3	0	5	2	9	0	4	5			
C	873									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	4	0	3	0	5	2	9	0	4	5			

CAR LOADED 9/4/71 1130 AND MUST BE UNLOADED BY 9/6/71 1130
DATE TIME DATE TIME

CAR SHIPPED 9/4/71 1400 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR D. G. Winston

SHIPPING SUPERVISOR D. G. Winston

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2139

CAR NO.

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	871	9 2 6 0				
B	872	9 2 6 0				
C	873	9 2 6 0				

CAR LOADED

9/4/71
DATE1130
TIME

AND MUST BE UNLOADED BY

9/6/71
DATE1130
TIME

CAR SHIPPED

9/4/71
DATE1400
TIME

CAR TO BE DELIVERED TO

PER X
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW 100 L FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

20 MATERIAL TRANSFER

152A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-17	9-11-73	1800	LRD	72-A-1-73	9-11-73	1830	JF
B	D-8	✓	✓	✓	✓	✓	✓	✓
C	D-9	✓	✓	✓	✓	✓	✓	✓

DECLASSIFIED

NOT BE RETURNED TO POINT OF ORIGIN
 RECEIVED BY RECEIVER
 DATE

~~SECRET~~
AFTER FULL-IN

SS MATERIAL TRANSFER

LOAD NO.
2158

CAR NO.
42

BLDG.
105 KW

AREA
100 K

ARH-2132 SEP 2 1971

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	1134	9 2 6 0	1 6 1 6	2 7 0 5 5 5	5 5 5 5	4 5	4911.35
B	1133	9 2 6 0	1 6 1 6	2 7 0 5 5 5	5 5 5 5	4 5	1164
C	1132	9 2 6 0	1 6 1 8	2 7 0 5 5 5	5 5 5 5	4 5	1321.16

CAR LOADED 9/5/71 21:45
DATE TIME

AND MUST BE UNLOADED BY 9/7/71 21:45
DATE TIME

CAR SHIPPED 9-5-71 22:45
DATE TIME

CAR TO BE DELIVERED TO PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

NUCLEAR MATERIALS

ARH-2132 SEP 154

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2158CAR NO.
12BLDG.
105 KWAREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	1134	9 2 6 0																		
B	1133	9 2 6 0																		
C	1132	9 2 6 0																		

CAR LOADED 9/5/71 21:45 AND MUST BE UNLOADED BY 9/7/71 21:45
DATE TIME DATE TIME

CAR SHIPPED 9/5/71 21:45 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-60)

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

154 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-A-1-73	9-7-71	0550	1139
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS FORM CANNOT BE REPRODUCED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF THE U.S. GOVERNMENT. IT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOUR AGENCY. IT AND ITS CONTENTS ARE TO BE RETURNED TO THE U.S. GOVERNMENT AT THE END OF THE LOAN PERIOD.

~~SECRET~~
AFTER, L-IN

SS MATERIAL TRANSFER

LOAD NO.
2159

CAR NO.
47

BLDG.
105 KW

AREA
100 K

ARH-2132 SEP 7 155

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1137									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	3	0	5	2	9				4	5		
B	1136									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	5	3	0	5	2	9				4	5		
C	1135									2	7	0	5	5	15	5	5	9			
		9	2	6	0	1	6	1	6	3	0	5	2	9				4	5		

DECLASSIFIED

EW-METAL

4911.35
11.64
1321.16
#119
1812

CAR LOADED 94 9/5/71 22:30 AND MUST BE UNLOADED BY 9/7/71 22:30
DATE TIME DATE TIME
CAR SHIPPED 9-571 22:45 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR [Signature]

SHIPPING SUPERVISOR [Signature]

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

4-5000-265 (4-66)

NUCLEAR MATERIALS

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2159

CAR NO.
47

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS														
A	1137	9 2 6 0																		
B	1136	9 2 6 0																		
C	1135	9 2 6 0																		

CAR LOADED 9/5/71 22:30 AND MUST BE UNLOADED BY 9/7/71 22:30
DATE TIME DATE TIME

CAR SHIPPED 9/5/71 CAR TO BE DELIVERED TO PURIX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY M. P. H.

DATE

TIME

9-5-71

22:45

RECEIVED BY R. A. Palk

DATE

TIME

9/6/71

1900

AREA

BLDG.

200-K

202-H

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

AREA 2 100 2
BDDG 102 24

72

72 MATERIAL TRANSFER

DECLASSIFIED

DECLASSIFIED

156 A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	06:30	7-7-71			72-A-1-73	7-7-71	06:50	J. S.
B								
C								

DECLASSIFIED

DECLASSIFIED

THIS DOCUMENT IS UNCLASSIFIED BY DATE 11/11/01 AND IS BEING RETURNED TO POINT OF ORIGIN

~~SECRET~~
AFTER PROCESSING

SS MATERIAL TRANSFER

LOAD NO.
2161CAR NO.
38BLDG.
105 KWAREA
100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1144	9	2	6	0	1	6	1	4	2	7	0	5	5	15	5	5	9			
B	1145	9	2	6	0	1	6	1	4	2	7	0	5	5	15	5	5	9			
C	1146	9	2	6	0	1	6	1	4	2	7	0	5	5	15	5	5	9			

DECLASSIFIED

4911.35

11.64

1321.16

#119

1812

CAR LOADED 9/6/71 20:30
DATE TIMEAND MUST BE UNLOADED BY 9/8/75 20:30
DATE TIMECAR SHIPPED 9-6-71 21:10
DATE TIMECAR TO BE DELIVERED TO PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS: KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED	SS MATERIAL TRANSFER	LOAD NO. 2161	CAR NO. 38	BLDG. 105 KW	AREA 100 K
---------------------	----------------------	------------------	---------------	-----------------	---------------

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1314	9 2 6 0				
B	1315	9 2 6 0				
C	1316	9 2 6 0				

E-METAL

DECLASSIFIED

CAR LOADED	9/6/71	20:30	AND MUST BE UNLOADED BY	9/8/71	20:30
	DATE	TIME		DATE	TIME
CAR SHIPPED	9/6/71	21:00	CAR TO BE DELIVERED TO	PULIX	
	DATE	TIME		BUILDING	

LOADING SUPERVISOR <i>[Signature]</i>	SHIPPING SUPERVISOR <i>[Signature]</i>		
RECEIVED FOR SHIPPING BY <i>M. H. F.</i>	DATE 9/6/71	TIME 2110	
RECEIVED BY <i>R. A. Falk</i>	DATE 9/6/71	TIME 2245	AREA 200-E
			BLDG. 202 H

REMARKS: KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

22 MATERIAL TRANSFER

158A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	50:33	7-1-73	11:55		72-A-1-73	9-7-71	05:50	
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THE CAR CANNOT BE RELOADED BY THE CAR DRIVER. IT MUST BE RETURNED TO POINT OF ORIGIN FOR RELOADING OR PROVISION FOR RELOADING MUST BE MADE BY RECEIVER.

SECRET
AFTER 10/1/71

SS MATERIAL TRANSFER

LOAD NO.

2165

CAR NO.

39

BLDG.

105 KW

AREA

100 K

DECLASSIFIED

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	1047	9 1 0 9 1 6 1 6	3 0 0 5 5 3 6 0 0	4865.02			
B	1046	9 1 0 9 1 6 1 5	3 0 0 5 5 15 6 0 0	12.10 1348.66 #119			
C	1045	9 1 0 9 1 6 1 5	3 0 0 5 5 15 6 0 0				

CAR LOADED 9/7/71 0930 AND MUST BE UNLOADED BY 9/9/71 0930
DATE TIME DATE TIME

CAR SHIPPED 9-7-71 2115 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR J. S. Winston

SHIPPING SUPERVISOR [Signature]

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

J. S. Winston #3

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ACCOMPANY SHIPMENT

DECLASSIFIED

DECLASSIFIED

160A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-74	9-8-71	0230	gg
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

SECRET
AFTER FILL IN

SS MATERIAL TRANSFER

LOAD NO.

2166

CAR NO.

46

BLDG.

105 KW

AREA

100 K

ARM-2102 SEP 16/

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDT				
A	1080	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5	9	9	4865.02			
B	1079	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5	9	9	12.10			
																			1348.66			
																			#119			
C	1078	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5	9	9				

CAR LOADED

9/7/71

DATE

1015

TIME

AND MUST BE UNLOADED BY

9/9/71

DATE

1015

TIME

CAR SHIPPED

9-7-71

DATE

21:15

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

L.B. Winston

SHIPPING SUPERVISOR

[Signature]

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2166

CAR NO.

46

BLDG.

105 NW

AREA

100 K

ARH-2132 SEP

102

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1080	9 1 0 9				
B	1079	9 1 0 9				
C	1078	9 1 0 9				

CAR LOADED

9/7/71

DATE

1015

TIME

AND MUST BE UNLOADED BY

9/9/71

DATE

1015

TIME

CAR SHIPPED

9-7-71

DATE

2115

TIME

CAR TO BE DELIVERED TO

PILIX

BUILDING

LOADING SUPERVISOR

E. S. Winston

SHIPPING SUPERVISOR

[Signature]

RECEIVED FOR SHIPPING BY

M. G. F.

DATE

9-7-71

TIME

2130

RECEIVED BY

R. A. Paek

DATE

9/7/71

TIME

2220

AREA

200-C

BLDG.

202-A

REMARKS:

DECLASSIFIED

KW TOTAL FROM KW SIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54 5000-265 (4-66)

ACCOMPANY SHIPMENT

100

ARRH-0135 SEP

22 MATERIAL TRANSFER

DECLASSIFIED

162A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-14	9-8-71	0230	33
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS FORM IS TO BE USED FOR THE RECORDING OF THE UNLOADING AND CHARGING OF MATERIAL FROM THE DISSOLVER TO THE POOL. IT IS TO BE FILLED OUT BY THE OPERATOR AT THE TIME OF THE OPERATION. IT IS TO BE RETURNED TO THE POINT OF ORIGIN BY THE OPERATOR AT THE END OF THE OPERATION. IT IS TO BE KEPT FOR RECORD BY THE RECEIVER.

PM

SECRET
AFTER DOWNGRADING

SS MATERIAL TRANSFER

LOAD NO.
2168

CAR NO.
38

BLDG.
105 KW

AREA
100 K

DECLASSIFIED

STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1050	9 1 0 9 1 6 1 6	3 0 0 5 5 15 6	0 0	4845.02 12.10. 1348.66 #119
B	1049	9 1 0 9 1 6 1 6	3 0 0 5 5 15 6	0 0	
C	1048	9 1 0 9 1 6 1 6	3 0 0 5 5 15 6	0 0	

CAR LOADED 94 9/7/71 19:30 AND MUST BE UNLOADED BY 9/9/71 19:30
DATE TIME DATE TIME

CAR SHIPPED 9-7-71 21:15 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR E. C. Jones

SHIPPING SUPERVISOR E. C. Jones

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS: **KW METAL FROM KW BASIN**

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2160CAR NO.
38

ARH-2132 SEP 7 1971

BLDG.
105 KWAREA
200 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACT OR WT.	MWDS
A	1050	9 1 0 9				
B	1049	9 1 0 9				
C	1048	9 1 0 9				

CAR LOADED 9/7/71 19:30 AND MUST BE UNLOADED BY 9/9/71 19:30
DATE TIME DATE TIMECAR SHIPPED 9-7-71 21:15 CAR TO BE DELIVERED TO PULHEX
DATE TIME BUILDING

LOADING SUPERVISOR <i>[Signature]</i>	SHIPPING SUPERVISOR <i>[Signature]</i>
RECEIVED FOR SHIPPING BY <i>[Signature]</i>	DATE <u>9-7-71</u> TIME <u>2120</u>
RECEIVED BY <i>R.A. Pack</i>	DATE <u>9/7/71</u> TIME <u>2230</u> AREA <u>200-L</u> BLDG. <u>202-A</u>
REMARKS: KW METAL FROM KW BLDG	

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

DECLASSIFIED

22 MATERIAL TRANSFER

164A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-74	9-8-71	0325	3.
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS FORM IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM.

~~SECRET~~
AFTER DECLASSIFICATION

SS MATERIAL TRANSFER

LOAD NO.

2169

CAR NO.

42

BLDG.

105 KW

AREA

100 K

ARH-2132 SEP 1971

165

DECLASSIFIED

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				WGT.			
A	1053	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5	9	9	4865.02		
B	1052	9	1	0	9	1	6	2	2	0	0	5	2	2	5	9	9	12.10 1348.66 #119			
C	1051	9	1	0	9	1	6	1	8	3	0	0	5	5	15	6	0	0	0		

CAR LOADED

9/7/71
DATE

22:00
TIME

AND MUST BE UNLOADED BY

9/9/71
DATE

22:00
TIME

CAR SHIPPED

9/8/71
DATE

0845
TIME

CAR TO BE DELIVERED TO

PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

NUCLEAR MATERIALS

ARH-2132 SEP 7 1966

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2169

CAR NO.

12

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1053	9 1 0 9				
B	1052	9 1 0 9				
C	1051	9 1 0 9				

CAR LOADED

9/7/71
DATE22:00
TIME

AND MUST BE UNLOADED BY

9/9/71
DATE22:00
TIME

CAR SHIPPED

9/8/71
DATE22:45
TIME

CAR TO BE DELIVERED TO

PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

SA-5000-265 (4-65)

ACCOMPANY SHIPMENT

ARR-1102 SP

AREA

BLOG

FOR

100

MATERIAL TRANSFER

A991

DECLASSIFIED

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	00155	8-8-71	8-4		72-B-1-74	9-8-71	8-4	QMS
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

THIS CHARGE IS TO BE RECORDED BY DATE AND TIME SHOWING THE POINT OF ORIGIN
 AND THE CHARGE IS TO BE RECORDED BY DATE AND TIME SHOWING THE POINT OF ORIGIN

~~SECRET~~
AFTER TELL-IN

SS MATERIAL TRANSFER

LOAD NO.
2167

CAR NO.
47

ARH-2132 SEP 167

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS			
A	654	9 1 5 7 1 6 1 8 3 0 0 5 5 1 1 00 6							
B	653	9 1 5 7 1 6 1 7 3 0 0 5 5 1 1 00 6							
C	652	9 1 5 7 1 6 1 6 3 0 0 5 5 1 1 00 6							

DECLASSIFIED

CAR LOADED 94 9/7/71 17:45 AND MUST BE UNLOADED BY 9/9/71 17:45
DATE TIME DATE TIME

CAR SHIPPED 9-7-71 21:15 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR [Signature]

SHIPPING SUPERVISOR [Signature]

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

210

CAR NO.

47

ARH-2132 SEP 7 1971

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTORY WT.	MWDS
A	654	9 1 5 7				
B	653	9 1 5 7				
C	652	9 1 5 7				

CAR LOADED

9/7/71

DATE

17:45

TIME

AND MUST BE UNLOADED BY

9/9/71

DATE

17:45

TIME

CAR SHIPPED

9-9-71

DATE

21:15

TIME

CAR TO BE DELIVERED TO

PULLEX

BUILDING

LOADING SUPERVISOR <i>[Signature]</i>		SHIPPING SUPERVISOR <i>[Signature]</i>		
RECEIVED FOR SHIPPING BY		DATE	TIME	
<i>M. E. F.</i>		<i>9/7/71</i>	<i>2120</i>	
RECEIVED BY	DATE	TIME	AREA	BLDG.
<i>R. A. Palk</i>	<i>8/2/71</i>	<i>2230</i>	<i>200-L</i>	<i>202-A</i>
REMARKS: KW METAL FROM KW BASTN				

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

84-5000-265 (4-6-71)

ACCOMPANY SHIPMENT

~~SECRET~~
AFTER TAIL-IN

SS MATERIAL TRANSFER

LOAD NO.

2170

CAR NO.

44

ARH-2132 SEP 169

BLDG.

105 KW

AREA

100 K

DECLASSIFIED

E-METAL

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS		
A	655	9	1	5	7	1	6	1	7	3	0	0	5	5	2	1	00	6	4946.21	
B	656	9	1	5	7	1	6	1	8	3	0	0	5	5	1	1	00	6	22.15	
																			2069.73	
C	657	9	1	5	7	1	6	1	6	3	0	0	5	5	1	1	00	6	#119	

CAR LOADED

9/7/71

DATE

TIME

AND MUST BE UNLOADED BY

9/9/71

DATE

TIME

CAR SHIPPED

9/8/71

DATE

0945

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2170

CAR NO.

44

ARR 2132 SEP

170

BLDG.

105 KW

AREA

100 E

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	655	9 1 5 7				
B	656	9 1 5 7				
C	657	9 1 5 7				

CAR LOADED

9/1/71

DATE

TIME

AND MUST BE UNLOADED BY

9/9/71

DATE

TIME

CAR SHIPPED

9/1/71

DATE

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPMENT BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

FORM 100-101A

STATION 2

1707

DECLASSIFIED

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					72-B-1-74	9-8-71	8-4	ACS
B					✓	✓	✓	✓
C					✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

REPRODUCTION OF THIS DOCUMENT IS PROHIBITED WITHOUT THE WRITTEN PERMISSION OF THE NATIONAL ARCHIVES

~~SECRET.~~
AFTER FULL-IN

SS MATERIAL TRANSFER

LOAD NO.
2162

CAR NO.
36

ARH-2132 SEP 77

BLDG.
105 KW

AREA
100 K

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1140																				
		9	2	6	0	1	6	2	0	2	7	0	5	5	15	5	5	9			
B	1139																				
		9	2	6	0	1	6	1	6	2	7	0	5	5	15	5	5	9			
C	1138																				
		9	2	6	0	1	6	1	6	2	7	0	5	5	15	5	5	9			

DECLASSIFIED

CAR LOADED 9/6/71 21:00
DATE TIME

AND MUST BE UNLOADED BY 9/8/71 21:00
DATE TIME

CAR SHIPPED 9/6/71 23:00
DATE TIME

CAR TO BE DELIVERED TO PUREX
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

Je #3

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2132 SEP 71

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2162CAR NO.
36BLDG.
105 KWAREA
100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1140	9 2 6 0				
B	1139	9 2 6 0				
C	1138	9 2 6 0				

DECLASSIFIED

CAR LOADED 9/6/71 21:00 AND MUST BE UNLOADED BY 9/8/71 21:00
DATE TIME DATE TIME

CAR SHIPPED 9/6/71 23:00 CAR TO BE DELIVERED TO PURKX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

KW METAL FROM KW BASIN

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN
 FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

7-12-71
22 MATERIALS
172A

DECLASSIFIED

172A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-10	9-9-71	1800	YAD	92A-1-7	9-8	2315	YAD
B	D-11	✓	✓	✓	✓	✓	✓	✓
C	D-12	✓	✓	✓	✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

~~SECRET~~
AFTER TELL-IN

SS MATERIAL TRANSFER

LOAD NO.

2171

CAR NO.

37

BLDG.

105 KW

AREA

100 K

ARH-2132 S-P 17

WELL	STATION	KEY NO.				NET WT.				NO. PIECES				FACTOR WT.				MWDS			
A	1056	9	1	0	9	1	5	2	7	3	0	0	5	2	2	5	9	9			
B	1055	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5	9	9			
C	1054	9	1	0	9	1	5	2	4	3	0	0	5	2	2	5	9	9			

CAR LOADED

9/8/71

DATE

0915

TIME

AND MUST BE UNLOADED BY

9/10/71

DATE

0915

TIME

CAR SHIPPED

9-8-71

DATE

1800

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

D. S. Winston

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2171

CAR NO.

37

ARH-2132 SEP

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1056	9 1 0 9				
B	1055	9 1 0 9				
C	1054	9 1 0 9				

CAR LOADED

9/8/71

DATE

0915

TIME

AND MUST BE UNLOADED BY

9/10/71

DATE

0915

TIME

CAR SHIPPED

9-8-71

DATE

1900

TIME

CAR TO BE DELIVERED TO

PITIX

BUILDING

LOADING SUPERVISOR

L. S. Winston

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

R. H. H.

DATE

9/8/71

TIME

1200

RECEIVED BY

H. Harford

DATE

9/8/71

TIME

1900

AREA

200 E

BLDG.

202A

REMARKS:

DECLASSIFIED

FOR TOTAL FROM KW BASIN

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

84-5000-265 (4-66)

ACCOMPANY SHIPMENT

PPT.

22 MATERIAL TRANSFER

174A

DECLASSIFIED

DECLASSIFIED

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					22A1-73	8.8	7.30	
B								
C								

DECLASSIFIED

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2172

CAR NO.

36

ARH-2132 SEP 17 75

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.			NET WT.			NO. PIECES			FACTOR WT.			MWDS		
A	1077	9	1	0	9	1	5	2	4	0	0	5	2	2	5	9
		9	1	0	9	1	5	2	4	0	0	5	2	2	5	9
B	1076	9	1	0	9	1	5	2	4	0	0	5	2	2	5	9
		9	1	0	9	1	5	2	4	0	0	5	2	2	5	9
C	1075	9	1	0	9	1	5	2	5	3	0	0	5	2	2	5
		9	1	0	9	1	5	2	5	3	0	0	5	2	2	5

CAR LOADED

9/8/71

DATE

1000

TIME

AND MUST BE UNLOADED BY

9/10/71

DATE

1000

TIME

CAR SHIPPED

9-8-71

DATE

1800

TIME

CAR TO BE DELIVERED TO

PUREX

BUILDING

LOADING SUPERVISOR

D. B. Winston

SHIPPING SUPERVISOR

J. Wickstrom

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KW METAL FROM KW BASIN

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2172

CAR NO.

36

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1077	9 1 0 9				
B	1076	9 1 0 9				
C	1075	9 1 0 9				

CAR LOADED 9/8/71 1000
DATE

AND MUST BE UNLOADED BY 9/10/71 1000
DATE TIME

CAR SHIPPED 9-8-77 1800
DATE TIME

CAR TO BE DELIVERED TO **PLEX**
BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE _____

TIME

RECEIVED BY

DATE _____

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

KN 4741 FROM KN 4637

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

1764

DECLASSIFIED

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A					47A-1-72	9-8	2:30	
B								
C								

DECLASSIFIED

DECLASSIFIED

THIS RECORD IS TO BE RETURNED TO POINT OF ORIGIN
 IF NOT REQUIRED FOR RECORDS BY RECEIVER

~~SECRET~~
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2174

CAR NO.

38

ARH-2132 SUP

BLDG.

105

AREA

KW

DECLASSIFIED

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS	
A	1057	9 1 0 9	1 5 2 6	1 0 0 5 5 15	0 0 5 2 2 5	9 9	4865.02
B	1058	9 1 0 9	1 5 2 2	0 0 5 2 2 5	9 9		12.10 1348.66 #119
C	1059	9 1 0 9	1 5 2 4	3 0 0 5 2 2 5	9 9		1491

CAR LOADED

9-8-71

1800

DATE

TIME

AND MUST BE UNLOADED BY

9-10-71

1800

DATE

TIME

CAR SHIPPED

9-8-71

1800

DATE

TIME

CAR TO BE DELIVERED TO

Purex

BUILDING

LOADING SUPERVISOR

RECEIVED FOR SHIPPING BY

SHIPPING SUPERVISOR

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2174

CAR NO.

38

BLDG.

105

AREA

KW

ARH-2132 SEP 7 1971

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	1057	9 1 0 9				
B	1058	9 1 0 9				
C	1059	9 1 0 9				

CAR LOADED

9-8-71

1800

DATE

TIME

AND MUST BE UNLOADED BY

9-10-71

1800

DATE

TIME

CAR SHIPPED

9-8-71

1500

DATE

TIME

CAR TO BE DELIVERED TO

Purcell

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

TIME

RECEIVED BY

DATE

TIME

AREA

BLDG.

REMARKS:

DECLASSIFIED

IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-65)

ACCOMPANY SHIPMENT

DECLASSIFIED
DECLASSIFIED

22 MATERIAL TRANSFER

198A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	1001	11-11-75			72A1-75	9-8	2130	PA
B					/	/	/	/
C					/	/	/	/

DECLASSIFIED

THIS DOCUMENT IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE BY THE FOLLOWING INFORMATION

~~SECRET~~
AFTER TELL-IN

SS MATERIAL TRANSFER

LOAD NO.
2164

CAR NO.
45

BLDG.
105 KW

AREA
100 K

ARH-2132 SEP 179

DECLASSIFIED

E-METAL

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS													
A	649	9 1 5 7 1 6 1 2 3 0 0 5 5 1 1 00 6																	
B	650	9 1 5 7 1 6 1 3 0 0 5 5 1 1 00 6																	
C	651	9 1 5 7 1 6 1 6 3 0 0 5 5 1 1 00 6																	

CAR LOADED 94 9/6/71 22:45 AND MUST BE UNLOADED BY 9/8/71 22:45
DATE TIME DATE TIME

CAR SHIPPED 9-6-71 23:00 CAR TO BE DELIVERED TO PUREX
DATE TIME BUILDING

LOADING SUPERVISOR <i>[Signature]</i>	SHIPPING SUPERVISOR <i>[Signature]</i>
RECEIVED FOR SHIPPING BY	DATE TIME
RECEIVED BY	DATE TIME AREA BLDG.

REMARKS: **KW METAL FROM KW BASIN**

Casks in A and B wells need Lid tightening bolt lubricated, very difficult to move.

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.

2164

CAR NO.

15

ARH-2132 S-P 180

BLDG.

105 KW

AREA

100 K

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	60	9 1 5 7				
B	650	9 1 5 7				
C	651	9 1 5 7				

CAR LOADED

9/6/71

DATE

22:15

TIME

AND MUST BE UNLOADED BY

9/8/71

DATE

22:15

TIME

CAR SHIPPED

9-6-71

DATE

23:00

TIME

CAR TO BE DELIVERED TO

PUEX

BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY

DATE

9-6-71

TIME

2100

RECEIVED BY

DATE

9-7-71

TIME

1400

AREA

200E

BLDG.

202A

REMARKS:

EN METAL FROM EN BAST

Casks in A and B wells need lid tightening bolt lubricated, very difficult to move.

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-265 (4-66)

ACCOMPANY SHIPMENT

DECLASSIFIED

180A

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	D-7	9-7-71	1800	LRA	22A-1-7	9-8	231	[Signature]
B	D-8	✓	✓	✓	✓	✓	✓	✓
C	D-9	✓	✓	✓	✓	✓	✓	✓

DECLASSIFIED

DECLASSIFIED

SECRET
AFTER FILL-IN

SS MATERIAL TRANSFER

LOAD NO.

2173

CAR NO.

BLDG.

05

AREA

KW

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	WTS														
A	577	9 1 5 7 1 6 1 6	3 0 0 5 5 2	1 0 07	4 946.21															
B	689	9 1 5 7 1 6 1 6	3 0 0 5 5 1	1 0 06	22.15															
C	688	9 1 5 7 1 6 1 6	3 0 0 5 5 1	1 0 06	2069.73															

94
CAR LOADED 9-8-71 1800 AND MUST BE UNLOADED BY 9-8-71 1800
DATE TIME DATE TIME
CAR SHIPPED 9-8-71 1800 CAR TO BE DELIVERED TO Purex
DATE TIME BUILDING

LOADING SUPERVISOR <i>J. Wickstrom</i>		SHIPPING SUPERVISOR <i>J. Wickstrom</i>			
RECEIVED FOR SHIPPING BY		DATE	TIME		
RECEIVED BY		DATE	TIME	AREA	BLDG.

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

ARH-2432 SEP 7 82

UNCLASSIFIED

SS MATERIAL TRANSFER

LOAD NO.
2173

CAR NO.
47

BLDG.
105

AREA
IV

WELL	STATION	KEY NO.	NET WT.	NO. PIECES	FACTOR WT.	MWDS
A	577 ✓	9 1 5 7				
B	689 ✓	9 1 5 7				
C	688 ✓	9 1 5 7				

E-METAL

DECLASSIFIED

CAR LOADED 94 9-8-71 1800 AND MUST BE UNLOADED BY 9-8-71 1800
DATE TIME DATE TIME

CAR SHIPPED 7-57 1800 CAR TO BE DELIVERED TO INDEX
DATE TIME BUILDING

LOADING SUPERVISOR

SHIPPING SUPERVISOR

RECEIVED FOR SHIPPING BY *[Signature]*

DATE 9/8/71 TIME 1800

RECEIVED BY *[Signature]*

DATE 9/8/71 TIME 1900

AREA 200-E BLDG. 202-A

REMARKS:

DECLASSIFIED

→ IF CAR CANNOT BE UNLOADED BY DATE AND TIME SHOWN, IT MUST BE RETURNED TO POINT OF ORIGIN FOR UNLOADING OR PROVISION FOR COOLING OF WELLS MUST BE MADE BY RECEIVER.

54-5000-255 (A-65)

ACCOMPANY SHIPMENT




AREA	BLOOD	CAR NO.	DATE	TIME	TEST	REMARKS
102	102	102	102	102	102	102

182A

DECLASSIFIED

DECLASSIFIED

UNLOADING AND CHARGING RECORD

WELL	TO POOL POSITION NO.	DATE	TIME	BUILDING DISPATCHER	TO DISSOLVER NO.	DATE	TIME	BUILDING DISPATCHER
A	001	11-3-6			72A1-75	9-8	2220	
B	002				/	/	/	
C	003				/	/	/	

1900 7005 7005 7005

DECLASSIFIED

DECLASSIFIED

[illegible]