

Exceptional service in the national interest



Photos placed in horizontal position
with even amount of white space
between photos and header


Z 3005 Hardware Pictures

Sean Grant




Experiment Description


- Z3005 was a strip-line configuration, shock-ramp Dynamic Material Properties experiment
- Samples were cerium with LiF windows and an aluminum spot coating
- These pictures show the sample panel assembly as well as the diagnostic probe body; diagnostics included ellipsometry and VISAR




Shot3005




Shot3005




Shot3005




Shot3005




Shot3005




Shot3005



Shot3005




Shot3005




Shot3005




Shot3005




Shot3005



Shot3005



Shot3005



Shot3005

Z Machine Status Diagram

