

**U.S. DEPARTMENT OF ENERGY
SANDIA CORPORATION**

**SANDIA NATIONAL LABORATORIES
EPA ID NM5890110518**

New Mexico Environment Department
Soil Samples
Thermal Treatment Unit

November 21, 2013

Figures and Photos

- Figure 1. NMED TTU Soil Sample Locations, November 21, 2013
- Figure 2. Personnel Collecting Sample TTU-1
- Figure 3. Location of Sample TTU-2
- Figure 4. Location of Samples TTU-3 and TTU-3 dup
- Figure 5. Location of Sample TTU-4

Figure 1. NMED TTU Soil Sample Locations, November 21, 2013




Figure 2. Personnel Collecting Sample TTU-1



The TTU burn cage and soil berm are visible. The fence at the north edge of the TTU is visible in the foreground.

Figure 3. Location of Sample TTU-2



The sample was collected from 0-6 inch depth in the disturbed area at the base of the marker flag on the inside face of the east berm.

Figure 4. Location of Samples TTU-3 and TTU-3 dup



The samples were collected from 0-6 inch depth in the disturbed area at the base of the marker flag on the inside face of the south berm

Figure 5. Location of Sample TTU-4



The sample was collected from 0-6 inch depth in the disturbed areas on the inside face of the west berm.