

---

## **A Comparison of the Effect of Outdoor Exposure on the Optical Properties of Solar Mirrors and Transparent Encapsulant Materials**

**L. S. Dake  
M. A. Lind  
C. R. Maag**

---

**September 1981**

**Prepared for  
the Solar Energy Research Institute  
under Related Services Agreement XP-9-8366-2  
and the U.S. Department of Energy under  
Contract DE-AC06-76RLO 1830**

**Pacific Northwest Laboratory  
Operated for the U.S. Department of Energy  
by Battelle Memorial Institute**



## NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the Department of Energy, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

The views, opinions and conclusions contained in this report are those of the contractor and do not necessarily represent those of the United States Government or the United States Department of Energy.

PACIFIC NORTHWEST LABORATORY  
*operated by*  
BATTELLE  
*for the*  
UNITED STATES DEPARTMENT OF ENERGY  
*Under Contract DE-AC06-76RLO 1830*

Printed in the United States of America  
Available from  
National Technical Information Service  
United States Department of Commerce  
5285 Port Royal Road  
Springfield, Virginia 22151

Price: Printed Copy \$\_\_\_\_\_.\*: Microfiche \$3.00

*Pages	NTIS
	Selling Price
001-025	\$4.00
026-050	\$4.50
051-075	\$5.25
076-100	\$6.00
101-125	\$6.50
126-150	\$7.25
151-175	\$8.00
176-200	\$9.00
201-225	\$9.25
226-250	\$9.50
251-275	\$10.75
276-300	\$11.00

3 3679 00059 5670

A COMPARISON OF THE EFFECT OF  
OUTDOOR EXPOSURE ON THE OPTICAL  
PROPERTIES OF SOLAR MIRRORS AND  
TRANSPARENT ENCAPSULANT MATERIALS

L. S. Dake  
M. A. Lind  
C. R. Maag<sup>(a)</sup>

September 1981

Prepared for  
the Solar Energy Research Institute  
under Related Services Agreement XP-9-8366-2  
and the U.S. Department of Energy under  
Contract DE-AC06-76RLO 1830

Pacific Northwest Laboratory  
Richland, Washington 99352

<sup>(a)</sup>Jet Propulsion Laboratory  
Pasadena, CA. 91103

1  
2  
3  
4

5  
6  
7

## ACKNOWLEDGEMENTS

The authors wish to express their appreciation to D. Chaudiere, K. Mallory, D. Nelson, M. Nordmeyer and T. Stewart for their substantial contributions to the optical evaluations. The authors also wish to thank F. Morrelli and W. Neiderheiser of JPL for their assistance in the outdoor exposure testing. W. Neiderheiser was particularly helpful in forwarding samples and data and in assembling the characterizations of the California test sites.



## EXECUTIVE SUMMARY

This joint PNL and JPL study is an assessment and comparison of the effects of outdoor exposure on solar mirrors and transparent encapsulant materials. The encapsulant materials tested included glasses, polymers and silicones. Samples of the materials were placed on stationary exposure racks in six locations that represented urban, desert, oceanside and high altitude mountain areas. Samples were removed periodically and sent to PNL for optical characterizations. The spectral hemispherical and diffuse reflectance of the mirror samples was measured. The spectral hemispherical transmittance and diffuse reflectance of the encapsulant materials was measured. In addition JPL measured the "relative normal hemispherical transmittance" of the encapsulant materials.

Correlations between the glass and mirror data showed that the average diffuse reflectance losses were six times larger for the mirrors than for the glass samples. The average specular reflectance losses for the mirror samples were seven times as large as the average hemispherical transmittance losses for the glass samples. These correlations may enable one to predict the performance of mirrors made using the other encapsulant materials for superstrates.

It was found that the urban and oceanside sites were the dirtiest, while the desert and mountain sites were the cleanest. Average specular reflectance losses varied from 4% at the cleanest site to 50% at the dirtiest site. The range in hemispherical transmittance losses for the encapsulant materials varied between 0% and 6%. At one site, the average daily specular reflectance losses were .04% for the mirror samples and average daily hemispherical transmittance losses were about .01% for the glass samples. The polymer materials degraded somewhat more rapidly than the glasses, and the silicones irreversibly degraded too rapidly and severely to be useful for either photovoltaic or solar thermal applications.





## TABLE OF CONTENTS

ACKNOWLEDGEMENTS . . . . .	iii
EXECUTIVE SUMMARY . . . . .	v
INTRODUCTION . . . . .	1
EXPERIMENTAL PROCEDURE . . . . .	1
MATERIALS TESTED . . . . .	1
EXPOSURE RACKS . . . . .	3
EXPOSURE TEST SITES . . . . .	3
OPTICAL MEASUREMENTS . . . . .	6
METHODS OF DATA ANALYSIS . . . . .	14
RESULTS AND DISCUSSION . . . . .	16
MIRROR AND GLASS DATA . . . . .	16
GLASS AND POLYMER DATA . . . . .	19
CONCLUSIONS . . . . .	26
REFERENCES . . . . .	28
APPENDIX A - DESCRIPTIONS OF OUTDOOR EXPOSURE TEST SITES	
APPENDIX B - SODA LIME SILICATE GLASS MIRROR AND ENCAPSULANT DATA	
APPENDIX C - GLASS AND POLYMER ENCAPSULANT DATA - SECOND YEAR STUDY	
APPENDIX D - GLASS AND POLYMER ENCAPSULANT DATA - FIRST YEAR STUDY	

## LIST OF FIGURES

1.	Photograph Showing the JPL Exposure Rack . . . .	4
2.	Maps Showing Location of Exposure Sites . . . .	5
3.	Spectral Reflectance Curves and Solar Weighted Values for Second Surface Silvered Soda Lime Silicate Float Glass Mirrors . . . . .	7
4.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Soda Lime Silicate Float Glass . . . . .	8
5.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Aluminosilicate Glass . . . .	9
6.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Borosilicate (7070) Glass . . . . .	10
7.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Borosilicate (7809) Glass . . . . .	11
8.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Polyvinylfluoride (Tedlar) . .	12
9.	Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Acrylic (Korad) . . . .	13
B.1.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Torrance Site, 1980-1981 . . . .	B.1
B.2.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Torrance Site, 1980-1981 .	B.2
B.3.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Pasadena Site, 1980-1981 . . . .	B.3
B.4.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Pasadena Site, 1980-1981 .	B.4
B.5.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Point Vicente Site, 1980-1981 . . .	B.5

B.6.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Point Vicente Site, 1980-1981 . . . . .	B.6
B.7.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Richland Site, 1980-1981 . . . . .	B.7
B.8.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Richland Site, 1980-1981 . . . . .	B.8
B.9.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Goldstone Site, 1980-1981 . . . . .	B.9
B.10.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Goldstone Site, 1980-1981 . . . . .	B.10
B.11.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Table Mountain Site, 1980-1981 . . . . .	B.11
B.12.	Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Glass Weathered at the Table Mountain Site, 1980-1981 . . . . .	B.12
C.1.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Torrance Site, 1980-1981 . . . . .	C.1
C.2.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Torrance Site, 1980-1981 . . . . .	C.2
C.3.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Torrance Site, 1980-1981 . . . . .	C.3
C.4.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Torrance Site, 1980-1981 . . . . .	C.4
C.5.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Pasadena Site, 1980-1981 . . . . .	C.5

C.6.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Pasadena Site, 1980-1981	C.6
C.7.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Pasadena Site, 1980-1981	C.7
C.8.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Pasadena Site, 1980-1981	C.8
C.9.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Point Vicente Site, 1980-1981	C.9
C.10.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Point Vicente Site, 1980-1981	C.10
C.11.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Point Vicente Site, 1980-1981	C.11
C.12.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Point Vicente Site, 1980-1981	C.12
C.13.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Richland Site, 1980-1981	C.13
C.14.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Richland Site, 1980-1981	C.14
C.15.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Richland Site, 1980-1981	C.15
C.16.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Richland Site, 1980-1981	C.16
C.17.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Goldstone Site, 1980-1981	C.17
C.18.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Goldstone Site, 1980-1981	C.18

C.19.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Goldstone Site, 1980-1981 . . . . .	C.19
C.20.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Goldstone Site, 1980-1981 . . . . .	C.20
C.21.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Table Mountain Site, 1980-1981 . . . . .	C.21
C.22.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Table Mountain Site, 1980-1981 . . . . .	C.22
C.23.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Table Mountain Site, 1980-1981 . . . . .	C.23
C.24.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Table Mountain Site, 1980-1981 . . . . .	C.24
D.1.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Torrance Site, 1979-1980 . . . . .	D.1
D.2.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Torrance Site, 1979-1980 . . . . .	D.2
D.3.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Torrance Site, 1979-1980 . . . . .	D.3
D.4.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Torrance Site, 1979-1980 . . . . .	D.4
D.5.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Pasadena Site, 1979-1980 . . . . .	D.5
D.6.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Pasadena Site, 1979-1980 . . . . .	D.6

D.7.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Pasadena Site, 1979-1980	D.7
D.8.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Pasadena Site, 1979-1980	D.8
D.9.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Point Vicente Site, 1979-1980	D.9
D.10.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Point Vicente Site, 1979-1980	D.10
D.11.	Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Point Vicente Site, 1979-1980	D.11
D.12.	Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Point Vicente Site, 1979-1980	D.12

## LIST OF TABLES

1. Materials Deployed at the Outdoor Exposure Test Sites . . .	2
2. Average Solar Weighted Optical Losses at Each Site for Soda Lime Silicate Float Glass and Mirrors. Second Year Data (1980-1981). . . . .	17
3. Daily Degradation Rates and Correlation Coefficients (in parentheses) as Calculated by a Linear Regression Analysis for the Entire Exposure Period for Soda Lime Silicate Float Glass and Mirror Samples. Second Year Data (1980-1981). . . . .	20
4. Daily Degradation Rates and Correlation Coefficients (in parentheses) as Calculated by a Linear Regression Analysis After the First 45 Days of Exposure for Soda Lime Silicate Float Glass and Mirror Samples. Second Year Data (1980-1981). . . . .	21
5. Average Solar Weighted Optical Losses for Glasses. Second Year Data (1980-1981). . . . .	22
6. Average Solar Weighted Optical Losses for Glasses. First Year Data (1979-1980). . . . .	23
7. Average Solar Weighted Optical Losses for Polymers. Second Year Data (1980-1981). . . . .	24
8. Average Solar Weighted Optical Losses for Polymers. First Year Data (1979-1980). . . . .	25





## INTRODUCTION

The Pacific Northwest Laboratory (PNL) and the Jet Propulsion Laboratory (JPL) conducted a joint study on the effects of outdoor exposure on the optical properties of some transparent encapsulant and reflector materials. JPL performed exposure testing on stationary racks located at several different sites as part of their Low-Cost Solar Array (LSA) photovoltaic program. PNL provided the mirror samples and did the optical characterizations in support of the solar thermal Research and Advanced Development (RAD) program. Average degradation rates were calculated. Linear regression analysis was performed on the data to determine average daily degradation rates for each material at each site. The data was also analyzed to determine the range of degradation between the cleanest and dirtiest sites.

One purpose of the study was to determine correlations between the glass encapsulant materials and the mirror optical degradation data. If these correlations could be extended to the other encapsulant materials tested, predictions could be made about the performance of mirrors constructed using the different encapsulant materials as substrates. Correlations were also sought between the different measurement techniques to determine which measurements were most useful in predicting the end use performance of the materials.

## EXPERIMENTAL PROCEDURE

### MATERIALS TESTED

The mirrors used in the exposure tests were standard industry wet-chemistry second surface silvered float glass with PPG grey paint backing. The encapsulant materials tested included three different glasses, two polymers and two silicones. A detailed description of the materials is supplied in Table 1. Samples of each material were cut into .05 m x .05 m (2 in. x 2 in.) square coupons for deployment on the exposure racks.

TABLE 1. Materials Deployed at the  
Outdoor Exposure Test Sites

Mirrors:

Second surface silvered soda lime  
silicate float glass with grey paint  
backing.

Glasses:

Soda lime silicate float glass  
CGW 7070 and 7809 borosilicate glass  
CGW 0317 aluminosilicate glass

Polymers:

DuPont Tedlar polyvinylfluoride  
XCEL Korad 212 acrylic

Silicones:

G.E RTV-615 silicone rubber  
D.C. Q1-2577 hardcoat silicone on  
CGW 7070 borosilicate glass substrate

It was quickly discovered that both of the silicone materials irreversibly degraded too rapidly to be useful for either photovoltaic or solar thermal applications. Therefore, no analysis of the silicone materials is presented in this report.

### EXPOSURE RACKS

Special racks were constructed by JPL for sample deployment at all the sites. The racks were constructed of stainless steel coated with a black epoxy paint. Stainless steel strips were bolted to the racks. Samples were placed between the stainless steel strips, which were then tightened so that the samples were held securely in place. A sample rack containing coupons is shown in Figure 1. The polymer samples were too thin to be held in place by the stainless steel strips. These samples were put in polymer slide holders, which could be secured in the racks. Rain channels were constructed between each row of samples to direct rain water to the side of the rack. In this manner, samples in lower rows were not contaminated by dirt washed off the samples above them.

The racks were deployed at each site so that the samples faced to the south. The racks were tilted at a 45° angle. A sample of each material was removed periodically and sent to PNL and JPL for evaluation. Two studies were done at every site except Richland, Washington. In the first study, only encapsulant materials were exposed, and samples were collected once a month. In the second study both encapsulant and reflector materials were deployed. Samples were collected about every three months and evaluated.

### EXPOSURE TEST SITES

JPL deployed sample racks throughout the United States as a part of their LSA project. Six sites were chosen for consideration in this report. The map in Figure 2 shows the location of the sites. The sites chosen represented urban areas (Pasadena and Torrance, CA); desert regions (Richland, WA and Goldstone, CA); high altitude mountains (Table Mountain, CA); and an oceanside location (Point Vicente, CA). More complete descriptions of each site can be found in Appendix A.





FIGURE 1. Photograph Showing the JPL Exposure Rack



**FIGURE 2.** Maps Showing Location of Exposure Sites (solid circles). Reference cities are designated by the open circles.

## OPTICAL MEASUREMENTS

The sample coupons were sent to PNL for optical characterizations. Spectral hemispherical and diffuse reflectance measurements were performed on the mirror samples. Spectral hemispherical transmittance and diffuse reflectance measurements were performed on the encapsulant materials. All the measurements were done over the wavelength interval 300-2500 nm using a Beckman 5270 spectrophotometer with a 15 cm (6 in.) integrating sphere. The accuracy of the measurements is believed to be  $\pm .005$  reflectance units and  $\pm .010$  transmittance units. The spectral data was weighted to the NASA AM 1.5<sup>(1)</sup> terrestrial solar spectral irradiance distribution (TSSID) using a best fit approximation routine to obtain the solar reflectance and transmittance. The result of this calculation is a single number between 0 and 1.000 (called the solar weighted reflectance or transmittance) that characterizes the entire spectral scan. The solar weighted value represents the fraction of solar energy reflected from or transmitted through the sample.

Typical spectral reflectance and transmittance curves are shown for each material in Figures 3 through 9. In each figure, the curves for a clean, unweathered sample and a heavily soiled sample are plotted to illustrate some extreme changes in the optical performance that can occur. For all the materials, the hemispherical transmittances ( $T_H$ ) and reflectances ( $R_H$ ) decrease while the diffuse reflectances ( $R_D$ ) increase after weathering. The decreases in the hemispherical transmittances and reflectances are usually greatest in the ultraviolet-visible portion of the spectra (300-750 nm).

Samples were measured before ( $R_i$ ,  $T_i$ ) and after ( $R_f$ ,  $T_f$ ) outdoor exposure. For the encapsulant materials, the changes in the transmittance and diffuse reflectance values (i.e., the difference ( $\Delta T_H$  and  $-\Delta R_D$ ) between the weathered sample and clean sample values) were plotted as a function of exposure time. In a similar manner, the changes in hemispherical, diffuse and specular reflectance were plotted for the mirror data. The change in hemispherical reflectance ( $\Delta R_H$ ) indicates the absorption of the dust layer. The change in diffuse reflectance ( $-\Delta R_D$ ) shows the losses due to scattering. The sum of the hemispherical and diffuse reflectance losses equals the total specular loss for the mirror samples ( $\Delta R_S = \Delta R_H - \Delta R_D$ ).




FIGURE 3. Spectral Reflectance Curves and Solar Weighted Values for Second Surface Silvered Soda Lime Silicate Float Glass Mirrors (weathered 120 days)




FIGURE 4. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Soda Lime Silicate Float Glass (weathered 430 days)






FIGURE 5. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Aluminosilicate Glass (CGW-0317) (weathered 130 days)




FIGURE 6. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Borosilicate Glass (CGW 7070) (weathered 430 days)




FIGURE 7. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Borosilicate Glass (CGW 7809) (weathered 364 days)




FIGURE 8. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Polyvinylfluoride (Tedlar) (weathered 430 days)




FIGURE 9. Spectral Reflectance and Transmittance Curves and Solar Weighted Values for Acrylic (Korad) (weathered 430 days)

In addition to the optical characterizations performed by PNL, JPL monitored the optical transmission of the encapsulant materials using their "relative normal hemispherical transmittance" measurement apparatus.<sup>(2)</sup> The weathered coupon and a coupon of the same material that has not been weathered are placed over two matched solar cells. The two cells are illuminated, and the ratio of the two short-circuit currents is recorded. This ratio is called the relative normal hemispherical transmittance (RNHT) and is a measure of the change in transmittance of the weathered material.

#### METHODS OF DATA ANALYSIS

For the mirror samples, changes in hemispherical, diffuse and specular reflectance data ( $\Delta R_H$ ,  $-\Delta R_D$ , and  $\Delta R_S$ ) were plotted as a function of exposure time for each site. For the encapsulant materials, changes in transmittance ( $\Delta T_H$ ) and diffuse reflectance ( $-\Delta R_D$ ) were plotted. The average losses ( $\overline{\Delta R_S}$ ,  $\overline{\Delta T_H}$ , etc.) were calculated for each site and are presented in tabular form. For the glass and mirror data, ratios of the average losses (i.e.,  $\overline{\Delta R_S}/\overline{\Delta R_H}$ ,  $\overline{\Delta T_H}/\overline{\Delta R_D}$  etc.) were calculated to determine if correlations existed between the glass and mirror data. These correlations could be used to predict the performance of the other encapsulant materials used as superstrates for mirrors.

A linear regression analysis was performed to calculate the average daily losses for each material at each site. The analysis calculates the best fit straight line through the data. This line is represented by the equation:

$$y = ax + b \quad (1)$$

where the slope is given by

$$a = \frac{\sum x_i y_i - \frac{\sum x_i \sum y_i}{n}}{\sum x_i^2 - \frac{(\sum x_i)^2}{n}} \quad (2)$$

and the intercept is given by

$$b = \frac{\sum y_i}{n} - \frac{a \sum x_i}{n} \quad (3)$$

Here the slope represents the average degradation rate. Since other studies<sup>(3)</sup> have shown that the degradation rates may be significantly larger for the initial exposure period, the analysis was performed over the entire data set and over the data set after the first 45 days of exposure.

Correlation coefficients can be calculated using the following relationship:

$$r^2 = \frac{\sum x_i y_i - \frac{\sum x_i \sum y_i}{n}}{\sum x_i^2 - \frac{(\sum x_i)^2}{n}} \frac{\sum x_i y_i - \frac{\sum x_i \sum y_i}{n}}{\sum y_i^2 - \frac{(\sum y_i)^2}{n}}$$

The correlation coefficient is a number between 0 and 1. It is a measure of how closely the experimental data fits the line generated by the linear regression analysis. If  $r^2 = 1$ , the data is a perfect fit to the regression line. For the purposes of this study, the average daily degradation rates are considered reliable if the associated correlation coefficient is greater than 0.5.

The data was examined for site specific variations that would help distinguish between the cleanest and dirtiest sites. Results for each measurement were analyzed to determine which specific measurements gave the most representative information about the material performance. Data from the first-year study was used to confirm trends noted in the second-year study.

## RESULTS AND DISCUSSION

### MIRROR AND GLASS DATA

The solar weighted optical loss data is plotted as a function of exposure time for the soda lime silicate glass and mirrors in Appendix B. In many cases, the variation between successive data points is large. The widely scattered data swamps any readily discernible average trends.

The average optical losses and the standard deviation in the data for each site are summarized in Table 2. For the mirror coupons, the average specular reflectance losses varied between 4% (Table Mountain site) and 50% (Torrance site). For the glass samples, the average hemispherical transmittance losses varied between 0% (Table Mountain site) and 5% (Torrance site). Similar average losses occurred in the diffuse reflectance measurements. The average RNHT losses varied between 1% (Table Mountain) and 9% (Pasadena).

It is easy to differentiate between the sites on the basis of the mirror data since the range in average optical losses was large. It is more difficult to distinguish between the sites on the basis of the glass data, since the  $\Delta T_H$  data varied at most between 0 and 10%. The standard deviations were large enough to make absolute determinations of cleanest and dirtiest sites difficult, but some generalizations can be made. The urban and oceanside sites were the dirtiest (Torrance, Pasadena and Point Vicente). The Richland Desert site appeared to be somewhat cleaner. The Goldstone desert site and the Table Mountain site were by far the cleanest locations.

The ratios of the various optical losses were calculated for each site and then averaged to determine if any meaningful correlations between the measurements existed. With the exception of Table Mountain, these ratios were surprisingly consistent. The ratios for the Table Mountain site often varied wildly from the other sites. Since this was a very clean site, changes in the optical losses were small. These small differences impact greatly the calculated ratios.



TABLE 2. Average Solar Weighted Optical Losses at Each Site for  
Soda Lime Silicate Float Glass and Mirrors.  
Second Year Data (1980-1981).

Site	Mirrors (Absolute Units)			Soda Lime Silicate Float Glass (Absolute Units)		
	$\Delta R_H$	$-\Delta R_D$	$\Delta R_S$	$\Delta T_H$	$-\Delta R_D$	$\Delta RNHT^*$
Torrance	$-.2 \pm .1$	$-.3 \pm .1$	$-.5 \pm .2$	$-.05 \pm .03$	$-.04 \pm .02$	$-.08 \pm .05$
Pasadena	$-.10 \pm .03$	$-.18 \pm .04$	$-.3 \pm .1$	$-.06 \pm .02$	$-.03 \pm .01$	$-.09 \pm .03$
Point Vicente	$-.07 \pm .03$	$-.19 \pm .09$	$-.3 \pm .1$	$-.05 \pm .02$	$-.04 \pm .02$	$-.02 \pm .02$
Richland	$-.04 \pm .02$	$-.16 \pm .08$	$-.2 \pm .1$	$-.03 \pm .03$	$-.03 \pm .02$	$-.02 \pm .01$
Goldstone	$-.02 \pm .01$	$-.06 \pm .03$	$-.08 \pm .04$	$-.01 \pm .01$	$-.01 \pm .003$	$-.02 \pm .01$
Table Mountain	$-.01 \pm .01$	$-.03 \pm .01$	$-.04 \pm .02$	$-.002 \pm .002$	$-.01 \pm .01$	$-.01 \pm .01$

\*Relative normal hemispherical transmittance

It was discovered that average diffuse reflectance losses in the mirror samples were about six times as great as the average diffuse reflectance losses for the glass samples:

$$\frac{\overline{-\Delta R_D} \text{ (mirror)}}{\overline{-\Delta R_D} \text{ (glass)}} = 6 \pm 1 \text{ (Table Mountain data excluded)}$$

It was also found that the average specular reflectance losses for the mirror samples were about seven times as large as the average hemispherical transmittance losses for the glass samples:

$$\frac{\Delta R_S \text{ (mirror)}}{\Delta T_H \text{ (glass)}} = 7 \pm 2 \text{ (Table Mountain data excluded)}$$

For all the other mirror/glass ratios, standard deviations were so large that no meaningful relationships could be determined.

For the mirror data alone, it was found that the ratio of specular to hemispherical reflectance losses was approximately 4:1, and the ratio of diffuse to hemispherical reflectance losses was about 3:1.

$$\frac{\Delta R_S \text{ (mirror)}}{\Delta R_H \text{ (mirror)}} = 4 \pm 1$$

$$\frac{-\Delta R_D \text{ (mirror)}}{\Delta R_H \text{ (mirror)}} = 3 \pm 1$$

For the glass data the ratio of hemispherical transmittance losses to diffuse reflectance losses was nearly 1:1.

$$\frac{\Delta T_H \text{ (glass)}}{-\Delta R_D \text{ (glass)}} = 1.3 \pm .4$$

No meaningful relationships were found between the RNHT losses and any of the other measurements.

The results from linear regression analysis of the second year data are shown in Tables 3 and 4. Since the correlation coefficients were small in most cases, the degradation rates are not very useful. An exception was the data from the Richland site. This data had correlation coefficients of .8 and .9. Specular reflectance degradation rates were .04%/day for the mirror samples. For the glass samples, hemispherical transmittance and diffuse reflectance degradation rates were approximately .01%/day.

#### GLASS AND POLYMER DATA

Optical loss curves for the first and second year studies of the glass and polymer samples are shown in Appendix C and D. The average solar weighted optical losses are shown for each site in Tables 5 through 8.

Looking at the second year data for the glass samples in Table 5, it is difficult to discern meaningful differences between the four glass types. From site to site, the average hemispherical transmittance losses varied between 0 and 7%, and the average diffuse reflectance losses varied between 0 and 4%. The large standard deviations make any differences between the glasses ambiguous. The borosilicate (CGW-7070) glass may have performed slightly better on the average. The first year data in Table 6 shows the same general trends as the second year data. The magnitude of the losses was comparable for the two studies.

Again, the correlation coefficients were very small for most of the linear regression analysis. The Richland data was again the exception, with correlation coefficients of 0.6 to 0.9. For all the glasses, the daily degradation rates for both transmittance and diffuse reflectance was approximately .01%/day (calculated over the entire curve). Similar rates were found when the analysis was done on the data after the first 45 days of exposure.

It was difficult to distinguish between the two polymer materials on the basis of the hemispherical transmittance losses. But the diffuse reflectance losses are smaller for the polyvinylfluoride (Tedlar) samples, as seen in Tables 7 and 8. Of more significance is the fact that the ratio of the average hemispherical transmittance to diffuse reflectance

TABLE 3. Daily Degradation Rates and Correlation Coefficients (in parentheses) as Calculated by a Linear Regression Analysis for the Entire Exposure Period for Soda Lime Silicate Float Glass and Mirror Samples. Second Year Data (1980-1981).

<u>Site</u>	<u>Mirrors</u> <u>(Absolute Units)</u>			<u>Soda Lime Silicate Float Glass</u> <u>Absolute Units)</u>		
	<u><math>\Delta R_H/\text{day}</math></u>	<u><math>-\Delta R_D/\text{day}</math></u>	<u><math>\Delta R_S/\text{day}</math></u>	<u><math>\Delta T_H/\text{day}</math></u>	<u><math>-\Delta R_D/\text{day}</math></u>	<u><math>\Delta RNHT/\text{day}</math></u>
Torrance	-.00002 (.001)	-.00004 (.002)	-.00002 (0)	-.0001 (.3)	-.00007 (.3)	-.00006 (.02)
Pasadena	-.0002 (.16)	-.0002 (.14)	-.0004 (.2)	-.0001 (.2)	-.00005 (.2)	-.00009 (.3)
Point Vicente	-.00005 (.05)	-.00007 (.01)	-.0001 (.02)	-.0002 (.5)	-.0001 (.6)	-.00008 (.3)
Richland	-.0001 (.9)	-.0004 (.9)	-.0004 (.8)	-.0001 (.8)	-.00008 (.9)	-.00006 (.8)
Goldstone	-.00003 (.2)	0 (0)	-.00003 (.01)	-.00004 (.2)	-.00003 (.7)	-.00009 (.9)
Table Mountain	-.00002 (.3)	-.00007 (.4)	-.0001 (.4)	0 (.004)	-.00001 (.03)	-.00005 (.9)

TABLE 4. Daily Degradation Rates and Correlation Coefficients (in parentheses) as Calculated by a Linear Regression Analysis After the First 45 Days of Exposure for Soda Lime Silicate Float Glass and Mirror Samples. Second Year Data (1980-1981).

Site	Mirrors (Absolute Units)			Soda Lime Silicate Float Glass (Absolute Units)		
	$\Delta R_H/\text{day}$	$-\Delta R_D/\text{day}$	$\Delta R_S/\text{day}$	$\Delta T_H/\text{day}$	$-\Delta R_D/\text{day}$	$\Delta RNHT/\text{day}^*$
Torrance	+ .0007 (.6)	+ .0006 (.4)	+ .001 (.5)	- .00001 (.001)	- .00001 (.004)	+ .0002 (.2)
Pasadena	+ .0002 (.3)	+ .0003 (.9)	+ .0005 (.7)	- .0001 (.3)	- .00006 (.4)	- .0001 (.3)
Point Vicente	+ .00002 (.05)	+ .0001 (.03)	+ .0001 (.02)	- .0001 (.2)	- .00007 (.3)	- .00004 (.06)
Richland	- .00008 (.8)	- .0003 (.8)	- .0003 (.7)	- .0001 (.8)	- .00007 (.8)	- .00005 (.5)
Goldstone	- .00003 (.5)	+ .00003 (.02)	+ .00004 (0)	- .00002 (.08)	- .00002 (.4)	- .00009 (.8)
Table Mountain	- .00001 (.02)	- .00003 (.07)	- .00004 (.06)	+ .00001 (.7)	+ .00005 (.9)	- .00005 (.8)

\*Relative normal hemispherical transmittance

TABLE 5. Average Solar Weighted Optical Losses for Glasses  
Second Year Data (1980-1981)

Site	Soda Lime Silicate		Aluminosilicate		Borosilicate (7070)		Borosilicate (7809)	
	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$
Torrance	$-.05 \pm .03$	$-.04 \pm .02$	$-.07 \pm .04$	$-.03 \pm .02$	$-.05 \pm .03$	$-.03 \pm .01$	$-.06 \pm .03$	$-.04 \pm .01$
Pasadena	$-.06 \pm .02$	$-.03 \pm .01$	$-.05 \pm .01$	$-.03 \pm .01$	$-.03 \pm .02$	$-.02 \pm .01$	$-.03 \pm .01$	$-.02 \pm .001$
Point Vicente	$-.05 \pm .02$	$-.04 \pm .02$	$-.04 \pm .02$	$-.03 \pm .01$	$-.03 \pm .02$	$-.02 \pm .01$	$-.04 \pm .02$	$-.03 \pm .01$
Richland	$-.03 \pm .03$	$-.03 \pm .02$	$-.05 \pm .05$	$-.03 \pm .02$	$-.03 \pm .04$	$-.03 \pm .02$	---	---
Goldstone	$-.01 \pm .01$	$-.01 \pm .003$	$-.02 \pm .004$	$-.01 \pm .004$	$-.004 \pm .003$	$-.007 \pm .001$	$-.01 \pm .01$	$-.007 \pm .003$
Table Mountain	$-.002 \pm .002$	$-.01 \pm .01$	$-.01 \pm .01$	$-.009 \pm .005$	$-.002 \pm .002$	$-.009 \pm .004$	$-.01 \pm .01$	$-.009 \pm .004$

TABLE 6. Average Solar Weighted Optical Losses for Glasses  
First Year Data (1979-1980)

Site	Soda Lime Silicate		Aluminosilicate		Borosilicate (7070)	
	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$
Torrance	$-.07 \pm .04$	$-.04 \pm .02$	$-.07 \pm .04$	$-.04 \pm .02$	$-.07 \pm .06$	$-.03 \pm .02$
Pasadena	$-.06 \pm .03$	$-.04 \pm .01$	$-.05 \pm .02$	$-.04 \pm .02$	$-.04 \pm .02$	$-.03 \pm .02$
Point Vicente	$-.04 \pm .02$	$-.04 \pm .02$	$-.06 \pm .03$	$-.03 \pm .02$	$-.03 \pm .02$	$-.03 \pm .02$

TABLE 7. Average Solar Weighted Optical Losses for Polymers  
Second Year Data (1980-1981)

Site	Polyvinylfluoride (Tedlar)		Acrylic (Korad)	
	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$
Torrance	$-.09 \pm .04$	$-.03 \pm .01$	$-.11 \pm .04$	$-.06 \pm .02$
Pasadena	$-.11 \pm .04$	$-.02 \pm .01$	$-.11 \pm .02$	$-.04 \pm .01$
Point Vicente	$-.05 \pm .02$	$-.02 \pm .01$	$-.06 \pm .03$	$-.06 \pm .02$
Richland	$-.02 \pm .002$	$-.004 \pm .003$	$-.03 \pm .01$	$-.03 \pm .02$
Goldstone	$-.02 \pm .002$	$-.004 \pm .003$	$-.03 \pm .01$	$-.03 \pm .02$
Table Mountain	$-.03 \pm .001$	$-.009 \pm .002$	$-.03 \pm .01$	$-.03 \pm .02$



TABLE 8. Average Solar Weighted Optical Losses for Polymers  
First Year Data (1979-1980)

Site	Polyvinylfluoride (Tedlar)		Acrylic (Korad)	
	$\Delta T_H$	$-\Delta R_D$	$\Delta T_H$	$-\Delta R_D$
Torrance	$-.11 \pm .06$	$-.03 \pm .02$	$-.10 \pm .05$	$-.05 \pm .02$
Pasadena	$-.09 \pm .04$	$-.02 \pm .01$	$-.07 \pm .03$	$-.06 \pm .02$
Point Vicente	$-.06 \pm .03$	$-.03 \pm .01$	$-.05 \pm .03$	$-.05 \pm .02$

losses is quite different for the two polymers. For both the first and second year data, the ratio is approximately 4:1 for the polyvinylfluoride, but is only about 1:1 for the acrylic.

$$\text{Polyvinylfluoride: } \frac{\Delta T_H}{-\Delta R_D} = 4 \pm 1$$

(Tedlar)

$$\text{Acrylic: } \frac{\Delta T_H}{-\Delta R_D} = 1.4 \pm .7$$

(Korad)

This ratio for the acrylic material is about the same magnitude as the same ratio for the glass data, but this ratio for the polyvinylfluoride material is much larger. The reason for this is unknown.

Again, the linear regression analysis was only meaningful for the Richland data. Daily degradation rates for the acrylic (Korad) material were approximately .01%/day for both the diffuse reflectance and hemispherical transmittance losses. The daily degradation rate for the hemispherical transmittance of the polyvinylfluoride (Tedlar) was also about .01%/day. But, the diffuse reflectance for the polyvinylfluoride was an exception; having a much smaller daily degradation rate of .003%/day.

### CONCLUSIONS

Analysis of the glass and mirror data revealed some interesting correlations. The average diffuse reflectance losses for the mirrors were six times larger than the average diffuse reflectance losses for the glass samples. The average specular reflectance losses for the mirror samples were seven times as large as the average hemispherical transmittance losses for the corresponding glass samples.

In addition to correlations between the mirror and glass data, several correlations were found within the glass and mirror measurements. Average specular reflectance losses were four times as large as average hemispherical reflectance losses for the mirrors. Average diffuse reflectance

losses were three times as large as the average hemispherical reflectance losses for the mirror samples. For the glass samples, average hemispherical transmittance losses were slightly greater than average diffuse reflectance losses. No strong correlations were found between the RNHT measurements and any of the other measurements performed.

Average daily degradation rates were calculated using linear regression analysis for all the sites, but only the data from the Richland site had high enough correlation coefficients to be considered predictable. For the Richland site, the average daily specular reflectance loss was .04% for the mirror samples. The average daily diffuse reflectance and hemispherical transmittance losses were .01% for the glass samples.

The range of average specular reflectance losses for the mirrors varied from 4% at the Table Mountain site, to 50% at the Torrance site. The range of hemispherical transmittance losses varied between 0% for the Table Mountain site, and 6% at the Pasadena site. Because of the magnitude of the standard deviation in the average loss data, it was difficult to determine an absolute ranking from dirtiest to cleanest for the sites. In general, the Torrance and Pasadena urban sites and the Point Vicente oceanside site were the dirtiest. The Goldstone desert site and the Table Mountain mountain site were cleanest. The Richland site was in between.

Comparisons between the glass and polymer data were also performed. It was difficult to distinguish between the performance of the glasses, again due to the scatter in the average loss data. The borosilicate (CGW-7070) glass may have shown slightly less degradation. The site to site range in average hemispherical transmittance losses for the glasses was 0-7%, while the range for average losses in diffuse reflectance was between 0 and 4%. Again, only the Richland data provided valid daily degradation rates. Average daily losses at Richland for both hemispherical transmittance and diffuse reflectance were .01%/day.

In general, the polymer materials were dirtier than the glass materials. The average hemispherical transmittance losses were about the same for the polyvinylfluoride and the acrylic. But the diffuse reflectance losses were smaller for the polyvinylfluoride material. The ratio of average hemispherical transmittance loss to average diffuse reflectance loss was approximately 1:1 for the acrylic, but was nearly 4:1 for the polyvinylfluoride. From the Richland data, average daily degradation rates were approximately .01%/day for all the polymer measurements except the average change in diffuse reflectance for the polyvinylfluoride, whose daily degradation rate was .003%. The first year data verified the second year data in both general trends and absolute magnitude of the losses.

One recommendation for future studies of this type would be to take data more frequently--at least once a week. It has been found that daily degradation rates are much larger for the initial weathering period at some sites. By taking more frequent data, information about short term degradation rates can also be determined.

#### REFERENCES

1. H.W. Brandhorst, Jr., et al. 1977. "Terrestrial Photovoltaic Measurement Procedures." NASA TM 73702. ERDA/NASA/1022-77116, NASA Lewis Research Center, Cleveland, OH.
2. A.R. Hoffman and C.R. Maag. 1980. "Photovoltaic Module Soiling Studies May 1978 - October 1980." DOE/JPL-1012-49. Jet Propulsion Laboratory, Pasadena, CA.
3. L.S. Dake and M.A. Lind. 1981. "The Optical Losses of Solar Mirrors Due to Atmospheric Contamination at Liberal, Kansas and Oologah, Oklahoma." PNL-4073. Pacific Northwest Laboratory, Richland, Washington.

APPENDIX A

DESCRIPTIONS OF OUTDOOR  
EXPOSURE TEST SITES

## APPENDIX A

### DESCRIPTIONS OF EXPOSURE TEST SITES

Torrance: Located on corner of Imperial Highway and La Cienega Boulevard in metropolitan Los Angeles.

Rack is mounted on top of one story building facing South to a parking lot near the flight path of LAX Airport to the North and the San Diego Freeway (405) 1/2 block to the East.

Plant life: Several large trees in the area but not within 75 feet of panel.

Soil: Parking lot to the South, asphalt streets to the West and North. Buildings and Freeway to the East.

Elevation: 75 ft. above sea level.

Weather conditions: Moderate to heavy rains (winter season), moderate winds.

Pasadena: Located in Pasadena, CA, 2 blocks South of 210 (Foothill) Freeway, Central Pasadena. South facing rack mounted on top of one story building facing parking lot and three story apartment building about 100 ft. away.

Plant life: Several large trees, general industrial area and business offices.

Soil: Parking lot to South, streets to the North, East and West.

Elevation: 867 ft. above sea level.

Weather: Moderate rains (winter season), occasional light to heavy winds.

Point Vicente: Located in Palos Verdes at U.S. Coast Guard station.

Rack is 10 feet from edge of 100 foot cliff facing South to Pacific Ocean.

Plant life: Iceplant, wild grass, weeds.

Soil: Rocks, loamy, moving soil condition.

Elevation: 100 ft. above sea level.

Weather conditions: High winds, heavy rains (winter season).

Richland: Located on the Hanford reservation 5 miles north of Richland, WA.

Rack is in desert location facing South.

Plant life: Tumbleweeds, sagebrush and grasses.

Soil: Sand, small rocks.

Elevation: 400 ft. above sea level.

Weather conditions: Hot, dry summers, high winds, dust storms.

Goldstone: Located in Central Mojave desert of California 58 miles north of Barstow. Rack is in desert locale facing South to gradual up hill slope.

Plant life: Tumbleweeds, coyote bush, Yucca trees.

Soil: Sand, rocks, small stones.

Elevation: 2200 ft. above sea level.

Weather conditions: Flash flooding, heavy rains, high winds, occasional snow.

Table Mountain: Located near the city of Wrightwood in Big Pines area U.S. Forestry service property. Rack is 15 ft. from edge of 200 ft. South facing cliff (sloping).

Plant life: Pine trees, wild shrub, weeds.

Soil: Rocks, sand, sliding soil.

Elevation: 7500 ft. above sea level.

Weather conditions: Snow, high winds, heavy rains.

NOTE: California site descriptions courtesy of W. Neiderheiser, JPL.

APPENDIX B

SODA LIME SILICATE GLASS  
MIRROR AND ENCAPSULANT DATA






FIGURE B.1. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Torrance Site, 1980-1981




FIGURE B.2. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Torrance Site, 1980-1981




FIGURE B.3. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Pasadena Site, 1980-1981




FIGURE B.4. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Pasadena Site, 1980-1981




FIGURE B.5. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Point Vicente Site, 1980-1981





FIGURE B.6. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Point Vicente Site, 1980-1981



**FIGURE B.7.** Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Richland Site, 1980-1981




FIGURE B.8. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Richland Site, 1980-1981






FIGURE B.9. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Goldstone Site, 1980-1981




FIGURE B.10. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Float Glass Weathered at the Goldstone Site, 1980-1981




FIGURE B.11. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Float Glass Mirrors Weathered at the Table Mountain Site, 1980-1981




FIGURE B.12. Effects of Atmospheric Contamination on the Solar Weighted Optical Properties of Soda Lime Silicate Glass Weathered at the Table Mountain Site, 1980-1981

## APPENDIX C

### GLASS AND POLYMER ENCAPSULANT DATA SECOND YEAR STUDY

C.1  
CHANGE (ABSOLUTE UNITS)




FIGURE C.1. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Torrance Site, 1980-1981




FIGURE C.2. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Torrance Site, 1980-1981




FIGURE C.3. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Torrance Site, 1980-1981






FIGURE C.4. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Torrance Site, 1980-1981




FIGURE C.5. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Pasadena Site, 1980-1981




FIGURE C.6. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Pasadena Site, 1980-1981




FIGURE C.7. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Pasadena Site, 1980-1981





FIGURE C.8. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Pasadena Site, 1980-1981



**FIGURE C.9.** Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Point Vicente Site, 1980-1981




FIGURE C.10. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Point Vicente Site, 1980-1981




FIGURE C.11. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Point Vicente Site, 1980-1981






FIGURE C.12. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Point Vicente Site, 1980-1981




FIGURE C.13. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Richland Site, 1980-1981




FIGURE C.14. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Richland Site, 1980-1981




FIGURE C.15. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Richland Site, 1980-1981




FIGURE C.16. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Richland Site, 1980-1981




FIGURE C.17. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Goldstone Site, 1980-1981




FIGURE C.18. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Goldstone Site, 1980-1981




FIGURE C.19. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Goldstone Site, 1980-1981



C.20  
CHANGE (ABSOLUTE UNITS)




FIGURE C.20. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Goldstone Site, 1980-1981




FIGURE C.21. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Table Mountain Site, 1980-1981




FIGURE C.22. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Table Mountain Site, 1980-1981




FIGURE C.23. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Table Mountain Site, 1980-1981




FIGURE C.24. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Table Mountain Site, 1980-1981

## APPENDIX D

### GLASS AND POLYMER ENCAPSULANT DATA FIRST YEAR STUDY




FIGURE D.2. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Torrance Site, 1979-1980




FIGURE D.3. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Torrance Site, 1979-1980






FIGURE D.4. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Torrance Site, 1979-1980




FIGURE D.5. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Pasadena Site, 1979-1980




FIGURE D.6. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Pasadena Site, 1979-1980




FIGURE D.7. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Pasadena Site, 1979-1980




FIGURE D.8. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Pasadena Site, 1979-1980




FIGURE D.9. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Glasses Weathered at the Point Vicente Site, 1979-1980




FIGURE D.10. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Glasses Weathered at the Point Vicente Site, 1979-1980




FIGURE D.11. Effects of Atmospheric Contamination on the Solar Weighted Transmittance ( $\Delta T_H$ ) of Polymers Weathered at the Point Vicente Site, 1979-1980






FIGURE D.12. Effects of Atmospheric Contamination on the Solar Weighted Diffuse Reflectance ( $-\Delta R_D$ ) of Polymers Weathered at the Point Vicente Site, 1979-1980

DISTRIBUTION

No. of  
Copies

No. of  
Copies

OFFSITE

27 Technical Information Center

B. Ackerman  
Corning Glass Works  
Main Plant, Bldg. 8-5  
Corning, NY 14830

M. Adams  
Jet Propulsion Laboratory  
4800 Oak Grove Drive  
Pasadena, CA 91108

J.F. Banas, 4722  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

M. Berry  
Boeing Engr. and Const.  
P.O. Box 3707  
Seattle, WA 98124

J. Bigger  
Electric Power Research Insti.  
P.O. Box 10412  
Palo Alto, CA 93403

F. Blake  
Northrup, Inc., Blake Lab.  
Suite 306  
7061 S. University Blvd.  
Littleton, CO 80122

T. Blaney  
Sunpower Systems Corp.  
510 So. 52nd Street  
Tempe, AR 85281

F.L. Bouquet  
Jet Propulsion Laboratory  
4800 Oak Grove Drive  
Pasadena, CA 91108

G. Braun  
DOE Division of Solar Technology  
Forrestahl Building  
Washington, DC 20545

C.J. Brinker, 5845  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

T.D. Brumleve, 8451  
Sandia Laboratories  
Livermore, CA 94550

V. Burolla  
Sandia Laboratories  
Livermore, CA 94550

Ken Busche  
Busche Energy Systems  
7288 Murdy Circle  
Huntington Beach, CA 92647

B. Butler  
Solar Energy Research Institute  
1536 Cole Boulevard  
Golden, CO 80401

P. Call  
Solar Energy Research Institute  
1536 Cole Boulevard  
Golden, CO 80401

R.E. Cambron  
Springborn Laboratories  
Water Street  
Enfield, CT 06082

W. Carroll  
Jet Propulsion Laboratory  
4800 Oak Grove Drive  
Pasadena, CA 91108

A.A. Churm  
DOE Chicago Patent Group  
9800 South Cass Avenue  
Argonne, IL 60439

No of  
Copies

E. Clark  
National Bureau of Standards  
Washington, DC 20234

N.H. Clark, 1415  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

G. Cottingham  
Brookhaven National Lab.  
Upton, NY 11973

T. Coyle  
Solar Energy Research Insti.  
1536 Cole Boulevard  
Golden, CO 80401

E. Cuddihy  
Jet Propulsion Laboratory  
4800 Oak Grove  
Pasadena, CA 91108

D. Culler  
Gardner Mirror Corp.  
P.O. Box 638, Hwy. 268E.  
N. Wilkesboro, NC 28659

A. Czanderna  
Solar Energy Research Insti.  
1536 Cole Boulevard  
Golden, CO 80401

W.R. Delameter, 8451  
Sandia Laboratories  
Livermore, CA 94550

E.J. Dempsey  
London Laboratories Limited  
Box 3637  
Woodbridge, CT 06525

C.R. Easton  
McDonnell Douglas  
Astronautics Co.  
5307 Bolsa Avenue  
Huntington Beach, CA 92647

No of  
Copies

P.J. Eicker, 8326  
Sandia Laboratories  
Livermore, CA 94550

S.D. Elliott  
DOE San Francisco  
Operations Office  
1333 Broadway  
Wells Fargo Building  
Oakland, CA 94612

R.A. England  
Martin Marietta  
MS S0403  
P.O. Box 179  
Denver, CO 80201

H.E. Felix  
Solaramics, Inc.  
1301 El Segundo Blvd.  
El Segundo, CA 90245

C.R. Frownfelter  
PPG Industries, Inc.  
One Gateway Center  
Pittsburg, PA 15222

John Garate  
General Electric  
1 River Road  
Schenectady, NY 12345

R. Gillette  
MS 9A-46  
Boeing Engr. and Const.  
P.O. Box 3707  
Seattle, WA 98124

D. Gray  
Black & Veatch  
P.5.D.5  
P.O. Box 8405  
Kansas City, MO 64114

R.N. Griffin  
General Electric  
1 River Road  
Schenectady, NY 12345

No. of  
Copies

No. of  
Copies

G. Gross  
Solar Energy Research Insti.  
1536 Cole Boulevard  
Golden, CO 80401

B. Gupta  
Solar Energy Research Insti.  
1536 Cole Boulevard  
Golden, CO 80401

M.U. Gutstein  
DOE Division of Solar Tech.  
Forrestahl Building  
Washington, DC 20545

R. Hobbs  
General Electric Company  
P.O. Box 8661, Room 7310  
Philadelphia, PA 19101

P.L. Hofmann  
Battelle  
505 King Avenue  
Columbus, OH 43201

L. Hornberger  
Acurex Corporation  
485 Clyde MS2-2240  
Mountain View, CA 94042

Richard Horton  
General Electric  
1 River Road  
Schenectady, NY 12345

C.G. Howard  
Booz, Allen & Hamilton, Inc.  
8801 E. Pleasant Valley Road  
Cleveland, OH 44131

W. Jankowski  
Engelhard Industries  
1 West Central Avenue  
E. Newark, NJ 07029

E.L. Katz  
Aerospace Corporation  
Solar Thermal Projects  
Energy Systems Group  
P.O. Box 92957  
Los Angeles, CA 90009

Ernie Lam  
Bechtel National Inc.  
MS 50/16  
P.O. Box 3965  
San Francisco, CA 94119

S. Lamensdorf  
Binswanger Mirror Co.  
1355 Lynnfield Road  
Suite 205  
P.O. Box 17127  
Memphis, TN 38117

C.M. Lampert  
Lawrence Berkeley Laboratory  
Building 62, Room 235  
University of California  
Berkeley, CA 94720

J.A. Leonard, 4725  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

I.E. Lewis  
Ford Aerospace  
3939 Fabian Way  
Palo Alto, CA 94303

K. Masterson  
Solar Energy Research Institute  
1536 Cole Boulevard  
Golden, CO 80401

C.L. Mavis  
Sandia Laboratories  
Livermore, CA 94550

Mrs. McHugh  
Sanders Associates  
95 Canal Street  
MS MER12-1214  
Nashua, NH 03061

J. Megland  
PRC 1 EAC  
7600 Old Springhouse Road  
McClaine, VA 22102

C. R. Maag (5)  
4800 Oak Grove Drive  
Pasadena, CA 91103

No. of  
Copies

No of  
Copies

Walter Moore  
Veda, Inc.  
400 N. Mobil, Bldg. D  
Camarillo, CA 93010

V. Morris  
McDonnell Douglas  
5301 Bolsa Avenue  
Huntington Beach, CA 92647

E. Nelson  
ACUREX Corporation  
485 Clyde Avenue  
Mountain View, CA 94042

L.P. Oldham  
Martin Marietta Corp.  
MS S8120  
P.O. Box 179  
Denver, CO 80201

R. Pettit, 5842  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

J.A. Pietsch  
Northrup, Incorporated  
302 Nichols Drive  
Hutchins, TX 75141

P. Roth  
Sandia Laboratories  
Box 5800  
Albuquerque, NM 87115

J. Schrauth  
Jena Glaswerk Schoot  
& Gen., Inc.  
11 East 26th Street  
New York, NY 10010

J.C. Schumacher  
Schumacher & Associates  
2550 Fair Oaks Blvd., Suite 120  
Sacramento, CA 95825

R.N. Schweinberg  
DOE San Francisco Operations  
Office  
1333 Broadway  
Wells Fargo Building  
Oakland, CA 94612

J. Shelby  
Sandia Laboratories  
Livermore, CA 94550

A.F. Shoemaker  
Corning Glass Works  
Corning, NY 14830

John Thornton  
Solar Energy Research Institute  
1536 Cold Boulevard  
Golden, CO 80401

W. Tomlinson  
Environmental Library  
758 Eddy Street  
University of Montana  
Missoula, MT 59812

P. Tremblay  
Foster-Miller Associates  
135 Second Avenue  
Waltham, MA 02154

R.R. Walters  
E. Systems  
Energy Technology Center  
P.O. Box 6118  
Dallas, TX 75222

J.D. Walton, Jr.  
Engineering Experiment Station  
Georgia Institute of Technology  
Atlanta, GA 30332

R.C. Wayne, 8450  
Sandia Laboratories  
Livermore, CA 94550

No of  
Copies

L. Weinstein  
McDonnell Douglas  
Astronautics Co.  
5301 Bolsa Avenue  
Huntington Beach, CA 92647

S. White, 8451  
Sandia Laboratories  
Livermore, CA 94550

W.G. Wilson  
Sandia Laboratories  
Livermore, CA 94550

No of  
Copies

ONSITE

2 DOE Richland Operations Office

H.E. Ransom  
R. Stewart

44 Pacific Northwest Laboratory

L.S. Dake (24)  
K. Drumheller  
J.S. Hartman  
M.A. Lind (10)  
A.M. Sutey  
Publishing Coordination (2)  
Technical Information (5)

